

OWNER: DUNCAN AVIATION INCORPORATED -
BATTLE CREEK
ADDRESS: 15745 SOUTH AIRPORT ROAD
BATTLE CREEK MI 49015
PHONE: 269-969-8400
FAX: 269-969-8432

OPERATOR: DUNCAN AVIATION INCORPORATED -
BATTLE CREEK
ADDRESS: 15745 SOUTH AIRPORT ROAD
BATTLE CREEK MI 49015
PHONE: 269-969-8400
FAX: 269-969-8432

ANALYST: GARY JUST
EMAIL: GJUST@CAMPSYSTEMS.COM

+1-631-619-4583 (DIRECT)
877-411-CAMP (2267) (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PLEASE RECORD CHANGES TO ADDRESS, LAST
ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO
CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 3209/N430FJ **MODEL:** DORNIER 328-300 **MANUFACTURER:** 328 SUPPORT SERVICES GMBH

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	27-FEB-2002	6590.1 A/C HRS	as of 13-AUG-2019	A/C HRS	as of ___/___/___
INSERVICE DATE:	27-FEB-2002	6430 AFL	as of 13-AUG-2019	AFL	as of ___/___/___
		6157 APH	as of 05-FEB-2018	APH	as of ___/___/___
		0 APS	as of 11-AUG-2016	APS	as of ___/___/___

APU SERIAL/PART: P-293/3800498-3 **MODEL:** GTCP 36-150DD **MANUFACTURER:** HONEYWELL

INSTALLED ON 27-FEB-2002		LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS		6157 APU HRS	as of 05-FEB-2018	APU HRS	as of ___/___/___
0 APUS		0 APUS	as of 15-MAR-2016	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: CD-0233/PW306B **MODEL:** PW306B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 24-AUG-2011		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	6621.1 ENG. HRS	as of 13-AUG-2019	ENG. HRS	as of ___/___/___
0 ENC		6309 ENC	as of 13-AUG-2019	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: CD-0237/PW306B **MODEL:** PW306B **MANUFACTURER:** PRATT & WHITNEY CANADA CORP.

INSTALLED ON 24-AUG-2011		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	6631.2 ENG. HRS	as of 13-AUG-2019	ENG. HRS	as of ___/___/___
0 ENC		6383 ENC	as of 13-AUG-2019	ENC	as of ___/___/___

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION							
00100	AIRCRAFT REGISTRATION-FAR 47.40							
	PKG 7	MOS	36	-6m		31-JUL-2014	31-JUL-2017	
	REF:	HRS/MSC				5933.9		
		AFL				6154		
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
050001	PHASE 1 INSPECTION							
+	PKG 1	DAYS	15	+2		13-JUN-2019	28-JUN-2019	30-JUN-2019
	REF: LUMP SECTION A	HRS/MSC				6590.1		
		AFL				6430		
050002	PHASE 2 INSPECTION							
+	PKG 2	DAYS	225	+14		20-FEB-2019	03-OCT-2019	17-OCT-2019
	REF: LUMP SECTION A	HRS/MSC				6584.3		
		AFL				6425		
050003	PHASE 3 INSPECTION							
+	PKG 3	MOS	15	+1m		01-DEC-2017	01-MAR-2019	01-APR-2019
	REF: LUMP SECTION A	HRS/MSC				6428.4		
		AFL				6367		
050004	PHASE 4 INSPECTION							
+	PKG 4	MOS	30	+2m		01-DEC-2017	01-JUN-2020	01-AUG-2020
	REF: LUMP SECTION A	HRS/MSC				6428.4		
		AFL				6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050005	PHASE 5 INSPECTION							
+								
	PKG 5	MOS	60			08-JUN-2018	08-JUN-2023	08-OCT-2023
		HRS/MSC				6504.7		
	REF: LUMP SECTION A	AFL				6393		
<hr/>								
050006	PHASE 6 INSPECTION							
+								
	PKG 6	MOS	120			04-FEB-2011	04-FEB-2021	04-AUG-2021
		HRS/MSC				5276.6		
	REF: LUMP SECTION A	AFL				5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
00-00-01-00-00	INSPECTION REQUIREMENTS FOR PRINCIPLE STRUCTURAL ELEMENTS	MOS					27-FEB-2002		
	REF:	HRS/MSC -					0		
		AFL					0		
00200	REDUCED VERTICAL SEPARATION MINIMUM (RVSM) MONITORING REQUIREMENTS	MOS					24-SEP-2011		
	REF:	HRS/MSC 1000					5486.8	6486.8	
		AFL					5957		
3283-160430-TR-114	REVIEW DORNIER 328-300 TR LUMPD-114	MOS					27-FEB-2002		
	REQUIREMENT CHANGE FORMS	HRS/MSC -		TSI:0			0		
	REF: RCF 3283	AFL		TSI:0			0		
3283-160530-TR-115	REVIEW DORNIER 328-300 TR LUMPD-115	MOS					(EBT)		
	REQUIREMENT CHANGE FORMS	HRS/MSC -							
	REF: GENERIC NO REF	AFL							
3283-160601	REVIEW DORNIER 328-300 LUMPD REVISION 12	MOS					27-FEB-2002		
	REQUIREMENT CHANGE FORMS	HRS/MSC -		TSI:0			0		
	REF: RCF 3283	AFL		TSI:0			0		
3283-160701-TR-116	REVIEW DORNIER 328-300 TR LUMPD-116	MOS					(EBT)		
	REQUIREMENT CHANGE FORMS	HRS/MSC -							
	REF: RCF 3283	AFL							



Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3283-160729-TR-117	REVIEW DORNIER 328-300 TR LUMPD-117	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 3283	HRS/MSC - AFL							
3283-170101-TR-122	REVIEW DORNIER 328-300 TR LUMPD-122	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 3283	HRS/MSC - AFL							
3283-180430	REVIEW DORNIER 328-300 TR LUMPD-130	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 3283	HRS/MSC - AFL							
3283-180831	REVIEW DORNIER 328-300 TR LUMPD-131	MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF 3283	HRS/MSC - AFL							
ENROLLMENT DOCUMENTS	ENROLLMENT DOCUMENTATION ARCHIVE (SEE REMARKS)	MOS					27-FEB-2002		
	REF:	HRS/MSC - AFL					0		
							0		
ENGINE NO. 1	Model : PW306B	Serial # CD-0233	Part # PW306B						
E028-160516	NO. 1 ENGINE - REVIEW PW306B MAINTENANCE MANUAL (P/N 30B41320) REVISION NO. 30.0 DATED MAY 16/2016								
REQUIREMENT CHANGE FORMS	REF: RCF E028	MOS HRS/MSC - ENC					(EBT)		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

E028-170619	NO. 1 ENGINE - REVIEW PW306B EMM REV 32.0						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E028	MOS HRS/MSC - ENC							

ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B

E028-160516	NO. 2 ENGINE - REVIEW PW306B MAINTENANCE MANUAL (P/N 30B41320) REVISION NO. 30.0 DATED MAY 16/2016						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E028	MOS HRS/MSC - ENC							

E028-170619	NO. 2 ENGINE - REVIEW PW306B EMM REV 32.0						(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF E028	MOS HRS/MSC - ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

+ Z-100-01-01 (s)	100, LOWER FUSELAGE - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL LOWER FUSELAGE FROM GROUND						PKG		
05.010	PKG 1	DAYS	15	+2			13-JUN-2019	6590.1	6430
	REF: AMM 05-29-10	HRS/MSC AFL							

+ Z-100-02-01 (s)	100, LOWER FUSELAGE - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL LOWER FUSELAGE COMPONENTS						PKG		
05.015	PKG 4	MOS	30	+4m			01-DEC-2017	6428.4	6367
	REF: AMM 05-29-10	HRS/MSC AFL							

+ Z-110-01-01 (s)	110, RADOME AND FRONT AVIONIC BAY - PERFORM GENERAL VISUAL INSPECTION OF RADOME AND FRONT AVIONIC BAY						PKG		
05.020	PKG 3	MOS	15	+1m		-20	01-DEC-2017	6428.4	6367
	REF: AMM 05-29-10	HRS/MSC AFL							

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-122-01-01 (s)	122, LOWER FUSELAGE FRONT SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE FRONT SECTION, RIGHT (EWIS)						PKG		
05.025	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ Z-123-01-01 (s)	123, LOWER FUSELAGE FRONT SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE FRONT SECTION, LEFT (EWIS)						PKG		
05.030	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ Z-124-01-01 (s)	124, LOWER FUSELAGE FRONT SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE FRONT SECTION, RIGHT (EWIS)						PKG		
05.035	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ Z-125-01-01 (s)	125, LOWER FUSELAGE FRONT SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE FRONT SECTION, LEFT (EWIS)						PKG		
05.040	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ Z-131-01-01 (s)	131, MLG NACELLE FORWARD EQUIPMENT BAY, LEFT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE FORWARD EQUIPMENT BAY, LEFT						PKG		
05.045	PKG 2 REF: AMM 05-29-10	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-131-02-01 (s)	131, MLG NACELLE FORWARD EQUIPMENT BAY, LEFT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE FORWARD EQUIPMENT BAY, LEFT						PKG		
05.050	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-132-01-01 (s)	132, MLG NACELLE FORWARD EQUIPMENT BAY, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE FORWARD EQUIPMENT BAY, RIGHT						PKG		
05.055	PKG 2 REF: AMM 05-29-10	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-132-02-01 (s)	132, MLG NACELLE FORWARD EQUIPMENT BAY, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE FORWARD EQUIPMENT BAY, RIGHT						PKG		
05.060	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-135-01-01 (s)	135, MLG NACELLE REAR EQUIPMENT BAY, LEFT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE REAR EQUIPMENT BAY, LEFT (EWIS)						PKG		
05.065	PKG 3 REF: AMM 05-29-10	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
+ Z-136-01-01 (s)	136, MLG NACELLE REAR EQUIPMENT BAY, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE REAR EQUIPMENT BAY, RIGHT (EWIS)						PKG		
05.070	PKG 3 REF: AMM 05-29-10	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
+ Z-137-01-01 (s)	137, MLG NACELLE REAR CENTER EQUIPMENT BAY - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE REAR CENTER EQUIPMENT BAY						PKG		
05.075	PKG 4 REF: AMM 05-29-10	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ Z-137-02-01 (s)	137, MLG NACELLE REAR CENTER EQUIPMENT BAY - PERFORM GENERAL VISUAL INSPECTION OF MLG NACELLE REAR CENTER EQUIPMENT BAY (EWIS)						PKG		
05.080	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-138-01-01 (s)	138, LOWER FUSELAGE CENTER SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE CENTER SECTION, RIGHT (EWIS)						PKG		
05.085	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ Z-139-01-01 (s)	139, LOWER FUSELAGE CENTER SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE CENTER SECTION, LEFT (EWIS)						PKG		
05.090	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60			-61	08-JUN-2018 6504.7 6393		
+ Z-141-01-01 (s)	141, LOWER FUSELAGE AFT SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE AFT SECTION, LEFT						PKG		
05.095	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-142-01-01 (s)	142, LOWER FUSELAGE AFT SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL LOWER FUSELAGE AFT SECTION, RIGHT						PKG		
05.100	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-143-01-01 (s)	143, LOWER FUSELAGE AFT AVIONIC COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF LOWER FUSELAGE AFT SECTION AVIONIC COMPARTMENT						PKG		
05.105	PKG 5 REF: AMM 05-29-10	MOS HRS/MSC AFL	60				08-JUN-2018 6504.7 6393		
+ Z-200-01-01 (s)	200, UPPER FUSELAGE - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL UPPER FUSELAGE FROM GROUND						PKG		
05.110	PKG 1 REF: AMM 05-29-20	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-200-02-01 (s)	200, UPPER FUSELAGE - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL UPPER FUSELAGE						PKG		
05.115	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-210-01-01 (s)	210, FLIGHT COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL FLIGHT COMPARTMENT						PKG		
05.120	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-210-03-01 (s)	210, FLIGHT COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL FLIGHT COMPARTMENT (EWIS)						PKG		
05.125	PKG 6 REF: AMM 05-29-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-210-04-01 (s)	210, FLIGHT COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL FLIGHT COMPARTMENT						PKG		
05.130	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-221-01-01 (s)	221, PASSENGER COMPARTMENT, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL PASSENGER COMPARTMENT, LEFT (EWIS)						PKG		
05.135	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ Z-221-02-01 (s)	221, PASSENGER COMPARTMENT, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL PASSENGER COMPARTMENT, LEFT						PKG		
05.140	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-222-01-01 (s)	222, PASSENGER COMPARTMENT, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL PASSENGER COMPARTMENT, RIGHT (EWIS)						PKG		
05.145	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ Z-222-02-01 (s)	222, PASSENGER COMPARTMENT, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL PASSENGER COMPARTMENT, RIGHT						PKG		
05.150	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-223-01-01 (s)	223, OVERHEAD PASSENGER UTILITIES, LEFT - PERFORM GENERAL VISUAL INSPECTION OF OVERHEAD PASSENGER UTILITIES, LEFT						PKG		
05.155	PKG 6 REF: AMM 05-29-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-224-01-01 LU (s)	224, OVERHEAD PASSENGER UTILITIES AND STOWAGE, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF OVERHEAD PASSENGER UTILITIES AND STOWAGE COMPARTMENTS, RIGHT						PKG		
05.160	PKG 6 REF: AMM 05-29-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-228-01-01 LU (s)	228, GALLEY - PERFORM GENERAL VISUAL INSPECTION OF GALLEY						PKG		
05.165	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+6m			01-DEC-2017 6428.4 6367		
+ Z-229-01-01 LU (s)	229, LAVATORY - PERFORM GENERAL VISUAL INSPECTION OF LAVATORY						PKG		
05.170	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-230-01-01 LU (s)	230, CARGO COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL CARGO COMPARTMENT						PKG		
05.175	PKG 6 REF: AMM 05-29-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-230-03-01 LU (s)	230, CARGO COMPARTMENT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL CARGO COMPARTMENT						PKG		
05.180	PKG 4 REF: AMM 05-29-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-241-01-01 LU (s)	241, UPPER FORWARD TRANSITION FAIRING, FRONT SECTION - PERFORM GENERAL VISUAL INSPECTION OF UPPER FORWARD TRANSITION FAIRING FRONT SECTION						PKG		
05.185	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
Z-241-02-01 (s)	241, UPPER TRANSITION FAIRING FRONT SECTION - PERFORM GENERAL VISUAL INSPECTION OF UPPER TRANSITION FAIRING FRONT SECTION						PKG		
	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60				08-JUN-2018 6504.7 6393		
Z-241-03-01 (s)	241, UPPER FORWARD TRANSITION FAIRING FRONT SECTION - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL UPPER FORWARD TRANSITION FAIRING FRONT SECTION						PKG		
	PKG 6 REF: AMM 05-29-20	MOS HRS/MSC AFL	120				11-FEB-2011 5276.6 5873		
+ Z-242-01-01 LU (s)	242, UPPER FORWARD TRANSITION FAIRING REAR SECTION, RIGHT ECS AREA - PERFORM GENERAL VISUAL INSPECTION OF UPPER FORWARD TRANSITION FAIRING REAR SECTION, RIGHT ECS AREA						PKG		
05.190	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-243-01-01 LU (s)	243, UPPER FORWARD TRANSITION FAIRING REAR SECTION, LEFT ECS AREA - PERFORM GENERAL VISUAL INSPECTION OF UPPER FORWARD TRANSITION FAIRING REAR SECTION, LEFT ECS AREA						PKG		
05.195	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-251-01-01 LU (s)	251, UPPER REAR TRANSITION FAIRING FRONT SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF UPPER REAR TRANSITION FAIRING FRONT SECTION, LEFT (EWIS)						PKG		
05.200	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
Z-251-02-01 (s)	251, UPPER REAR TRANSITION FAIRING FRONT SECTION, LEFT - PERFORM GENERAL VISUAL INSPECTION OF UPPER REAR TRANSITION FAIRING FRONT SECTION, LEFT (EWIS)						PKG		
	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60				08-JUN-2018 6504.7 6393		
+ Z-252-01-01 LU (s)	252, UPPER REAR TRANSITION FAIRING FRONT SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF UPPER REAR TRANSITION FAIRING FRONT SECTION, RIGHT (EWIS)						PKG		
05.205	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
Z-252-02-01 (s)	252, UPPER REAR TRANSITION FAIRING FRONT SECTION, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF UPPER REAR TRANSITION FAIRING FRONT SECTION, RIGHT (EWIS)						PKG		
	PKG 5 REF: AMM 05-29-20	MOS HRS/MSC AFL	60				08-JUN-2018 6504.7 6393		
+ Z-253-01-01 LU (s)	253, UPPER REAR TRANSITION FAIRING CENTER SECTION - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL UPPER REAR TRANSITION FAIRING CENTER SECTION (EWIS)						PKG		
05.210	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
Z-253-02-01 (s)	253, UPPER REAR TRANSITION FAIRING CENTER SECTION - PERFORM GENERAL VISUAL INSPECTION OF UPPER REAR TRANSITION FAIRING CENTER SECTION						PKG		
	PKG 5	MOS	60				08-JUN-2018		
	REF: AMM 05-29-20	HRS/MSC					6504.7		
		AFL					6393		
Z-253-03-01 (s)	253, UPPER REAR TRANSITION FAIRING CENTER SECTION - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL UPPER REAR TRANSITION FAIRING CENTER SECTION						PKG		
	PKG 6	MOS	120				11-FEB-2011		
	REF: AMM 05-29-20	HRS/MSC					5276.6		
		AFL					5873		
+ Z-254-01-01 LU (s)	254, DORSAL FIN - PERFORM GENERAL VISUAL INSPECTION OF DORSAL FIN (EWIS)						PKG		
	PKG 5	MOS	60	+4m			08-JUN-2018		
05.215	REF: AMM 05-29-20	HRS/MSC					6504.7		
		AFL					6393		
+ Z-300-01-01 LU (s)	300, STABILIZER - PERFORM GENERAL VISUAL INSPECTION OF REAR FUSELAGE AND EMPENNAGE FROM GROUND						PKG		
	PKG 1	DAYS	15	+2			13-JUN-2019		
05.220	REF: AMM 05-29-30	HRS/MSC					6590.1		
		AFL					6430		
+ Z-300-02-01 LU (s)	300, STABILIZER - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL REAR FUSELAGE AND EMPENNAGE. ELEVATOR / RUDDER DEFLECTED						PKG		
	PKG 4	MOS	30	+4m			01-DEC-2017		
05.225	REF: AMM 05-29-30	HRS/MSC					6428.4		
		AFL					6367		
+ Z-311-01-01 LU (s)	311, REAR FUSELAGE - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL REAR FUSELAGE (EWIS)						PKG		
	PKG 4	MOS	30	+2m			01-DEC-2017		
05.230	REF: AMM 05-29-30	HRS/MSC					6428.4		
		AFL					6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-312-01-01 LU (s)	312, TAIL CONE - PERFORM GENERAL VISUAL INSPECTION OF APU COMPARTMENT (EWIS)						PKG		
05.235	PKG 2 REF: AMM 05-29-30	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-312-03-01 LU (s)	312, TAIL CONE - PERFORM GENERAL VISUAL INSPECTION OF TAIL CONE / APU COMPARTMENT						PKG		
05.240	PKG 4 REF: AMM 05-29-30	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-321-01-01 LU (s)	321, VERTICAL STABILIZER LEADING EDGE - PERFORM GENERAL VISUAL INSPECTION OF THE VERTICAL STABILIZER LEADING EDGE						PKG		
05.245	PKG 5 REF: AMM 05-29-30	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-322-01-01 LU (s)	322, VERTICAL STABILIZER SPAR BOX, LEFT AND RIGHT - PERFORM GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER SPAR BOX, LEFT AND RIGHT						PKG		
05.250	PKG 5 REF: AMM 05-29-30	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
Z-323-01-01 LU (s)	323, VERTICAL STABILIZER TIP - PERFORM GENERAL VISUAL INSPECTION OF VERTICAL STABILIZER TIP						PKG		
28.320	PKG 6 REF: AMM 05-29-30	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ Z-324-01-01 LU (s)	324, RUDDER, LEFT AND RIGHT - PERFORM GENERAL VISUAL INSPECTION OF RUDDER AND TRIM/SPRING TAB, LEFT AND RIGHT						PKG		
05.255	PKG 5 REF: AMM 05-29-30	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-330-01-01 LU (s)	330, HORIZONTAL STABILIZER, LEFT - PERFORM GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER AND TRIM TAB, LEFT						PKG		
05.260	PKG 5 REF: AMM 05-29-30	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-340-01-01 LU (s)	340, HORIZONTAL STABILIZER, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF HORIZONTAL STABILIZER AND TRIM TAB, RIGHT						PKG		
05.265	PKG 5 REF: AMM 05-29-30	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-400-01-01 LU (s)	400, POWERPLANT - PERFORM GENERAL VISUAL INSPECTION OF VISIBLE PORTIONS OF POWER PLANTS FROM GROUND						PKG		
05.270	PKG 1 REF: AMM 05-29-40	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ Z-411-01-01 LU (s)	411, INLET, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INLET, LEFT						PKG		
05.275	PKG 2 REF: AMM 05-29-40	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-412-01-01 LU (s)	412, ENGINE, LEFT - PERFORM GENERAL VISUAL INSPECTION OF ENGINE, LEFT (EWIS)						PKG		
05.280	PKG 2 REF: AMM 05-29-40	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-413-01-01 LU (s)	413, BYPASS DUCT AND EXHAUST, LEFT - PERFORM GENERAL VISUAL INSPECTION OF BYPASS DUCT AND EXHAUST, LEFT						PKG		
05.285	PKG 3 REF: AMM 05-29-40	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-421-01-01 LU (s)	421, INLET, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INLET, RIGHT						PKG		
05.290	PKG 2 REF: AMM 05-29-40	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-422-01-01 LU (s)	422, ENGINE, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF ENGINE, RIGHT (EWIS)						PKG		
05.295	PKG 2 REF: AMM 05-29-40	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-423-01-01 LU (s)	423, BYPASS DUCT AND EXHAUST, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF BYPASS DUCT AND EXHAUST, RIGHT						PKG		
05.300	PKG 3 REF: AMM 05-29-40	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
+ Z-430-01-01 LU (s)	430, PYLON, LEFT - PERFORM GENERAL VISUAL INSPECTION OF PYLON, LEFT (EWIS)						PKG		
05.305	PKG 4 REF: AMM 05-29-40	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ Z-440-01-01 LU (s)	430, PYLON, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF PYLON, RIGHT (EWIS)						PKG		
05.310	PKG 4 REF: AMM 05-29-40	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ Z-500-01-01 LU (s)	500, WING, LEFT - PERFORM GENERAL VISUAL INSPECTION OF WING FROM GROUND, LEFT						PKG		
05.315	PKG 1 REF: AMM 05-29-50	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ Z-500-02-01 LU (s)	500, WING, LEFT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL WING, LEFT						PKG		
05.320	PKG 4 REF: AMM 05-29-50	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-511-01-01 LU (s)	511, LEADING EDGE INNER WING, LEFT - PERFORM GENERAL VISUAL INSPECTION OF LEADING EDGE INNER WING, LEFT (EWIS)						PKG		
05.325	PKG 4 REF: AMM 05-29-50	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-512-01-01 LU (s)	512, LEADING EDGE OUTER WING, LEFT - PERFORM GENERAL VISUAL INSPECTION OF LEADING EDGE OUTER WING, LEFT						PKG		
05.330	PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
Z-513-01-01 (s)	513, WING TIP, LEFT - PERFORM GENERAL VISUAL INSPECTION OF WING TIP, LEFT						PKG		
Z.05	PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ Z-521-01-01 LU (s)	521, SPAR BOX CENTER WING, INNER WING TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL INBOARD WING TANK, LEFT						PKG		
05.335	PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-521-02-01 LU (s)	521, SPAR BOX CENTER WING, INNER WING TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL INBOARD WING TANK, LEFT						PKG		
05.340	PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-522-01-01 LU (s)	522, SPAR BOX OUTER WING, OUTER WING TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL OUTER WING TANK, LEFT						PKG		
05.345	PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-522-02-01 LU (s)	522, SPAR BOX OUTER WING, OUTER WING TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL OUTER WING TANK, LEFT						PKG		
05.350	PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-523-01-01 LU (s)	523, SPAR BOX OUTER WING, FEEDER TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL FEEDER TANK, LEFT						PKG		
05.355	PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-523-02-01 LU (s)	523, SPAR BOX OUTER WING, FEEDER TANK, LEFT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL FEEDER TANK, LEFT						PKG		
05.360	PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-530-01-01 LU (s)	530, TRAILING EDGE , LEFT - PERFORM GENERAL VISUAL INSPECTION OF TRAILING EDGE , LEFT (EWIS)						PKG		
05.365	PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ Z-540-01-01 LU (s)	540, FLAP, LEFT - PERFORM GENERAL VISUAL INSPECTION OF FLAP, LEFT						PKG		
05.370	PKG 4 REF: AMM 05-29-50	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-550-01-01 LU (s)	550, AILERON, LEFT - PERFORM GENERAL VISUAL INSPECTION OF AILERON, LEFT						PKG		
05.375	PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-560-01-01 LU (s) 05.380	560, GROUNDSPOILER, LEFT - PERFORM GENERAL VISUAL INSPECTION OF GROUNDSPOILER, LEFT PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			PKG 08-JUN-2018 6504.7 6393		
+ Z-570-01-01 LU (s) 05.385	570, ROLLSPOILER, LEFT - PERFORM GENERAL VISUAL INSPECTION OF THE ROLLSPOILER, LEFT PKG 5 REF: AMM 05-29-50	MOS HRS/MSC AFL	60	+6m			PKG 08-JUN-2018 6504.7 6393		
+ Z-600-01-01 LU (s) 05.390	600, WING, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF WING FROM GROUND, RIGHT PKG 1 REF: AMM 05-29-60	DAYS HRS/MSC AFL	15	+2			PKG 13-JUN-2019 6590.1 6430		
+ Z-600-02-01 LU (s) 05.395	600, WING, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL WING, RIGHT PKG 4 REF: AMM 05-29-60	MOS HRS/MSC AFL	30	+4m			PKG 01-DEC-2017 6428.4 6367		
+ Z-611-01-01 LU (s) 05.400	611, LEADING EDGE INNER WING, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF LEADING EDGE INNER WING, RIGHT (EWIS) PKG 4 REF: AMM 05-29-60	MOS HRS/MSC AFL	30	+4m			PKG 01-DEC-2017 6428.4 6367		
+ Z-612-01-01 LU (s) 05.405	612, LEADING EDGE OUTER WING, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF LEADING EDGE OUTER WING, RIGHT PKG 6 REF: AMM 05-29-60	MOS HRS/MSC AFL	120	+6m			PKG 11-FEB-2011 5276.6 5873		
Z-613-01-01 (s) Z.010	613, WING TIP, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF WING TIP, RIGHT PKG 6 REF: AMM 05-29-50	MOS HRS/MSC AFL	120	+6m			PKG 04-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-621-01-01 LU (s)	621, SPAR BOX CENTER WING, INNER WING TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL INBOARD WING TANK, RIGHT						PKG		
05.410	PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-621-02-01 LU (s)	621, SPAR BOX CENTER WING, INNER WING TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL INBOARD WING TANK, RIGHT						PKG		
05.415	PKG 6 REF: AMM 05-29-60	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-622-01-01 LU (s)	622, SPAR BOX OUTER WING, OUTER WING TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL OUTER WING TANK, RIGHT						PKG		
05.420	PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-622-02-01 LU (s)	622, SPAR BOX OUTER WING, OUTER WING TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL OUTER WING TANK, RIGHT						PKG		
05.425	PKG 6 REF: AMM 05-29-60	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ Z-623-01-01 LU (s)	623, SPAR BOX OUTER WING, FEEDER TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF EXTERNAL FEEDER TANK, RIGHT						PKG		
05.430	PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ Z-623-02-01 LU (s)	623, SPAR BOX OUTER WING, FEEDER TANK, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF INTERNAL FEEDER TANK, RIGHT						PKG		
05.435	PKG 6 REF: AMM 05-29-60	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-630-01-01 LU (s) 05.440	630, OF TRAILING EDGE, RIGHT - PERFORM PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+4m		-61	PKG 08-JUN-2018 6504.7 6393		
+ Z-640-01-01 LU (s) 05.445	640, FLAP, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF FLAP, RIGHT PKG 4 REF: AMM 05-29-60	MOS HRS/MSC AFL	30				PKG 01-DEC-2017 6428.4 6367		
+ Z-650-01-01 LU (s) 05.450	650, AILERON, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF AILERON, RIGHT PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			PKG 08-JUN-2018 6504.7 6393		
+ Z-660-01-01 LU (s) 05.455	660, GROUNDSPOILER, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF GROUNDSPOILER, RIGHT PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			PKG 08-JUN-2018 6504.7 6393		
+ Z-670-01-01 LU (s) 05.460	670, ROLLSPOILER, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF THE ROLLSPOILER, RIGHT PKG 5 REF: AMM 05-29-60	MOS HRS/MSC AFL	60	+6m			PKG 08-JUN-2018 6504.7 6393		
+ Z-700-01-01 LU (s) 05.465	700, LANDING GEAR AND DOORS - PERFORM GENERAL VISUAL INSPECTION OF MLG, NLG AND DOORS PKG 1 REF: AMM 05-29-70	DAYS HRS/MSC AFL	15	+2			PKG 13-JUN-2019 6590.1 6430		
+ Z-710-01-01 LU (s) 05.470	710, NOSE LANDING GEAR AND DOORS - PERFORM GENERAL VISUAL INSPECTION OF NLG, DOORS AND NLG BAY (EWIS) PKG 2 REF: AMM 05-29-70	DAYS HRS/MSC AFL	225	+14			PKG 20-FEB-2019 6584.3 6425		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-720-01-01 LU (s)	720, MAIN LANDING GEAR AND DOORS - PERFORM GENERAL VISUAL INSPECTION OF MLG, DOORS AND MLG BAY (EWIS)						PKG		
05.475	PKG 2 REF: AMM 05-29-70	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ Z-800-01-01 LU (s)	800, DOORS - PERFORM GENERAL VISUAL INSPECTION OF VISIBLE PARTS OF PASSENGER, CARGO, SERVICE DOORS AND EMERGENCY EXITS FROM GROUND						PKG		
05.480	PKG 1 REF: AMM 05-29-80	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ Z-811-01-01 LU (s)	811, PASSENGER / CREW DOOR - PERFORM GENERAL VISUAL INSPECTION OF PASSENGER / CREW DOOR						PKG		
05.485	PKG 3 REF: AMM 05-29-80	MOS HRS/MSC AFL	15	+4m			01-DEC-2017 6428.4 6367		
+ Z-812-01-01 LU (s)	812, EMERGENCY EXIT, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF EMERGENCY EXIT, RIGHT						PKG		
05.490	PKG 4 REF: AMM 05-29-80	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-813-01-01 LU (s)	813, EMERGENCY EXIT, LEFT - PERFORM GENERAL VISUAL INSPECTION OF EMERGENCY EXIT, LEFT						PKG		
05.495	PKG 4 REF: AMM 05-29-80	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-814-01-01 LU (s)	814, SERVICE DOOR - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR						PKG		
05.500	PKG 4 REF: AMM 05-29-80	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ Z-815-01-01 LU (s)	815, CARGO DOOR - PERFORM GENERAL VISUAL INSPECTION OF CARGO DOOR						PKG		
05.505	PKG 4 REF: AMM 05-29-80	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ Z-816-01-01 LU (s)	816, CREW HATCH - PERFORM GENERAL VISUAL INSPECTION OF CREW EMERGENCY HATCH						PKG		
05.510	PKG 4 REF: AMM 05-29-80	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B

055000	NO. 1 ENGINE - OVERTEMPERATURE EXCEEDANCE						04-FEB-2002		
	REF:	MOS HRS/MSC - ENC					0 0		

057101	NO. 1 ENGINE - MINOR INSPECTION						01-DEC-2017 6459.5	01-JUN-2018	
	REF: See Workcard	MOS HRS/MSC ENC	6						

057120	NO. 1 ENGINE - INSPECTION LOW UTILIZATION						09-MAY-2019 6621.1 6309	09-MAY-2021	09-MAY-2022
	REF: EMM 72-00-00	MOS HRS/MSC ENC	24	+12m					

ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B

055000	NO. 2 ENGINE - OVERTEMPERATURE EXCEEDANCE						24-JAN-2002		
	REF:	MOS HRS/MSC - ENC					0 0		

057101	NO. 2 ENGINE - MINOR INSPECTION						01-DEC-2017 6469.5	01-JUN-2018	
	REF: See Workcard	MOS HRS/MSC ENC	6						

057120	NO. 2 ENGINE - INSPECTION LOW UTILIZATION						09-MAY-2019 6631.2	09-MAY-2021	09-MAY-2022
	REF: EMM 72-00-00	MOS HRS/MSC ENC	24	+12m					

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 20 STANDARD PRACTICES - AIRFRAME									
20-04-30-01-01 (s)	FORWARD PYLON SUPPORT, LH - PERFORM DETAILED INSPECTION OF EWIS AT FORWARD PYLON SUPPORT, LH (EWIS)						PKG		
20.215	PKG 4 REF: AMM 05-29-40	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
20-04-40-01-01 (s)	FORWARD PYLON SUPPORT, RH - PERFORM DETAILED INSPECTION OF EWIS AT FORWARD PYLON SUPPORT, RH (EWIS)						PKG		
20.220	PKG 4 REF: AMM 05-29-40	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 20-28-00-03-01 (s)	AIRCRAFT ELECTRICAL BONDING - PERFORM DETAILED INSPECTION OF LEFT ENGINE FADEC SHOCK ABSORBER BYPASSING BONDING STRAPS AND IGNITER BOXES BONDING STRAPS						PKG		
20.010	PKG 2 REF: See Workcard	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 20-28-00-03-02 (s)	AIRCRAFT ELECTRICAL BONDING - PERFORM DETAILED INSPECTION OF RIGHT ENGINE FADEC SHOCK ABSORBER BYPASSING BONDING STRAPS AND IGNITER BOXES BONDING STRAPS						PKG		
20.080	PKG 2 REF: See Workcard	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 20-28-00-04-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF LEFT ENGINE FADEC SHOCK ABSORBER BYPASSING BONDING STRAPS AND IGNITER BOXES BONDING STRAPS FOR ELECTRICAL RESISTANCE								
20.015	REF: AMM 20-28-70	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 20-28-00-04-02	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF RIGHT ENGINE FADEC SHOCK ABSORBER BYPASSING BONDING STRAPS AND IGNITER BOXES BONDING STRAPS FOR ELECTRICAL RESISTANCE								
20.090	REF: AMM 20-28-70	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020
+ 20-28-00-05-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF RADOME - FRONT FUSELAGE BONDING FOR ELECTRICAL RESISTANCE								
20.020	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-06-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF AFT CENTER FUSELAGE - TAIL CONE BONDING FOR ELECTRICAL RESISTANCE								
20.025	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-07-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF WING - PYLON (LEFT & RIGHT) BONDING FOR ELECTRICAL RESISTANCE								
20.030	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-08-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF VERTICAL STABILIZER, UPPER END RIB - REAR FUSELAGE BONDING FOR ELECTRICAL RESISTANCE								
20.035	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-09-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF VERTICAL STABILIZER, UPPER END RIB - ELEVATOR, OUTER RIB BONDING FOR ELECTRICAL RESISTANCE								
20.040	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 20-28-00-10-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF VERTICAL STABILIZER, UPPER END RIB - RUDDER, UPPER END RIB BONDING FOR ELECTRICAL RESISTANCE								
20.045	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-11-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF WING - FUSELAGE BONDING FOR ELECTRICAL RESISTANCE								
20.050	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-12-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF WING - UPPER FUEL TANK ACCESS PANEL BONDING FOR ELECTRICAL RESISTANCE								
20.055	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-13-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF WING - AILERON, OUTER RIB (LEFT AND RIGHT) BONDING FOR ELECTRICAL RESISTANCE								
20.060	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-14-01	AIRCRAFT ELECTRICAL BONDING - PERFORM FUNCTIONAL CHECK OF WING - FLAP, TRAILING EDGE (LEFT AND RIGHT) BONDING FOR ELECTRICAL RESISTANCE								
20.065	REF: AMM 20-28-00	MOS HRS/MSC AFL	90	+6m			01-DEC-2017 6428.4 6367	01-JUN-2025	01-DEC-2025
+ 20-28-00-15-01 (s)	AIRCRAFT ELECTRICAL BONDING - PERFORM DETAILED INSPECTION OF ANTI SKID CONTROL UNIT A/C CONNECTOR SHELL EMI SPRING						PKG		
20.070	PKG 2 REF: AMM 32-40-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
20-28-00-16-01 (s)	BONDING AT WINDSHIELD Z-BAR - PERFORM DETAILED INSPECTION OF BONDING AT WINDSHIELD Z-BAR						PKG		
20.225	PKG 4 REF: AMM 56-11-00	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
20-28-00-17-01 (s)	AIRCRAFT ELECTRICAL BONDING - PERFORM GENERAL VISUAL INSPECTION OF WING - FLAP BONDING STRAPS						PKG		
	PKG 4 REF: AMM 20-28-00	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
CHAPTER 21 AIR CONDITIONING									
21-20-00-01-01 (s)	AIR DISTRIBUTION - DISCARD CABIN RECIRCULATION FAN FILTER LOCATED BETWEEN FRAME 27 AND 31						PKG		
21.010	PH4 PKG 4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
21-20-00-02-01 (s)	AIR DISTRIBUTION - DISCARD OF COCKPIT RECIRCULATION FAN FILTER LOCATED BETWEEN FRAME 13 AND 18						PKG		
21.010	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
21-20-00-03-01 (s)	AIR DISTRIBUTION - DISCARD EFIS FAN FILTER						PKG		
21.020	PH2 PKG 3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	15	+14d	-20		01-DEC-2017 6428.4 6367		
+ 21-30-00-01-01 (s)	PRESSURIZATION CONTROL - PERFORM OPERATIONAL CHECK OF PRESSURIZATION CONTROL SYSTEM MAN / AUTO DUMP MODE						PKG		
21.040	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-30-00-02-01 (s)	PRESSURIZATION CONTROL - PERFORM OPERATIONAL CHECK OF PRESSURIZATION CONTROL SYSTEM MAN MODE						PKG		
21.035	PKG 4 REF: AMM 21-31-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 21-30-00-03-01 (s)	PRESSURIZATION CONTROL - PERFORM DETAILED INSPECTION OF ELECTRO - PNEUMATIC-OUTFLOW VALVE (EPOV) FOR CONDITION						PKG		
21.070	PH4 PKG 4 SN-UNKNOWN REF: AMM 21-31-03	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
21-30-00-04-01 (s)	PRESSURIZATION CONTROL - EPOV - DISCARD ELECTRO - PNEUMATIC-OUTFLOW VALVE (EPOV) AIR FILTER						PKG		
21.070	PH4 PKG 4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 21-30-00-05-01 (s)	PRESSURIZATION CONTROL - PERFORM DETAILED INSPECTION OF PNEUMATIC-OUTFLOW-VALVE FOR CONDITION						PKG		
21.065	PH5 PKG 4 SN-UNKNOWN REF: AMM 21-31-05	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 21-30-00-05-02 (s)	PNEUMATIC OUTFLOW VALVE - CLEAN PNEUMATIC OUTFLOW VALVE FILTER PLUGS						PKG		
21.065	PKG 3 REF: AMM 21-31-05	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367		
+ 21-30-00-06-01 (s)	PRESSURIZATION CONTROL - PERFORM OPERATIONAL CHECK OF 6.5 INCHES NON RETURN VALVE (NRV) (GROUND CONNECTION)						PKG		
21.015	PH5 PKG 4 SN-UNKNOWN REF: AMM 21-21-04	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 21-50-00-01-01 (s)	COOLING - PERFORM DETAILED INSPECTION OF DUAL HEAT EXCHANGER (LEFT AND RIGHT) FOR CONTAMINATION						PKG		
21.075	PKG 4 REF: AMM 21-51-12	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 21-50-00-02-01 (s)	COOLING - PERFORM FUNCTIONAL CHECKS OF THE OVER TEMPERATURE SWITCHES 5HB AND 15HB						PKG		
21.125	PKG 5 REF: AMM 21-51-14	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 21-50-00-03-01 (s)	COOLING - PERFORM VISUAL CHECK OF HEAT EXCHANGER FAN 61HB AND 68HB NON-RETURN VALVES						PKG		
21.130	PKG 5 REF: AMM 21-51-23	MOS HRS/MSC AFL	60	+2m		-61	08-JUN-2018 6504.7 6393		
+ 21-50-00-05-01 (s)	COOLING - PERFORM VISUAL CHECK OF ENVIRONMENTAL CONTROL UNIT (ECU) VIBRATION ABSORBERS (LEFT AND RIGHT)						PKG		
21.080	PKG 5 REF: AMM 21-51-99	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
212002	F28-29 RECIRCULATION FAN								
21.010	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
212007	NON-RETURN VALVE								
21.015	PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212009	FORWARD AVIONICS FAN								
21.020	PH2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
213011	ELECTRO-PNEUMATIC OUTFLOW VALVE								
21.070	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
213021	PNEUMATIC OUTFLOW VALVE								
21.065	PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
V21-30-00-03-01	ELECTRO-PNEUMATIC OUTFLOW VALVE - PERFORM CLEANING OF ELECTRO-PNEUMATIC OUTFLOW VALVE								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	2000				01-DEC-2017 6428.4 6367	8428.4	
V21-51-00-01-01	ECS SYSTEM - RESTORATION (CLEANING) OF PNEUMATIC TEMPERATURE SENSOR PN 5677C000 OR PN 5677C000-002 AND WATER SPRAY NOZZLE, LEFT AND RIGHT (OFF-AIRCRAFT)								
	REF: AMM 21-51-21	MOS HRS/MSC AFL	1600				01-DEC-2017 6428.4 6367	8028.4	
CHAPTER 22 AUTO FLIGHT									
+ 22-10-00-01-01 (s)	AUTOPILOT - PERFORM OPERATIONAL CHECK OF TOUCH CONTROL STEERING (TCS) AND GO AROUND SWITCHING						PKG		
22.010	PKG 4 REF: AMM 22-11-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-10-00-02-01 (s)	AUTOPILOT - PERFORM OPERATIONAL CHECK OF AUTOPILOT YAW, PITCH AND ROLL SERVO						PKG		
22.035	PKG 3 REF: AMM 22-11-00	MOS HRS/MSC AFL	15 1000	+1m +100			13-JUN-2019 6590.1 6430		
CHAPTER 23 COMMUNICATIONS									
+ 23-00-00-01-01 (s)	COMMUNICATIONS - PERFORM OPERATIONAL CHECK OF COCKPIT VOICE RECORDER (CVR) P/N 2100-1020-00 CHANNELS AND ERASE FUNCTION						PKG		
23.075	PKG 2 REF: AMM 23-71-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 23-00-00-02-01	COMMUNICATIONS - PERFORM OPERATIONAL CHECK (OFF-AIRCRAFT) OF UNDERWATER LOCATOR DEVICE OF COCKPIT VOICE RECORDER (CVR)								
23.075	REF: See Workcard	MOS HRS/MSC AFL	24	+2m	-67		13-JUN-2019 6590.1 6430	07-APR-2021	07-JUN-2021
23-00-00-03-01	COMMUNICATIONS - DISCARD COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATOR DEVICE (ULD) BATTERY (OFF-AIRCRAFT)								
23.075	DK120/90 AT54387 REF: See Workcard	MOS HRS/MSC AFL	72	+6m			13-JUN-2019 6590.1 6430	01-NOV-2023	M 01-MAY-2024
231001	NO. 1 INTEGRATED COMMUNICATION UNIT								
23.010	7510733-666 0602A389 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
231002	NO. 2 INTEGRATED COMMUNICATION UNIT								
23.010	7510733-666 99074184 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231011	NO. 1 RADIO MANAGEMENT UNIT								
23.020	7013270-966 95030324 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
231012	NO. 2 RADIO MANAGEMENT UNIT								
23.020	7013270-966 93090166 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
235001	AUDIO PANEL PEDESTAL								
23.060	7511001-912 99043872 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			28-NOV-2018 6558.8 6416		
237004	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON								
27.320	DK120/90 AT54387 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:26 TSN:251.5 TSN:100			13-JUN-2019 6590.1 6430		
CHAPTER 24 ELECTRICAL POWER									
24-21-00-01-01	LEFT ENGINE ALTERNATOR								
24.025 OVERHAUL	ALT 3524 1175 REF: See Workcard	MOS HRS/MSC AFL	4000	+200			15-JAN-2008 5233.9 5854	9233.9	M 9433.9
24-21-00-01-02	RIGHT ENGINE ALTERNATOR								
24.025 OVERHAUL	ALT 3524 1061 REF: See Workcard	MOS HRS/MSC AFL	4000	+200	TSN:0 TSN:0 TSN:0		27-FEB-2002 5247 0	9247	9447
24-23-00-03-01 (s)	MISSION POWER DISTRIBUTION - PERFORM OPERATIONAL CHECK OF MISSION POWER SUPPLY AND AUTOMATIC BUS SWITCHING						PKG		
24.115	PKG 3 REF: AMM 24-24-03	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-23-00-03-02 (s)	MISSION POWER DISTRIBUTION - PERFORM OPERATIONAL CHECK OF MISSION POWER SUPPLY AND AUTOMATIC BUS SWITCHING PKG 3 REF: See Workcard	MOS HRS/MSC AFL	15				PKG 01-DEC-2017 6428.4 6367		
24-23-00-04-01 (s) 24.120	MISSION POWER DISTRIBUTION - PERFORM OPERATIONAL CHECK OF FAULT CURRENT CIRCUIT BREAKERS PKG 2 REF: AMM 24-24-03	DAYS HRS/MSC AFL	225	+14	-221		PKG 20-FEB-2019 6584.3 6425		
24-30-00-01A-01 24.055	DISCARD NO. 1 ENGINE DC GENERATOR (OFF-AIRCRAFT) THE DC GENERATOR BRUSHES 8160-121 593 REF: See Workcard	MOS HRS/MSC AFL	600	+100			13-JUN-2019 6590.1 6430	7190.1	7290.1
24-30-00-01A-02	DISCARD NO. 2 ENGINE DC GENERATOR (OFF-AIRCRAFT) THE DC GENERATOR BRUSHES 8160-121 602 REF: See Workcard	MOS HRS/MSC AFL	600	+100			13-JUN-2019 6590.1 6430	7190.1	7290.1
24-30-00-02-01 24.055	DISCARD NO. 1 ENGINE DC GENERATOR BEARINGS (OFF-AIRCRAFT) 8160-121 593 REF: See Workcard	MOS HRS/MSC AFL	1200	+100			13-JUN-2019 6590.1 6430	7790.1	7890.1
24-30-00-02-02 24.055	DISCARD NO. 2 ENGINE DC GENERATOR BEARINGS (OFF-AIRCRAFT) 8160-121 602 REF: See Workcard	MOS HRS/MSC AFL	1200	+100			13-JUN-2019 6590.1 6430	7790.1	7890.1
24-30-00-03-01 24.055 RESTORE	NO. 1 ENGINE DC GENERATOR 8160-121 593 REF: See Workcard	MOS HRS/MSC AFL	2400	+200	TSO:0 TSO:0 TSO:0		13-JUN-2019 6590.1 6430	8990.1	9190.1

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-00-03-02	NO. 2 ENGINE DC GENERATOR								
24.055	8160-121	MOS		TSO:0			13-JUN-2019		
RESTORE	602	HRS/MSC	2400 +200	TSO:0			6590.1	8990.1	9190.1
	REF: See Workcard	AFL		TSO:0			6430		
+ 24-30-00-06-01	RESTORATION LEFT BATTERY (PER CMM) (OFF-AIRCRAFT)								
24.070	31879-001	MOS	12				27-JUN-2017	27-JUN-2018	
	10302784	HRS/MSC					6370.9		
	REF: See Workcard	AFL					6348		
24-30-00-06-02	RESTORATION RIGHT BATTERY (PER CMM) (OFF-AIRCRAFT)								
24.070	DTSP-400L	MOS	12				07-APR-2017	07-APR-2018	
	9905283	HRS/MSC					6338.6		
	REF: See Workcard	AFL					6330		
24-30-00-06-03	RESTORATION LEFT BATTERY (PER CMM) (OFF AIRCRAFT) INTERVAL IN ACCORDANCE WITH VENDOR RECOMMENDATIONS								
24.125	31879-001	MOS					27-JUN-2017		
	10302784	HRS/MSC	N/A				6370.9		
	REF: See Workcard	AFL					6348		
24-30-00-06-04	RESTORATION RIGHT BATTERY (PER CMM) (OFF AIRCRAFT). INTERVAL IN ACCORDANCE WITH VENDOR RECOMMENDATIONS								
24.125	DTSP-400L	MOS					04-MAR-2016		
	9905283	HRS/MSC	N/A				6157.3		
	REF: See Workcard	AFL					6242		
24-30-00-06-05	#2 INVERTER								
	PC-251-2A	MOS					11-NOV-2011		
	10612	HRS/MSC	O/C				5538.2		
	REF:	AFL					5973		
24-30-00-06-06	DC JUNCTION BOX								
	230GC02Y04	MOS					07-APR-2017		
	273	HRS/MSC	O/C				6338.6		
	REF:	AFL					6330		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 24-33-00-01-01 (s)	EMERGENCY DC POWER - PERFORM OPERATIONAL CHECK OF EMERGENCY DC POWER SYSTEM						PKG		
24.065	PKG 3 REF: AMM 24-33-00	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
24-34-00-01B-01	DETAILED INSPECTION APU STARTER/GENERATOR OF DC GENERATOR BRUSHES FOR WEAR								
	8160-121 769 REF: AMM 24-31-01	MOS HRS/MSC AFL APH	600	+100			05-FEB-2018 6465.9 6381 6157	6757	6857
24-34-00-03-01	APU STARTER/GENERATOR								
24.110 RESTORE	8160-121 769 REF: See Workcard	MOS HRS/MSC AFL APH	2400	+200			05-FEB-2018 6465.9 6381 6157	? ?	
243500	LEFT BATTERY								
24.070	31879-001 10302784 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2017 6370.9 6348		
243501	RIGHT BATTERY								
24.070	DTSP-400L 9905283 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSO:13 TSO:181.3 TSO:88		07-APR-2017 6338.6 6330		
243813	TAIL CONE HALL-EFFECT SENSOR								
24.090	103-020-0 5115 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUN-2019 6590.1 6430		
243848	BUS-POWER CONTROLLER								
24.095	106-000-4 1326 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		27-JUN-2017 6370.9 6348		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
V24-60-00-01-01	DC POWER CONTROL UNIT - PERFORM RESTORATION (OVERHAUL) OF DC POWER CONTROL UNIT (OFF AIRCRAFT)	MOS		TSI:0			27-FEB-2002		
	REF: See Workcard	HRS/MSC AFL	18000	TSI:0 TSI:0			0 0		18000
APU Model : GTCP 36-150DD Serial # P-293 Part # 3800498-3									
24-34-00-01A-01	APU - DISCARD STARTER/GENERATOR BRUSHES	MOS					08-JUN-2018		
24.010	8160-121 769 REF: See Workcard	HRS/MSC APUS	600					? ?	
24-34-00-01B-01 (s)	APU - DETAILED INSPECTION STARTER/GENERATOR APU OF DC GENERATOR BRUSHES FOR WEAR	MOS					05-FEB-2018		
	8160-121 769 REF: AMM 24-34-02	HRS/MSC APUS	300				6157		
24-34-00-02-01	APU - REPLACE STARTER/GENERATOR BEARING	MOS					08-JUN-2018		
24.015	8160-121 769 REF: See Workcard	HRS/MSC APUS	1200					? ?	
24-34-00-03-01	APU - STARTER/GENERATOR	MOS		TSO:0			08-JUN-2018		
24.005 RESTORE	8160-121 769 REF: See Workcard	HRS/MSC APUS	2400	TSO:0 TSO:0				? ?	
CHAPTER 25 EQUIPMENT/FURNISHINGS									
25-10-00-00-01	FLIGHT CREW SEAT BELTS	MOS					01-DEC-2017		
25.140 DISCARD	SEE REMARKS SN-UNKNOWN REF: GENERIC CMM	HRS/MSC AFL	A/R				6367 6428		
25-10-00-00-02	FIRST AID PACK INSPECTION	MOS	12				07-APR-2017	07-APR-2018	
	REF:	HRS/MSC AFL					6338.6 6330		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-11-00-01-01 (s)	FLIGHT CREW SEAT WITH SEAT BELT - PERFORM DETAILED INSPECTION OF FLIGHT CREW / OBSERVER SEAT ATTACHMENT						PKG		
25.020	PKG 4 REF: AMM 25-11-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 25-11-00-02-01 (s)	FLIGHT CREW SEAT WITH SEAT BELT - PERFORM DETAILED INSPECTION OF FLIGHT CREW / OBSERVER SEAT STRUCTURE						PKG		
25.025	PKG 5 REF: AMM 25-11-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 25-11-00-03-01 (s)	FLIGHT CREW SEAT WITH SEAT BELT - PERFORM OPERATIONAL CHECK OF FLIGHT CREW / OBSERVER SEAT MECHANISM						PKG		
25.030	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 25-11-00-04-01	FLIGHT CREW SEAT WITH SEAT BELT - PERFORM VISUAL CHECK OF FLIGHT CREW / OBSERVER SEAT BELT AND SEAT BELT ATTACHMENT								
25.035	REF: AMM 25-11-01	MOS HRS/MSC AFL	12	+1m			20-FEB-2019 6584.3 6425	20-FEB-2020	20-MAR-2020
25-20-00-00-01CMM	PASSENGER SEAT BELTS - DISCARD OF PASSENGER SEAT BELTS SEE REMARKS SN-UNKNOWN REF:	MOS HRS/MSC AFL					01-DEC-2017 6367 6428		
25-20-00-00-02CMM	FLIGHT ATTENDANT SEAT BELT - DISCARD OF FLIGHT ATTENDANT SEAT BELT SEE REMARKS SN-UNKNOWN REF:	MOS HRS/MSC AFL					04-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-20-00-00-03	#5 DISPLAY UNIT 7014300-902 00097184 REF:	MOS HRS/MSC AFL	O/C				23-JAN-2012 5538.2 5973		
+ 25-21-00-01-01 (s)	PASSENGER SEAT/BERTH WITH SEAT BELT - PERFORM VISUAL CHECK OF PASSENGER SEAT/BERTH ATTACHMENT PKG 4 REF: AMM 25-21-00	MOS HRS/MSC AFL	30	+2m		-456	20-FEB-2019 6584.3 6425		
+ 25-21-00-02-01 (s)	PASSENGER SEAT/BERTH WITH SEAT BELT - PERFORM DETAILED INSPECTION OF PASSENGER SEAT/BERTH STRUCTURE PKG 5 REF: AMM 25-21-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 25-21-00-03-01 (s)	PASSENGER SEAT/BERTH WITH SEAT BELT - PERFORM OPERATIONAL CHECK OF PASSENGER SEAT/BERTH RECLINING MECHANISM (INCLUDING MOVABLE ARM AND FOOD TABLE IN ARM REST) PKG 4 REF: AMM 25-21-00	MOS HRS/MSC AFL	30	+2m		-456	20-FEB-2019 6584.3 6425		
+ 25-21-00-05-01	PASSENGER SEAT/BERTH WITH SEAT BELT - PERFORM OPERATIONAL CHECK OF PASSENGER SEAT/BERTH BELT LOCK MECHANISM REF: AMM 25-21-00	MOS HRS/MSC AFL	12	+1m			20-FEB-2019 6584.3 6425	20-FEB-2020	20-MAR-2020
+ 25-21-00-06-01 (s)	ATTENDANT SEAT WITH SEAT BELT - PERFORM VISUAL CHECK OF ATTENDANT SEAT ATTACHMENT PH5 PKG 4 SN-UNKNOWN REF: AMM 25-21-03	MOS HRS/MSC AFL	30	+4m			20-FEB-2019 6584.3 6425		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-21-00-07-01 (s)	ATTENDANT SEAT WITH SEAT BELT - PERFORM DETAILED INSPECTION OF ATTENDANT SEAT STRUCTURE						PKG		
25.065	PH5 PKG 5 SN-UNKNOWN REF: AMM 25-21-03	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 25-21-00-08-01 (s)	ATTENDANT SEAT WITH SEAT BELT - PERFORM OPERATIONAL CHECK OF ATTENDANT SEAT MECHANISM						PKG		
25.065	PH5 PKG 4 SN-UNKNOWN REF: AMM 25-21-03	MOS HRS/MSC AFL	30	+4m			20-FEB-2019 6584.3 6425		
+ 25-30-00-01-01 (s)	BUFFET / GALLEY - PERFORM DETAILED INSPECTION OF GALLEY ATTACHMENT POINTS						PKG		
25.070	PKG 5 REF: AMM 25-31-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
25-34-00-01-01 (s)	COFFEE MAKER - PERFORM VISUAL CHECK OF COFFEE MAKER WITH WATER TANK AND PUMP (INCLUDING WATER TUBES AND HOSES - SYSTEM ACTIVATED)						PKG		
	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
25-34-00-02-01 (s)	OVEN - PERFORM OPERATIONAL CHECK OF OVEN (INCLUDING COOLING SYSTEM)						PKG		
	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
25-34-00-02-02 (s)	OVEN - PERFORM OPERATIONAL CHECK OF OVEN (INCLUDING COOLING SYSTEM)						PKG		
	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
25-34-00-02-03 (s)	OVEN - PERFORM OPERATIONAL CHECK OF OVEN (INCLUDING COOLING SYSTEM)						PKG		
	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-34-00-02-04 (s)	OVEN - PERFORM OPERATIONAL CHECK OF OVEN (INCLUDING COOLING SYSTEM) PKG 4	MOS	30				PKG 01-DEC-2017 6428.4 6367		
	REF: See Workcard	HRS/MSC AFL							
25-34-00-02-05 (s)	OVEN - PERFORM OPERATIONAL CHECK OF OVEN (INCLUDING COOLING SYSTEM) PKG 4	MOS	30				PKG 01-DEC-2017 6428.4 6367		
	REF: See Workcard	HRS/MSC AFL							
+ 25-41-00-01-01 (s)	LAVATORY - PERFORM DETAILED INSPECTION OF LAVATORY ATTACHMENT POINTS PKG 5	MOS	60	+4m			PKG 08-JUN-2018 6504.7 6393		
25.080	REF: AMM 25-42-00	HRS/MSC AFL			-61				
+ 25-41-00-03-01 (s)	LAVATORY - PERFORM OPERATIONAL CHECK OF LAVATORY WASTE BIN FLAP PKG 4	MOS	30	+4m			PKG 01-DEC-2017 6428.4 6367		
25.085	REF: AMM 25-42-00	HRS/MSC AFL							
25-41-00-04-01 (s)	LAVATORY DOOR - PERFORM DETAILED INSPECTION OF LOCKING AND LATCHING MECHANISM OF LAVATORY DOOR FOR CONDITION AND SECURITY PKG 5	MOS	60	+4m			PKG 08-JUN-2018 6504.7 6393		
28.325	REF: AMM 25-44-00	HRS/MSC AFL			-61				
+ 25-51-00-01-01 (s)	CARGO COMPARTMENT - PERFORM DETAILED INSPECTION OF CARGO COMPARTMENT DIVIDER AND DOOR NETS PKG 4	MOS	30	+4m			PKG 01-DEC-2017 6428.4 6367		
25.090	REF: AMM 25-51-05	HRS/MSC AFL							

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 25-51-00-02-01 (s)	CARGO COMPARTMENT - PERFORM DETAILED INSPECTION OF NET ATTACHMENT POINTS (INCLUDING HOOK AND ROD)						PKG		
25.095	PKG 5 REF: AMM 25-51-05	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 25-51-00-03-01 (s)	CARGO COMPARTMENT - PERFORM VISUAL CHECK OF DECOMPRESSION BLOW OUT PANELS AT FRAME 37 AND FRAME 44						PKG		
25.100	PKG 4 REF: AMM 25-51-10	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 25-51-00-04-01 (s)	CARGO COMPARTMENT - PERFORM DETAILED INSPECTION OF CARGO COMPARTMENT TIE DOWN POINTS						PKG		
25.105	PKG 5 REF: AMM 25-51-03	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 25-61-00-01-01	EMERGENCY EQUIPMENT - PERFORM VISUAL CHECK OF EMERGENCY EQUIPMENT - FIRST AID KIT - FIRST AID MASK (PORTABLE) - CRASH AXE - ESCAPE ROPE - FLASH LIGHT								
25.115	REF: AMM 25-61-00	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020
+ 25-61-00-02-01	EMERGENCY EQUIPMENT - PERFORM OPERATIONAL CHECK OF EMERGENCY LOCATOR TRANSMITTER (ELT)								
25.120	REF:	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020
25-61-00-02-03	EMERGENCY EQUIPMENT - PERFORM OPERATIONAL CHECK OF PORTABLE EMERGENCY LOCATOR TRANSMITTER (ELT)								
	REF: AMM 25-61-08	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-61-00-03-01	EMERGENCY EQUIPMENT - DISCARD EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY								
25.120	453-5000-366 170-05839 REF: See Workcard	MOS HRS/MSC AFL	60				13-JUN-2019 6590.1 6430	01-MAY-2024 M	
+ 25-62-00-01-02	OVERWATER EQUIPMENT - PERFORM VISUAL CHECK OF PASSENGER/CREW LIFE VESTS								
25.125	REF: AMM 25-62-01	MOS HRS/MSC AFL	A/R				07-APR-2017 6338.6 6330		
25-62-00-02-01	OVERWATER EQUIPMENT - RESTORATION (OVERHAUL) OF LIFE VEST (OFF-AIRCRAFT)								
25.125 RESTORE	P0640-101 B15087 REF: GENERIC CMM	MOS HRS/MSC AFL	A/R				17-JAN-2003 0 0		
25-62-00-02-02	OVERWATER EQUIPMENT - RESTORATION (OVERHAUL) OF LIFE VEST (OFF-AIRCRAFT)								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		
25-62-00-03-01.1	LIFE RAFT INSPECTION								
	REF:	MOS HRS/MSC AFL	-				08-APR-2013 5700.2 6053		
25-62-00-04-01.1	LIFE RAFT OVERHAUL								
	RAF1108-105 11640FV/1513EV REF:	MOS HRS/MSC AFL	DUE				05-FEB-2018 6465.9 6381	? ?	
25-62-00-05-01.1	LIFE RAFT ELT OPS CHECK AFTER BATTERY REPLACEMENT								
	REF:	MOS HRS/MSC AFL	-				08-APR-2013 5700.2 6053		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-62-00-06-01.1	LIFE RAFT SURVIVAL KIT REPLENISH 119003-11 004-7086M REF:	MOS HRS/MSC AFL	-	TSN:0 TSN:0 TSN:0			08-APR-2013 5700.2 6053		
25-63-00-00	AUDIO PANEL 751/001-912 01066886 REF:	MOS HRS/MSC AFL	O/C				01-JUL-2012 5505.7 5963		
25-63-00-00.1	DISPLAY CONTROL UNIT 7014332-902 01034970 REF:	MOS HRS/MSC AFL	O/C				01-JUL-2012 5505.7 5963		
25-63-00-01	LIFE VEST #1 P0640-101 16071270032 REF:	MOS HRS/MSC AFL	O/C	TSN:9 TSN:0 TSN:0			07-APR-2017 6338.6 6330		
25-63-00-02	LIFE VEST #2 100021300999117 1008 REF:	MOS HRS/MSC AFL	O/C	TSN:3 TSN:0 TSN:0			07-APR-2017 6338.6 6330		
25-63-00-03	LIFE VEST #3 100021300999117 15388 REF:	MOS HRS/MSC AFL	O/C				07-APR-2017 6338.6 6330		
25-63-00-04	#4 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110077 REF:	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
	Manufacture Date: 25-OCT-2016								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-05	#5 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 1612111026 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC - AFL		TSN:0			25-OCT-2016		
25-63-00-05	#5 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 1612111026 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL APH	60	TSN:0 TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-06	# 6 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16101880018 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL APH	60	TSN:0 TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-07	# 7 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110077 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL APH	60	TSN:0 TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-08	# 8 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110009 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-09	# 9 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110147 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-10	# 10 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110177 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL APH	60	TSN:0 TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-11	# 11 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110112 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-12	# 12 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110189 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-13	# 13 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110016 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-14	# 14 CABIN LIFE VEST 60 MO. INSPECTION. P01074-101W 16121110190 REF: Manufacture Date: 25-OCT-2016	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	31-OCT-2021	
25-63-00-15	# 1 CHILD LIFE VEST S-10002-1300-99917 07-16-15388 REF:	MOS HRS/MSC AFL APH	60	TSN:0 TSO:0 TSO:0 TSO:0 TSO:0			07-APR-2017 6338.6 6330	31-JUL-2026 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-63-00-16	# 2 CHILD LIFE VEST S-10002-1300-99917 01-17-1008 REF:	MOS HRS/MSC AFL	60				07-APR-2017 6338.6 6330	31-JAN-2027 M	
25-63-00-17	# 3 CHILD LIFE VEST P0640-101 16071270032 REF:	MOS HRS/MSC AFL	60	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330	21-JUL-2021 M	
25-63-00-18	# 4 CHILD LIFE VEST S-10002-1300-99902 04-17-9-8161 REF: Manufacture Date: 30-APR-2019	MOS HRS/MSC AFL	60	TSO:0 TSO:0 TSO:0			13-JUN-2019 6590.1 6430	30-APR-2024	
252115	FLIGHT ATTENDANT SEAT PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
256301	EMERGENCY LOCATOR TRANSMITTER 453-5000-366 170-05839 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUN-2019 6590.1 6430		
V25-11-00-03-01	CREW SEAT ASSEMBLY - DISCARD SEAT PAN CUSHION REF: GENERIC NO REF	MOS HRS/MSC AFL	36				13-JUN-2019 6590.1 6430	13-JUN-2022	
CHAPTER 26 FIRE PROTECTION									
26-00-00-01-01	LEFT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE LEFT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903870 30903870 1523WA REF:	MOS HRS/MSC AFL	120					01-MAY-2028 M	
26.025	LIFE LIMIT								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-00-00-01-02	LEFT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE LEFT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903870								
26.025	30903964	MOS	120					? ?	
LIFE LIMIT	1534WA	HRS/MSC							
	REF:	AFL							
26-00-00-01-03	RIGHT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE RIGHT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903870								
26.030	30903964	MOS	120					? ?	
LIFE LIMIT	1533WA	HRS/MSC							
	REF:	AFL							
26-00-00-01-04	RIGHT ENGINE REAR FIRE BOLLTE DISCHARGE CARTRIDGE - REPLACE RIGHT ENGINE REAR BOTTLE DISCHARGE CARTRIDGE P/N 30903870								
26.030	30903964	MOS	120					? ?	
LIFE LIMIT	4032UD	HRS/MSC							
	REF:	AFL							
26-00-00-01-06	CARGO COMPARTMENT METERED FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE CARGO COMPARTMENT METERED FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903870								
26.085	30903870	MOS	120				08-JUN-2018	01-MAY-2028 M	
LIFE LIMIT	1514WA	HRS/MSC					6504.7		
	REF: See Workcard	AFL					6393		
26-00-00-01-07	CARGO COMPARTMENT HIGH RATE FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE CARGO COMPARTMENT HIGH RATE FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903870								
26.080	30903964	MOS	120					? ?	
LIFE LIMIT	4029UD	HRS/MSC							
	REF: See Workcard	AFL							
26-00-00-02-01	FLIGHT COMPARTMENT FRAME 9 HAND FIRE EXTINGUISHER								
26.055	BA21741/GR2	MOS	120	TSN:2			26-JAN-2011	26-NOV-2020	
LIFE LIMIT	072340	HRS/MSC		TSN:0			5408.9		
	REF: GENERIC NO REF	AFL		TSN:0			5915		
26-00-00-02-02	PASSENGER COMPARTMENT FRAME 11 HAND FIRE EXTINGUISHER								
26.055	BA21741/GR2	MOS	120	TSN:2			26-JAN-2011	26-NOV-2020	
LIFE LIMIT	072341	HRS/MSC		TSN:0			5408.9		
	REF: GENERIC NO REF	AFL		TSN:0			5915		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-00-00-02-03	PASSENGER COMPARTMENT FRAME 32/33 HAND FIRE EXTINGUISHER BA21741/GR2 072342 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	TSN:2 TSN:0 TSN:0			26-JAN-2011 5408.9 5915	26-NOV-2020	
LIFE LIMIT									
26-00-00-03-02	LEFT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE LEFT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903964 30903964 1534WA REF:	MOS HRS/MSC AFL	108				08-JUN-2018 6504.7 6393	01-MAY-2028 M	
LIFE LIMIT									
26-00-00-03-03	RIGHT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE RIGHT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903964 30903964 1533WA REF:	MOS HRS/MSC AFL	108				08-JUN-2018 6504.7 6393	01-MAY-2028 M	
LIFE LIMIT									
26-00-00-03-04	RIGHT ENGINE REAR FIRE BOLLTE DISCHARGE CARTRIDGE - REPLACE RIGHT ENGINE REAR BOTTLE DISCHARGE CARTRIDGE P/N 30903964 30903964 4032UD REF:	MOS HRS/MSC AFL	108				08-JUN-2018 6504.7 6393	01-MAY-2028 M	
LIFE LIMIT									
26-00-00-03-05	APU FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE APU FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903964 30903964 1531WA REF:	MOS HRS/MSC AFL	108				08-JUN-2018 6504.7 6393	01-MAY-2028 M	
LIFE LIMIT									
26-00-00-03-07	CARGO COMPARTMENT HIGH RATE FIRE BOTTLE DISCHARGE CARTRIDGE - REPLACE CARGO COMPARTMENT HIGH RATE FIRE BOTTLE DISCHARGE CARTRIDGE P/N 30903964 30903964 4029UD REF:	MOS HRS/MSC AFL	108				08-JUN-2018 6504.7 6393	01-MAY-2028 M	
LIFE LIMIT									
+ 26-11-00-01-01 (s)	ENGINE FIRE DETECTION SYSTEM - PERFORM OPERATIONAL CHECK OF ENGINE FIRE DETECTION SYSTEM PKG 1 REF: AMM 26-11-00	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
26.020									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 26-21-00-01-01 (s)	ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING SYSTEM INCLUDING SHUT-OFF FUNCTIONS						PKG		
26.035	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
26-21-00-01-02 (s)	ENGINE FIRE EXTINGUISHING SYSTEM - PERFORM FUNCTIONAL CHECK OF ENGINE FIRE EXTINGUISHING SYSTEM INCLUDING SHUT-OFF FUNCTIONS						PKG		
	PKG 4 REF:	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 26-21-00-02-01	RESTORATION (CLEANING) OF LEFT ENGINE FWD FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE ENGINE FIRE EXTINGUISHER BOTTLE								
26.025	33500012-1 21301C1 REF:	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
+ 26-21-00-02-02	RESTORATION LEFT ENGINE REAR FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE ENGINE FIRE EXTINGUISHER BOTTLE								
26.025	33500012-1 21302C1 REF:	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
+ 26-21-00-02-03	RESTORATION RIGHT ENGINE FWD FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE ENGINE FIRE EXTINGUISHER BOTTLE								
26.030	33500012-1 21306C1 REF:	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
+ 26-21-00-02-04	RESTORATION RIGHT ENGINE REAR FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE ENGINE FIRE EXTINGUISHER BOTTLE								
26.030	33500012-1 21380C1 REF:	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
+ 26-22-00-01-01 (s)	APU FIRE EXTINGUISHING SYSTEM - PERFORM FUNCTIONAL CHECK OF APU FIRE EXTINGUISHING SYSTEM INCLUDING SHUT-OFF FUNCTIONS						PKG		
26.045	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-22-00-01-02 (s)	APU FIRE EXTINGUISHING SYSTEM - PERFORM FUNCTIONAL CHECK OF APU FIRE EXTINGUISHING SYSTEM INCLUDING SHUT-OFF FUNCTIONS PKG 4 REF:	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
+ 26-22-00-02-01 26.040	RESTORATION APU FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE APU FIRE EXTINGUISHER BOTTLE 33100016-2 46454B1 REF: See Workcard	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
26-24-00-02-01 (s) 26.075	CARGO COMPARTMENT FIRE EXTINGUISHING LINES - PERFORM DETAILED INSPECTION OF CARGO COMPARTMENT FIRE EXTINGUISHING LINES AND FITTINGS FOR DAMAGE AND PROPER INSTALLATION PKG 5 REF: AMM 26-24-00	MOS HRS/MSC AFL	60	+4m		-61	PKG 08-JUN-2018 6504.7 6393		
26-24-00-03-01 26.085	RESTORATION CARGO COMPARTMENT METERED FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE CARGO COMPARTMENT METERED FIRE EXTINGUISHER BOTTLE 34200408-1 06463E1 REF: AMM 26-24-01	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
26-24-00-03-02 26.080	RESTORATION CARGO COMPARTMENT HIGH RATE FIRE BOTTLE (INSPECTION AND HYDROSTATICAL TEST) (OFF-AIRCRAFT) OF THE CARGO COMPARTMENT HIGH RATE FIRE EXTINGUISHER BOTTLE 33500013-1 21089C1 REF: AMM 26-24-01	MOS HRS/MSC AFL	60				08-JUN-2018	08-JUN-2023	
+ 26-25-00-01-01 26.050	WEIGHT CHECK LAVATORY FIRE EXTINGUISHING BOTTLE PN SN-UNKNOWN REF: AMM 26-25-01	MOS HRS/MSC AFL	12	+1m			07-APR-2017	07-APR-2018	07-MAY-2018
26-27-00-01-03 26.050	HAND FIRE EXTINGUISHER - FRAME 9 - PERFORM VISUAL CHECK OF THE HAND HELD FIRE EXTINGUISHER FOR OBVIOUS DAMAGE, PROPER INSTALLATION AND UNIT "FULL" INDICATOR STILL IN PLACE BA21741/GR2 072340 REF: See Workcard	MOS HRS/MSC AFL	12				07-APR-2017 6338.6 6330	07-APR-2018	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-27-00-01-04	HAND FIRE EXTINGUISHER - FRAME 11 - PERFORM VISUAL CHECK OF THE HAND HELD FIRE EXTINGUISHER FOR OBVIOUS DAMAGE, PROPER INSTALLATION AND UNIT "FULL" INDICATOR STILL IN PLACE BA21741/GR2 072341 REF: See Workcard	MOS HRS/MSC AFL	12				07-APR-2017 6338.6 6330	07-APR-2018	
+ 26-27-00-01-05	HAND HELD FIRE EXTINGUISHER- FRAME 31/32 - PERFORM VISUAL CHECK OF THE HANL HELD FIRE EXTINGUISHER FOR OBVIOUS DAMAGE, PROPER INSTALLATION AND UNIT "FULL" INDICATOR STILL IN PLACE BA21741/GR-2, IF INSTALLED SN-UNKNOWN REF: AMM 26-27-00	MOS HRS/MSC AFL	12	+1m			07-APR-2017 6338.6 6330	07-APR-2018	07-MAY-2018
26.065									
26-27-00-02-03	HAND FIRE EXTINGUISHER - FRAME 9 - PERFORM WEIGHT CHECK OF HAND HELD FIRE EXTINGUISHER BA21741/GR2 072340 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			11-AUG-2016 6269.8 6291	11-AUG-2017	11-SEP-2017
26-27-00-02-04	HAND FIRE EXTINGUISHER - FRAME 11 - PERFORM WEIGHT CHECK OF HAND HELD FIRE EXTINGUISHER BA21741/GR2 072341 REF: See Workcard	MOS HRS/MSC AFL	12	+1m			11-AUG-2016 6269.8 6291	11-AUG-2017	11-SEP-2017
+ 26-27-00-02-05	HAND HELD FIRE EXTINGUISHER- FRAME 31/32 - PERFORM WEIGHT CHECK BA21741/GR-2, IF INSTALLED SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	12	+1m	-82		11-AUG-2016 6269.8 6291	21-MAY-2017	21-JUN-2017
26.065									
260001	ENGINE/APU EXTINGUISHER PANEL 715355-2 0302074 REF: GENERIC NO REF	MOS HRS/MSC AFL				O/C	23-MAR-2009 0 0		
26.010									
262101	LEFT ENGINE FWD FIRE BOTTLE 33500012-1 21301C1 REF: GENERIC NO REF	MOS HRS/MSC AFL				O/C	TSO:0 TSO:0 TSO:0 08-JUN-2018 6504.7 6393		
26.025									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262102	LEFT ENGINE REAR FIRE BOTTLE								
26.025	33500012-1 21302C1 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
262103	RIGHT ENGINE FWD FIRE BOTTLE								
26.030	33500012-1 21306C1 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
262104	RIGHT ENGINE REAR FIRE BOTTLE								
26.030	33500012-1 21380C1 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
262105	LEFT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903870 1523WA REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262106	LEFT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903964 1534WA REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262107	RIGHT ENGINE FORWARD FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903964 1533WA REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262108	RIGHT ENGINE REAR FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903964 4032UD REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262109	CARGO COMPARTMENT METERED FIRE BOTTLE								
26.085	34200408-1 06463E1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262110	CARGO COMPARTMENT HIGH RATE FIRE BOTTLE								
26.080	33500013-1 21089C1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
262111	CARGO COMPARTMENT METERED FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903870 1514WA REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262112	CARGO COMPARTMENT HIGH RATE FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903964 4029UD REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262113	APU FIRE BOTTLE DISCHARGE CARTRIDGE								
	30903964 1531WA REF: See Workcard	MOS HRS/MSC AFL	H/T	TSN:0 TSN:0 TSN:0			08-JUN-2018 6504.7 6393		
262200	APU FIRE BOTTLE								
26.040	33100016-2 46454B1 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
CHAPTER 27 FLIGHT CONTROLS									
27-00-00-02-01	LEFT FLIGHT SPOILER ACTUATOR								
27.310	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		
27-00-00-02-02	RIGHT FLIGHT SPOILER ACTUATOR								
27.315	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-03-01 (s)	RUDDER CONTROL CABLES AND PULLEYS AT FRAME 45 - PERFORM DETAILED INSPECTION OF RUDDER CONTROL CABLES AND PULLEYS AT FRAME 45 (REAR PRESSURE BULKHEAD)						PKG		
	PKG 4	MOS	30	+2m				01-DEC-2017	
	REF: AMM 27-21-04	HRS/MSC						6428.4	
		AFL						6367	
27-00-00-03-02 (s)	ELEVATOR CONTROL CABLES AND PULLEYS AT FRAME 45 - PERFORM DETAILED INSPECTION OF ELEVATOR CONTROL CABLES AND PULLEYS AT FRAME 45 (REAR PRESSURE BULKHEAD)						PKG		
	PKG 4	MOS	30	+2m				01-DEC-2017	
	REF: AMM 27-31-00	HRS/MSC						6428.4	
		AFL						6367	
+ 27-10-00-01-01 (s)	AILERON AND TAB - PERFORM FUNCTIONAL CHECK OF AILERON, ROLL/FLIGHT SPOILER AND TRIM SYSTEM						PKG		
27.010	PKG 5	MOS	60	+4m				08-JUN-2018	
	REF: See Workcard	HRS/MSC						6504.7	
		AFL						6393	
+ 27-10-00-02-01 (s)	AILERON AND TAB - PERFORM DETAILED INSPECTION OF AILERON CONTROL SYSTEM COMPONENTS						PKG		
27.015	PKG 5	MOS	60	+6m				08-JUN-2018	
	REF: AMM 27-11-00	HRS/MSC						6504.7	
		AFL						6393	
+ 27-10-00-03-01 (s)	AILERON AND TAB - PERFORM FUNCTIONAL CHECK OF AILERON CONTROL CABLES (BETWEEN CONTROL WHEEL, TENSION REGULATOR AND TRANSITION UNIT) AND AUTOPILOT CABLE FOR CORRECT TENSION						PKG		
27.020	PKG 5	MOS	60	+4m				08-JUN-2018	
	REF: AMM 27-11-03	HRS/MSC						6504.7	
		AFL						6393	
+ 27-10-00-04-01 (s)	AILERON AND TAB - PERFORM FUNCTIONAL CHECK OF THE AILERON DISCONNECT UNIT						PKG		
27.050	PH4 PKG 4	MOS	30	+2m				01-DEC-2017	
	SN-UNKNOWN	HRS/MSC						6428.4	
	REF: AMM 27-11-07	AFL						6367	
+ 27-10-00-06-01 (s)	AILERON AND TAB - PERFORM OPERATIONAL CHECK OF AILERON TRIM NORMAL / STANDBY (OVER THE FULL RANGE)						PKG		
27.045	PKG 2	DAYS	225	+14				20-FEB-2019	
	REF: AMM 27-12-00	HRS/MSC						6584.3	
		AFL						6425	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-10-00-08-01 (s)	AILERON AND TAB - PERFORM DETAILED INSPECTION OF AILERON TRIM ACTUATOR MOISTURE INDICATOR						PKG		
27.040	8410 PKG 4 118 REF: AMM 27-12-03	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 27-10-00-09-01 (s)	AILERON AND TAB - PERFORM DETAILED INSPECTION OF AILERON CONTROL CABLES FOR WEAR AT FRAME 15, 24 AND 26						PKG		
27.055	PKG 4 REF: AMM 27-11-03	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-10-00-10-01 (s)	AILERON AND TAB - PERFORM DETAILED INSPECTION OF AILERON AUTOPILOT CONTROL CABLE						PKG		
27.060	PKG 4 REF: AMM 27-11-03	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-10-00-13-01	AILERON AND TAB - PERFORM VISUAL CHECK OF LINKAGE AILERON TRIM TABS TO ACTUATOR								
27.025	REF: AMM 27-12-00	MOS HRS/MSC AFL	500				07-APR-2017 6338.6 6330	6838.6	
+ 27-10-00-14-01	AILERON AND TAB - PERFORM DETAILED INSPECTION OF AILERON TRIM ACTUATOR DUAL LOAD PATH								
27.052	REF: AMM 27-12-00	MOS HRS/MSC AFL	5000				07-APR-2017 6338.6 6330	11338.6	
+ 27-20-00-01-01 (s)	RUDDER AND TAB - PERFORM FUNCTIONAL CHECK OF RUDDER CONTROL AND TRIM SYSTEM						PKG		
27.070	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60		-61		08-JUN-2018 6504.7 6393		
+ 27-20-00-02-01 (s)	RUDDER AND TAB - PERFORM DETAILED INSPECTION OF RUDDER CONTROL SYSTEM COMPONENTS						PKG		
27.075	PKG 5 REF: AMM 27-21-00	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20-00-03-01 (s)	RUDDER AND TAB - PERFORM FUNCTIONAL CHECK OF RUDDER PEDAL ADJUSTMENT						PKG		
27.070	PKG 5 REF: AMM 27-21-01	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 27-20-00-04-01 (s)	RUDDER AND TAB - PERFORM FUNCTIONAL CHECK OF RUDDER CONTROL CABLES (BETWEEN FRONT CONTROL CABLE LEVER AND REAR CONTROL QUADRANT) AND AUTOPILOT CABLE FOR CORRECT TENSION						PKG		
27.090	PKG 5 REF: AMM 27-21-04	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 27-20-00-05-01 (s)	RUDDER AND TAB - PERFORM OPERATIONAL CHECK OF RUDDER TRIM (OVER THE FULL RANGE)						PKG		
27.085	PKG 2 REF: AMM 27-22-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 27-20-00-06-01 (s)	RUDDER AND TAB - PERFORM DETAILED INSPECTION OF RUDDER LIMITER MOISTURE INDICATOR						PKG		
27.086	PKG 4 REF: AMM 27-23-04	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-20-00-07-01 (s)	RUDDER AND TAB - PERFORM DETAILED INSPECTION OF RUDDER TRIM ACTUATOR MOISTURE INDICATOR						PKG		
27.080	PKG 4 REF: AMM 27-22-03	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-20-00-08-01 (s)	RUDDER CONTROL CABLES - PERFORM DETAILED INSPECTION OF RUDDER CONTROL CABLES AT FRAME 15 AND 39 FAIRLEAD						PKG		
27.095	PKG 4 REF: AMM 27-21-04	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-20-00-09-01 (s)	RUDDER AND TAB - PERFORM DETAILED INSPECTION OF RUDDER AUTOPILOT CONTROL CABLE						PKG		
27.095	PKG 4 REF: AMM 27-21-04	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-20-00-11-01	RUDDER AND TAB - PERFORM VISUAL CHECK OF LINKAGE RUDDER TRIM TAB / SPRING TAB								
27.100	REF: See Workcard	MOS HRS/MSC AFL	500				11-AUG-2016 6269.8 6291	6769.8	
+ 27-20-00-12-01	RUDDER AND TAB - PERFORM DETAILED INSPECTION OF RUDDER TRIM TAB / SPRING TAB ACTUATOR DUAL LOAD PATH								
27.080	REF: AMM 27-22-00	MOS HRS/MSC AFL	5000				08-APR-2013 5700.2 6053	10700.2	
+ 27-30-00-01-01 (s)	ELEVATOR AND TAB - PERFORM FUNCTIONAL CHECK OF ELEVATOR CONTROL AND TRIM SYSTEM						PKG		
27.115	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 27-30-00-02-01 (s)	ELEVATOR CONTROLS - PERFORM DETAILED INSPECTION OF THE ELEVATOR PULLEYS AND CABLES AT FRAME 39						PKG		
27.125	PKG 4 REF: AMM 27-31-00	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 27-30-00-03-01 (s)	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF ELEVATOR CONTROL SYSTEM COMPONENTS						PKG		
27.120	PKG 5 REF: AMM 27-31-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 27-30-00-04-01 (s)	ELEVATOR AND TAB - PERFORM FUNCTIONAL CHECK OF THE ELEVATOR CONTROL CABLES (BETWEEN TENSION REGULATOR AND QUADRANT ASSEMBLY) AND AUTOPILOT CABLE FOR CORRECT TENSION						PKG		
27.110	PKG 5 REF: AMM 27-31-04	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 27-30-00-05-01 (s)	ELEVATOR AND TAB - PERFORM FUNCTIONAL CHECK OF ELEVATOR DISCONNECT UNIT						PKG		
27.160	PH4 PKG 4 SN-UNKNOWN REF: AMM 27-31-09	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30-00-06-01 (s)	ELEVATOR AND TAB - PERFORM OPERATIONAL CHECK OF THE ELEVATOR TRIM / STANDBY (OVER THE FULL RANGE)						PKG		
27.145	PKG 2 REF: AMM 27-32-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 27-30-00-07-01 (s)	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF THE ELEVATOR DISCONNECT UNIT MOISTURE INDICATOR						PKG		
27.160	PKG 4 REF: AMM 27-31-09	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-30-00-08-01 (s)	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF THE ELEVATOR TRIM ACTUATOR MOISTURE INDICATOR						PKG		
27.140	PKG 3 REF: AMM 27-32-01	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
+ 27-30-00-09-01 (s)	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF STICK PUSHER MOISTURE INDICATOR						PKG		
27.150	PKG 4 REF: AMM 27-33-03	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-30-00-10-01 (s)	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF THE ELEVATOR AUTOPILOT CONTROL CABLE FOR WEAR						PKG		
27.175	PKG 4 REF: AMM 27-31-04	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 27-30-00-11-01 (s)	ELEVATOR AND TAB - PERFORM FUNCTIONAL CHECK OF FORCE DETECTION ROD						PKG		
27.190	PH6 PKG 6 SN-UNKNOWN REF: AMM 27-31-11	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 27-30-00-14-01	ELEVATOR AND TAB - PERFORM VISUAL CHECK OF LINKAGE ELEVATOR TRIM TABS TO ACTUATOR								
27.145	REF: AMM 27-32-00	MOS HRS/MSC AFL	500				13-JUN-2019 6590.1 6430	7090.1	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-30-00-15-01	ELEVATOR AND TAB - PERFORM DETAILED INSPECTION OF ELEVATOR TRIM ACTUATOR DUAL LOAD PATH								
27.135	REF: AMM 27-32-00	MOS HRS/MSC AFL	5000				08-APR-2013 5700.2 6053	10700.2	
+ 27-30-00-16-01	ELEVATOR AND TAB - PERFORM OPERATIONAL CHECK OF STICK PUSHER MECHANICAL LOCK DURING STALL WARNING AND PREVENTION OPERATIONAL TEST								
27.150	REF: AMM 27-33-00	MOS HRS/MSC AFL	6000				21-MAY-2015 5991.4 6177	11991.4	
+ 27-30-00-17-01	ELEVATOR AND TAB - PERFORM FUNCTIONAL TEST OF STICK PUSHER MOTOR BRAKE (OFF AIRCRAFT)								
27.155	REF: See Workcard	MOS HRS/MSC AFL	6000				21-MAY-2015 5991.4 6177	11991.4	
27-30-00-19-01 (s)	STALL WARNING - PERFORM OPERATIONAL CHECK OF STALL WARNING AND PREVENTION SYSTEM						PKG		
27.350	PKG 2 REF: AMM 27-33-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 27-50-00-01-01 (s)	FLAPS - PERFORM DETAILED INSPECTION OF FLAP CONTROL SYSTEM COMPONENTS								
27.200	PKG 4 REF: AMM 27-50-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 27-50-00-02-01 (s)	FLAPS - PERFORM FUNCTIONAL CHECK OF THE FLAP SYSTEM								
27.205	PKG 5 REF: AMM 27-50-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 27-60-00-01-01 (s)	SPOILER - PERFORM OPERATIONAL CHECK OF GROUND SPOILER SWITCHES								
27.270	PKG 3 REF: AMM 27-61-00	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-60-00-02-01 (s)	ROLL SPOILER - PERFORM DETAILED INSPECTION OF ROLL SPOILER MECHANICAL LINKAGES						PKG		
27.245	PKG 5 REF: AMM 27-62-00	MOS HRS/MSC AFL	96	+6m			08-JUN-2018 6504.7 6393		
+ 27-60-00-04-01 (s)	SPOILER - PERFORM FUNCTIONAL CHECK OF GROUND SPOILER						PKG		
27.250	PKG 5 REF: AMM 27-61-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 27-60-00-05-01 (s)	SPOILER - PERFORM DETAILED INSPECTION OF GROUND SPOILER MECHANICAL LINKAGES						PKG		
27.265	PKG 5 REF: AMM 05-25-27	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 27-60-00-07-01 (s)	SPOILER - PERFORM DETAILED INSPECTION OF GROUND SPOILER ACTUATOR MECHANICAL LOCK DEVICE						PKG		
27.255	PKG 4 REF: AMM 27-61-01	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
27-60-00-11-01 (s)	FLIGHT SPOILER - PERFORM DETAILED INSPECTION OF FLIGHT SPOILER ACTUATOR AND ATTACHMENT FOR CONDITION AND SECURITY						PKG		
27.330	PKG 5 REF: AMM 27-63-01	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 27-60-00-12-01 (s)	FLIGHT SPOILER - PERFORM FUNCTIONAL CHECK OF FLIGHT SPOILER AIRBRAKE MODE						PKG		
27.335	PKG 4 REF: AMM 27-63-00	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 27-60-00-13-01 (s)	FLIGHT SPOILER - PERFORM DETAILED INSPECTION OF FLIGHT SPOILER MECHANICAL LINKAGES						PKG		
27.340	PKG 5 REF: AMM 27-63-05	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-70-00-01-01 (s)	GUST LOCK AND DAMPER - PERFORM FUNCTIONAL CHECK OF GUST LOCK						PKG		
27.290	PH6 PKG 5 SN-UNKNOWN REF: AMM 27-71-00	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 27-70-00-02-01 (s)	RUDDER DAMPER - PERFORM GENERAL VISUAL INSPECTION OF RUDDER DAMPER FOR LEAKAGE AND CORRECT FLUID LEVEL INDICATION						PKG		
27.295	PKG 3 REF: AMM 27-72-01	MOS HRS/MSC AFL	15	+2m			01-DEC-2017 6428.4 6367		
+ 27-70-00-03-01 (s)	GUST LOCK AND DAMPER - PERFORM DETAILED INSPECTION OF THE MECHANICAL LINKAGES OF THE RUDDER DAMPER (LINKAGE RUDDER DAMPER TO RUDDER AND VERTICAL STABILIZER)						PKG		
27.295	PKG 5 REF: AMM 27-72-01	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 27-70-00-04-01 (s)	GUST LOCK AND DAMPER - PERFORM DETAILED INSPECTION OF AILERON AND ELEVATOR GUST LOCK SYSTEM COMPONENTS						PKG		
27.300	PKG 5 REF: AMM 05-25-27	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
27-70-00-05-01 (s)	GUST LOCK AND DAMPER - PERFORM DETAILED INSPECTION OF GUST LOCK LEVER INSTALLATION AND CONNECTING LINKAGES FOR WEAR AND CONDITION						PKG		
27.345	PKG 4 REF: AMM 27-71-01	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
271021	AILERON TRIM ACTUATOR								
27.040	8410 118 REF: See Workcard	MOS HRS/MSC AFL	O/C		TSR:0 TSR:0 TSR:0		01-DEC-2017 6428.4 6367		
271031	AILERON CONTROL DISCONNECT UNIT								
27.050	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272011	RUDDER TRIM ACTUATOR								
27.080	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
272021	RUDDER LIMITER ACTUATOR								
27.086	PH2 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
273012	RIGHT ELEVATOR TRIM ACTUATOR								
27.130	8409-03 764 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-AUG-2016 6269.8 6291		
273021	ELEVATOR AND TAB PUSHER STICK								
27.150	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
273031	ELEVATOR DISCONNECT UNIT								
27.160	PH4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
273071	ELEVATOR CONTROL FORCE DETECTION ROD								
27.190	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
277001	FLIGHT CONTROL GUST LOCK								
27.290	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
277005	RUDDER DAMPER								
27.295	FF255-001 BB0858 REF: AMM 27-72-01	MOS HRS/MSC AFL	O/C				11-AUG-2016 6269.8 6291		

CHAPTER 28 FUEL

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-00-02-01	OUTER FUEL TANK HARNESS - LEFT - PERFORM DETAILED INSPECTION OF LEFT OUTER FUEL TANK HARNESS, INTER								
28.280	REF: AMM 05-25-28	MOS HRS/MSC AFL	33000	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		33000
28-00-00-02-02	OUTER FUEL TANK HARNESS - RIGHT - PERFORM DETAILED INSPECTION OF RIGHT OUTER FUEL TANK HARNESS, INTERNAL								
28.285	REF: AMM 05-25-28	MOS HRS/MSC AFL	33000	TSI:0 TSI:0 TSI:0			17-MAR-2009 5234.6 5856		38234.6
28-00-00-03-01	INNER FUEL TANK HARNESS - LEFT - PERFORM DETAILED INSPECTION OF LEFT INNER FUEL TANK HARNESS,INTERNAL								
28.300	REF: AMM 05-25-28	MOS HRS/MSC AFL	33000	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		33000
28-00-00-03-02	INNER FUEL TANK HARNESS - RIGHT - PERFORM DETAILED INSPECTION OF RIGHT INNER FUEL TANK HARNESS, INTERNAL								
28.305	REF: AMM 05-25-28	MOS HRS/MSC AFL	33000	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		33000
28-00-99-01-01 (s)	FUEL FEEDER TANK - LEFT - PERFORM DETAILED INSPECTION OF LEFT FUEL FEEDER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS, INTERNAL (EWIS)								
28.335	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		
28-00-99-01-02 (s)	FUEL FEEDER TANK - RIGHT - PERFORM DETAILED INSPECTION OF RIGHT FUEL FEEDER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS INTERNAL (EWIS)								
28.335	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		
28-00-99-02-01 (s)	OUTER FUEL TANK - LEFT - PERFORM DETAILED INSPECTION OF LEFT FUEL OUTER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS INTERNAL (EWIS)								
28.340	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-99-02-02 (s)	OUTER FUEL TANK - RIGHT - PERFORM DETAILED INSPECTION OR RIGHT FUEL OUTER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS INTERNAL (EWIS)						PKG		
28.340	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		
28-00-99-03-01 (s)	INNER FUEL TANK - LEFT - PERFORM DETAILED INSPECTION OF LEFT FUEL INNER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS INTERNAL (EWIS)						PKG		
28.345	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		
28-00-99-03-02 (s)	INNER FUEL TANK - RIGHT - PERFORM DETAILED INSPECTION OF RIGHT FUEL INNER WING TANK EQUIPMENT, HARNESS AND BONDING LEADS INTERNAL (EWIS)						PKG		
28.345	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			27-FEB-2010 5247 5862		
28-00-99-04-01 (s)	FORWARD AND AFT AUXILIARY TANKS - LEFT - PERFORM DETAILED INSPECTION OF FORWARD AND AFT AUXILIARY LEFT TANKS EQUIPMENT, HARNESS AND BONDING LEADS, INTERNAL (EWIS)						PKG		
28.350	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-04-02 (s)	FORWARD AND AFT AUXILIARY TANKS - RIGHT - PERFORM DETAILED INSPECTION OF FORWARD AND AFT AUXILIARY RIGHT TANKS EQUIPMENT, HARNESS AND BONDING LEADS, INTERNAL (EWIS)						PKG		
28.350	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-05-01 (s)	UPPER FORWARD TRANSITION FAIRING - PERFORM GENERAL VISUAL INSPECTION OF CDCCL CABLE MARKINGS AND HARNESS FOR CONDITION AND SECURITY (EWIS)						PKG		
28.355	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-99-06-01 (s)	LEADING EDGE - RIGHT - PERFORM GENERAL VISUAL INSPECTION OF 28VDC FQIS LINE AND ARINC 429 LINE FOR CONDITION AND CDCCL MARKINGS, EXTERNAL (EWIS)						PKG		
28.360	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-07-01 (s)	CENTER FUSELAGE - PERFORM DETAILED INSPECTION OF 28VDC FQIS LINE AND ARINC 429 LINE FOR CHAFING OF CABLE HARNESS AND CDCCL MARKING, INTERNAL (EWIS)						PKG		
28.360	PKG 6 REF: AMM 05-25-28	MOS HRS/MSC AFL	120	+6m			20-JAN-2010 5247 5862		
28-00-99-08-01 (s)	REAR SPAR FUEL PUMP - LEFT - PERFORM GENERAL VISUAL INSPECTION OF REAR SPAR LEFT FUEL PUMP HARNESS, EXTERNAL (EWIS)						PKG		
28.365	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-08-02 (s)	REAR SPAR FUEL PUMP - RIGHT - PERFORM GENERAL VISUAL INSPECTION OF REAR SPAR RIGHT FUEL PUMP HARNESS, EXTERNAL (EWIS)						PKG		
28.365	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-09-01 (s)	FRONT AUXILIARY TANK - PERFORM GENERAL VISUAL INSPECTION OF FRONT AUXILIARY TANK FUEL INDICATION CABLE HARNESS OVERBRAID PROTECTION (EWIS)						PKG		
28.370	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-10-01 (s)	REAR AUXILIARY TANK - LEFT - PERFORM GENERAL VISUAL INSPECTION OF REAR AUXILIARY LEFT FUEL INDICATION CABLE HARNESS OVERBRAID PROTECTION (EWIS)						PKG		
28.370	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
28-00-99-10-02 (s)	REAR AUXILIARY TANK - RIGHT - PERFORM GENERAL VISUAL INSPECTION OF REAR AUXILIARY TANK FUEL INDICATION CABLE HARNESS OVERBRAID PROTECTION (EWIS)						PKG		
28.370	PKG 5 REF: AMM 05-25-28	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-00-99-11-01 (s)	TEMPERATURE INSULATION OF BLEED AIR DUCT AND ECS VALVES - PERFORM GENERAL VISUAL INSPECTION OF TEMPERATURE INSULATION OF BLEED AIR DUCT AND ECS VALVES						PKG		
28.375	PKG 4 REF: AMM 05-25-21	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
28-11-00-03-01 (s)	FUEL TANKS - DRAIN WATER FROM WING FUEL TANKS						PKG		
28.030	PKG 1 REF: See Workcard	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 28-11-00-04-01 (s)	FUEL TANKS - PERFORM FUNCTIONAL CHECK OF LEFT AND RIGHT FUEL TANK PRESSURE RELIEF VALVE						PKG		
28.025	PKG 4 REF: AMM 28-11-05	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 28-11-00-07-01 (s)	AUXILIARY FUEL TANKS - DRAIN WATER FROM AUXILIARY FUEL TANKS						PKG		
28.250	PKG 2 REF: AMM 12-11-60	DAYS HRS/MSC AFL	225	+2			20-FEB-2019 6584.3 6425		
+ 28-11-00-08-01 (s)	AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF AUXILIARY FUEL TANK SUPPORTS FOR DAMAGE AND PROPER INSTALLATION						PKG		
28.260	PKG 5 REF: AMM 53-85-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 28-11-00-09-01 (s)	AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF BONDING OF THE AUXILIARY FUEL TANKS AND EQUIPMENT						PKG		
28.255	PKG 5 REF: AMM 53-85-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
28-13-00-02-01 (s)	FUEL TANKS VENT - DRAIN VENT TANK						PKG		
28.060	PKG 1 REF: AMM 28-13-03	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 28-13-00-03-01 (s)	FUEL TANKS VENT - PERFORM OPERATIONAL CHECK / VISUAL CHECK (OFF-AIRCRAFT) OF LEFT AND RIGHT WING TANKS FUEL VENT FLOAT VALVE AND CHECK VALVE VENT OUTLET						PKG		
28.065	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 28-13-00-05-01 (s)	AUXILIARY FUEL TANKS VENT - PERFORM OPERATIONAL CHECK / VISUAL CHECK (OFF AIRCRAFT) OF AUXILIARY TANKS VENT FLOAT VALVES						PKG		
28.265	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 28-21-00-03-01 (s)	FUEL FEED SYSTEM - PERFORM FUNCTIONAL CHECK OF THE AUTOMATIC FUEL DRAIN VALVES INNER AND OUTER TANK						PKG		
28.085	PKG 6 REF: AMM 28-23-05	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 28-21-00-05-01 (s)	FUEL FEED SYSTEM - PERFORM FUNCTIONAL CHECK OF LEFT AND RIGHT FUEL THERMAL RELIEF VALVE						PKG		
28.140	PKG 6 REF: AMM 28-21-09	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 28-21-00-06-01 (s)	FUEL FEED SYSTEM - PERFORM OPERATIONAL CHECK OF FUEL CROSSFEED VALVE						PKG		
28.125	PKG 4 REF: AMM 28-21-10	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 28-40-00-01-01 (s)	FUEL INDICATION - PERFORM FUNCTIONAL CHECK OF FUEL TEMPERATURE SENSING SYSTEM						PKG		
28.185	PKG 6 REF: AMM 28-42-04	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 28-40-00-03-01 (s)	FUEL INDICATION - PERFORM OPERATIONAL CHECK OF FUEL QUANTITY INDICATION OF AUXILIARY FUEL TANKS						PKG		
28.270	PKG 1 REF: AMM 28-41-00	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-40-00-04-01 (s)	AUXILIARY FUEL QUANTITY INDICATION - PERFORM FUNCTIONAL CHECK OF AUXILIARY FUEL QUANTITY INDICATION						PKG		
28.310	PKG 2 REF: AMM 28-41-00	DAYS HRS/MSC AFL	225 500	+20			6269.8 6291		
28-40-00-05-01 (s)	HIGH LEVEL SHUTT-OFF AND INDICATION - PERFORM FUNCTIONAL CHECK OF HIGH LEVEL SHUT-OFF AND INDICATION						PKG		
28.295	PKG 5 REF: AMM 28-41-00	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
282191	FUEL THERMAL RELIEF VALVE								
28.135	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
284171	REFUELING PANEL								
28.235	6033-03-1 C361 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
CHAPTER 29 HYDRAULIC POWER									
29-00-00-03-01	DC STANDBY PUMP								
	4100-849049 SN-UNKNOWN REF:	MOS HRS/MSC AFL					TSN:0 TSN:0 TSN:5862	27-FEB-2002 0 0	21638
29-00-00-04-01	STANDBY PUMP CONTROL PRESSURE SWITCH								
29.165	0910676 0748T REF: See Workcard	MOS HRS/MSC AFL	120				TSN:0 TSN:0 TSN:0	27-JUN-2017 6370.9 6348	27-JUN-2027
29-00-00-05-01	EMERGENCY/PARK BRAKE ACCUMULATOR PRESSURE SWITCH								
29.170	98505-15667-1A 0644T REF: See Workcard	MOS HRS/MSC AFL APH	120				TSN:0 TSO:0 TSO:0	08-APR-2013 5700.2 6053	08-APR-2023

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-00-00-06-01	ALTERNATE BRAKE RETURN LINE CHECK VALVE 1C4158 0329	MOS HRS/MSC AFL	27500	TSN:5247			27-FEB-2002 0 0		22253
29.120 LIFE LIMIT	REF: See Workcard								
29-00-00-06-02	NORMAL BRAKE RETURN LINE CHECK VALVE 1C4158 0330	MOS HRS/MSC AFL	27500	TSN:5247			27-FEB-2002 0 0		22253
29.125 LIFE LIMIT	REF: See Workcard								
29-00-00-06-03	PARK BRAKE RETURN LINE CHECK VALVE 1C4158 0334	MOS HRS/MSC AFL	27500	TSN:5247			27-FEB-2002 0 0		22253
29.125 LIFE LIMIT	REF: See Workcard								
29-00-00-10-01	FLEXIBLE HYDRAULIC HOSE 001D324A1058050 0123	MOS HRS/MSC AFL	6000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 5852		11852
LIFE LIMIT	REF:								
29-00-00-11-01	FLEXIBLE HYDRAULIC HOSE 001D324A1058050 0047	MOS HRS/MSC AFL	6000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 5852		11852
LIFE LIMIT	REF:								
29-10-00-01-01	LEFT AC MOTOR 5DA PUMP 42152 AF042	MOS HRS/MSC AFL	10000	+400			14-JUL-2009 5247 5862		15247 M 15647
29.065 OVERHAUL	REF: See Workcard								
29-10-00-01-02	RIGHT AC MOTOR 50DA PUMP 42152 AF380	MOS HRS/MSC AFL	10000	+400			14-JUL-2009 5247 5862		15247 M 15647
29.070 OVERHAUL	REF: See Workcard								
29-10-00-02-01	AC MOTOR PUMP 5DA, LEFT - DISCARD OF MOTOR BEARINGS OF AC MOTOR PUMP P/N 42152, LEFT, (OFF AIRCRAFT)	MOS HRS/MSC AFL	3800				27-FEB-2002 5247 0		9047
29.210	REF: See Workcard								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-10-00-02-02	AC MOTOR PUMP 50DA, RIGHT - DISCARD OF MOTOR BEARINGS OF AC MOTOR PUMP P/N 42152, RIGHT, (OFF AIRCRAFT)								
29.210	REF: See Workcard	MOS HRS/MSC AFL	3800	+200			27-FEB-2002 5247 0	9047	9247
29-10-00-03-01 (s)	HYDRAULIC FLUID, HYDRAULIC SYSTEM A - SPECIAL DETAILED INSPECTION OF HYDRAULIC FLUID FOR CONTAMINATION								
	REF: AMM 29-10-00	MOS HRS/MSC AFL	30 5000		TSI:0 TSI:0 TSI:0		27-JUN-2017 6370.9 6348		
29-10-00-03-02 (s)	HYDRAULIC FLUID, HYDRAULIC SYSTEM B - SPECIAL DETAILED INSPECTION OF HYDRAULIC FLUID FOR CONTAMINATION								
	REF: AMM 29-10-00	MOS HRS/MSC AFL	30 5000				27-JUN-2017 6370.9 6348		
+ 29-11-00-01-01 (s)	HYDRAULIC SYSTEM A - PERFORM VISUAL CHECK OF THE HIGH PRESSURE FILTER POP-OUT, HYDRAULIC SYSTEM A								
29.045	PKG 2 REF: AMM 29-11-08	DAYS HRS/MSC AFL	225	+14			PKG 20-FEB-2019 6584.3 6425		
+ 29-11-00-02-01 (s)	HYDRAULIC SYSTEM A - PERFORM DETAILED INSPECTION OF THE HIGH PRESSURE FILTER AND RETURN FILTER PACKAGE FOR CONDITION, DISCARD OF RETURN FILTER ELEMENT AND DISCARD OF RESERVIOR VENT FILTER, HYDRAULIC SYSTEM A								
29.050	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 29-11-00-04-01 (s)	HYDRAULIC SYSTEM A - PERFORM VISUAL CHECK OF RESERVOIR FLUID LEVEL VIA SIGHT GLASS								
29.035	PH2 PKG 2 SN-UNKNOWN REF: AMM 29-11-01	DAYS HRS/MSC AFL	225	+14			PKG 20-FEB-2019 6584.3 6425		
+ 29-11-00-05-01 (s)	HYDRAULIC SYSTEM A - PERFORM FUNCTIONAL CHECK OF THE MAIN SYSTEM ACCUMULATOR FOR PRECHARGE PRESSURE AND INTERNAL LEAKAGE, HYDRAULIC SYSTEM A								
29.025	PKG 4 REF: AMM 29-11-10	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-11-00-06-01 (s)	HYDRAULIC SYSTEM A - PERFORM OPERATIONAL CHECK OF THE AUTOMATIC CHANGE- OVER ELECTRICAL POWER SUPPLY OF AC MAIN PUMP, HYDRAULIC SYSTEM A						PKG		
29.075	PKG 4 REF: AMM 29-11-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 29-12-00-01-01 (s)	HYDRAULIC SYSTEM B - PERFORM VISUAL CHECK OF THE HIGH PRESSURE FILTER POP-OUT, HYDRAULIC SYSTEM B						PKG		
29.055	PKG 2 REF: AMM 29-12-08	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 29-12-00-02-01 (s)	HYDRAULIC SYSTEM B - PERFORM DETAILED INSPECTION OF THE HIGH PRESSURE FILTER AND RETURN FILTER PACKAGE FOR CONDITION, DISCARD OF RETURN FILTER ELEMENT AND DISCARD OF RESERVIOR VENT FILTER, HYDRAULIC SYSTEM B						PKG		
29.060	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 29-12-00-04-01 (s)	HYDRAULIC SYSTEM B - PERFORM VISUAL CHECK OF RESERVOIR FLUID LEVEL VIA SIGHT GLASS, HYDRAULIC SYSTEM B						PKG		
29.040	PKG 2 REF: AMM 29-12-01	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 29-12-00-05-01 (s)	HYDRAULIC SYSTEM B - PERFORM FUNCTIONAL CHECK OF THE MAIN SYSTEM EMERGENCY / PARK BRAKE ACCUMULATOR FOR PRECHARGE PRESSURE AND INTERNAL LEAKAGE, HYDRAULIC SYSTEM B						PKG		
29.030	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 29-12-00-06-01 (s)	HYDRAULIC SYSTEM B - PERFORM OPERATIONAL CHECK OF THE AUTOMATIC CHANGE OVER ELECTRICAL POWER SUPPLY OF AC MAIN PUMP, HYDRAULIC SYSTEM B						PKG		
29.095	PKG 4 REF: AMM 29-12-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 29-12-00-08-01 (s)	HYDRAULIC SYSTEM B - PERFORM DETAILED INSPECTION OF THE DC STANDBY PUMP MOTOR BRUSHES FOR EXCESSIVE WEAR						PKG		
29.090	4100-849048 PKG 5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	60	+6m		-101	08-JUN-2018 6504.7 6393		
29-12-00-08-02 (s)	HYDRAULIC SYSTEM B - PERFORM DETAILED INSPECTION OF THE DC STANDBY PUMP MOTOR BRUSHES FOR EXCESSIVE WEAR						PKG		
	4100-849049 PKG 5 SN-UNKNOWN REF:	MOS HRS/MSC AFL	60				08-JUN-2018 6504.7 6393		
29-12-32-00(A)	SYSTEM A HYDRAULIC ACCUMULATOR								
	3900001-107 EFS0310, EFS0311,EFS0319 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
29-12-32-00(B)	SYSTEM B HYDRAULIC ACCUMULATOR								
	3900001-107 EFS0310, EFS0311,EFS0319 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
29-12-32-00(C)	EMERGENCY/PARK BRAKE HYDRAULIC ACCUMULATOR								
	3900001-107 EFS0310, EFS0311,EFS0319 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
29-12-32-01-01(A)	REPLACE SYSTEM A HYDRAULIC ACCUMULATOR HYDRAULIC ACCUMULATOR P/N 3900001-107, INSTALLED IN MAIN SYSTEM A								
	3900001-107 EFS0310, EFS0311,EFS0319 REF:	MOS HRS/MSC AFL	162		TSI:0		09-OCT-2010 5253.1 0	09-APR-2024	
LIFE LIMIT			26760		TSI:0				20898
29-12-32-01-01(B)	REPLACE SYSTEM B HYDRAULIC ACCUMULATOR HYDRAULIC ACCUMULATOR P/N 3900001-107, INSTALLED IN MAIN SYSTEM B.								
	3900001-107 EFS0310, EFS0311,EFS0319 REF:	MOS HRS/MSC AFL	162		TSI:0		09-OCT-2010 0 0	09-APR-2024	
LIFE LIMIT			26760		TSI:0				20898

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-12-32-01-01(C)	REPLACE EMERGENCY/PARK BRAKE HYDRAULIC ACCUMULATOR INSTALLED IN PARK BRAKE SYSTEM								
	3900001-107	MOS	162	TSI:0			09-OCT-2010	09-APR-2024	
	EFS0310, EFS0311, EFS0319	HRS/MSC		TSI:0			0		
LIFE LIMIT	REF:	AFL	26760	TSI:0			0	20898	
291101	MAIN SYSTEM A RESERVOIR								
	PH2	MOS					27-FEB-2002		
29.035	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
291102	MAIN SYSTEM B RESERVOIR								
	PH2	MOS					27-FEB-2002		
29.040	SN-UNKNOWN	HRS/MSC	O/C				0		
	REF: See Workcard	AFL					0		
CHAPTER 30 ICE AND RAIN PROTECTION									
+ 30-10-00-02-01 (s)	DE-ICER BOOTS - PERFORM OPERATIONAL CHECK OF DE-ICER SHUT OFF VALVES 4HP AND 14HP						PKG		
	PKG 5	MOS	60	+4m		-61	08-JUN-2018		
30.025		HRS/MSC					6504.7		
	REF: AMM 30-13-09	AFL					6393		
30-10-00-03-01 (s)	DE-ICER BOOTS - PERFORM OPERATIONAL CHECK OF DE-ICER CHECK VALVES						PKG		
	PKG 5	MOS	60	+4m		-61	08-JUN-2018		
30.035		HRS/MSC					6504.7		
	REF: AMM 30-13-08	AFL					6393		
+ 30-10-00-04-01 (s)	RESTORATION LEFT PRECOOLER (CLEAN, OFF-AIRCRAFT)						PKG		
	PH5 PKG 5	MOS	60	+4m		-61	08-JUN-2018		
30.110	SN-UNKNOWN	HRS/MSC					6504.7		
	REF: See Workcard	AFL					6393		
+ 30-10-00-04-02 (s)	RESTORATION RIGHT PRECOOLER (CLEAN, OFF-AIRCRAFT)						PKG		
	PH5 PKG 5	MOS	60	+4m		-61	08-JUN-2018		
30.110	SN-UNKNOWN	HRS/MSC					6504.7		
	REF: See Workcard	AFL					6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-10-00-05-01 (s)	DE-ICER BOOTS - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF LEFT PRESSURE REGULATOR / RELIEF VALVE						PKG		
30.020	PH6 PKG 6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 30-10-00-05-02 (s)	DE-ICER BOOTS - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF RIGHT PRESSURE REGULATOR / RELIEF VALVE						PKG		
30.020	PH6 PKG 6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	120	+6m			04-FEB-2011 5276.6 5873		
+ 30-10-00-06-01 (s)	DE-ICER BOOTS - PERFORM DETAILED INSPECTION OF WING / STABILIZER DE-ICER BOOTS						PKG		
30.015	PKG 3 REF: AMM 30-10-00	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
+ 30-10-00-09-01 (s)	DE-ICER BOOTS - PERFORM OPERATIONAL CHECK OF SINGLE / CYCLE MODE (INCLUDING VISUAL CHECK OF BOOT INFLATION)						PKG		
30.045	PKG 4 REF: AMM 30-10-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 30-10-00-11-01	DE-ICING CONTROL SYSTEM - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF DE-ICING CONTROL SYSTEM OVER-TEMPERATURE SWITCH								
30.050	REF: See Workcard	MOS HRS/MSC AFL	1300		-5.6		12-OCT-2018 6539.5 6408	7833.9	
+ 30-14-00-01-01 (s)	ELEVATOR / RUDDER HORN ANTI-ICING SYSTEM - PERFORM OPERATIONAL CHECK OF ELEVATOR / RUDDER HORN ANTI-ICING SYSTEM						PKG		
30.140	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 30-14-00-02-01 (s)	ELEVATOR / RUDDER HORN ANTI-ICING SYSTEM - PERFORM VISUAL CHECK OF NEOPRENE ANTI-ICE ELEVATOR / RUDDER HORN						PKG		
30.145	PKG 4 REF: AMM 30-14-02	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-14-00-03-01 (s)	ELEVATOR / RUDDER HORN ANTI-ICING SYSTEM - PERFORM OPERATIONAL CHECK OF FAILURE INDICATING SYSTEM (SWITCHING AIRCRAFT POWER OFF)						PKG		
30.150	PKG 5 REF: AMM 30-14-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
301011	LEFT PRESSURE REGULATOR								
30.020	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
301012	RIGHT PRESSURE REGULATOR								
30.020	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
301051	LEFT WING OUTBOARD DE-ICING BOOT								
30.070	S29S-7D5240-75 MS66330 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				03-APR-2009 0 0		
301052	RIGHT WING OUTBOARD DE-ICING BOOT								
30.070	PS29S-7D5240-74 MS83040 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				23-MAR-2009 0 0		
301057	LEFT HORIZONTAL STABILIZER DE-ICING BOOT								
30.085	S29S-7D5240-91 MZKX580 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				09-JUN-2010 0 0		
301059	VERTICAL STABILIZER DE-ICING BOOT								
30.090	S29S-7D5240-83 MV26110 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-APR-2009 0 0		
301071	LEFT PRECOOLER								
30.110	PH5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
301072	RIGHT PRECOOLER									
30.110	PH5 SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0			
308001	ICE DETECTOR									
30.175	0871DW1 0099 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393			
CHAPTER 31 INDICATING/RECORDING SYSTEMS										
31-00-00-01A-01 (s)	INDICATING / RECORDING SYSTEMS - PERFORM OPERATIONAL CHECK OF REVERSIONARY CONTROL PANEL SWITCHING. DU-870 INSTALLED. (PRE SB 328J-31-323)						PKG			
	PKG 2	DAYS	225	+14			20-FEB-2019 6584.3 6425			
	REF: GENERIC NO REF	AFL								
31-00-00-01B-01 (s)	INDICATING / RECORDING SYSTEMS - PERFORM OPERATIONAL CHECK OF REVERSIONARY CONTROL PANEL SWITCHING. DU-875 INSTALLED. (POST SB 328J-31-323)						PKG			
	PKG 2	DAYS	225	+14			20-FEB-2019 6584.3 6425			
	REF: GENERIC NO REF	AFL								
+ 31-00-00-02-01 (s)	INDICATING / RECORDING SYSTEMS - PERFORM FUNCTIONAL CHECK OF FLIGHT DATA RECORDER (FDR) DATA RECORDING						PKG			
31.010	PH4, POST SB 328J-31-097 SN-UNKNOWN REF: See Workcard	PKG 4 MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367			
31-00-00-02-02 (s)	INDICATING / RECORDING SYSTEMS - PERFORM FUNCTIONAL CHECK OF FLIGHT DATA RECORDER (FDR) DATA RECORDING						PKG			
	PKG 4	MOS	30	+2m		-10	01-DEC-2017 6428.4 6367			
	REF:	AFL								
+ 31-00-00-03-01	INDICATING / RECORDING SYSTEMS - PERFORM OPERATIONAL CHECK (OFF-AIRCRAFT) OF THE UNDERWATER LOCATOR DEVICE (ULD) OF FLIGHT DATA RECORDER (FDR)									
31.010		MOS HRS/MSC AFL	24	+2m		-67	13-JUN-2019 6590.1 6430	07-APR-2021	07-JUN-2021	
	REF: See Workcard									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-00-00-04-01	INDICATING / RECORDING SYSTEMS - DISCARD OF FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATOR DEVICE (ULD) BATTERY (OFF AIRCRAFT)								
31.010	ELP-362D 38462 REF: See Workcard	MOS HRS/MSC AFL	72	+6m			13-JUN-2019 6590.1 6430	01-MAY-2026	M 01-NOV-2026
31-01-00-01-01	INDICATING / RECORDING SYSTEMS - MANDATORY RETROFIT OF NACELLE ANTI-ICE EICAS INDICATION								
	REF:	MOS HRS/MSC AFL	A/R	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		
313001	FLIGHT DATA RECORDER PH4, POST SB 328J-31-097 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
313003	FLIGHT DATA RECORDER (FDR) UNDERWATER LOCATOR (ULD) DEVICE								
28.330	ELP-362D 38462 REF: See Workcard	MOS HRS/MSC AFL	O/C				13-JUN-2019 6590.1 6430		
CHAPTER 32 LANDING GEAR									
32-00-00-02-01	LEFT MAIN LANDING GEAR SIDE BRACE UNIVERSAL JOINT LIFE LIMIT								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	48624	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		48624
32-00-00-02-02	RIGHT MMAIN LANDING GEAR SIDE BRACE UNIVERSAL JOINT LIFE LIMIT								
	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	48624	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		48624
32-00-00-03-01	NOSE LANDING GEAR LIFE LIMIT								
	23100-300-4 IL-038 REF:	MOS HRS/MSC AFL	65000				23-JAN-2012 5538.2 5973		70973 M
32-00-00-06-01	CHANGE OVER VALVE								
32.185 LIFE LIMIT	AC70077-1 ZF112 REF: See Workcard	MOS HRS/MSC AFL	12000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		12000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-00-12-01	MAIN LANDING GEAR - PERFORM DETAILED INSPECTION OF LEFT MLG SHOCK ABSORBER COUPLING JOINT PIN (P/N D66791)								
32.355	REF: See Workcard	MOS HRS/MSC AFL	3000				27-FEB-2002 0 5862		8862
32-00-00-12-01	MAIN LANDING GEAR - PERFORM DETAILED INSPECTION OF RIGHT MLG SHOCK ABSORBER COUPLING JOINT PIN (P/N D66791)								
32.350	REF: See Workcard	MOS HRS/MSC AFL	3000				27-FEB-2002 0 5862		8862
32-00-00-20-01	PARK BRAKE VALVE AC70082-1 0187	MOS HRS/MSC AFL	-				05-FEB-2018 6465.9 6381		
LIFE LIMIT	REF: See Workcard								
32-00-00-27-01	PARK BRAKE SHUTTLE VALVE AC70066-2 ZC156	MOS HRS/MSC AFL	46640	TSN:0			27-FEB-2002 0 0		46640
LIFE LIMIT	REF:			TSN:0					
32-00-00-31-01	NORMAL BRAKE SHUTTLE VALVE AC70068-2 XX133	MOS HRS/MSC AFL	44220	TSN:0			27-FEB-2002 0 0		44220
LIFE LIMIT	REF:			TSN:0					
32-00-00-32-01	NORMAL BRAKE SHUTTLE VALVE AC70086-2 SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: GENERIC NO REF			TSN:0					
32-00-01-01-01	LEFT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: See Workcard			TSN:0					
32-00-01-02-01	RIGHT MAIN LANDING GEAR PN SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: See Workcard			TSN:0					

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-01-03-01	LEFT MAIN LANDING GEAR 22730-310-1 CE072	MOS HRS/MSC AFL APH	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
LIFE LIMIT	REF: GENERIC NO REF								
32-00-01-04-01	RIGHT MAIN LANDING GEAR 22731-310-1 CE072	MOS HRS/MSC AFL APH	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
LIFE LIMIT	REF: GENERIC NO REF								
32-00-01-06-01	RIGHT MAIN LANDING GEAR 22731-320-Y SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: GENERIC NO REF								
32-00-01-07-01	LEFT MAIN LANDING GEAR BODY 22415-300-Y SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.340 LIFE LIMIT	REF: See Workcard								
32-00-01-09-01	RIGHT MAIN LANDING GEAR BODY 22416-300-Y SN-UNKNOWN	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.340 LIFE LIMIT	REF: See Workcard								
32-00-01-11-01	LEFT MAIN LANDING GEAR BODY P/N 22415-310-YY CE066	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: GENERIC NO REF								
32-00-01-13-01	RIGHT MAIN LANDING GEAR BODY P/N 22416-310-YY CE066	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT	REF: GENERIC NO REF								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-01-15-01	LEFT MAIN LANDING GEAR TRAILING ARM 22435-300-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.380 LIFE LIMIT									
32-00-01-15-01	RIGHT MAIN LANDING GEAR TRAILING ARM 22435-300-3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
27.325 LIFE LIMIT									
32-00-01-16-01	LEFT MAIN LANDING GEAR TRAILING ARM P/N 22435-300-YY CE131, CE132 REF: GENERIC NO REF	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT									
32-00-01-16-01	RIGHT MAIN LANDING GEAR TRAILING ARM P/N 22435-300-YY CE131, CE132 REF: GENERIC NO REF	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
LIFE LIMIT									
32-00-01-18-01	LEFT MAIN LANDING GEAR BRACE ASSEMBLY 24260-310-0 IL-143 REF:	MOS HRS/MSC AFL	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
LIFE LIMIT									
32-00-01-18-01	RIGHT MAIN LANDING GEAR BRACE ASSEMBLY 24260-310-0 B11 REF:	MOS HRS/MSC AFL	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
LIFE LIMIT									
32-00-01-19-01	LEFT MAIN LANDING GEAR UPLOCK P/N 22405-300-YY IL327, IL328 REF: See Workcard	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.390 LIFE LIMIT									
32-00-01-19-01	RIGHT MAIN LANDING GEAR UPLOCK P/N 22405-300-YY IL327, IL328 REF: See Workcard	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.440 LIFE LIMIT									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-02-01-01	NOSE LANDING GEAR SHOCK STRUT ASSEMBLY 23100-300-4 IL-038 REF: See Workcard	MOS HRS/MSC AFL APH	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
32.400 LIFE LIMIT									
32-00-02-02-01	NOSE LANDING GEAR BRACE ASSEMBLY 23200-300-02 IL-120 REF: See Workcard	MOS HRS/MSC AFL APH	65000	TSO:0 TSN:5001.5 TSO:0 TSN:5604			23-JAN-2012 5538.2 5973		65369 M
32.410 LIFE LIMIT									
32-00-02-03-01	NOSE LANDING GEAR UPLOCK P/N 22405-300-YY IL315 REF: See Workcard	MOS HRS/MSC AFL	65000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		65000
32.410 LIFE LIMIT									
+ 32-10-00-01-01 (s)	MAIN GEAR AND DOORS - PERFORM DETAILED INSPECTION OF LEFT MAIN LANDING GEAR SHOCK ABSORBER STROKE AND SHOCK ABSORBER FOR SIGNS OF LEAKAGE AND IMPACT TAPE FOR DAMAGE PKG 1 REF: AMM 32-11-04	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430	PKG	
32.020									
+ 32-10-00-01-01 (s)	MAIN GEAR AND DOORS - PERFORM DETAILED INSPECTION OF RIGHT MAIN LANDING GEAR SHOCK ABSORBER STROKE AND SHOCK ABSORBER FOR SIGNS OF LEAKAGE AND IMPACT TAPE FOR DAMAGE PKG 1 REF: AMM 32-11-04	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430	PKG	
32.025									
+ 32-10-00-02-01 (s)	MAIN GEAR AND DOORS - PERFORM SERVICING OF LEFT MAIN LANDING GEAR SHOCK ABSORBER PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367	PKG	
32.020									
+ 32-10-00-02-01 (s)	MAIN GEAR AND DOORS - PERFORM SERVICING OF RIGHT MAIN LANDING GEAR SHOCK ABSORBER PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367	PKG	
32.025									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-02-02 (s)	MAIN GEAR AND DOORS - PERFORM SERVICING OF LEFT MAIN LANDING GEAR SHOCK ABSORBER PKG 4	MOS HRS/MSC AFL	30			-10	PKG 01-DEC-2017 6428.4 6367		
	REF: AMM 12-13-32								
32-10-00-02-02 (s)	MAIN GEAR AND DOORS - PERFORM SERVICING OF RIGHT MAIN LANDING GEAR SHOCK ABSORBER PKG 4	MOS HRS/MSC AFL	30			-10	PKG 01-DEC-2017 6428.4 6367		
	REF: AMM 12-13-32								
32-10-00-03-02 (s)	MAIN GEAR AND DOORS - PERFORM LUBRICATION OF LEFT MAIN LANDING GEAR PKG 2	DAYS HRS/MSC AFL	225	+14		-221	PKG 20-FEB-2019 6584.3 6425		
32.035	REF: AMM 12-24-10								
32-10-00-03-02 (s)	MAIN GEAR AND DOORS - PERFORM LUBRICATION OF RIGHT MAIN LANDING GEAR PKG 2	DAYS HRS/MSC AFL	225	+14		-221	PKG 20-FEB-2019 6584.3 6425		
32.035	REF: AMM 12-24-10								
+ 32-10-00-04-01 (s)	MAIN GEAR AND DOORS - PERFORM DETAILED INSPECTION OF LEFT MAIN LANDING GEAR COMPONENTS FOR WEAR AND CONDITION PKG 4	MOS HRS/MSC AFL	30	+4m			PKG 01-DEC-2017 6428.4 6367		
32.040	REF: AMM 32-11-00								
+ 32-10-00-04-01 (s)	MAIN GEAR AND DOORS - PERFORM DETAILED INSPECTION OF RIGHT MAIN LANDING GEAR COMPONENTS FOR WEAR AND CONDITION PKG 4	MOS HRS/MSC AFL	30	+4m			PKG 01-DEC-2017 6428.4 6367		
32.040	REF: AMM 32-11-00								
32-10-00-06-01	LEFT MAIN LANDING GEAR/SIDE BRACE ASSEMBLY 22730-310-1 CE072	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022 M	23-JUL-2022
32.010 RESTORE	REF: See Workcard		22000					27973 M	
32-10-00-06-02	RIGHT MAIN LANDING GEAR/SIDE BRACE ASSEMBLY 24260-310-0 B11	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5528.2 5973	23-JAN-2022 M	23-JUL-2022
32.011 RESTORE	REF: See Workcard		22000					27973 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-11-01 (s)	MAIN GEAR BOLTS - PERFORM DETAILED INSPECTION OF MAIN LANDING GEAR ACTUATOR-, ASSIST ACTUATOR- AND BRACE BOLTS, LEFT AND RIGHT						PKG		
32.335	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 32-11-13-01-01	MLG MAIN STRUT ASSEMBLY, UPPER HINGE PIN - PERFORM DETAILED INSPECTION OF LEFT MLG MAIN STRUT ASSEMBLY, UPPER HINGE PIN.								
32.010	REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-11-13-01-01 (s)	MLG MAIN STRUT ASSEMBLY, UPPER HINGE PIN - PERFORM DETAILED INSPECTION OF RIGHT MLG MAIN STRUT ASSEMBLY, UPPER HINGE PIN.						PKG		
32.011	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973		
+ 32-11-15-01-01	MLG MAIN STRUT ASSEMBLY- LOWER ARM HINGE PIN - PERFORM DETAILED INSPECTION OF LEFT MLG MAIN STRUT ASSEMBLY, LOWER ARM HINGE PINS								
32.010	REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-11-15-01-01 (s)	MLG MAIN STRUT ASSEMBLY- LOWER ARM HINGE PIN - PERFORM DETAILED INSPECTION OF RIGHT MLG MAIN STRUT ASSEMBLY, LOWER ARM HINGE PINS.						PKG		
32.011	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973		
32-11-17-01-01	MLG MAIN STRUT ASSEMBLY - PERFORM DETAILED INSPECTION OF MLG MAIN STRUT ASSEMBLY, LOWER HINGE PINS, LEFT AND RIGHT								
32.370	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
32-11-19-01-01	MLG - TRAILING ARM HINGE PINS - PERFORM DETAILED INSPECTION OF MLG TRAILING ARM HINGE PINS, LEFT AND RIGHT								
32.370	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-11-21-01-01	MLG - BARREL HINGE PIN - PERFORM DETAILED INSPECTION OF MLG BARREL HINGE PIN, LEFT AND RIGHT.								
32.370	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-11-31-01-01	MLG - HINGE PIN, SHOCK ABSORBER - PERFORM DETAILED INSPECTION OF THE LEFT MLG SHOCK ABSORBER HINGE PIN								
32.010	REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-11-31-01-01 (s)	MLG - HINGE PIN, SHOCK ABSORBER - PERFORM DETAILED INSPECTION OF THE RIGHT MLG SHOCK ABSORBER HINGE PIN.						PKG		
32.011	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973		
+ 32-11-33-01-01 (s)	MLG - COUPLING JOINT, SHOCK ABSORBER, PINS - PERFORM DETAILED INSPECTION OF THE LEFT MLG COUPLING JOINT, SHOCK ABSORBER PINS.						PKG		
32.010	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973		
+ 32-11-33-01-01	MLG - COUPLING JOINT, SHOCK ABSORBER, PINS - PERFORM DETAILED INSPECTION OF THE RIGHT MLG COUPLING JOINT, SHOCK ABSORBER PINS.								
32.011	REF: See Workcard	MOS HRS/MSC AFL	120	+6m	TSI:0 TSI:0 TSI:0		23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-20-00-01-01 (s)	NOSE GEAR AND DOORS - PERFORM DETAILED INSPECTION OF NOSE LANDING GEAR SHOCK ABSORBER STROKE AND SHOCK ABSORBER FOR SIGNS OF LEAKAGE AND IMPACT TAPE FOR DAMAGE						PKG		
32.070	PKG 1 REF: AMM 32-21-01	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
32-20-00-02-01 (s)	NOSE GEAR AND DOORS - PERFORM SERVICING OF NOSE LANDING GEAR SHOCK ABSORBER						PKG		
32.070	PKG 4 REF: AMM 12-13-42	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-20-00-03-01 (s)	NOSE GEAR AND DOORS - PERFORM DETAILED INSPECTION OF NOSE LANDING GEAR COMPONENTS FOR WEAR AND CONDITION						PKG		
32.075	PKG 4 REF: AMM 32-21-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
32-20-00-04-02 (s)	NOSE GEAR AND DOORS - PERFORM LUBRICATION OF NOSE LANDING GEAR						PKG		
32.035	PKG 2 REF: AMM 12-24-10	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 32-20-00-05-01 (s)	NOSE GEAR AND DOORS - PERFORM DETAILED INSPECTION OF NOSE LANDING GEAR FRONT DOOR SHEAR RODS						PKG		
32.085	PKG 2 REF: AMM 32-22-14	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 32-20-00-06-01 (s)	NOSE GEAR AND DOORS - PERFORM FUNCTIONAL CHECK OF PRELOAD OF THE NOSE LANDING GEAR FORWARD DOORS						PKG		
32.080	PKG 4 REF: AMM 32-22-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
32-20-00-08-01	NOSE LANDING GEAR/BRACE ASSEMBLY								
32.015 OVERHAUL	32100-300-2 IL-038 REF: See Workcard	MOS HRS/MSC AFL	120 22000	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022 M 23-JUL-2022 27973 M	
32-20-00-09-01 (s)	NOSE GEAR BOLTS - PERFORM DETAILED INSPECTION OF NOSE LANDING GEAR BRACE BOLTS						PKG		
32.160	PKG 4 REF: AMM 32-21-16	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 32-21-03-01-01	NLG-PIN TRUNNION - PERFORMED DETAILED INSPECTION OF THE NOSE LANDING GEAR-PIN TRUNNION								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022 23-JUL-2022	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-15-01-01	NLG-PIN TRUNNION , UPPER BRACE - PERFORMED DETAILED INSPECTION OF THE NOSE LANDING GEAR -PIN TRUNNION, UPPER BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-21-19-01-01	NLG - UPPER PIN, LOWER BRACE - PERFORM DETAILED INSPECTION OF THE NOSE LANDING GEAR UPPER PIN, LOWER BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-21-21-01-01	NLG - LOWER PIN, LOWER BRACE - PERFORM DETAILED INSPECTION OF THE NOSE LANDING GEAR LOWER PIN, LOWER BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-21-23-01-01	NLG - LOWER PIN, UPPER BRACE - PERFORM DETAILED INSPECTION OF THE NOSE LANDING GEAR LOWER PIN, UPPER BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-21-25-01-01	NLG - UPPER PIN, UPPER JURY BRACE - PERFORM DETAILED INSPECTION OF THE NOSE LANDING GEAR UPPER PIN, UPPER JURY BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-21-27-01-01	NLG - LOWER PIN, UPPER JURY BRACE - PERFORM DETAILED INSPECTION OF THE NOSE LANDING GEAR LOWER PIN, UPPER JURY BRACE								
32.015	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			23-JAN-2012 5538.2 5973	23-JAN-2022	23-JUL-2022
+ 32-30-00-02-01 (s)	EXTENSION AND RETRACTION - FUNCTIONAL CHECK OF THE LANDING GEAR NORMAL AND EMERGENCY EXTENSION/RETRACTION						PKG		
32.045	PKG 4 REF: AMM 32-30-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-00-01-01 (s)	WHEELS AND BRAKES - PERFORM TIRE PRESSURE CHECK OF MAIN LANDING GEAR AND NOSE LANDING GEAR TIRES						PKG		
32.210	PKG 1 REF: See Workcard	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
32-40-00-01-02 (s)	WHEELS AND BRAKES - PERFORM TIRE PRESSURE CHECK OF MLG AND NLG TIRES						PKG		
32.210	PKG 1 REF:	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 32-40-00-02-01 (s)	WHEELS AND BRAKES - PERFORM DETAILED INSPECTION OF THE MAIN LANDING GEAR AND NOSE LANDING GEAR TIRES AND RIMS FOR WEAR AND CONDITION						PKG		
32.215	PKG 1 REF: See Workcard	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 32-40-00-04-01 (s)	WHEELS AND BRAKES - PERFORM DETAILED INSPECTION OF EMERGENCY / PARK BRAKE MECHANISM FOR WEAR AND CONDITION						PKG		
32.220	PKG 5 REF: AMM 32-44-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 32-40-00-07-01 (s)	WHEELS AND BRAKES - PERFORM DETAILED INSPECTION OF THE BRAKE MASTER CYLINDERS FOR WEAR AND CONDITION						PKG		
32.225	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 32-40-00-08-01 (s)	WHEELS AND BRAKES - PERFORM DETAILED INSPECTION OF BRAKE ASSEMBLY WEAR INDICATORS						PKG		
32.230	PKG 1 REF: AMM 32-42-07	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 32-40-00-09-01 (s)	WHEELS AND BRAKES - PERFORM DETAILED INSPECTION OF THE MASTER CYLINDER RESERVOIRS FOR FLUID LEVEL AND CONDITION						PKG		
32.235	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+14d		-10	01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-40-00-11-01	WHEELS AND BRAKES - PERFORM OPERATIONAL CHECK OF THE ALTERNATE BRAKE SYSTEM								
32.240	REF: AMM 32-43-00	MOS HRS/MSC AFL	800				08-APR-2013 5700.2 6053	6500.2	
+ 32-40-00-12-01 (s)	WHEELS AND BRAKES - PERFORM FUNCTIONAL CHECK OF BRAKE CHECK VALVES (NON RETURN VALVES)								
32.245	PKG 4 REF: AMM 32-40-00	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 32-40-00-13-01 (s)	WHEELS AND BRAKES - PERFORM FUNCTIONAL CHECK OF NORMAL AND ALTERNATE BRAKE HYDRAULIC FUSES								
32.190	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 32-40-00-14-01 (s)	WHEELS AND BRAKES - PERFORM OPERATIONAL CHECK OF ANTI SKID INDICATION								
32.250	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 32-50-00-01-01 (s)	STEERING - PERFORM DETAILED INSPECTION OF THE RUDDER PEDAL COMMAND POTENTIOMETER LINKAGE FOR WEAR AND CONDITION								
32.305	PKG 5 REF: AMM 05-25-32	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
32-50-00-06-01 (s)	STEERING - PERFORM LUBRICATION OF THE NOSE LANDING GEAR SHOCK STRUT								
32.070	PKG 3 REF: AMM 32-21-03	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367		
32-60-00-01-01 (s)	POSITION AND WARNING - PERFORM OPERATIONAL CHECK OF LANDING GEAR DOWNLOCK INDICATION								
32.420	PKG 3 REF: AMM 32-61-00	MOS HRS/MSC AFL	15	+1m		-20	01-DEC-2017 6428.4 6367		
32-70-00-05	LH MLG IBD WHEEL SPEED SENSOR								
	ACM31356 YA030 REF:	MOS HRS/MSC AFL	O/C				23-JAN-2012 5538.2 5973		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323011	LEFT MAIN LANDING GEAR UPLOCK								
32.095	22405-300-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		
323012	RIGHT MAIN LANDING GEAR UPLOCK								
32.095	22405-300-00 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		
323111	LEFT MAIN LANDING GEAR RETRACT ACTUATOR								
32.110	24125-000-00 H149 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-APR-2017 6338.6 6330		
324130	LEFT OUTBOARD MAIN LANDING GEAR (7GD) BRAKE								
32.200	AHA2227-3 XC166 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			07-APR-2017 6338.6 6330		
324131	LEFT INBOARD MAIN LANDING GEAR (5GD) BRAKE								
32.200	AHA2227-6 YF 005 REF: See Workcard	MOS HRS/MSC AFL	O/C				23-MAR-2009 0 0		
324133	RIGHT OUTBOARD MAIN LANDING GEAR (11GD) BRAKE								
32.205	AHA2226-2 YN184 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-APR-2009 0 0		
324401	LEFT NOSE WHEEL								
32.280	AHA2225 YA051 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-APR-2013 5700.2 6053		
324402	RIGHT NOSE WHEEL								
32.280	AHA2225 A0076 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-APR-2013 5700.2 6053		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324403	LEFT NOSE TIRE								
32.425	DR30520T 18221189 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-FEB-2019 6584.3 6425		
324404	RIGHT NOSE TIRE								
32.425	DR30520T 18221089 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-FEB-2019 6584.3 6425		
324411	LEFT MAIN LANDING GEAR INBOARD WHEEL								
32.285	AHA2226-2 YV113 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			18-SEP-2013 5781.1 6100		
324412	LEFT MAIN LANDING GEAR OUTBOARD WHEEL								
32.285	AHA2226-2 YB034 REF: See Workcard	MOS HRS/MSC AFL	O/C				07-APR-2017 6338.6 6330		
324413	RIGHT MAIN LANDING GEAR INBOARD WHEEL								
32.290	AHA2226-2 YN184 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-JUN-2017 6370.9 6348		
324414	RIGHT MAIN LANDING GEAR OUTBOARD WHEEL								
32.290	AHA2226-2 YN184 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-DEC-2017 6428.4 6367		
324415	LEFT MAIN LANDING GEAR INBOARD TIRE								
32.430	DR30621T 18169208 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			20-FEB-2019 6584.3 6425		
324416	LEFT MAIN LANDING GEAR OUTBOARD TIRE								
32.430	DR30621T 16200272 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			07-APR-2017 6338.6 6330		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324417	#3 TIRE R/H INBD								
32.435	DR30621T 15304178 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-JUN-2017 6370.9 6348		
324418	RIGHT MAIN LANDING GEAR OUTBOARD TIRE								
32.435	DR30621T 15302244 REF: See Workcard	MOS HRS/MSC AFL	O/C				01-DEC-2017 6428.4 6367		
326001-U1	MLG LEFT BARREL ASSEMBLY LIFE LIMIT (MOD 10)								
	22415-310-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	29900	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		29900
326002	MLG RIGHT BARREL ASSEMBLY LIFE LIMIT (MOD 10)								
	22416-310-00 SN-UNKNOWN REF:	MOS HRS/MSC AFL	29900	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		29900
326021	MLG LEFT BRACE UNIVERSAL LIFE LIMIT (MOD 10)								
	GA66902. OR D66770 SN-UNKNOWN REF:	MOS HRS/MSC AFL	48624	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		48624
326022	MLG RIGHT BRACE UNIVERSAL LIFE LIMIT (MOD 10)								
	GA66902. OR D66770 SN-UNKNOWN REF:	MOS HRS/MSC AFL	48624	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		48624
V32-44-54-00-01	MAIN LANDING GEAR WHEEL ASSEMBLIES - NDT INSPECTION OF MLG WHEEL HALVES (P/N AHA2226)								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	-				20-FEB-2019 6584.3 6425		
V32-44-54-00-02	NOSE LANDING GEAR WHEEL ASSEMBLIES - NDT INSPECTION OF NLG WHEEL HALVES (P/N AHA2225)								
	REF: GENERIC NO REF	MOS HRS/MSC AFL	-				20-FEB-2019 6584.3 6425		

CHAPTER 33 LIGHTS

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
33-00-00-01-01	EMERGENCY POWER SUPPLY 4LK BATTERY PACK								
33.060	3214-31 782459 REF: See Workcard	MOS HRS/MSC AFL	36	TSN:0			07-APR-2017 6338.6 6330	07-APR-2020	
33-00-00-01-02	EMERGENCY POWER SUPPLY 5LK (AT FRAME 19-20) BATTERY PACK								
33.065	3214-31 782460 REF: See Workcard	MOS HRS/MSC AFL	36	TSN:0			07-APR-2017 6338.6 6330	07-APR-2020	
33-00-00-01-03	EMERGENCY POWER SUPPLY 6LK (AT FRAME 27-28) BATTERY PACK								
33.070	3214-31 781082 REF: See Workcard	MOS HRS/MSC AFL	36	TSN:0			07-APR-2017 6338.6 6330	07-APR-2020	
33-00-00-01-04	EMERGENCY POWER SUPPLY 7LK (AT FRAME 30-31) BATTERY PACK								
33.075	3214-31 782461 REF: See Workcard	MOS HRS/MSC AFL	36	TSN:0			07-APR-2017 6338.6 6330	07-APR-2020	
+ 33-42-40-00-01 (s)	DUAL NAVIGATION LIGHTS - PERFORM OPERATIONAL CHECK OF THE LEFT, RIGHT AND TAIL DUAL NAVIGATION LIGHTS						PKG		
33.055	PKG 2 REF: See Workcard	DAYS HRS/MSC AFL	225	+14		-221	20-FEB-2019 6584.3 6425		
33-42-40-00-02 (s)	DUAL NAVIGATION LIGHTS - PERFORM OPERATIONAL CHECK OF THE LEFT, RIGHT AND TAIL DUAL NAVIGATION LIGHTS						PKG		
	PKG 2 REF:	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 33-50-00-02-01 (s)	EMERGENCY LIGHTS - PERFORM OPERATIONAL CHECK OF EMERGENCY LIGHTING SYSTEM WITHOUT ACTIVATION OF AICRAFT OR GROUND POWER						PKG		
33.050	PKG 1 REF: AMM 33-50-00	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
V33-40-00-08-01	DUAL NAVIGATION/STROBE LIGHT-LEFT - REPLACE LEFT WINGTIP FLASHTUBE ASSEMBLY (P/N 03-2114-2000) INSTALLED IN ACL-1000 LIGHT ASSEMBLY	MOS HRS/MSC AFL	2000	TSl:0 TSl:0 TSl:0			27-FEB-2002 0 0		2000
	REF: LUMP APPENDIX 3								
V33-40-00-08-02	DUAL NAVIGATION/STROBE LIGHT-RIGHT - REPLACE RIGHT WINGTIP FLASHTUBE ASSEMBLY (P/N 03-2114-2000) INSTALLED IN ACL-1000 LIGHT ASSEMBLY	MOS HRS/MSC AFL	2000	TSl:0 TSl:0 TSl:0			27-FEB-2002 0 0		2000
	REF: LUMP APPENDIX 3								
CHAPTER 34 NAVIGATION									
+ 34-10-00-01-01 (s)	FLIGHT ENVIRONMENT DATA - PERFORM DETAILED INSPECTION OF PITOT PROBES / STATIC PORTS						PKG		
34.010	PKG 1	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
	REF: AMM 34-10-00								
+ 34-10-00-03-01 (s)	FLIGHT ENVIRONMENT DATA - PERFORM FUNCTIONAL CHECK OF STANDBY ALTIMETER / STANDBY AIRSPEED INDICATOR INCLUDING LEAK CHECK OF PITOT-STATIC SYSTEM / ALTIMETER						PKG		
34.015	PKG 5	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
	REF: AMM 34-10-00								
+ 34-10-00-05-01 (s)	FLIGHT ENVIRONMENT DATA - PERFORM FUNCTIONAL CHECK OF FLIGHT ENVIRONMENT DATA						PKG		
34.180	PKG 3	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430		
	REF: AMM 34-10-00								
+ 34-20-00-01-01 (s)	ATTITUDE AND DIRECTION - DISCARD ATTITUDE HEADING REFERENCE SYSTEM (AHRS) / INERTIAL REFERENCE SYSTEM (IRS) (SYSTEMS 1 AND 2) FAN FILTER						PKG		
34.045	PKG 4	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
	REF: See Workcard								
+ 34-20-00-02-01 (s)	ATTITUDE AND DIRECTION - PERFORM OPERATIONAL CHECK OF ATTITUDE HEADING REFERENCE SYSTEM (AHRS) / INERTIAL REFERENCE SYSTEM (IRS) (SYSTEMS 1 AND 2) FAN						PKG		
34.050	PKG 4	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
	REF: AMM 34-21-14								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-20-00-03-01 (s)	ATTITUDE AND DIRECTION - PERFORM FUNCTIONAL CHECK (CALIBRATION) OF STANDBY COMPASS						PKG		
34.055	PH5 PKG 5 SN-UNKNOWN REF: AMM 34-24-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
34-20-00-03-01-U1	NO.1 COMM UNIT 7510700-766 0708B604 REF:	MOS HRS/MSC AFL	O/C				11-AUG-2016 6269.8 6291		
34-20-00-03-02	NO.2 COMM UNIT 7510700-766 98062986 REF:	MOS HRS/MSC AFL	O/C				18-SEP-2013 5781.1 6100		
34-20-00-03-03	NO.1 DME 7510100-631 97092368 REF:	MOS HRS/MSC AFL	O/C				14-FEB-2012 5538.2 5973		
34-20-00-04	#2 FMS SCREEN 7007549-906 94091626 REF:	MOS HRS/MSC AFL	O/C				19-SEP-2012 5655.6 6021		
+ 34-20-00-04-01	ATTITUDE AND DIRECTION - PERFORM FUNCTIONAL (CAPACITY) CHECK (OFF-AIRCRAFT) OF EMERGENCY POWER SUPPLY (EPS) BATTERIES 2FM (FOR STANDBY INSTRUMENTS)								
34.080	REF: AMM 34-23-00	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	14-JUN-2020
34-20-00-04-01.1	FORWARD EMERGENCY POWER SUPPLY (EPS) BATTERIES 2FM CAPACITY CHECK								
	REF:	MOS HRS/MSC AFL	12	+1m		-111	07-APR-2017 6338.6 6330	17-DEC-2017	17-JAN-2018
34-20-00-04-01.2	AFT EMERGENCY POWER SUPPLY (EPS) BATTERIES 35FM CAPACITY CHECK								
	REF:	MOS HRS/MSC AFL	12	+1m		-111	07-APR-2017 6338.6 6330	17-DEC-2017	17-JAN-2018

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 34-20-00-05-01 (s)	ATTITUDE AND DIRECTION - PERFORM OPERATIONAL CHECK OF EMERGENCY POWER SUPPLY (EPS) BATTERIES (FOR STANDBY INSTRUMENTS)						PKG		
34.085	PKG 1 REF: AMM 24-35-00	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 34-20-00-06-01	ATTITUDE AND DIRECTION - PERFORM FUNCTIONAL (CAPACITY) CHECK (OFF-AIRCRAFT) OF BACK-UP POWER SUPPLY BATTERY PACK (35FM)								
34.090	REF: AMM 24-35-00	MOS HRS/MSC AFL	12	+1m			13-JUN-2019 6590.1 6430	13-JUN-2020	13-JUL-2020
34-50-00-01-02	DEPENDENT POSITION DETERMINING - PERFORM FUNCTIONAL CHECK OF AIR TRAFFIC CONTROL (ATC) SYSTEM 1								
	REF:	MOS HRS/MSC AFL	12				13-JUN-2019 6590.1 6430	13-JUN-2020	
34-50-00-01-04	DEPENDENT POSITION DETERMINING - PERFORM FUNCTIONAL CHECK OF AIR TRAFFIC CONTROL (ATC) SYSTEM 2								
	REF:	MOS HRS/MSC AFL	12				13-JUN-2019 6590.1 6430	13-JUN-2020	
34-60-00-01	TCAS ANTENNA 7514081-910 ANE 26509 REF:	MOS HRS/MSC AFL	O/C				03-MAR-2009 0 0		
34-60-00-02	RIGHT RADIO ALTIMETER ANTENNA 7003586 01014362 REF:	MOS HRS/MSC AFL	O/C				11-NOV-2011 5538.2 5973		
34-60-00-03	LEFT ANGLE OF ATTACK SENSOR 861EF1 0408 REF:	MOS HRS/MSC AFL	O/C				11-MAY-2010 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340020	#1 DATA ACQUISITION UNIT 7012248-936 01044272 REF:	MOS HRS/MSC AFL	O/C				11-NOV-2011 5538.2 5973		
340031	NO. 1 AIR DATA COMPUTER 7014700-924 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0		
340032	NO. 2 AIR DATA COMPUTER 7014700-924 01065122 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-JUL-2013 5737.2 6076		
340040	HF CONTROL HEAD 064-1016-00 11318 REF:	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			11-JUL-2013 5737.2 6076		
341003 34.015	STANDBY ALTIMETER WL101AMS1 AJ559 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			05-FEB-2018 6465.9 6381		
341011 34.160	LEFT PITOT PROBE 0851GW1 277487 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-MAY-2010 0 0		
342005 34.055	STANDBY COMPASS PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
342021 34.070	EMERGENCY (35FR) POWER SUPPLY 501-1228-03 13288 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342031	STANDBY ATTITUDE INDICATOR								
34.075	501-1568-10 2627 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-APR-2017 6338.6 6330		
342041	EMERGENCY (2FM) POWER SUPPLY								
34.095	501-1228-03 8757 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				13-JUN-2019 6590.1 6430		
345021	GPS RECEIVER								
34.130	HG2021GD02 4397 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
345041	ADF ANTENNA								
34.140	7510300-901 1506N798 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSN:0 TSN:0 TSN:0			15-JAN-2016 6139.5 6230		
346001	CONTROL DISPLAY								
34.150	7007549-906 01104882 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSR:0 TSR:0 TSR:0			28-NOV-2018 6558.8 6416		
CHAPTER 35 OXYGEN									
+ 35-10-00-01-01	CREW OXYGEN SYSTEM - PERFORM FUNCTIONAL CHECK (OFF AIRCRAFT) OF OXYGEN CYLINDER REGULATOR ASSEMBLY								
35.010	4441019 00094 REF: See Workcard	MOS HRS/MSC AFL	36	+3m			08-JUN-2018 6504.7 6393	08-JUN-2021	08-SEP-2021
+ 35-10-00-02-02	RESTORATION OXYGEN CYLINDER (HYDROSTATIC TEST AND INSPECTION)								
35.010	176226-77 641329302 REF: See Workcard	MOS HRS/MSC AFL	36	+3m			08-JUN-2018 6504.7 6393	08-JUN-2021	08-SEP-2021
35-10-00-03-01	OXYGEN CYLINDER								
35.010	176226-77 641329302 REF: See Workcard	MOS HRS/MSC AFL	180				08-JUN-2018 6504.7 6393	? ?	
LIFE LIMIT									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-10-00-03-02	DISCARD OF OXYGEN CYLINDER(S)	MOS HRS/MSC AFL	180				21-MAY-2015 5991.4 6177	21-MAY-2030	
	REF: See Workcard								
+ 35-10-00-05-01 (s)	CREW OXYGEN SYSTEM - PERFORM DETAILED INSPECTION OF CREW MASK	MOS HRS/MSC AFL	30	+2m			PKG 01-DEC-2017 6428.4 6367		
35.050	REF: See Workcard								
35-10-00-05-02 (s)	CREW OXYGEN SYSTEM - PERFORM DETAILED INSPECTION OF CREW MASK	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
	REF:								
+ 35-10-00-06-01 (s)	CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF CREW OXYGEN MASKS	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
35.055	REF: See Workcard								
35-10-00-06-02 (s)	CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF CREW OXYGEN MASKS	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
	REF: See Workcard								
35-10-00-06-03 (s)	CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF CREW OXYGEN MASKS	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
	REF:								
+ 35-10-00-07-01 (s)	CREW OXYGEN SYSTEM - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF CREW OXYGEN MASKS	MOS HRS/MSC AFL	60	+4m			PKG 08-JUN-2018 6504.7 6393		
35.060	REF: GENERIC NO REF								
+ 35-10-00-08-01 (s)	CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF CREW OXYGEN MASKS MICROPHONE	MOS HRS/MSC AFL	30	+2m		-10	PKG 01-DEC-2017 6428.4 6367		
35.020	REF: AMM 35-11-12								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-10-00-09-01 (s)	CREW OXYGEN SYSTEM - CHECK OXYGEN QUANTITY ON EICAS						PKG		
35.025	PKG 1 REF: AMM 35-10-00	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 35-10-00-10-01 (s)	CREW OXYGEN SYSTEM - COMPARE PRESSURE READING OF OXYGEN CYLINDER GAUGE WITH EICAS QUANTITY INDICATION						PKG		
35.015	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
35-10-00-10-02 (s)	CREW OXYGEN SYSTEM - COMPARE PRESSURE READING OF OXYGEN CYLINDER GAUGE WITH EICAS QUANTITY INDICATION						PKG		
	PKG 5 REF: AMM 35-41-00	MOS HRS/MSC AFL	60		-61		08-JUN-2018 6504.7 6393		
+ 35-10-00-11-01 (s)	CREW OXYGEN SYSTEM - PERFORM VISUAL CHECK OF SMOKE GOGGLES						PKG		
35.065	PKG 4 REF: AMM 35-11-19	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
35-10-00-11-02 (s)	CREW OXYGEN SYSTEM - PERFORM VISUAL CHECK OF SMOKE GOGGLES						PKG		
	PKG 4 REF: AMM 35-11-19	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 35-10-00-13-01 (s)	PASSENGER / CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF PRESSURE SWITCH 10M0, 11M0						PKG		
35.080	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
35-10-00-13-02 (s)	PASSENGER / CREW OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF PRESSURE SWITCH 10M0, 11M0						PKG		
	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-20-00-01-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF PASSENGER OXYGEN MASKS FOR DEPLOYMENT						PKG		
35.125	PKG 5 REF: AMM 35-20-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 35-20-00-02-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM DETAILED INSPECTION OF PASSENGER OXYGEN MASKS						PKG		
35.130	PKG 5 REF: AMM 35-20-00	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 35-20-00-04-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF FIRST AID OUTLETS						PKG		
35.155	PKG 6 REF: AMM 35-21-05	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 35-20-00-05-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM FUNCTIONAL CHECK OF OXYGEN ALTITUDE COMPENSATOR 1 AND 2 (OFF AIRCRAFT)						PKG		
35.160	PKG 6 REF:	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 35-20-00-06-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM DETAILED INSPECTION OF FIRST AID MASKS						PKG		
35.140	PKG 4 REF: AMM 35-21-06	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 35-20-00-08-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM DOOR OPENING TEST						PKG		
35.185	PKG 4 REF: AMM 35-20-00	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 35-20-00-09-01 (s)	PASSENGER OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK OF PASSENGER OXYGEN SYSTEM SEAL VALVES						PKG		
35.120	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 35-30-00-01-01 (s)	PORTABLE OXYGEN SYSTEM - PERFORM VISUAL CHECK OF PROTECTIVE BREATHING EQUIPMENT (PBE) HOOD FOR CORRECT STOWAGE AND LOSS OF VACUUM, FRAME 11						PKG		
35.170	PKG 2 REF: AMM 35-31-01	DAYS HRS/MSC AFL	225	+14		-221	20-FEB-2019 6584.3 6425		
+ 35-30-00-01-02 (s)	PORTABLE OXYGEN SYSTEM - PERFORM VISUAL CHECK OF PROTECTIVE BREATHING EQUIPMENT (PBE) HOOD FOR CORRECT STOWAGE AND LOSS OF VACUUM, FRAME 11/12/32						PKG		
35.175	PKG 2 REF: AMM 35-31-01	DAYS HRS/MSC AFL	225	+14		-221	20-FEB-2019 6584.3 6425		
35-30-00-02-01	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 11 - DISCARD THE COCKPIT PROTECTIVE BREATHING EQUIPMENT (PBE)								
DISCARD	119003-11 003-51549M REF: GENERIC NO REF	MOS HRS/MSC AFL	120				01-MAY-2010	01-MAY-2020 M	
35-30-00-02-02	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 12 - DISCARD THE FORWARD CABIN PROTECTIVE BREATHING EQUIPMENT (PBE)								
DISCARD	119003-11, OPT 353-001 003-51547M REF: GENERIC NO REF	MOS HRS/MSC AFL	120				01-MAY-2010	01-MAY-2020 M	
35-30-00-02-03	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 32 - DISCARD THE AFT CABIN PROTECTIVE BREATHING EQUIPMENT (PBE)								
DISCARD	119003-11, OPT 353-001 004-79827M REF: GENERIC NO REF	MOS HRS/MSC AFL	120				01-MAR-2014	01-MAR-2024 M	
35-30-01-02-01	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 11								
35.170	119003-11 003-51549M REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-MAY-2010 0 0	01-MAY-2020 M	
35-30-01-02-02	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 12								
35.190	119003-11, OPT 353-001 003-51547M REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-MAY-2010 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-30-01-02-03 35.195	PBE-HOOD WITH INTEGRATED SUPPLY-FRAME 32 119003-11, OPT 353-001 004-79827M REF: GENERIC NO REF	MOS HRS/MSC AFL	H/T				01-MAR-2014 0 0		
35-31-00-02	OXYGEN COMPENSATING REGULATOR BACK 112052-01 00482 REF:	MOS HRS/MSC AFL	O/C				20-APR-2009 0 0		
351002 71.110	OXYGEN CYLINDER REGULATOR ASSEMBLY 4441019 00094 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-JUN-2018 6504.7 6393		
351021 35.040	PILOT/CREW MASK 174660-26 12645 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
351022 35.040	COPILOT/CREW MASK 174660-26 07990 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
351023 35.040	OBSERVER/CREW MASK 174660-26 12647 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			08-JUN-2018 6504.7 6393		
351030 35.070	LEFT PRESSURE SWITCH PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		
351031 35.075	CREW LOW PRESSURE SWITCH PH5 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
352051	LEFT FR23-24 PAX SEAL VALVE									
35.110	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0			
352052	RIGHT FR22-23 PAX SEAL VALVE									
35.110	PH6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C				27-FEB-2002 0 0			
CHAPTER 36 PNEUMATIC										
+ 36-00-00-02-01 (s)	PNEUMATIC - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF LEFT AND RIGHT MAIN DUCT OVER-PRESSURE SWITCH						PKG			
36.070	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873			
+ 36-00-00-03-01 (s)	PNEUMATIC - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF LEFT OVERTEMPERATURE SWITCH						PKG			
36.025	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873			
36-00-00-03-02 (s)	PNEUMATIC - PERFORM FUNCTIONAL CHECK (OFF-AIRCRAFT) OF RIGHT OVERTEMPERATURE SWITCH						PKG			
36.025	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873			
+ 36-00-00-04-01 (s)	PNEUMATIC - PERFORM OPERATIONAL CHECK OF CROSS-BLEED VALVE						PKG			
36.030	PKG 5 REF: AMM 36-11-10	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393			
+ 36-00-00-06-01 (s)	PNEUMATIC - PERFORM OPERATIONAL CHECK OF LEFT AND RIGHT PRESSURE REDUCING AND SHUT OFF VALVE (PRSOV) MAIN DUCT						PKG			
36.050	PKG 5 REF: AMM 36-10-03	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393			

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 36-00-00-07-01 (s)	PNEUMATIC - PERFORM OPERATIONAL CHECK OF BLEED AIR LEAK DETECTION SYSTEM						PKG		
36.035	PKG 4 REF: AMM 36-21-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 36-00-00-09-01 (s)	APU BLEED AIR LEAK DETECTION - PERFORM OPERATIONAL CHECK OF APU BLEED AIR LEAK DETECTION SYSTEM						PKG		
36.135	PKG 4 REF: AMM 36-21-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 36-00-00-11-01 (s)	PNEUMATIC - PERFORM OPERATIONAL CHECK OF APU NON RETURN VALVE						PKG		
36.075	PKG 5 REF: AMM 36-11-11	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
+ 36-00-00-12-01 (s)	PNEUMATIC - PERFORM OPERATIONAL CHECK OF NON RETURN VALVE GROUND SUPPLY						PKG		
36.080	PKG 5 REF: AMM 36-11-23	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
36-10-00-01-01	PNEUMATIC - RESTORATION (CLEANING) OF THERMOSTAT FILTER ELEMENT								
	REF: LUMP SECTION B	MOS HRS/MSC AFL	2000				27-FEB-2002 0 0	2000	
361021	NO. 1 ENGINE OVER PRESSURE SWITCH								
36.140	5682C000 112686-2 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-FEB-2018 6465.9 6381		
361041	NO. 1 ENGINE (82HB) OVER TEMPERATURE SWITCH								
36.090	5891C000-001 0285 REF: See Workcard	MOS HRS/MSC AFL	O/C				27-AUG-2009 0 0		
CHAPTER 38 WATER/WASTE									
+ 38-00-00-02-01 (s)	WATER / WASTE - PERFORM VISUAL CHECK OF WASTE DRAIN FLAPPER VALVE						PKG		
38.015	PKG 5 REF: AMM 38-32-15	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 49	AIRBORNE AUXILIARY POWER								
49-12-00-01-01	APU MOUNTING ELEMENTS INSPECTION	MOS HRS/MSC AFL	60	+4m			08-APR-2013 5700.2 6053	08-APR-2018	08-AUG-2018
	REF:								
49-13-00-01-01 (s)	APU FIRE SEALS & GENERATOR COOLING HOSE / AIR DUCT INSPECTION	MOS HRS/MSC AFL	30	+2m			PKG 21-MAY-2015 5991.4 6177		
	REF:								
49-17-00-01-01	APU DRAINS INSPECTION	MOS HRS/MSC AFL	48	+4m			21-MAY-2015 5991.4 6177	21-MAY-2019	21-SEP-2019
	REF:								
49-90-00-03-01 (s)	APU OIL LEVEL CHECK	DAYS HRS/MSC AFL	15	+2			PKG 13-JUN-2019 6590.1 6430		
	REF:								
49APU1	APU	MOS HRS/MSC AFL					09-OCT-2010 5253.1 5865		
49.APU1	3800498-3 P-293 REF: GENERIC NO REF	E/C			TSO:5649 TSO:0				
APU Model : GTCP 36-150DD Serial # P-293 Part # 3800498-3									
49-20-00-03-01	APU - COMPRESSOR ROTOR	MOS HRS/MSC APUS					27-FEB-2002 0 0	100000	
49.015	PN SN-UNKNOWN REF: See Workcard		100000		TSN:0 TSN:0 TSN:0				
	LIFE LIMIT								
+ 49-20-00-05-01	APU - APU ENGINE - PERFORM DETAILED INSPECTION OF APU LABYRINTH SEAL	MOS HRS/MSC APUS					27-FEB-2002 0 0		
49.040	REF: See Workcard	A/R							

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 49-20-00-06-01	APU - APU ENGINE - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF APU COMBUSTION CHAMBER								
49.020	REF: See Workcard	MOS HRS/MSC APUS	5000				08-APR-2013 5497 0	10497	
49-20-00-07-01	APU - TURBINE ROTOR								
49.010	REF: See Workcard	MOS HRS/MSC APUS	10000	TSN:0 TSN:0 TSN:0			27-FEB-2002 0 0	10000	
LIFE LIMIT									
+ 49-24-00-01-01	APU - APU MAGNETIC DRAIN PLUG - PERFORM DETAILED INSPECTION OF APU MAGNETIC DRAIN PLUG								
49.075	REF: See Workcard	MOS HRS/MSC APUS	500				18-SEP-2013 5649 0	6149	
49-30-00-01-01	APU - APU FUEL NOZZLES - RESTORATION (CLEANING AND INSPECTION) OF APU FUEL NOZZLE ASSEMBLIES (OFF-AIRCRAFT)								
49.055	REF: See Workcard	MOS HRS/MSC APUS	5000				08-APR-2013 5497 0	10497	
49-30-00-03-01	APU - APU FUEL FILTER - DISCARD APU FUEL FILTER ELEMENT								
49.045	REF: See Workcard	MOS HRS/MSC APUS	1000				18-SEP-2013 5649 0	6649	
+ 49-40-00-01-01	APU - APU IGNITER PLUG - PERFORM DETAILED INSPECTION OF APU IGNITER PLUG								
49.060	REF: See Workcard	MOS HRS/MSC APUS	1000				18-SEP-2013 5649 0	6649	
+ 49-40-00-02-01	APU - APU IGNITION LEAD - PERFORM DETAILED INSPECTION OF APU IGNITER PLUG LEAD FOR SECURITY AND EVIDENCE OF ARCING OR CARBONIZATION								
49.070	REF: See Workcard	MOS HRS/MSC APUS	1000				18-SEP-2013 5649 0	6649	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 49-60-00-01-01	APU - APU WIRING HARNESS - PERFORM DETAILED INSPECTION OF APU WIRING HARNESS AND CONNECTORS FOR DAMAGE, SECURITY OF INSTALLATION AND CHAFING								
49.065	REF: See Workcard	MOS HRS/MSC APUS	5000				08-APR-2013 5497 0	10497	
49-90-00-01-01 (s)	APU - APU OIL FILTER - DISCARD APU OIL FILTER ELEMENT						PKG		
49.080	PKG 3 REF: See Workcard	MOS HRS/MSC APUS	800				05-FEB-2018 6157		
+ 49-90-00-03-01 (s)	APU - APU OIL - CHECK APU OIL LEVEL						PKG		
49.085	PKG 1 REF: See Workcard	DAYS HRS/MSC APUS	15				13-JUN-2019		
493010	APU - FUEL CONTROL UNIT								
	PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C			TSN:0 TSN:0 TSN:0	27-FEB-2002 0 0		
493070	APU - LOAD CONTROL VALVE								
49.050	PN SN-UNKNOWN REF: MM 49-51-01	MOS HRS/MSC APUS	O/C			TSN:0 TSN:0 TSN:0	27-FEB-2002 0 0		
494010	APU - IGNITION EXCITER								
	PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C			TSN:0 TSN:0 TSN:0	27-FEB-2002 0 0		
497010	APU - OIL TEMP SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C			TSN:0 TSN:0 TSN:0	27-FEB-2002 0 0		
497020	APU - OIL PRESSURE SWITCH								
	PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C			TSN:0 TSN:0 TSN:0	27-FEB-2002 0 0		

CHAPTER 50 CARGO COMPARTMENTS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B									
+ 050010	NO. 1 ENGINE - FADEC MINOR FAULTS								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050015	NO. 1 ENGINE - FOREIGN OBJECT DAMAGE (FOD)								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050020	NO. 1 ENGINE - ENGINE WINDMILLING IN FLIGHT								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050025	NO. 1 ENGINE - LOW AND/OR FLUCTUATING OIL PRESSURE								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050030	NO. 1 ENGINE - LIGHTNING STRIKE								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050035	NO. 1 ENGINE - ENGINE IMMERSION IN WATER								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050040	NO. 1 ENGINE - DROPPED ENGINE								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050045	NO. 1 ENGINE - ENGINE OPERATION IN VISIBLE VOLCANIC ASH								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050050	NO. 1 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050055	NO. 1 ENGINE - HEAVY LANDING								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050060	NO. 1 ENGINE - SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE LIMITS								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050065	NO. 1 ENGINE - PERFORMANCE DETERIORATION								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050070	NO. 1 ENGINE - OVERSPEED IN EXCESS OF TRANSIENT								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050075	NO. 1 ENGINE - OVERTEMPERATURE								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050080	NO. 1 ENGINE - CHIP DETECTOR CIRCUIT COMPLETED								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050085	NO. 1 ENGINE - MAIN OIL FILTER BYPASS INDICATOR ACTIVATED								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050090	NO. 1 ENGINE - HIGH PRESSURE (HP) FUEL FILTER IMPENDING BYPASS INDICATOR ACTIVATED	MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050095	NO. 1 ENGINE - FUEL IN THE OIL SYSTEM	MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050100	NO. 1 ENGINE - OIL FIRE IN EXHAUST DUCT	MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050105	NO. 1 ENGINE - DC GENERATOR FAIL INDICATION	MOS		TSI:0			04-FEB-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
+ 050010	NO. 2 ENGINE - FADEC MINOR FAULTS	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050015	NO. 2 ENGINE - FOREIGN OBJECT DAMAGE (FOD)	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050020	NO. 2 ENGINE - ENGINE WINDMILLING IN FLIGHT	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050025	NO. 2 ENGINE - LOW AND/OR FLUCTUATING OIL PRESSURE	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050030	NO. 2 ENGINE - LIGHTNING STRIKE	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050035	NO. 2 ENGINE - ENGINE IMMERSION IN WATER	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050040	NO. 2 ENGINE - DROPPED ENGINE	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050045	NO. 2 ENGINE - ENGINE OPERATION IN VISIBLE VOLCANIC ASH	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050050	NO. 2 ENGINE - ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050055	NO. 2 ENGINE - HEAVY LANDING	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050060	NO. 2 ENGINE - SUSTAINED RUNNING AT AN OIL TEMPERATURE OUTSIDE LIMITS	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050065	NO. 2 ENGINE - PERFORMANCE DETERIORATION	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 050070	NO. 2 ENGINE - OVERSPEED IN EXCESS OF TRANSIENT								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050075	NO. 2 ENGINE - OVERTEMPERATURE								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050080	NO. 2 ENGINE - CHIP DETECTOR CIRCUIT COMPLETED								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050085	NO. 2 ENGINE - MAIN OIL FILTER BYPASS INDICATOR ACTIVATED								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050090	NO. 2 ENGINE - HIGH PRESSURE (HP) FUEL FILTER IMPENDING BYPASS INDICATOR ACTIVATED								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050095	NO. 2 ENGINE - FUEL IN THE OIL SYSTEM								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050100	NO. 2 ENGINE - OIL FIRE IN EXHAUST DUCT								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		
+ 050105	NO. 2 ENGINE - DC GENERATOR FAIL INDICATION								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	A/R	TSI:0			0		
	REF: EMM 05-50-00	ENC		TSI:0			0		

CHAPTER 52 DOORS

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-10-00-01-01 (s)	PASSENGER / CREW DOOR - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR OPERATING MECHANISM						PKG		
52.020	PKG 4 REF: AMM 52-10-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-10-00-03-01 (s)	PASSENGER / CREW DOOR - PERFORM GENERAL VISUAL INSPECTION OF PASSENGER / CREW DOOR SEAL						PKG		
52.025	PKG 4 REF: AMM 52-10-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-10-00-04-01 (s)	PASSENGER / CREW DOOR - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR MAIN HINGE / SUPPORT HINGE, STABILIZER, ROLLER / CAM, SUPPORT STRUTS / PIVOT SHAFT, FITTINGS / ROLLER FITTINGS						PKG		
52.035	PKG 4 REF: AMM 52-10-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-10-03-01-01 (s)	PASSENGER / CREW DOOR - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR, INTERNAL						PKG		
52.015	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+6m	-141		08-JUN-2018 6504.7 6393		
+ 52-11-01-02-01	PASSENGER / CREW DOOR - PERFORM GENERAL VISUAL INSPECTION OF PASSENGER / CREW DOOR, SKIN, EXTERNAL								
52.180	REF: AMM 52-11-10	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0	8000	
+ 52-11-03-02-01	PASSENGER / CREW DOOR - SKIN, FRAME, INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE PASSENGER / CREW DOOR SKIN, FRAME AND FITTINGS, INTERNAL								
52.185	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-11-03-03-01	PASSENGER / CREW DOOR - SKIN, FRAME, INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE PASSENGER / CREW DOOR SKIN, FRAME AND FITTINGS, INTERNAL								
	REF: NTM 52-11-03	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-11-05-01-01 (s)	PASSENGER / CREW DOOR - BONDING PARTS - EXTERNAL AND INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF PASSENGER / CREW DOOR, BONDING PART, EXTERNAL AND INTERNAL						PKG		
52.040	PKG 5 REF: NTM 52-11-05	MOS HRS/MSC AFL	60 8000	+4m			08-JUN-2018 6504.7 6393		
+ 52-11-07-02-01	PASSENGER / CREW DOOR, FITTINGS, INTERNAL - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR, FITTINGS, INTERNAL								
52.190	REF: AMM 52-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-11-07-03-01	PASSENGER / CREW DOOR, FITTINGS, INTERNAL - PERFORMED DETAILED INSPECTION OF PASSENGER / CREW DOOR, FITTINGS, INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-20-03-02-01 (s)	EMERGENCY EXITS - APPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) EMERGENCY EXITS, LEFT, INTERNAL						PKG		
52.010	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m	TSl:0 TSl:0 TSl:0		11-FEB-2011 5276.6 5873		
52-20-03-02-01 (s)	EMERGENCY EXITS - APPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) EMERGENCY EXITS, RIGHT, INTERNAL						PKG		
52.030	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m	TSl:0 TSl:0 TSl:0		11-FEB-2011 5276.6 5873		
+ 52-20-07-01-01 (s)	CREW HATCH - PERFORM DETAILED INSPECTION OF CREW HATCH, INTERNAL AND EXTERNAL						PKG		
52.055	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 52-22-00-01-01 (s)	EMERGENCY EXIT TYPE III - PERFORM OPERATIONAL CHECK OF LEFT EMERGENCY EXIT OPENING MECHANISM						PKG		
52.060	PKG 4 REF: AMM 52-22-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-22-00-01-01 (s)	EMERGENCY EXIT TYPE III - PERFORM OPERATIONAL CHECK OF RIGHT EMERGENCY EXIT OPENING MECHANISM						PKG		
52.060	PKG 4 REF: AMM 52-22-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-22-00-02-01 (s)	EMERGENCY EXIT TYPE III - PERFORM GENERAL VISUAL INSPECTION OF LEFT EMERGENCY EXIT SEAL						PKG		
52.065	PKG 4 REF: AMM 52-22-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-22-00-02-01 (s)	EMERGENCY EXIT TYPE III - PERFORM GENERAL VISUAL INSPECTION OF RIGHT EMERGENCY EXIT SEAL						PKG		
52.065	PKG 4 REF: AMM 52-22-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-22-01-02-01	EMERGENCY EXIT - EXTERNAL - PERFORM GENERAL VISUAL INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, SKIN, EXTERNAL								
52.195	REF: AMM 52-22-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-22-01-03-01	EMERGENCY EXIT - EXTERNAL - PERFORM GENERAL VISUAL INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, SKIN, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 52-22-03-02-01	EMERGENCY EXIT - INTERNAL - PERFORM GENERAL VISUAL INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, SKIN AND FRAME, INTERNAL								
52.200	REF: AMM 52-22-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-22-03-03-01	EMERGENCY EXIT - INTERNAL - PERFORM GENERAL VISUAL INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, SKIN AND FRAME, INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	



Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-22-05-02-01 (s)	SPECIAL DETAILED INSPECTION EMERGENCY EXIT - EXTERNAL AND INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, BONDING PART, EXTERNAL AND INTERNAL						PKG		
	PKG 6	MOS	120				11-FEB-2011		
	REF:	HRS/MSC					5276.6		
		AFL	8000				5873		
+ 52-22-07-01-01 (s)	EMERGENCY EXIT - INTERNAL - PERFORM DETAILED INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, FITTINGS, INTERNAL						PKG		
52.075	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-52	HRS/MSC					5276.6		
		AFL					5873		
52-22-07-02-01	EMERGENCY EXIT - INTERNAL - PERFORM DETAILED INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, FITTINGS, INTERNAL								
52.045		MOS					27-FEB-2002		
	REF: AMM 52-22-70	HRS/MSC					0		
		AFL	20000				0		20000
52-22-07-03-01	EMERGENCY EXIT - INTERNAL - PERFORM DETAILED INSPECTION OF RIGHT EMERGENCY EXIT BETWEEN FRAME 12-14, FITTINGS, INTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 52-22-09-02-01	EMERGENCY EXIT - EXTERNAL - PERFORM GENERAL VISUAL INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, SKIN, EXTERNAL								
52.205		MOS					27-FEB-2002		
	REF: AMM 52-22-10	HRS/MSC					0		
		AFL	20000				0		20000
52-22-09-03-01	EMERGENCY EXIT - EXTERNAL - PERFORM GENERAL VISUAL INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, SKIN, EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 52-22-11-02-01	EMERGENCY EXIT - INTERNAL - PERFORM GENERAL VISUAL INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, SKIN AND FRAME, INTERNAL								
52.210		MOS					27-FEB-2002		
	REF: AMM 52-22-20	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-22-11-03-01	EMERGENCY EXIT - INTERNAL - PERFORM GENERAL VISUAL INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, SKIN AND FRAME, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
52-22-13-02-01 (s)	EMERGENCY EXIT - EXTERNAL AND INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, BONDING PART, EXTERNAL AND INTERNAL	MOS HRS/MSC AFL	120 8000				11-FEB-2011 5276.6 5873	PKG	
+ 52-22-15-01-01 (s)	EMERGENCY EXIT - INSIDE - PERFORM DETAILED INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, FITTINGS, INTERNAL	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
52.075	REF: AMM 05-25-52								
+ 52-22-15-02-01	EMERGENCY EXIT - INTERNAL - PERFORM DETAILED INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, FITTINGS, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
52.215	REF: AMM 52-22-70								
52-22-15-03-01	EMERGENCY EXIT - INTERNAL - PERFORM DETAILED INSPECTION OF LEFT EMERGENCY EXIT BETWEEN FRAME 27-29, FITTINGS, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
52-22-15-03-01	REF: AMM 52-22-70								
+ 52-23-00-01-01 (s)	CREW EMERGENCY HATCH - PERFORM OPERATIONAL CHECK OF CREW EMERGENCY HATCH OPENING MECHANISM	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367	PKG	
52.080	REF: AMM 52-23-00								
+ 52-23-00-02-01 (s)	CREW EMERGENCY HATCH - PERFORM GENERAL VISUAL INSPECTION OF CREW EMERGENCY HATCH SEAL	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367	PKG	
52.085	REF: AMM 52-23-00								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-23-05-02-01	CREW HATCH - INTERNAL AND EXTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAB TEST) OF CREW HATCH SANDWICH PART, EXTERNAL AND INTERNAL								
52.220	REF: NTM 52-23-05	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 52-30-00-01-01 (s)	CARGO DOOR - PERFORM DETAILED INSPECTION OF CARGO DOOR LOCKING / LIFTING MECHANISM						PKG		
52.110	REF: AMM 52-30-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-30-00-03-01 (s)	CARGO DOOR - PERFORM GENERAL VISUAL INSPECTION OF CARGO DOOR SEAL						PKG		
52.105	REF: See Workcard	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-30-00-04-01 (s)	CARGO DOOR - PERFORM DETAILED INSPECTION OF CARGO DOOR MAIN / SECONDARY HINGE						PKG		
52.115	REF: AMM 52-30-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-30-03-01-01 (s)	CARGO DOOR - PERFORM DETAILED INSPECTION OF CARGO DOOR, INTERNAL						PKG		
52.100	REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 52-31-01-02-01	CARGO DOOR - PERFORM GENERAL VISUAL INSPECTION OF CARGO DOOR, SKIN, EXTERNAL								
52.225	REF: AMM 52-31-10	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
+ 52-31-03-02-01	CARGO DOOR - SKIN AND FRAME, INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE CARGO DOOR SKIN AND FRAME , INTERNAL								
52.230	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-31-03-03-01	CARGO DOOR - SKIN AND FRAME, INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE CARGO DOOR SKIN AND FRAME , INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
REF: NTM 52-31-03									
+ 52-31-05-01-01 (s)	CARGO DOOR - BONDING PARTS - EXTERNAL AND INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF CARGO DOOR, BONDING PART, EXTERNAL AND INTERNAL	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		
52.120	PKG 5		8000						
REF: NTM 52-31-05									
+ 52-31-07-02-01	CARGO DOOR, FITTINGS, INTERNAL - PERFORM DETAILED INSPECTION OF CARGO DOOR, FITTINGS, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
52.235	REF: AMM 52-31-70								
52-31-07-03-01	CARGO DOOR, FITTINGS, INTERNAL - PERFORM DETAILED INSPECTION OF CARGO DOOR, FITTINGS, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
REF:									
+ 52-40-00-01-01 (s)	SERVICE DOOR - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR LOCKING / LIFTING MECHANISM	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
52.140	PKG 4								
REF: AMM 52-41-00									
+ 52-40-00-03-01 (s)	SERVICE DOOR - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR SEAL	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
52.145	PKG 4								
REF: AMM 52-41-00									
+ 52-40-00-04-01 (s)	SERVICE DOOR - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR HINGES AND STABILIZER ROD	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
52.155	PKG 4								
REF: AMM 52-41-00									
+ 52-40-03-01-01 (s)	SERVICE DOOR - PERFORM DETAILED INSPECTION OF SERVICE DOOR, INTERNAL	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
52.135	PKG 6								
REF: GENERIC NO REF									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 52-41-01-02-01	SERVICE DOOR - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR, SKIN, EXTERNAL								
52.240	REF: AMM 52-41-10	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0	8000	
+ 52-41-03-02-01	SERVICE DOOR - SKIN AND FRAME , INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE SERVICE DOOR SKIN AND FRAME , INTERNAL								
52.245	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-41-03-03-01	SERVICE DOOR - SKIN AND FRAME , INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC AND RESONANCE FREQUENCY) OF THE SERVICE DOOR SKIN AND FRAME , INTERNAL								
	REF: NTM 52-41-03	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 52-41-05-01-01 (s)	SERVICE DOOR - BONDING PARTS - EXTERNAL AND INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF SERVICE DOOR, BONDING PART, EXTERNAL AND INTERNAL						PKG		
52.160	PKG 5 REF: NTM 52-41-05	MOS HRS/MSC AFL	60 8000	+4m			08-JUN-2018 6504.7 6393		
+ 52-41-07-02-01	CARGO DOOR, FITTINGS, INTERNAL - PERFORM DETAILED INSPECTION OF SERVICE DOOR, FITTINGS, INTERNAL								
52.250	REF: AMM 52-41-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
52-41-07-03-01	CARGO DOOR, FITTINGS, INTERNAL - PERFORM DETAILED INSPECTION OF SERVICE DOOR, FITTINGS, INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 52-42-01-02-01 (s)	MAINTENANCE ACCESS PANEL - REAPPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) AT MAINTENANCE ACCESS PANEL AT FRAME 46 AND SURROUNDING AREA						PKG		
52.255	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-51-10-01-01 (s)	FLIGHT COMPARTMENT DOOR - PERFORM DETAILED INSPECTION OF FLIGHT COMPARTMENT DOOR FOR CONDITION AN SECURITY INCLUSIVE OPERATIONAL TEST OF EGRESS PANEL						PKG		
52.260	PKG 4 REF: AMM 52-55-00	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 52-52-00-01-01 (s)	INTERIOR BAGGAGE COMPARTMENT DOOR - PERFORM DETAILED INSPECTION OF CABIN ACCESSIBLE CARGO COMPARTMENT DOOR SEAL FOR CONDITION AND PROPER INSTALLATION						PKG		
52.175	PKG 2 REF: AMM 52-52-00	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
CHAPTER 53 FUSELAGE									
+ 53-00-01-02-01	FUSELAGE STRUCTURE LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF PASSENGER WINDOW FRAMES, FRAMES 15-36 LEFT AND FRAMES 12-31 RIGHT, EXTERNAL								
53.595	REF: AMM 53-30-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-00-01-03-01	FUSELAGE STRUCTURE LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF PASSENGER WINDOW FRAMES, FRAMES 15-36 LEFT AND FRAMES 12-31 RIGHT, EXTERNAL								
	REF:	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0		16000
+ 53-00-05-02-01	FUSELAGE STRUCTURE- LONGITUDINAL JOINT STRAPS - PERFORM GENERAL VISUAL INSPECTION OF LONGITUDINAL JOINT STRAPS AT STRINGER 0 BETWEEN FRAMES 10-44 (CENTERLINE TOP), EXTERNAL								
53.600	REF: AMM 53-30-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-00-05-03-01	FUSELAGE STRUCTURE- LONGITUDINAL JOINT STRAPS - PERFORM GENERAL VISUAL INSPECTION OF LONGITUDINAL JOINT STRAPS AT STRINGER 0 BETWEEN FRAMES 10-44 (CENTERLINE TOP), EXTERNAL								
	REF:	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0		16000
53-00-05-03-02	FUSELAGE STRUCTURE- LONGITUDINAL JOINT STRAPS - PERFORM GENERAL VISUAL INSPECTION OF LONGITUDINAL JOINT STRAPS AT STRINGER 0 BETWEEN FRAMES 10-44 (CENTERLINE TOP), EXTERNAL								
	REF: AMM 53-30-00	MOS HRS/MSC AFL	16000		TSI:0 TSI:0 TSI:0		27-FEB-2002 0 0		16000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-07-01-01 (s)	FUSELAGE - LONGITUDINAL JOINT STRAPS - PERFORM DETAILED INSPECTION OF LONGITUDINAL JOINT STRAPS AT STRINGER 28 BETWEEN FRAME 15-22 AND FRAME 28-44, (CENTERLINE BOTTOM, EXTERNAL)						PKG		
53.010	PKG 5 REF: AMM 05-25-53	MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
53-00-07-02-01	FUSELAGE STRUCTURE- LONGITUDINAL JOINT STRAPS - PERFORM DETAILED INSPECTION OF LONGITUDINAL JOINT STRAPS AT STRINGER 28 BETWEEN FRAME 15-22 AND FRAME 28-44, (CENTERLINE BOTTOM), EXTERNAL								
53.035	REF: AMM 53-30-00	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
+ 53-00-09-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8-0-8', UPPER PART, EXTERNAL								
53.605	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-00-09-03-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8-0-8', UPPER PART, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-00-11-02-01	FUSELAGE STRUCTURE LEFT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8-23, EXTERNAL								
53.610	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-00-11-03-01	FUSELAGE STRUCTURE LEFT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8-23, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-00-13-02-01	FUSELAGE STRUCTURE, RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8'-16', EXTERNAL								
53.615	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-00-13-03-01	FUSELAGE STRUCTURE, RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 10 BETWEEN STRINGERS 8'-16', EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
REF:									
+ 53-00-15-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 15 BETWEEN STRINGERS 8-0-8', EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.620									
REF:	See Workcard								
53-00-15-03-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 15 BETWEEN STRINGERS 8-0-8', EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
REF:									
+ 53-00-17-01-01 (s)	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM DETAILED INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-0-8', UPPER PART, EXTERNAL	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		20000
53.015									
REF:	AMM 05-25-53								
+ 53-00-17-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-0-8', UPPER PART, EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.625									
REF:	See Workcard								
53-00-17-03-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-0-8', UPPER PART, EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
REF:									
+ 53-00-19-01-01 (s)	FUSELAGE STRUCTURE RIGHT - TRANSVERSAL SKIN JOINT - PERFORM DETAILED INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 32 BETWEEN STRINGER 0-28', RIGHT, EXTERNAL	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		20000
53.020									
REF:	AMM 05-25-53								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-19-02-01	FUSELAGE STRUCTURE RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 32 BETWEEN STRINGER 0-28', RIGHT, EXTERNAL								
53.625		MOS					27-FEB-2002		
	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-00-19-03-01	FUSELAGE STRUCTURE RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 32 BETWEEN STRINGER 0-28', RIGHT, EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-00-21-02-01	FUSELAGE STRUCTURE LEFT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 35 BETWEEN STRINGER 0-28, LEFT, EXTERNAL								
53.987		MOS					27-FEB-2002		
	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-00-21-03-01	FUSELAGE STRUCTURE LEFT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 35 BETWEEN STRINGER 0-28, LEFT, EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-00-23-02-01	FUSELAGE STRUCTURE RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 36 BETWEEN STRINGER 0-28', RIGHT, EXTERNAL								
53.630		MOS					27-FEB-2002		
	REF: See Workcard	HRS/MSC					0		
		AFL	20000				0		20000
53-00-23-03-01	FUSELAGE STRUCTURE RIGHT - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 36 BETWEEN STRINGER 0-28', RIGHT, EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-00-25-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM GENERAL VISUAL INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 44 BETWEEN STRINGER 8-0-8',UPPER PART, EXTERNAL								
53.635		MOS					27-FEB-2002		
	REF: AMM 53-51-20	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-00-27-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM GENERAL VISUAL INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 44 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL								
53.640	REF: AMM 53-51-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-00-29-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 15 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL								
53.645	REF: See Workcard	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
53-00-29-03-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 15 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL								
	REF:	MOS HRS/MSC AFL	12000				27-FEB-2002 0 0	12000	
+ 53-00-31-01-01 (s)	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM DETAILED INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL						PKG		
53.025	REF: AMM 05-25-53	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-00-31-02-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL								
53.650	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-00-31-03-01	FUSELAGE STRUCTURE - TRANSVERSAL SKIN JOINT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF TRANSVERSAL SKIN JOINT AT FRAME 22 BETWEEN STRINGER 8-28-8', LOWER PART, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-20-00-01-01	FRONT FUSELAGE - PERFORM DETAILED INSPECTION OF FUSELAGE SKIN FOR WAVINESS								
53.545	REF: AMM 51-10-21	MOS HRS/MSC AFL	12	+1m	-317		03-APR-2017 6338.6 6360	03-APR-2018 M 03-MAY-2018	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-00-02-01 (s)	FRONT FUSELAGE - PERFORM DETAILED INSPECTION OF AREA AROUND STATIC PRESSURE PORT HOLES LEFT/RIGHT						PKG		
53.550	PKG 1 REF: AMM 34-11-07	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 53-20-01-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 1 TO FRAME 3 FRONT SIDE, INTERNAL						PKG		
53.030	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-20-05-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 1 TO FRAME 8, NLG BAY						PKG		
53.040	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 53-20-07-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 3 REAR SIDE TO FRAME 10 FRONT SIDE, INTERNAL, ABOVE COCKPIT FLOOR, EXCEPT SURROUNDING AREA OF CREW HATCH						PKG		
53.045	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-20-09-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 3 REAR SIDE TO FRAME 10 FRONT SIDE, INTERNAL, UNDER COCKPIT FLOOR INCLUDING SEAT RAILS						PKG		
53.050	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-20-15-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORMED DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, UP TO FRAME 22, EXTERNAL, AREA UNDER TOP FAIRING						PKG		
53.065	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-20-15-01-02 (s)	FRONT FUSELAGE STRUCTURE - PERFORMED DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, UP TO FRAME 22, EXTERNAL, AREA UNDER TOP FAIRING AND AUXILIARY TANKS						PKG		
	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120				11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-15-03-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE ATTACHEMENT POINTS OF FAIRING ASSY 1 TOP (FRONT)						PKG		
	PKG 4	MOS	30	+4m			01-DEC-2017		
	REF: GENERIC NO REF	HRS/MSC					6428.4		
		AFL					6367		
53-20-15-05-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, ATTACHEMENT POINTS OF FRONT TOP FAIRING NO. 1 (241-DT)						PKG		
	PKG 4	MOS	30				01-DEC-2017		
	REF: GENERIC NO REF	HRS/MSC					6428.4		
		AFL					6367		
+ 53-20-19-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 10 REAR SIDE TO FRAME 22 FRONT SIDE, STRINGER 16-0-16' , INTERNAL, ABOVE CABIN FLOOR, EXCEPT SURROUNDING AREA OF PASSENGER / CREW DOOR AND EMERGENCY EXIT						PKG		
	PKG 6	MOS	120	+6m			11-FEB-2011		
53.075	REF: GENERIC NO REF	HRS/MSC					5276.6		
		AFL					5873		
+ 53-20-21-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 14A REAR SIDE TO FRAME 22 FRONT SIDE, INTERNAL, UNDER CABIN FLOOR INCLUDING SEAT RAILS						PKG		
	PKG 5	MOS	60	+4m		-61	08-JUN-2018		
53.080	REF: GENERIC NO REF	HRS/MSC					6504.7		
		AFL					6393		
+ 53-20-23-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 10 REAR SIDE TO FRAME 14A FRONT SIDE, INTERNAL, UNDER CABIN FLOOR INCLUDING SEAT RAILS						PKG		
	PKG 5	MOS	60	+4m		-61	08-JUN-2018		
53.085	REF: GENERIC NO REF	HRS/MSC					6504.7		
		AFL					6393		
53-20-23-02-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF FRONT FUSELAGE STRUCTURE, FRAME 10 REAR SIDE TO FRAME 14A FRONT SIDE, INTERNAL, UNDER FORWARD GALLEY						PKG		
	PKG 4	MOS	30	+2m			01-DEC-2017		
53.261	REF: GENERIC NO REF	HRS/MSC					6428.4		
		AFL					6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-20-25-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT / CENTER FUSELAGE STRUCTURE, SURROUNDING AREA OF PASSENGER / CREW DOOR, INTERNAL, INCLUDING AREA UNDER SCUFF PLATE						PKG		
53.090	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 53-20-27-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, SURROUNDING AREA OF EMERGENCY EXIT, RIGHT, INTERNAL						PKG		
53.095	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-20-29-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, SURROUNDING AREA OF CREW HATCH, INTERNAL						PKG		
53.100	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-21-01-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER FRAME 10 AND JOINTS WITH UPPER AND LOWER CHANNELS								
53.105	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-01-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER FRAME 10 AND JOINTS WITH UPPER AND LOWER CHANNELS								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-01-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER FRAME 10 AND JOINTS WITH UPPER AND LOWER CHANNELS								
	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000		TSl:0 TSl:0 TSl:0		27-FEB-2002 0 0		20000
+ 53-21-03-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAME 10 ASSEMBLY								
53.110	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-03-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAME 10 ASSEMBLY	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
53-21-03-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAME 10 ASSEMBLY	MOS		TSI:0			27-FEB-2002		
	REF: AMM 53-21-20	HRS/MSC		TSI:0			0		
		AFL	20000	TSI:0			0		20000
+ 53-21-05-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER POST AND JOINTS WITH FRAME 3, FRAME 4, UPPER AND LOWER CHANNELS AND FLIGHT COMPARTMENT LONGERONS	MOS					27-FEB-2002		
57.430	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-05-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER POST AND JOINTS WITH FRAME 3, FRAME 4, UPPER AND LOWER CHANNELS AND FLIGHT COMPARTMENT LONGERONS	MOS					27-FEB-2002		
53.988	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-07-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE POST, LEFT AND RIGHT, AND JOINTS WITH LOWER AND UPPER CHANNELS, FRAME 6 AND MAIN	MOS					27-FEB-2002		
53.655	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
53-21-07-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE POST, LEFT AND RIGHT, AND JOINTS WITH LOWER AND UPPER CHANNELS, FRAME 6 AND MAIN	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	13000				0		13000
53-21-07-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE POST, LEFT AND RIGHT, AND JOINTS WITH LOWER AND UPPER CHANNELS, FRAME 6 AND MAIN LONGERONS	MOS		TSI:0			27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC		TSI:0			0		
		AFL	-	TSI:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-09-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 3, REAR SIDE						PKG		
53.125	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			18-JAN-2010 5247 5862		
+ 53-21-09-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 3, REAR SIDE								
53.989	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-21-11-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 3, FRONT SIDE								
53.989	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-21-13-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER CHANNELS, LEFT AND RIGHT								
53.971	REF: AMM 53-21-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-13-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER CHANNELS, LEFT AND RIGHT								
	REF:	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0		16000
53-21-13-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER CHANNELS, LEFT AND RIGHT								
	REF: AMM 53-21-60	MOS HRS/MSC AFL	-				27-FEB-2002 0 0		
+ 53-21-15-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER CHANNELS, LEFT AND RIGHT								
53.972	REF: AMM 53-21-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-15-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER CHANNELS, LEFT AND RIGHT								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-15-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER CHANNELS, LEFT AND RIGHT	MOS		TSl:0			27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC		TSl:0			0		
		AFL	20000	TSl:0			0		20000
+ 53-21-17-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAME 10	MOS					27-FEB-2002		
53.660	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
53-21-17-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAME 10	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
53-21-17-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAME 10	MOS		TSl:0			27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC		TSl:0			0		
		AFL	20000	TSl:0			0		20000
+ 53-21-19-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER FRAMES FROM 4 TO 9 AND JOINTS BETWEEN FRAMES AND LOWER CHANNELS	MOS					27-FEB-2002		
53.665	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
53-21-19-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UPPER FRAMES FROM 4 TO 9 AND JOINTS BETWEEN FRAMES AND LOWER CHANNELS	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-21-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAMES FROM 4 TO 9	MOS					27-FEB-2002		
53.670	REF: AMM 53-21-20	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-21-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAMES FROM 4 TO 9	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
53-21-21-03-02 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER FRAMES FROM 4 TO 9	MOS					09-SEP-2010		
	REF: AMM 53-21-20	HRS/MSC					5247		
		AFL	20000				5862		
+ 53-21-23-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF RETAINER STRAPS, AT COCKPIT WINDOWS						PKG		
	PKG 6	MOS	120	+6m			11-FEB-2011		
53.160	REF: AMM 05-25-53	HRS/MSC					5276.6		
		AFL					5873		
53-21-23-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF RETAINER STRAPS, AT COCKPIT WINDOWS	MOS					27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC					0		
53.055		AFL	20000				0		20000
+ 53-21-25-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAMES 4 TO 9	MOS					27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC					0		
53.675		AFL	20000				0		20000
53-21-25-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAMES 4 TO 9	MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
53-21-25-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF JOINTS BETWEEN UPPER AND LOWER FRAMES 4 TO 9	MOS					27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC			TSI:0		0		
		AFL	20000		TSI:0		0		20000
					TSI:0		0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-27-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF NLG BAY BEAMS FROM FRAME 4 TO 7	MOS					08-APR-2013		
53.680	REF: AMM 53-21-40	HRS/MSC AFL	6000				5700.2 6053		12053
53-21-27-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF NLG BAY BEAMS FROM FRAME 4 TO 7	MOS					08-APR-2013		
	REF:	HRS/MSC AFL	4000				5700.2 6053		10053
53-21-27-03-02 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF NLG BAY BEAMS FROM FRAME 4 TO 7	MOS					09-SEP-2010		
	REF: AMM 53-21-40	HRS/MSC AFL	4000				5247 5862		
+ 53-21-29-01-01 (s)	FRONT FUSELAGE STRUCTURE -PERFORM DETAILED INSPECTION OF LOWER FRAMES FROM 11 TO 15	MOS	60	+4m			PKG		
53.175	PKG 5 REF: AMM 53-21-20	HRS/MSC AFL			-61		08-JUN-2018 6504.7 6393		
+ 53-21-29-02-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF LOWER FRAMES FROM 11 TO 15	MOS					27-FEB-2002		
53.973	REF: See Workcard	HRS/MSC AFL	20000				0 0		20000
53-21-29-03-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF LOWER FRAMES FROM 11 TO 15	MOS					27-FEB-2002		
	REF:	HRS/MSC AFL	20000				0 0		20000
+ 53-21-31-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF UNDERCARRIAGE BAY WALL BEAMS	MOS					09-SEP-2010		
53.685	REF: AMM 53-21-40	HRS/MSC AFL	6000				5247 5862		11862

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-33-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF HALF SHELL AT NLG TRUNNION, LEFT AND RIGHT								
53.690	REF: AMM 53-21-00	MOS HRS/MSC AFL	22000				27-FEB-2002 0 0		22000
+ 53-21-35-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF NLG UNDERCARRIAGE BAY WALL, EXTERNAL								
53.695	REF: AMM 53-21-25	MOS HRS/MSC AFL	12000				27-FEB-2002 0 0		12000
53-21-35-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF NLG UNDERCARRIAGE BAY WALL, EXTERNAL								
	REF:	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
+ 53-21-37-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CABIN FLOOR, FRAMES 3 TO 8								
53.700	PKG 5 REF: AMM 53-21-50	MOS HRS/MSC AFL	60	+4m	-61		PKG 08-JUN-2018 6504.7 6393		
+ 53-21-37-02-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF CABIN FLOOR, FRAMES 3 TO 8								
53.705	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-37-03-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF CABIN FLOOR, FRAMES 3 TO 8								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-21-39-02-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF FLIGHT COMPARTMENT LONGERONS, JOINTS INCLUDED								
53.710	REF: NTM 53-21-39	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-41-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF LOWER SHELL EXTERNAL SKIN, FRAMES FROM 1 TO 15								
53-715	REF: AMM 53-21-10	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
53-21-42-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, LOWER SHELL FROM FRAME 1 TO 15, SKIN CUTOUTS FOR NOSE LANDING GEAR BAY AND EXTERNAL POWER PANEL								
53.130	REF: AMM 53-21-10	MOS HRS/MSC AFL	12000				27-FEB-2002 0 0		12000
53-21-42-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT FUSELAGE STRUCTURE, LOWER SHELL FROM FRAME 1 TO 15, SKIN CUTOUTS FOR NOSE LANDING GEAR BAY AND EXTERNAL POWER PANEL								
	REF:	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
+ 53-21-43-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF UPPER SHELL, EXTERNAL SKIN, FRAMES 1 TO 7 AND FLIGHT COMPARTMENT								
53.720	REF: AMM 53-21-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-43-03-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF UPPER SHELL, EXTERNAL SKIN, FRAMES 1 TO 7 AND FLIGHT COMPARTMENT								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-21-45-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF UPPER SHELL, EXTERNAL SKIN, FRAMES 7 TO 10								
53.725	REF: AMM 53-21-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-45-03-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF UPPER SHELL, EXTERNAL SKIN, FRAMES 7 TO 10								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-47-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF SKIN JOINTS (STRAPS), LONGITUDINAL, INTERNAL						PKG		
53.190	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-21-47-02-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF SKIN JOINTS (STRAPS), LONGITUDINAL, INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-21-47-03-01	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF SKIN JOINTS (STRAPS), LONGITUDINAL, INTERNAL								
	REF:	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0		16000
53-21-47-03-02	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (BOROSCOPE) OF SKIN JOINTS (STRAPS), LONGITUDINAL, INTERNAL								
	REF: NTM 53-21-47	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
53-21-49-01-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF SKIN JOINTS (STRAPS), TRANSVERSAL, FRAME 3 TO FRAME 15, INTERNAL								
53.235	REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			09-SEP-2010 5247 5862	09-SEP-2020	09-MAR-2021
+ 53-21-49-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF SKIN JOINTS (STRAPS), TRANSVERSAL, FRAME 3 TO FRAME 15, INTERNAL								
53.974	REF: AMM 53-21-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-21-51-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF MAINTENANCE DOOR IN NLG BAY, EXTERNAL AND INTERNAL						PKG		
53.200	PKG 5 REF: See Workcard	MOS HRS/MSC AFL	60	+4m			08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-51-02-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (TAP TEST) OF MAINTENANCE DOOR IN NLG BAY, EXTERNAL AND INTERNAL						PKG		
	PKG 5	MOS	60				08-JUN-2018		
	REF:	HRS/MSC					6504.7		
		AFL	8000				6393		
+ 53-21-53-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF COMMUNICATION DOOR AND CUTOUT								
53.730		MOS					27-FEB-2002		
	REF: AMM 53-21-80	HRS/MSC					0		
		AFL	20000				0		20000
53-21-53-03-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF COMMUNICATION DOOR AND CUTOUT								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-53-04-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM REAPPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) AT COMMUNICATION DOOR						PKG		
53.735	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: GENERIC NO REF	HRS/MSC					5276.6		
		AFL					5873		
+ 53-21-55-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF PASSENGER / CREW DOOR SHELL, SKIN BETWEEN FRAMES 10-15, STRINGERS 0 - 23, EXTERNAL								
53.740		MOS					27-FEB-2002		
	REF: AMM 53-21-10	HRS/MSC					0		
		AFL	20000				0		20000
53-21-55-03-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF PASSENGER / CREW DOOR SHELL, SKIN BETWEEN FRAMES 10-15, STRINGERS 0 - 23, EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-57-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SHELL SURFACE BETWEEN FRAME 10-15, STRINGER 0-23, INTERNAL						PKG		
53.210	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-53	HRS/MSC					5276.6		
		AFL					5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-57-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SHELL SURFACE BETWEEN FRAME 10-15, STRINGER 0-23, INTERNAL								
53.060		MOS HRS/MSC REF: AMM 53-21-10	20000				27-FEB-2002 0 0	20000	
53-21-57-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SHELL SURFACE BETWEEN FRAME 10-15, STRINGER 0-23, INTERNAL								
		MOS HRS/MSC REF:	20000				27-FEB-2002 0 0	20000	
+ 53-21-59-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF PASSENGER / CREW DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND VISIBLE SURFACE OF PASSENGER / CREW DOOR FRAME (DOOR CUTOUT), EXTERNAL						PKG		
53.215		PKG 5 MOS HRS/MSC REF: AMM 05-25-53	60	+6m			08-JUN-2018 6504.7 6393		
+ 53-21-59-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF PASSENGER / CREW DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND VISIBLE SURFACE OF PASSENGER / CREW DOOR FRAME (DOOR CUTOUT), EXTERNAL								
53.976		MOS HRS/MSC REF: AMM 53-21-20	20000				27-FEB-2002 0 0	20000	
+ 53-21-61-01-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SKIN CUTOUT SURROUNDING AREAS AND PASSENGER / CREW DOOR FRAME, DOOR SHELL FRAME 10-15, STRINGER 0-23, INTERNAL						PKG		
53.220		PKG 5 MOS HRS/MSC REF: AMM 05-25-53	60	+6m			08-JUN-2018 6504.7 6393		
53-21-61-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SKIN CUTOUT SURROUNDING AREAS AND PASSENGER / CREW DOOR FRAME, DOOR SHELL FRAME 10-15, STRINGER 0-23, INTERNAL								
53.115		MOS HRS/MSC REF: AMM 53-21-20	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-61-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SKIN CUTOUT SURROUNDING AREAS AND PASSENGER / CREW DOOR FRAME, DOOR SHELL FRAME 10-15, STRINGER 0-23, INTERNAL	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0		16000
	REF:								
53-21-61-03-02	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF PASSENGER / CREW DOOR SKIN CUTOUT SURROUNDING AREAS AND PASSENGER / CREW DOOR FRAME, DOOR SHELL FRAME 10-15, STRINGER 0-23, INTERNAL	MOS HRS/MSC AFL		TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		
	REF: AMM 53-21-20								
+ 53-21-63-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CREW HATCH SURROUNDING AREA OF CUTOUT AND VISIBLE SURFACE OF CREW HATCH FRAME, EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.745	REF: AMM 53-21-60								
53-21-63-03-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CREW HATCH SURROUNDING AREA OF CUTOUT AND VISIBLE SURFACE OF CREW HATCH FRAME, EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF:								
+ 53-21-65-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CREW HATCH SKIN CUTOUT SURROUNDING AREAS AND CREW HATCH FRAME, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.750	REF: AMM 53-21-60								
53-21-65-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF CREW HATCH SKIN CUTOUT SURROUNDING AREAS AND CREW HATCH FRAME, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF:								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-67-02-01	FRONT FUSELAGE STRUCTURE RIGHT - PERFORM GENERAL VISUAL INSPECTION OF FRONT SIDE SHELL, SKIN BETWEEN FRAMES 10-15, STRINGERS 0-16', EXTERNAL								
53.755		MOS					27-FEB-2002		
	REF: AMM 53-21-10	HRS/MSC					0		
		AFL	20000				0		20000
53-21-67-03-01	FRONT FUSELAGE STRUCTURE RIGHT - PERFORM GENERAL VISUAL INSPECTION OF FRONT SIDE SHELL, SKIN BETWEEN FRAMES 10-15, STRINGERS 0-16', EXTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-69-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT SIDE SHELL RIGHT, SURFACE BETWEEN FRAME 10-15, STRINGER 0-16', INTERNAL								
53.760		MOS					27-FEB-2002		
	REF: AMM 53-21-10	HRS/MSC					0		
		AFL	20000				0		20000
53-21-69-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF FRONT SIDE SHELL RIGHT, SURFACE BETWEEN FRAME 10-15, STRINGER 0-16', INTERNAL								
		MOS					27-FEB-2002		
	REF:	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-71-02-01	FRONT FUSELAGE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CORNER SURROUNDING AREAS OF EMERGENCY EXIT SKIN CUTOUT AND VISIBLE SURFACE OF EMERGENCY EXIT FRAME, EXTERNAL								
53.765		MOS					27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000
+ 53-21-73-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF EMERGENCY EXIT SKIN CUTOUT SURROUNDING AREAS AND EMERGENCY EXIT FRAME BETWEEN FRAMES 11-14, INTERNAL								
53.770		MOS					27-FEB-2002		
	REF: AMM 53-21-60	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-21-73-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF EMERGENCY EXIT SKIN CUTOUT SURROUNDING AREAS AND EMERGENCY EXIT FRAME BETWEEN FRAMES 11-14, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
REF:									
+ 53-21-75-02-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF BRAKE VALVE DOOR AND SKIN CUTOUT	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53.775	REF: AMM 53-21-80								
53-21-75-03-01	FRONT FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF BRAKE VALVE DOOR AND SKIN CUTOUT	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
REF:									
+ 53-21-75-04-01 (s)	FRONT FUSELAGE STRUCTURE - PERFORM REAPPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) AT BRAKE VALVE DO	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
53.780	PKG 6 REF: GENERIC NO REF								
+ 53-21-81-01-01 (s)	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3-5, INTERNAL	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
53.785	PKG 6 REF: AMM 53-21-20								
53-21-81-02-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3-5, INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53.120	REF: AMM 53-21-20								
53-21-81-03-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3-5, INTERNAL	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
REF:	GENERIC NO REF								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-21-82-01-01 (s)	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3'-5', INTERNAL						PKG		
53.790	PKG 6 REF: AMM 53-21-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-21-82-02-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3'-5', INTERNAL						27-FEB-2002		
53.135	REF: AMM 53-21-20	MOS HRS/MSC AFL	20000				0 0	20000	
53-21-82-03-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT TANK ATTACHMENT JOINT AT FRAME 13 TO FRAME 14, STRINGERS 3'-5', INTERNAL						27-FEB-2002		
	REF: AMM 53-21-20	MOS HRS/MSC AFL	16000				0 0	16000	
+ 53-21-83-01-01 (s)	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT DOUBLER AT FRAME 13 TO FRAME 14, STRINGERS 3-5, EXTERNAL						PKG		
53.795	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-21-83-02-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT DOUBLER AT FRAME 13 TO FRAME 14, STRINGERS 3-5, EXTERNAL						27-FEB-2002		
53.800	REF: See Workcard	MOS HRS/MSC AFL	20000				0 0	20000	
+ 53-21-84-01-01 (s)	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT DOUBLER AT FRAME 13 TO FRAME 14, STRINGERS 3'-5', EXTERNAL						PKG		
53.805	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-21-84-02-01	FRONT FUSELAGE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT DOUBLER AT FRAME 13 TO FRAME 14, STRINGERS 3'-5', EXTERNAL						27-FEB-2002		
53.810	REF: See Workcard	MOS HRS/MSC AFL	20000				0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-31-01-02-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SIDE SHELL, LEFT AND RIGHT, SKIN BETWEEN FRAMES 15-22, STRINGERS 16-0-16', EXTERNAL								
53.815	REF: AMM 53-31-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-31-01-03-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT AND RIGHT SKIN BETWEEN FRAME 15-22, STRINGER 16-0-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
53-31-01-03-02	CENTER FUSELAGE FRONT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT AND RIGHT SKIN BETWEEN FRAME 15-22, STRINGER 16-0-16', INTERNAL								
	REF: AMM 53-31-10	MOS HRS/MSC AFL	4000				08-APR-2013 5700.2 6053	10053	
+ 53-31-03-02-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT AND RIGHT SURFACE BETWEEN FRAME 15-22, STRINGER 16-0-16', INTERNAL								
53.820	REF: AMM 53-31-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-31-03-03-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT AND RIGHT SURFACE BETWEEN FRAME 15-22, STRINGER 16-0-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-31-09-02-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF LOWER SHELL SKIN BETWEEN FRAME 15-22, STRINGER 16-28-16', EXTERNAL								
53.245	REF: AMM 53-31-10	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0	8000	
53-31-09-03-01	CENTER FUSELAGE FRONT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF LOWER SHELL SKIN BETWEEN FRAME 15-22, STRINGER 16-28-16', EXTERNAL								
	REF:	MOS HRS/MSC AFL	4000				09-SEP-2010 5247 5862	9862	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-31-11-02-01	CENTER FUSELAGE STRUCTURE FRONT - PERFORM DETAILED INSPECTION OF LOWER SHELL SURFACE BETWEEN FRAME 15-22, STRINGER 16-28-16', INTERNAL								
53.825	REF: AMM 53-31-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-31-11-03-01	CENTER FUSELAGE STRUCTURE FRONT - PERFORM DETAILED INSPECTION OF LOWER SHELL SURFACE BETWEEN FRAME 15-22, STRINGER 16-28-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-31-81-01-01 (s)	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT TANK - ATTACHMENT JOINTS, AT FRAME17 TO FRAME 18, STRINGERS 4-6, INTERNAL						PKG		
53.830	REF: AMM 53-31-20	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-31-81-02-01	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT TANK - ATTACHMENT JOINTS, AT FRAME17 TO FRAME 18, STRINGERS 4-6, INTERNAL								
53.140	REF: AMM 53-31-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-31-82-01-01 (s)	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT DOUBLERS AT FRAME17 TO FRAME 18, STRINGERS 4-6, EXTERNAL						PKG		
53.835	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-31-82-02-01	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LEFT DOUBLERS AT FRAME17 TO FRAME 18, STRINGERS 4-6, EXTERNAL								
53.840	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-31-83-01-01 (s)	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT DOUBLERS AT FRAME 17 TO FRAME 18, STRINGERS 4'-6', EXTERNAL						PKG		
53.845	REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-31-83-02-01	CENTER FUSELAGE FRONT STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF RIGHT DOUBLERS AT FRAME17 TO FRAME 18, STRINGERS 4'-6', EXTERNAL								
53.850	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-40-03-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, FRAME 22 TO FRAME 35, EXTERNAL, (STRINGER 16-28-16'), EXCEPT BATTERY COMPARTMENT						PKG		
53.260	REF: GENERIC NO REF	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-40-05-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, FRAME 22 TO FRAME 35, EXTERNAL, AREA UNDER TOP FAIRING						PKG		
53.265	REF: GENERIC NO REF	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-40-05-03-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE FRAME 22 TO FRAME 35 EXTERNAL, AREA UNDER TOP FAIRING.						PKG		
53-270	REF: GENERIC NO REF	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-40-05-05-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, ATTACHMENT POINTS OF AFT TOP FAIRING NO. 11 (253-AT)						PKG		
	REF: GENERIC NO REF	PKG 4 MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
53-40-05-07-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, ATTACHMENT POINTS OF AFT TOP FAIRING NO. 11 (254-CT)						PKG		
	REF: GENERIC NO REF	PKG 4 MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
+ 53-40-09-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, MLG BAYS, LEFT AND RIGHT						PKG		
53.275	REF: GENERIC NO REF	PKG 4 MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-11-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, FRAME 22 REAR SIDE TO FRAME 37 FRONT SIDE, INTERNAL, ABOVE CABIN FLOOR, EXCEPT SURROUNDING AREA OF SERVICE DOOR AND EMERGENCY EXIT, LEFT						PKG		
53.280	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-40-13-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, FRAME 22 REAR SIDE TO FRAME 37 FRONT SIDE, INTERNAL, UNDER CABIN FLOOR INCLUDING SEAT RAILS, EXCEPT AREA UNDER LAVATORY AND GALLEY						PKG		
53.285	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 53-40-15-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, RIGHT AREA UNDER LAVATORY, FRAME 35 REAR SIDE TO FRAME 37 FRONT SIDE, INTERNAL						PKG		
53.290	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
53-40-15-02-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, RIGHT AREA UNDER LAVATORY, FRAME 35 REAR SIDE TO FRAME 37, INTERNAL						PKG		
53.1000	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
53-40-15-04-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, RIGHT AREA UNDER LAVATORY FRAME 32 REAR SIDE TO FRAME 37 FRONT SIDE INTERNAL						PKG		
53.000	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
53-40-15-05-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORMED GENERAL VISUAL INSPECTION OF CENTER FUSELAGE MIDDLE STRUCTURE, RIGHT AREA UNDER LAVATORY, FRAME 32 REAR SIDE TO FRAME 37 FRONT SIDE, INTERNAL						PKG		
53.000	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
53-40-15-06-01	COVERED BY MPD TASK 53-40-15-04-01								
	REF:	MOS HRS/MSC AFL					27-FEB-2002 0 0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-40-17-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, AREA UNDER GALLEY, FRAME 32 REAR SIDE TO FRAME 35 FRONT SIDE, RIGHT						PKG		
53.300	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
53-40-17-02-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, AREA UNDER GALLEY, FRAME 32 REAR SIDE TO FRAME 35 FRONT SIDE, RIGHT						PKG		
53.170	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 53-40-19-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, SURROUNDING AREA OF SERVICE DOOR, INCLUDING AREA UNDER SCUFF PLATE						PKG		
53.305	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
53-40-19-03-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, SURROUNDING AREA OF SERVICE DOOR, INCLUDING AREA UNDER SCUFF PLATE						PKG		
53.180	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
53-40-19-03-02 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, SURROUNDING AREA OF SERVICE DOOR, INCLUDING AREA UNDER SCUFF PLATE						PKG		
	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 53-40-21-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, INTERNAL, SURROUNDING AREA OF EMERGENCY EXIT, LEFT						PKG		
53.310	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-40-23-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CENTER FUSELAGE STRUCTURE, BATTERY COMPARTMENTS, LEFT AND RIGHT						PKG		
53.315	PKG 5 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-01-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT, SKIN BETWEEN FRAME 22-35, STRINGER 16-0, EXTERNAL						PKG		
53.320	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-41-01-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT, SKIN BETWEEN FRAME 22-35, STRINGER 16-0, EXTERNAL								
53.185	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-41-01-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, LEFT, SKIN BETWEEN FRAME 22-35, STRINGER 16-0, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-41-03-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL SURFACE, LEFT , BETWEEN FRAME 22-35, STRINGER 16-0, INTERNAL								
53.855	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-41-03-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL SURFACE, LEFT , BETWEEN FRAME 22-35, STRINGER 16-0, INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-41-05-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF REARWARD EMERGENCY EXIT SKIN CUTOUT AND VISIBLE SURFACE OF EMERGENCY EXIT FRAME, EXTERNAL								
53.860	REF: AMM 53-41-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-41-07-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF EMERGENCY EXIT SKIN CUTOUT SURROUNDING AREAS AND EMERGENCY EXIT FRAME, BETWEEN FRAMES 27-30, INTERNAL								
53.870	REF: AMM 53-41-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-09-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, RIGHT, SKIN BETWEEN FRAME 22-32, STRINGER 0-16', EXTERNAL						PKG		
53.330	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-41-09-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, RIGHT, SKIN BETWEEN FRAME 22-32, STRINGER 0-16', EXTERNAL								
53.195	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-41-09-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, RIGHT, SKIN BETWEEN FRAME 22-32, STRINGER 0-16', EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-11-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, RIGHT, SURFACE BETWEEN FRAMES 22-32, STRINGERS 0-16', INTERNAL								
53.145	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-41-11-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL, RIGHT, SURFACE BETWEEN FRAMES 22-32, STRINGERS 0-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-13-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL SKIN BETWEEN FRAME 22-35, STRINGER 16-28-16', EXCEPT MLG BAY, EXTERNAL								
53.880	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-41-13-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL SKIN BETWEEN FRAME 22-35, STRINGER 16-28-16', EXCEPT MLG BAY, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-15-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL, SURFACE BETWEEN FRAMES 22-35, STRINGERS 16-28-16', INTERNAL								
53.885	REF: AMM 53-41-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-41-15-03-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL, SURFACE BETWEEN FRAMES 22-35, STRINGERS 16-28-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-17-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 23, INTERNAL						PKG		
53.340	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-41-17-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 23, INTERNAL								
53.205	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-19-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 23 FRONT WING SUPPORT FOR Z-LOADS, LEFT AND RIGHT, EXTERNAL								
53.890	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-21-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 23, FRONT WING SUPPORT FOR Y-LOADS, LEFT, EXTERNAL								
53.895	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-23-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 24, INTERNAL						PKG		
53.355	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-23-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 24, INTERNAL								
53.900	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-25-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 24, LOWER OUTER PART, FRONT SUPPORT FOR MAIN LANDING GEAR ATTACHMENT, EXTERNAL								
53.360	REF: See Workcard	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367	PKG	
+ 53-41-25-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 24, LOWER OUTER PART, FRONT SUPPORT FOR MAIN LANDING GEAR ATTACHMENT, EXTERNAL								
53.977	REF: See Workcard	MOS HRS/MSC AFL	8000				27-FEB-2002 0 0		8000
+ 53-41-27-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF WING SUPPORT FOR X-LOADS BETWEEN FRAME 24-25, LEFT AND RIGHT, EXTERNAL								
53.365	REF: GENERIC NO REF	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-29-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF WING SUPPORT FOR X-LOADS BETWEEN FRAME 24-25, LEFT AND RIGHT, INTERNAL								
53.370	REF: AMM 53-41-40	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-31-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 25, INTERNAL								
53.375	REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
+ 53-41-31-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 25, INTERNAL								
53.978	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-33-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 25, REAR WING SUPPORT FOR Z-LOADS, LEFT AND RIGHT, EXTERNAL								
53.900	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-35-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 25, REAR WING SUPPORT FOR Y-LOADS, LEFT, EXTERNAL								
53.895	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-37-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 26, INTERNAL								
53.390	PKG 6 REF: AMM 05-25-53	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
53-41-37-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 26, INTERNAL								
53.225	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-39-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF FRAME 26 LOWER OUTER PART, REAR SUPPORT FOR MAIN LANDING GEAR ATTACHMENT, EXTERNAL								
53.905	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-41-41-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF PRESSURE FLOOR BETWEEN FRAME 24-26, WITH MAIN LANDING GEAR BRACKETS FOR ACTUATOR AND STRUT, EXTERNAL								
53.436	REF: AMM 53-41-50	MOS HRS/MSC AFL	4000				09-SEP-2010 5247 5862		9862
+ 53-41-43-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF PRESSURE FLOOR BETWEEN FRAME 24-26, INTERNAL								
53.910	REF: AMM 53-41-50	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-41-45-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF MAIN LANDING GEAR SHEAR WALL BETWEEN FRAME 24-26, WITH LONGITUDINAL PROFILE, LEFT AND RIGHT, EXTERNAL								
53.915	REF: AMM 53-41-40	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
+ 53-41-47-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF KEEL BEAM BETWEEN FRAME 22-28, EXTERNAL						PKG		
53.415	REF: AMM 05-25-53	PKG 5 MOS HRS/MSC AFL	60	+4m	-61		08-JUN-2018 6504.7 6393		
53-41-47-02-01	CENTER FUSELAGE MIDDLE STRUCTURE - PERFORM DETAILED INSPECTION OF KEEL BEAM BETWEEN FRAME 22-28, EXTERNAL								
53.230	REF: AMM 53-41-40	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
+ 53-41-81-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 27A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL						PKG		
53.920	REF: See Workcard	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-41-81-02-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 27A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL								
	REF: AMM 53-41-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-41-81-03-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 27A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL								
	REF: AMM 53-41-20	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	
53-41-82-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 33A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL						PKG		
53.925	REF: See Workcard	PKG 6 MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-41-82-02-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 33A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 53-41-20								
53-41-82-03-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF AUXILIARY FRAME 33A AND FRAME ATTACHMENT JOINTS, STRINGERS 9-0-9' INTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 53-41-20								
+ 53-41-83-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT OUTBOARD DOUBLERS AND STRAPS AT FRAMES 27-28, STRINGERS 7-8 AND INBOARD DOUBLERS AND STRAPS AT FRAMES 27-28, STRINGERS 2-0-2', EXTERNAL	PKG 6					PKG 11-FEB-2011 5276.6 5873		
53.930	REF: See Workcard	MOS HRS/MSC AFL	120	+6m					
+ 53-41-83-02-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF LEFT AND RIGHT OUTBOARD DOUBLERS AND STRAPS AT FRAMES 27-28, STRINGERS 7-8 AND INBOARD DOUBLERS AND STRAPS AT FRAMES 27.28, STRINGERS 2-0-2', EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.935	REF: See Workcard								
+ 53-41-84-01-01 (s)	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT OUTBOARD DOUBLERS AND STRAPS AT FRAMES 32-33, STRINGERS 5-6 AND INBOARD DOUBLERS AND STRAPS AT FRAMES 32-33, STRINGERS 2- 0-2', EXTERNAL	PKG 6					PKG 11-FEB-2011 5276.6 5873		
53.940	REF: See Workcard	MOS HRS/MSC AFL	120	+6m					
+ 53-41-84-02-01	CENTER FUSELAGE MIDDLE STRUCTURE EXTENDED RANGE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT OUTBOARD DOUBLERS AND STRAPS AT FRAMES 32-33, STRINGERS 5-6 AND INBOARD DOUBLERS AND STRAPS AT FRAMES 32-33, STRINGERS 2- 0-2', EXTERNAL	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53.945	REF: See Workcard								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-50-05-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF REAR / CENTER FUSELAGE STRUCTURE, FRAME 37 REAR SIDE TO FRAME 44 FRONT SIDE, ABOVE CARGO COMPARTMENT FLOOR, EXCEPT SURROUNDING AREA OF CARGO DOOR, INTERNAL						PKG		
53.430	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-50-07-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF REAR / CENTER FUSELAGE STRUCTURE, FRAME 37 REAR SIDE TO FRAME 44 FRONT SIDE, UNDER CARGO COMPARTMENT FLOOR, INTERNAL						PKG		
53.435	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 53-50-09-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF REAR / CENTER FUSELAGE STRUCTURE, SURROUNDING AREA OF CARGO DOOR, INCLUDING AREA UNDER SCUFF PLATE, INTERNAL						PKG		
53.440	PKG 4 REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367		
+ 53-51-01-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SIDE SHELL, SKIN BETWEEN FRAMES 35-44, STRINGERS 0-16, EXCEPT AREA UNDER FAIRING / AUXILIARY TANKS, EXTERNAL								
53.950	REF: AMM 53-51-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
53-51-01-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SIDE SHELL, SKIN BETWEEN FRAMES 35-44, STRINGERS 0-16, EXCEPT AREA UNDER FAIRING / AUXILIARY TANKS, EXTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 53-51-02-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT SHELL, SKIN BETWEEN FRAME 28-44, EXTERNAL, AREA UNDER TOP FAIRINGS / AUXILIARY TANKS						PKG		
53.560	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-51-02-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT SHELL, SKIN BETWEEN FRAME 28-44, EXTERNAL, AREA UNDER TOP FAIRINGS / AUXILIARY TANKS								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-02-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LEFT AND RIGHT SHELL, SKIN BETWEEN FRAME 28-44, EXTERNAL, AREA UNDER TOP FAIRINGS / AUXILIARY TANKS	MOS HRS/MSC AFL					27-FEB-2002 0 0		20000
REF:		AFL	20000						
53-51-03-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LEFT SIDE SHELL SURFACE BETWEEN FRAME 35-44, STRINGER 0-16, INTERNAL	MOS HRS/MSC AFL					27-FEB-2002 0 0		20000
53.250	REF: AMM 53-51-10	AFL	20000						
+ 53-51-05-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF CARGO DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND CARGO DOOR FRAME, EXTERNAL	MOS HRS/MSC AFL	30	+2m		-10	01-DEC-2017 6428.4 6367	PKG	
53.450	PKG 4 REF: AMM 05-25-53	AFL							
53-51-05-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF CARGO DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND CARGO DOOR FRAME, EXTERNAL	MOS HRS/MSC AFL					09-SEP-2010 5247 5862		11862
53.255	REF: AMM 53-51-65	AFL	6000						
53-51-07-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CARGO DOOR SKIN CUTOUT SURROUNDING AREAS AND CARGO DOOR FRAME, INTERNAL	MOS HRS/MSC AFL					27-FEB-2002 0 0		20000
53.270	REF: AMM 53-51-60	AFL	20000						
+ 53-51-07-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CARGO DOOR SKIN CUTOUT SURROUNDING AREAS AND CARGO DOOR FRAME, INTERNAL	MOS HRS/MSC AFL					27-FEB-2002 0 0		16000
53.955	REF: AMM 53-51-60	AFL	16000						
53-51-07-03-02	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CARGO DOOR SKIN CUTOUT SURROUNDING AREAS AND CARGO DOOR FRAME, INTERNAL	MOS HRS/MSC AFL					08-APR-2013 5700.2 6053		8053
	REF: AMM 53-51-60	AFL	2000						

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-51-09-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR SHELL, RIGHT, SKIN BETWEEN FRAMES 32-36, STRINGERS 0-28', EXCEPT AREA UNDER FAIRINGS / AUXILIARY TANKS, EXTERNAL	MOS					27-FEB-2002		
53.960	REF: AMM 53-51-67	HRS/MSC AFL	8000				0 0		8000
53-51-09-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SERVICE DOOR SHELL, RIGHT, SKIN BETWEEN FRAMES 32-36, STRINGERS 0-28', EXCEPT AREA UNDER FAIRINGS / AUXILIARY TANKS, EXTERNAL	MOS					09-SEP-2010		
	REF:	HRS/MSC AFL	4000				5247 5862		9862
+ 53-51-11-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SERVICE DOOR SHELL SURFACE BETWEEN FRAME 32-37, STRINGER 0-28', RIGHT, INTERNAL	MOS					27-FEB-2002		
53.965	REF: AMM 53-51-60	HRS/MSC AFL	20000				0 0		20000
53-51-11-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SERVICE DOOR SHELL SURFACE BETWEEN FRAME 32-37, STRINGER 0-28', RIGHT, INTERNAL	MOS					27-FEB-2002		
	REF:	HRS/MSC AFL	20000				0 0		20000
+ 53-51-13-01-01 (s)	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF SERVICE DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND VISIBLE SURFACE OF SERVICE DOOR FRAME, EXTERNAL						PKG		
53.465	PKG 5 REF: AMM 05-25-53	MOS HRS/MSC AFL	60	+4m		-61	08-JUN-2018 6504.7 6393		
+ 53-51-13-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF CORNER SURROUNDING AREAS OF SERVICE DOOR SKIN CUTOUT INCLUDING SURFACE UNDERNEATH THE SCUFF PLATE AND VISIBLE SURFACE OF SERVICE DOOR FRAME, EXTERNAL	MOS					27-FEB-2002		
53.979	REF: AMM 53-51-60	HRS/MSC AFL	8000				0 0		8000
+ 53-51-15-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SERVICE DOOR SKIN CUTOUT SURROUNDING AREAS AND SERVICE DOOR FRAME, INTERNAL	MOS					27-FEB-2002		
53.970	REF: AMM 53-51-60	HRS/MSC AFL	20000				0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-15-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SERVICE DOOR SKIN CUTOUT SURROUNDING AREAS AND SERVICE DOOR FRAME, INTERNAL	MOS HRS/MSC REF: AFL	20000				27-FEB-2002 0 0		20000
+ 53-51-17-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SIDE SHELL RIGHT, SKIN BETWEEN FRAMES 36-44, STRINGERS 0-16', EXTERNAL	MOS HRS/MSC REF: AMM 53-51-10	20000				27-FEB-2002 0 0		20000
53-51-17-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF SIDE SHELL RIGHT, SKIN BETWEEN FRAMES 36-44, STRINGERS 0-16', EXTERNAL	MOS HRS/MSC REF: AFL	20000				27-FEB-2002 0 0		20000
+ 53-51-19-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL RIGHT, SURFACE BETWEEN FRAMES 37-44, STRINGERS 0-16', INTERNAL	MOS HRS/MSC REF: AMM 53-51-10	20000				27-FEB-2002 0 0		20000
53-51-19-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF SIDE SHELL RIGHT, SURFACE BETWEEN FRAMES 37-44, STRINGERS 0-16', INTERNAL	MOS HRS/MSC REF: AFL	20000				27-FEB-2002 0 0		20000
+ 53-51-21-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF LOWER SHELL SKIN BETWEEN FRAMES 35-44, STRINGERS 16-28-16', EXTERNAL	MOS HRS/MSC REF: AMM 53-51-10	8000				27-FEB-2002 0 0		8000
53-51-21-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM GENERAL VISUAL INSPECTION OF LOWER SHELL SKIN BETWEEN FRAMES 35-44, STRINGERS 16-28-16', EXTERNAL	MOS HRS/MSC REF: AFL	4000				09-SEP-2010 5247 5862		9862

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-51-23-02-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL, SURFACE BETWEEN FRAMES 35-44, STRINGERS 16-28-16', INTERNAL								
53.150	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
53-51-23-03-01	CENTER FUSELAGE AFT STRUCTURE - PERFORM DETAILED INSPECTION OF LOWER SHELL, SURFACE BETWEEN FRAMES 35-44, STRINGERS 16-28-16', INTERNAL								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-60-03-01-01 (s)	REAR FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF REAR FUSELAGE STRUCTURE, FRAME 44 REAR SIDE TO FRAME 50						PKG		
53.475	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-60-05-01-01 (s)	REAR FUSELAGE STRUCTURE - PERFORM DETAILED INSPECTION OF TRANSVERSAL SKIN JOINT AT FRAME 44, EXTERNAL						PKG		
53.480	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-61-15-02-01	REAR FUSELAGE - PERFORM DETAILED INSPECTION OF THE LOWER AND UPPER APU ATTACHMENT BRACKETS AT FRAME 50, INTERNAL								
53.495	REF: AMM 53-61-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-61-17-02-01	REAR FUSELAGE - PERFORM DETAILED INSPECTION OF APU ATTACHMENT BRACKET AT FRAME 51, INTERNAL								
53.500	REF: AMM 53-61-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-70-03-01-01 (s)	TAIL CONE STRUCTURE - PERFORM DETAILED INSPECTION OF TAIL CONE STRUCTURE AFTER FRAME 50, INTERNAL						PKG		
53.515	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-81-01-01-01 (s)	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF FUSELAGE FITTINGS AT ALL FOUR LOCATIONS, EXTERNAL						PKG		
53.993	PKG 6 REF: AMM 53-31-70	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 53-81-01-02-01	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF FUSELAGE FITTINGS AT ALL FOUR LOCATIONS, EXTERNAL								
53.155	REF: AMM 53-31-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-81-02-01-01 (s)	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF TANK FITTINGS AT ALL FOUR LOCATIONS, EXTERNAL						PKG		
53.994	PKG 6 REF: AMM 53-85-01	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-81-02-02-01	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF TANK FITTINGS AT ALL FOUR LOCATIONS, EXTERNAL								
53.165	REF: AMM 53-85-01	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-81-05-01-01 (s)	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF LOWER COVER, LOWER SIDE, EXTERNAL						PKG		
53.996	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-81-05-02-01	FORWARD AUXILIARY FUEL TANK - PERFORM DETAILED INSPECTION OF LOWER COVER, LOWER SIDE, EXTERNAL								
28.290	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-81-06-02-01	FORWARD AUXILIARY FUEL TANK - PERFORM GENERAL VISUAL INSPECTION OF TOP COVER EXTERNAL								
53.997	REF: AMM 53-85-01	MOS HRS/MSC AFL	16000				27-FEB-2002 0 0	16000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-81-07-01-01 (s)	FORWARD AUXILIARY FUEL TANK - PERFORM A SPECIAL DETAILED INSPECTION (BORESCOPE) OF BAFFLE WEBS AND STRINGERS, INTERNAL						PKG		
53.998	PKG 6 REF: NTM 53-81-07	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-81-07-02-01	FORWARD AUXILIARY FUEL TANK - PERFORM A SPECIAL DETAILED INSPECTION (BORESCOPE) OF BAFFLE WEBS AND STRINGERS, INTERNAL								
57.010	REF: NTM 53-81-07	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-81-08-01-01 (s)	FORWARD AUXILIARY FUEL TANK -PERFORM DETAILED INSPECTION OF SIDE WALLS, INCLUSIVE FRONT AND REAR SIDE, AND AUXILIARY FAIRING FRAMES, EXTERNAL						PKG		
53.999	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-81-08-02-01	FORWARD AUXILIARY FUEL TANK -PERFORM DETAILED INSPECTION OF SIDE WALLS, INCLUSIVE FRONT AND REAR SIDE, AND AUXILIARY FAIRING FRAMES, EXTERNAL								
28.275	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-82-01-01-01 (s)	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF FUSELAGE FITTINGS AT ALL EIGHT LOCATIONS						PKG		
53.981	PKG 6 REF: AMM 53-41-70	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
53-82-01-02-01	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF FUSELAGE FITTINGS AT ALL EIGHT LOCATIONS								
Z-001	REF: AMM 53-41-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-82-02-01-01 (s)	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF TANK FITTINGS AT ALL EIGHT LOCATIONS						PKG		
53.982	PKG 6 REF: AMM 53-85-02	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-82-02-02-01	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF TANK FITTINGS AT ALL EIGHT LOCATIONS	MOS					27-FEB-2002		
28.315		HRS/MSC					0		
	REF: AMM 53-85-02	AFL	20000				0		20000
+ 53-82-05-01-01 (s)	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF LOWER COVER, LOWER SIDE, EXTERNAL	MOS	120	+6m			11-FEB-2011		
53.983	PKG 6	HRS/MSC					5276.6		
	REF: See Workcard	AFL					5873		
53-82-05-02-01	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF LOWER COVER, LOWER SIDE, EXTERNAL	MOS					27-FEB-2002		
53.983		HRS/MSC					0		
	REF: See Workcard	AFL	20000				0		20000
+ 53-82-06-02-01	REAR AUXILIARY FUEL TANKS - PERFORM GENERAL VISUAL INSPECTION OF TOP COVER, EXTERNAL	MOS					27-FEB-2002		
53.984		HRS/MSC					0		
	REF: AMM 53-85-02	AFL	20000				0		20000
+ 53-82-07-01-01 (s)	REAR AUXILIARY FUEL TANKS - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF BAFFLE WEBS AND STRINGERS, INTERNAL	MOS	120	+6m			11-FEB-2011		
53.986	PKG 6	HRS/MSC					5276.6		
	REF: NTM 53-82-07	AFL					5873		
53-82-07-02-01	REAR AUXILIARY FUEL TANKS - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF BAFFLE WEBS AND STRINGERS, INTERNAL	MOS					27-FEB-2002		
53.986		HRS/MSC					0		
	REF: NTM 53-82-07	AFL	20000				0		20000
+ 53-82-08-01-01 (s)	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF SIDE WALLS, INCLUSIVE FRONT AND REAR SIDE AND AUXILIARY FAIRING FRAMES, EXTERNAL	MOS	120	+6m			11-FEB-2011		
53.240	PKG 6	HRS/MSC					5276.6		
	REF: See Workcard	AFL					5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-82-08-02-01	REAR AUXILIARY FUEL TANKS - PERFORM DETAILED INSPECTION OF SIDE WALLS, INCLUSIVE FRONT AND REAR SIDE AND AUXILIARY FAIRING FRAMES, EXTERNAL								
53.240	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 53-90-00-01-01 (s)	DRAIN SYSTEM - PERFORM OPERATIONAL CHECK OF FUSELAGE DRAIN VALVES (FROM EXTERNAL)						PKG		
53.520	REF: AMM 53-00-10	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
53-90-00-01-02 (s)	DRAIN SYSTEMS - PERFORM OPERATIONAL CHECK OF FUSELAGE DRAIN VALVES (FROM EXTERNAL)						PKG		
53.1001	REF: AMM 53-00-10	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		
+ 53-90-00-02-01 (s)	DRAIN SYSTEM - PERFORM DETAILED INSPECTION OF FUSELAGE DRAIN VALVES (FROM INTERNAL)						PKG		
53.525	REF: AMM 53-00-10	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 53-90-00-03-01 (s)	FUSELAGE DRAIN LINES - PERFORM OPERATIONAL CHECK OF FUSELAGE DRAIN LINE AT FRAME 25 FOR BLOCKAGE						PKG		
53.325	REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
53-90-00-03-02 (s)	FUSELAGE DRAIN LINES - PERFORM OPERATIONAL CHECK OF FUSELAGE DRAIN LINE AT FRAME 25 FOR BLOCKAGE						PKG		
	REF: GENERIC NO REF	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
53-90-00-03-03 (s)	FUSELAGE DRAIN LINES - PERFORM OPERATIONAL CHECK OF FUSELAGE DRAIN LINE AT FRAMES 12, 25 AND 33 FOR BLOCKAGE						PKG		
	REF: GENERIC NO REF	MOS HRS/MSC AFL	30	+2m	-10		01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 53-90-00-04-01 (s)	FUSELAGE DRAIN LINES - PERFORM DETAILED INSPECTION OF FUSELAGE DRAINLINE AT FRAME 25 INCLUSIVE PRESSURE TEST, INTERNAL						PKG		
53.335	PKG 4 REF: See Workcard	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
53-90-00-04-02 (s)	FUSELAGE DRAIN LINES - PERFORM DETAILED INSPECTION OF FUSELAGE DRAINLINE AT FRAME 25 INCLUSIVE PRESSURE TEST, INTERNAL						PKG		
	PKG 4 REF: AMM 53-42-97	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
53-90-00-04-03 (s)	FUSELAGE DRAIN LINES - DETAILED INSPECTION OF FUSELAGE DRAIN LINE AT FRAMES 12, 25 AND 33 INCLUSIVE PRESSURE TEST, INTERNAL						PKG		
	PKG 4 REF: AMM 53-42-97	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
53-90-00-05-01 (s)	FUSELAGE DRAIN LINES - PERFORM RESTORATION (CLEANING) OF FLAME ARRESTOR (OFF AIRCRAFT) LEFT AND RIGHT INSTALLED IN LOWER DRAIN LINE AT FRAME 25						PKG		
53.345	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
53-90-00-05-02 (s)	FUSELAGE DRAIN LINES - PERFORM RESTORATION (CLEANING) OF FLAME ARRESTOR (OFF AIRCRAFT) LEFT AND RIGHT INSTALLED IN LOWER DRAIN LINE AT FRAME 25						PKG		
	PKG 3 REF: See Workcard	MOS HRS/MSC AFL	15	+1m	-20		01-DEC-2017 6428.4 6367		
530001	EDDY CURRENT INSPECTION OF DENT IN R/H FUSELAGE SKIN AT FRAME 8 AND STRINGER 19								
COMPLIED WITH	REF:	MOS HRS/MSC AFL	24 4000				01-DEC-2017 6428.4 6367	01-DEC-2019 10367	
CHAPTER 54		NACELLES/PYLONS							
+ 54-50-15-02-01	NACELLES - PYLON, LEFT - PERFORM GENERAL VISUAL INSPECTION OF PYLON, EXTERNAL SURFACE, LEFT								
54.085	REF: AMM 54-51-10	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-15-02-02	NACELLES - PYLON, RIGHT - PERFORM GENERAL VISUAL INSPECTION OF PYLON, EXTERNAL SURFACE, RIGHT								
54.085		MOS					27-FEB-2002		
	REF: AMM 54-51-10	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-17-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON, LEFT, FORWARD INNER STRUCTURE, ENGINE ATTACHMENT FITTING REAR SIDE TO RIB 4 FRONT SIDE, INCLUDING SIDEWALLS INNER SURFACES, FRONT SPAR LOWER SURFACE AND FIREWALL UPPER SURFACE								
54.090		MOS					27-FEB-2002		
	REF: AMM 54-51-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-17-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON, RIGHT, FORWARD INNER STRUCTURE, ENGINE ATTACHMENT FITTING REAR SIDE TO RIB 4 FRONT SIDE, INCLUDING SIDEWALLS INNER SURFACES, FRONT SPAR LOWER SURFACE AND FIREWALL UPPER SURFACE								
54.090		MOS					27-FEB-2002		
	REF: AMM 54-51-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-19-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLONS - REAR INNER STRUCTURE - RIB 4 REAR SIDE TO END RIB FRONT SIDE, INCLUDING SIDEWALL INNER SURFACES, SHEARWALL LOWER SURFACE AND REAR SPAR UPPER SURFACE, LEFT								
54.100		MOS					27-FEB-2002		
	REF: AMM 54-51-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-19-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLONS - REAR INNER STRUCTURE - RIB 4 REAR SIDE TO END RIB FRONT SIDE, INCLUDING SIDEWALL INNER SURFACES, SHEARWALL LOWER SURFACE AND REAR SPAR UPPER SURFACE, RIGHT								
54.100		MOS					27-FEB-2002		
	REF: AMM 54-51-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-21-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON, LEFT , UPPER FRONT SPAR, UPPER SURFACES.								
54.105		MOS					27-FEB-2002		
	REF: AMM 54-51-50	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-21-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON, RIGHT , UPPER FRONT SPAR, UPPER SURFACES.								
54.105	REF: AMM 54-51-50	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 54-50-23-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLONS, LOWER REAR SPAR - LOWER SURFACE, LEFT								
54.110	REF: AMM 54-51-50	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 54-50-23-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLONS, LOWER REAR SPAR - LOWER SURFACE, RIGHT								
54.110	REF: AMM 54-51-50	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 54-50-25-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON, LEFT, FIREWALL, LOWER SURFACE								
54.115	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 54-50-25-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON, RIGHT, FIREWALL, LOWER SURFACE								
54.115	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 54-50-27-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON SHEARWALL UPPER SURFACE, LEFT						PKG		
54.020	PKG 6 REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-27-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON SHEARWALL UPPER SURFACE, RIGHT						PKG		
54.020	PKG 6 REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-27-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON SHEARWALL UPPER SURFACE, LEFT								
54.120		MOS					27-FEB-2002		
	REF: AMM 54-51-10	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-27-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON SHEARWALL UPPER SURFACE, RIGHT								
54.120		MOS					27-FEB-2002		
	REF: AMM 54-51-10	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-29-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF FORWARD ENGINE SUPPORT, EXCEPT AREA UNDER ADAPTER PLATE, LEFT						PKG		
54.025	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-54	HRS/MSC					5276.6		
		AFL					5873		
+ 54-50-29-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF FORWARD ENGINE SUPPORT, EXCEPT AREA UNDER ADAPTER PLATE, RIGHT						PKG		
54.025	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-54	HRS/MSC					5276.6		
		AFL					5873		
+ 54-50-29-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF FORWARD ENGINE SUPPORT, EXCEPT AREA UNDER ADAPTER PLATE, LEFT								
54.080		MOS					27-FEB-2002		
	REF: AMM 54-41-70	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-29-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF FORWARD ENGINE SUPPORT, EXCEPT AREA UNDER ADAPTER PLATE, RIGHT								
54.080		MOS					27-FEB-2002		
	REF: AMM 54-41-70	HRS/MSC					0		
		AFL	20000				0		20000
+ 54-50-31-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLONS - REAR ENGINE SUPPORT BRACKET, LEFT								
54.060		MOS					27-FEB-2002		
	REF: AMM 54-42-70	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-31-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLONS - REAR ENGINE SUPPORT BRACKET, RIGHT								
54.060	REF: AMM 54-42-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-33-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF FORWARD PYLON SUPPORT, INBOARD / OUTBOARD, LEFT						PKG		
54.030	REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-33-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF FORWARD PYLON SUPPORT, INBOARD / OUTBOARD, RIGHT						PKG		
54.030	REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
54-50-33-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF FORWARD PYLON SUPPORT, INBOARD / OUTBOARD, LEFT								
54.055	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
54-50-33-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF FORWARD PYLON SUPPORT, INBOARD / OUTBOARD, RIGHT								
54.075	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-35-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF REAR PYLON SUPPORT INCLUDING BOLTS, LEFT						PKG		
54.070	REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-35-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF REAR PYLON SUPPORT INCLUDING BOLTS, RIGHT						PKG		
54.070	REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-35-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF REAR PYLON SUPPORT INCLUDING BOLTS, LEFT								
54.035	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-35-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF REAR PYLON SUPPORT INCLUDING BOLTS, RIGHT								
54.035	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-37-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON FITTING INBOARD/OUTBOARD, REAR SPAR, LEFT						PKG		
54.040	PKG 6 REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-37-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON FITTING INBOARD/OUTBOARD, REAR SPAR, RIGHT						PKG		
54.040	PKG 6 REF: AMM 05-25-54	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-37-02-01	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION OF PYLON FITTINGS, INBOARD / OUTBOARD, REAR SPAR, LEFT								
54.125	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-37-02-02	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION OF PYLON FITTINGS, INBOARD / OUTBOARD, REAR SPAR, RIGHT								
54.125	REF: AMM 54-51-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-41-01-01 (s)	NACELLES - PYLON, LEFT - PERFORM DETAILED INSPECTION (ULTRASONIC) OF FORWARD ENGINE SUPPORT AREA UNDER ADAPTER PLATE AND MOUNTING SURFACE OF YOKE, LEFT						PKG		
54.045	PKG 6 REF: NTM 54-50-41	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 54-50-41-01-02 (s)	NACELLES - PYLON, RIGHT - PERFORM DETAILED INSPECTION (ULTRASONIC) OF FORWARD ENGINE SUPPORT AREA UNDER ADAPTER PLATE AND MOUNTING SURFACE OF YOKE, RIGHT						PKG		
54.045	PKG 6 REF: NTM 54-50-41	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 54-50-41-02-03	NACELLES - PYLON, LEFT - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC) OF FORWARD ENGINE SUPPORT TENSION BOLTS, LEFT								
54.135	REF: NTM 54-50-41	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 54-50-41-02-04	NACELLES - PYLON, RIGHT - PERFORM SPECIAL DETAILED INSPECTION (ULTRASONIC) OF FORWARD ENGINE SUPPORT TENSION BOLTS, RIGHT								
54.135	REF: NTM 54-50-41	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
CHAPTER 55 STABILIZERS									
+ 55-10-01-01-01 (s)	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF HORIZONTAL STABILIZER, LEFT AND RIGHT						PKG		
55.010	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-11-05-01-01 (s)	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR BOX, INTERNAL, INCLUDING RIBS, PANELS, STRINGER AND SPARS						PKG		
55.015	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-11-05-02-01	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF SPAR BOX, INTERNAL, METAL PARTS								
55.160	REF: NTM 55-11-05	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-11-09-01-01 (s)	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF REAR SPAR, REAR SIDE						PKG		
55.020	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-11-11-01-01 (s)	HORIZONTAL STABILIZER - PERFORM DETAILED INSPECTION OF FRONT, CENTER AND REAR SUPPORT TO VERTICAL STABILIZER INCLUDING BOLTS						PKG		
55.025	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-11-11-02-01	HORIZONTAL STABILIZER - PERFORM DETAILED INSPECTION OF FRONT SUPPORT TO VERTICAL STABILIZER INCLUDING BOLTS								
55.165	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-11-13-02-01	HORIZONTAL STABILIZER - PERFORM DETAILED INSPECTION OF CENTER SUPPORT TO VERTICAL STABILIZER INCLUDING BOLTS								
55.165	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-11-15-02-01	HORIZONTAL STABILIZER - PERFORM DETAILED INSPECTION OF REAR SUPPORT TO VERTICAL STABILIZER INCLUDING BOLTS								
55.165	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-11-17-01-01 (s)	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR SUPPORTS, LEFT AND RIGHT						PKG		
55.040	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-11-17-02-01	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR SUPPORTS, LEFT AND RIGHT								
55.170	REF: AMM 55-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-11-19-01-01 (s)	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF FITTING FOR TRIM ACTUATOR, LEFT AND RIGHT						PKG		
55.045	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-11-19-02-01	HORIZONTAL STABILIZER, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF FITTING FOR TRIM ACTUATOR, LEFT AND RIGHT								
55.175	REF: AMM 55-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-20-01-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF ELEVATOR, LEFT AND RIGHT						PKG		
55.050	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-03-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF ELEVATOR BOX, INTERNAL, LEADING EDGE, SPAR BOX COMPOSITE PART, LEFT AND RIGHT						PKG		
55.055	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-05-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR SUPPORTS INCLUDING FASTENERS, LEFT AND RIGHT						PKG		
55.060	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-05-02-01	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR SUPPORTS INCLUDING FASTENERS, LEFT AND RIGHT								
55.180	REF: AMM 55-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-21-07-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR DRIVE SUPPORT, LEFT AND RIGHT						PKG		
55.065	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-07-02-01	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF ELEVATOR DRIVE SUPPORT, LEFT AND RIGHT								
55.185	REF: AMM 55-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-21-09-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF DRIVE SUPPORT COMPLETE AT TRIM TAB, LEFT AND RIGHT						PKG		
55.250	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
55-21-09-02-01	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF DRIVE SUPPORT COMPLETE AT TRIM TAB, LEFT AND RIGHT								
55.255	REF: AMM 55-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-21-11-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF TRIM TAB SUPPORTS, LEFT AND RIGHT						PKG		
55.070	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-11-02-01	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF TRIM TAB SUPPORTS, LEFT AND RIGHT								
55.190	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-21-13-01-01 (s)	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF TRIM TAB FITTINGS AND CONNECTING PARTS, LEFT AND RIGHT						PKG		
55.075	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-21-13-02-01	ELEVATOR, LEFT AND RIGHT - PERFORM DETAILED INSPECTION OF TRIM TAB FITTINGS AND CONNECTING PARTS, LEFT AND RIGHT								
55.195	REF: AMM 55-22-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-30-01-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF VERTICAL STABILIZER						PKG		
55.080	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-31-03-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF SPAR BOX, INTERNAL						PKG		
55.085	PKG 5 REF: AMM 05-25-55	MOS HRS/MSC AFL	60	+6m			08-JUN-2018 6504.7 6393		
+ 55-31-03-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF SPAR BOX, INTERNAL								
55.200	REF: AMM 53-63-01	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-31-07-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF REAR SPAR, REAR SIDE						PKG		
55.090	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-31-09-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF CONNECTING FITTING FOR FRONT SPAR						PKG		
55.095	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-31-09-02-01	VERTICLE STABILIZER - FRONT SPAR - PERFORM DETAILED INSPECTION OF CONNECTING FITTING FOR FRONT SPAR								
55.205	REF: AMM 53-63-20	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-31-11-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RIB 8, UPPER AREA								
55.210	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-31-13-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RIB 8, LOWER AREA								
55.210	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 55-31-15-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RUDDER SUPPORTS						PKG		
55.110	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-31-15-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RUDDER SUPPORTS								
55.215		MOS					27-FEB-2002		
	REF: AMM 53-63-70	HRS/MSC					0		
		AFL	20000				0		20000
+ 55-31-17-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF DAMPER SUPPORT						PKG		
55.115	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-55	HRS/MSC					5276.6		
		AFL					5873		
+ 55-31-17-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF DAMPER SUPPORT								
55.215		MOS					27-FEB-2002		
	REF: AMM 53-63-70	HRS/MSC					0		
		AFL	20000				0		20000
+ 55-31-19-01-01 (s)	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RUDDER CONTROL FITTING						PKG		
55.120	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-55	HRS/MSC					5276.6		
		AFL					5873		
55-31-19-02-01	VERTICAL STABILIZER - PERFORM DETAILED INSPECTION OF RUDDER CONTROL FITTING								
55.220		MOS					27-FEB-2002		
	REF: AMM 53-63-70	HRS/MSC					0		
		AFL	20000				0		20000
+ 55-40-01-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF RUDDER						PKG		
55.125	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: GENERIC NO REF	HRS/MSC					5276.6		
		AFL					5873		
+ 55-41-03-01-01 (s)	RUDDER - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE RUDDER BOX, INTERNAL						PKG		
55.130	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: See Workcard	HRS/MSC					5276.6		
		AFL					5873		
+ 55-41-05-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER SUPPORTS INCLUDING BOLTS						PKG		
55.135	PKG 6	MOS	120	+6m			11-FEB-2011		
	REF: AMM 05-25-55	HRS/MSC					5276.6		
		AFL					5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-41-05-02-01	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER SUPPORTS INCLUDING BOLTS								
55.225	REF: AMM 55-41-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-41-07-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER CONTROL FITTING								
55.140	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-41-07-02-01	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER CONTROL FITTING								
55.230	REF: AMM 55-41-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-41-09-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF THE RUDDER TRIM BLOCK								
55.145	PKG 6 REF: AMM 05-25-55	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-41-09-02-01	RUDDER - PERFORM DETAILED INSPECTION OF THE RUDDER TRIM BLOCK								
55.235	REF: AMM 55-41-60	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
55-41-15-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER TRIM TAB SUPPORTS AND CONNECTING PARTS								
55.150	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 55-41-15-02-01	RUDDER - PERFORM DETAILED INSPECTION OF RUDDER TRIM TAB SUPPORTS AND CONNECTING PARTS								
55.240	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 55-41-17-01-01 (s)	RUDDER - PERFORM DETAILED INSPECTION OF SPRING TAB SUPPORTS AND CONNECTING PARTS								
55.100	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 55-41-17-02-01	RUDDER - PERFORM DETAILED INSPECTION OF SPRING TAB SUPPORTS AND CONNECTING PARTS								
55.155	REF: See Workcard	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
CHAPTER 56 WINDOWS									
560001	L/H COCKPIT SIDE WINDOW								
	PN	MOS		TSN:0			27-FEB-2002		
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF:	AFL		TSN:0			0		
560002	R/H COCKPIT SIDE WINDOW								
	SPSD0328-3-2-1	MOS		TSN:0			11-JUL-2013		
	1336	HRS/MSC	O/C	TSN:0			5737.2		
	REF:	AFL		TSN:0			6076		
CHAPTER 57 WINGS									
57-00-00-02-01	FLAP SUPPORTS 3 AND 4 - MANDATORY RETROFIT OF FLAP SUPPORTS 3 AND 4, LEFT								
57.255	REF: GENERIC NO REF	MOS HRS/MSC AFL	8000	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		8000
MANDATORY									
57-00-00-02-01	FLAP SUPPORTS 3 AND 4 - MANDATORY RETROFIT OF FLAP SUPPORTS 3 AND 4, RIGHT								
57.255	REF: GENERIC NO REF	MOS HRS/MSC AFL	8000	TSI:0 TSI:0 TSI:0			27-FEB-2002 0 0		8000
MANDATORY									
57-00-03-02-01 (s)	WING - APPLICATION OF TEMPORARY PROTECTION SYSTEM (TPS) OF SPAR BOX ASSEMBLIES, RIB 0 TO RIB 11, EXTERNAL, LOWER PANEL, LEFT AND RIGHT, UNDER FAIRINGS						PKG		
	PKG 6	MOS	120				11-FEB-2011		
	REF:	HRS/MSC AFL					5276.6 5873		
+ 57-00-05-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF SPAR BOX ASSEMBLIES, INTERNAL, RIB 0 TO RIB 11 INBOARD, LEFT AND RIGHT						PKG		
57.015	REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011		
							5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-00-11-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF SPAR BOX ASSEMBLIES, INTERNAL, RIB 11 OUTBOARD TO RIB 19 INBOARD, LEFT AND RIGHT						PKG		
57.025	PKG 6 REF: AMM 57-11-00	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-00-17-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF SPAR BOX ASSEMBLIES, INTERNAL, RIB 19 OUTBOARD TO RIB 21 INBOARD, LEFT AND RIGHT						PKG		
57.035	PKG 6 REF:	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-00-23-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF WING TIP ASSEMBLIES, INTERNAL, FROM RIB 21 OUTBOARD, LEFT AND RIGHT						PKG		
57.045	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-00-25-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF WING FRONT SPAR INCLUDING ALL FITTINGS AND SUPPORTS, EXTERNAL, LEFT AND RIGHT, EXCLUDING AREA AT WING BOX						PKG		
57.050	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-00-27-01-01 (s)	WING - PERFORM DETAILED INSPECTION OF WING REAR SPAR, INCLUDING ALL FITTINGS AND SUPPORTS, EXTERNAL, LEFT AND RIGHT						PKG		
57.055	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-10-01-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE FORWARD Z-CONNECTIONS						PKG		
57.060	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-10-01-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE FORWARD Z-CONNECTIONS								
57.320	REF: AMM 57-11-99	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-03-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE REAR Z-CONNECTIONS						PKG		
57.020	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-10-03-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE REAR Z-CONNECTIONS								
57.320	REF: AMM 57-11-99	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
57-10-05-01-01A	CENTER WING, X-CONNECTIONS - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF X-STRUT CONNECTIONS								
	REF: NTM 57-10-05	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
57-10-05-02-01A (s)	WING, CENTER WING, X-CONNECTIONS - PERFORM DETAILED INSPECTION OF WING, CENTER WING "X" CONNECTIONS						PKG		
	PKG 5 REF: AMM 05-25-57	MOS HRS/MSC AFL	60		-61		08-JUN-2018 6504.7 6393		
57-10-07-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE FORWARD Y-CONNECTIONS						PKG		
57.030	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-10-07-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE FORWARD Y-CONNECTIONS								
57.325	REF: AMM 57-11-99	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
57-10-09-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE REAR Y-CONNECTIONS						PKG		
57.040	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
57-10-09-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF THE WING / FUSELAGE REAR Y-CONNECTIONS								
57.325	REF: AMM 57-11-99	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-01-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF Z / X-BRACKETS, FRONT SIDE, LEFT AND RIGHT						PKG		
57.075	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-01-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF Z / X-BRACKETS, FRONT SIDE, LEFT AND RIGHT								
57.330	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-11-03-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF Z / X-BRACKETS, REAR SIDE, LEFT AND RIGHT						PKG		
57.080	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-03-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF Z / X-BRACKETS, REAR SIDE, LEFT AND RIGHT								
57.330	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-11-05-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF Y-CONNECTION, FRONT SIDE						PKG		
57.085	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-05-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF Y-CONNECTION, FRONT SIDE								
57.335	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-11-07-01-01 (s)	CENTER WING - PERFORM DETAILED INSPECTION OF Y-CONNECTION, REAR SIDE						PKG		
57.090	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-07-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF Y-CONNECTION, REAR SIDE								
57.335	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-09-02-01	CENTER WING - TANK - INTERNAL - PERFORM DETAILED INSPECTION OF CENTER WING TANK, INTERNAL								
57.340		MOS					27-FEB-2002		
	REF: AMM 57-11-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 57-11-11-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF SPAR BOX, INTERNAL, RIB 11 TO RIB 19, LEFT AND RIGHT								
57.345		MOS					27-FEB-2002		
	REF: AMM 57-11-00	HRS/MSC					0		
		AFL	20000				0		20000
+ 57-11-13-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF WING, LOWER SKIN, CENTER, EXTERNAL								
57.270		MOS					27-FEB-2002		
	REF: AMM 57-11-10	HRS/MSC					0		
		AFL	20000				0		20000
57-11-13-03-01	WING, LOWER SKIN; CENTER AT TRAILING EDGE 3 TO 9 LH/RH - PERFORM SPECIAL DETAILED INSPECTION OF LOWER SKIN, CENTER AT TAILING EDGE RIB 3 TO 9 LH/RH								
57.435		MOS					08-APR-2013		
	REF: NTM 57-11-13	HRS/MSC					5700.2		
		AFL	1500				6053		7553
57-11-13-04-01	WING, LOWER SKIN; CENTER AT TRAILING EDGE 3 TO 9 LH/RH - PERFORM SPECIAL DETAILED INSPECTION OF LOWER SKIN, CENTER AT TAILING EDGE RIB 3 TO 9 LH/RH								
57.440		MOS					27-FEB-2002		
	REF: NTM 57-11-13	HRS/MSC					0		
		AFL	20000				0		20000
+ 57-11-15-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF OUTER WING, LOWER SKIN EXTERNAL, LEFT AND RIGHT								
57.275		MOS					27-FEB-2002		
	REF: AMM 57-11-10	HRS/MSC					0		
		AFL	20000				0		20000
+ 57-11-17-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF FRONT SPAR, CENTER WING INCLUDING JOINT, LEFT AND RIGHT								
57.350		MOS					27-FEB-2002		
	REF: AMM 57-11-20	HRS/MSC					0		
		AFL	20000				0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-19-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF FRONT SPAR, OUTER WING , LEFT AND RIGHT, EXTERNAL								
57.280		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-21-20								
+ 57-11-20-01-01 (s)	CENTER WING - BRIDGE - PERFORM DETAILED INSPECTION OF BRIDGE, INCLUDING FORWARD BRACKETS AND BOLTS, LEFT AND RIGHT								
57.160	PKG 6	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
	REF: AMM 05-25-54								
+ 57-11-20-02-01	CENTER WING -BRIDGE - PERFORM DETAILED INSPECTION OF BRIDGE, INCLUDING FORWARD BRACKETS AND BOLTS, LEFT AND RIGHT								
57.285		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-11-60								
+ 57-11-21-02-01	CENTER WING - PERFORM DETAILED INSPECTION OF CENTER WING, REAR SPAR INCLUDING JOINT, LEFT AND RIGHT								
57.355		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-11-20								
+ 57-11-22-01-01	CENTER WING - BRIDGE - PERFORM DETAILED INSPECTION OF BRIDGE, BOLT AND SLEEVE, LEFT AND RIGHT								
57.290		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-11-60								
+ 57-11-23-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF OUTER REAR SPAR, LEFT AND RIGHT								
57.360		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-21-20								
+ 57-11-25-02-01	WING - PERFORM GENERAL VISUAL INSPECTION OF WING UPPER SKIN, COMPLETE, LEFT AND RIGHT								
57.295		MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
	REF: AMM 57-11-10								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-27-02-01	WING - JOINTS - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF SKIN, UPPER AND LOWER JOINTS								
57.300	REF: NTM 57-11-27	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-11-29-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF THE LEFT AND RIGHT SPAR BOX, DRY SECTION, INTERNAL								
57.120	REF: AMM 57-21-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-11-31-01-01 (s)	WING - FLAP SUPPORT 1 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 1, LEFT AND RIGHT								
57.125	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-31-02-01	WING - FLAP SUPPORT 1 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 1, LEFT AND RIGHT								
57.365	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-11-33-01-01 (s)	WING - FLAP SUPPORT 2 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 2, LEFT AND RIGHT								
57.130	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-33-02-01	WING - FLAP SUPPORT 2 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 2, LEFT AND RIGHT								
57.365	REF: AMM 57-11-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-11-35-01-01 (s)	WING - FLAP SUPPORT 3 AND 4 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 3 AND 4, LEFT AND RIGHT								
57.135	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-35-02-01	WING - FLAP SUPPORTS 3 AND 4 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 3 AND 4, LEFT AND RIGHT								
57.370	REF: AMM 57-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-11-37-01-01 (s)	WING - AILERON SUPPORTS 1, 2, 3 AND 4 - PERFORM DETAILED INSPECTION OF AILERON SUPPORTS 1, 2, 3 AND 4, LEFT AND RIGHT						PKG		
57.140	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-37-02-01	WING - AILERON SUPPORTS 1, 2, 3 AND 4 - PERFORM DETAILED INSPECTION OF AILERON SUPPORTS 1, 2, 3 AND 4, LEFT AND RIGHT								
57.375	REF: AMM 57-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-11-39-01-01 (s)	WING - GROUND SPOILER SUPPORTS - PERFORM DETAILED INSPECTION OF GROUND SPOILER SUPPORTS, LEFT AND RIGHT						PKG		
57.145	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-39-02-01	WING - GROUND SPOILER SUPPORTS - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF GROUND SPOILER SUPPORTS, LEFT AND RIGHT								
57.380	REF: See Workcard	MOS HRS/MSC AFL	15000				27-FEB-2002 0 0	15000	
57-11-39-03-01	WING - GROUND SPOILER SUPPORTS - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF GROUND SPOILER SUPPORTS, LEFT AND RIGHT								
	REF:	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-11-41-01-01 (s)	WING - ROLL SPOILER SUPPORTS - PERFORM DETAILED INSPECTION OF ROLL SPOILER SUPPORTS, LEFT AND RIGHT						PKG		
57.150	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-11-41-02-01	WING - ROLL SPOILER SUPPORTS - PERFORM DETAILED INSPECTION OF ROLL SPOILER SUPPORTS, LEFT AND RIGHT								
57.385	REF: AMM 57-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-11-41-04-01	WING - FLIGHT SPOILER SUPPORTS - PERFORM DETAILED INSPECTION OF FLIGHT SPOILER SUPPORTS, LEFT AND RIGHT								
57.070	REF: AMM 57-21-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-11-43-02-01	OUTER WING - PERFORM DETAILED INSPECTION OF SPAR BOX BETWEEN RIB 19 AND RIB 21 (LEFT AND RIGHT FEEDER TANK INTERNAL) INTERNAL								
57.395	REF: AMM 57-21-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-60-03-01-01 (s)	AILERONS - INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF AILERON, INTERNAL, LEFT AND RIGHT								
57.170	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
+ 57-60-05-01-01 (s)	AILERONS - HINGES - PERFORM DETAILED INSPECTION OF AILERON HINGES, LEFT AND RIGHT								
57.175	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
+ 57-60-05-02-01	AILERONS - HINGES - PERFORM DETAILED INSPECTION OF AILERON HINGES, LEFT AND RIGHT								
57.400	REF: AMM 57-61-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-60-07-01-01 (s)	AILERONS - DRIVE FITTING - PERFORM DETAILED INSPECTION OF DRIVE FITTING, LEFT AND RIGHT								
57.180	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873	PKG	
+ 57-60-07-02-01	AILERON DRIVE FITTING - PERFORM DETAILED INSPECTION OF DRIVE FITTING, LEFT AND RIGHT								
57.405	REF: AMM 57-61-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-60-09-01-01 (s)	AILERONS - TRIM TAB - PERFORM DETAILED INSPECTION OF TRIM TAB WITH SUPPORT AND BOLT, LEFT AND RIGHT						PKG		
57.185	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-60-09-02-01	AILERON - TRIM TAB - PERFORM DETAILED INSPECTION OF TRIM TAB WITH SUPPORT AND BOLT, LEFT AND RIGHT								
57.410	REF: AMM 57-62-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-61-01-01-01 (s)	AILERON ASSEMBLY - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF AILERON ASSEMBLY, LEFT AND RIGHT						PKG		
57.190	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-70-01-01-01 (s)	GROUND SPOILER - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF GROUND SPOILER ASSEMBLY, LEFT AND RIGHT						PKG		
57.195	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-70-03-01-01 (s)	ROLL SPOILER ASSEMBLY - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF ROLL SPOILER ASSEMBLIES, LEFT AND RIGHT						PKG		
57.200	PKG 6 REF: AMM 57-21-70	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-71-01-01-01	GROUND SPOILER - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF GROUND SPOILER, LEFT AND RIGHT								
57.210	REF: NTM 57-71-01	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-71-01-03-01	GROUND SPOILER SUPPORTS - PERFORM DETAILED INSPECTION OF GROUND SPOILER SUPPORTS, LEFT AND RIGHT								
57.415	REF: AMM 57-71-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-71-01-04-01 (s)	GROUND SPOILER - PERFORM DETAILED INSPECTION OF GROUND SPOILER, EXTERNAL, LEFT AND RIGHT						PKG		
57.305	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-71-03-02-01	ROLL SPOILER - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF ROLL SPOILER HINGES, LEFT AND RIGHT								
57.310	REF: NTM 57-71-03	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-80-01-02-01	FLAPS - PERFORM GENERAL VISUAL INSPECTION OF FLAP, LEFT AND RIGHT EXTERNAL								
57.315	REF: AMM 57-81-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-80-03-01-01 (s)	FLAPS - INTERNAL - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF FLAPS INTERNAL, LEFT AND RIGHT						PKG		
57.215	PKG 6 REF: See Workcard	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-80-05-01-01 (s)	FLAPS - SUPPORT 1 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 1 (FLAP SIDE), LEFT AND RIGHT						PKG		
57.220	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-80-05-02-01	FLAP SUPPORT 1 - PERFORM DETAILED INSPECTION OF FLAP SUPPORT 1 (FLAP SIDE), LEFT AND RIGHT								
57.420	REF: AMM 57-81-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000
+ 57-80-07-01-01 (s)	FLAPS - SUPPORT 2 - PERFORM DETAILED INSPECTION OF THE FLAP SUPPORT 2 (FLAP SIDE), LEFT AND RIGHT						PKG		
57.225	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-80-07-02-01	FLAP SUPPORT 2 - PERFORM DETAILED INSPECTION OF THE FLAP SUPPORT 2 (FLAP SIDE), LEFT AND RIGHT								
57.420	REF: AMM 57-81-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0		20000

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 57-80-09-01-01 (s)	FLAPS - SUPPORTS 3 AND 4 - PERFORM DETAILED INSPECTION OF THE FLAP SUPPORTS 3 AND 4 (FLAP SIDE), LEFT AND RIGHT						PKG		
57.230	PKG 6 REF: AMM 05-25-57	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 57-80-09-02-01	FLAPS SUPPORTS 3 AND 4 - PERFORM DETAILED INSPECTION OF THE FLAP SUPPORTS 3 AND 4 (FLAP SIDE), LEFT AND RIGHT								
57.425	REF: AMM 57-81-70	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 57-81-01-01-01 (s)	FLAP ASSEMBLY - PERFORM DETAILED INSPECTION OF METALLIC COMPONENTS OF FLAP ASSEMBLIES, LEFT AND RIGHT						PKG		
57.235	PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
CHAPTER 71 POWER PLANT									
+ 71-00-00-01-01	LEFT ENGINE FORWARD ISOLATOR INBOARD - REPLACE LEFT ENGINE FORWARD ISOLATOR INBOARD ELASTOMER COMPONENTS P/N 96052-01								
71.030 LIFE LIMIT	REF: See Workcard	MOS HRS/MSC AFL	10000 13000				15-JAN-2008 5233.9 5854	15233.9 18854	
71-00-00-01-02	LEFT ENGINE FORWARD ISOLATOR OUTBOARD - REPLACE LEFT ENGINE FORWARD ISOLATOR OUTBOARD ELASTOMER COMPONENTS P/N 96052-01								
71.030 LIFE LIMIT	REF: See Workcard	MOS HRS/MSC AFL	10000 13000		TSI:0 TSI:0 TSI:0		27-FEB-2002 4377.4 4856	10931.9 14649	
71-00-00-01-03	RIGHT ENGINE FORWARD ISOLATOR INBOARD - REPLACE RIGHT ENGINE FORWARD ISOLATOR INBOARD ELASTOMER COMPONENTS P/N 96052-01								
71.035 LIFE LIMIT	REF: See Workcard	MOS HRS/MSC AFL	10000 13000		TSI:0 TSI:0 TSI:0		15-JAN-2008 5233.3 5854	15233.3 18854	
71-00-00-01-04	RIGHT ENGINE FORWARD ISOLATOR OUTBOARD - REPLACE RIGHT ENGINE FORWARD ISOLATOR OUTBOARD ELASTOMER COMPONENTS P/N 96052-01								
71.035 LIFE LIMIT	REF: See Workcard	MOS HRS/MSC AFL	10000 13000				15-JAN-2008 5233.9 5854	15233.9 18854	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-00-00-03-01 (s)	NACELLE ANTI-ICE VALVE - MANDATORY RETROFIT OF NACELLE ANTI-ICE INSTALLATION OF INSULATION BLANKET(PRIOR TO DEC. 31/2008)	MOS					07-APR-2008		
	REF:	HRS/MSC - AFL					5233.9 5854		
71-00-00-05-01	LEFT ENGINE REAR ISOLATOR - REPLACE LEFT ENGINE REAR ISOLATOR ELASTOMER COMPONENTS P/N 96052-04	MOS					27-FEB-2002		
LIFE LIMIT	REF: GENERIC NO REF	HRS/MSC AFL	10000 13000				4768.4 4		9384.4 13004
71-00-00-05-02	RIGHT ENGINE REAR ISOLATOR - REPLACE RIGHT ENGINE REAR ISOLATOR ELASTOMER COMPONENTS P/N 96052-04	MOS					27-FEB-2002		
LIFE LIMIT	REF:	HRS/MSC AFL	10000 13000				5233.3 5854		14529.8 18032
+ 71-10-00-01-01 (s)	LEFT ENGINE COWLING - PERFORM DETAILED INSPECTION OF LEFT ENGINE COWLING, DOORS, FIRE WALLS AND FIRE SEALS FOR CONDITION						PKG		
71.025	PKG 4	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
REF:	See Workcard								
+ 71-10-00-01-02 (s)	RIGHT ENGINE COWLING - PERFORM DETAILED INSPECTION OF RIGHT ENGINE COWLING, DOORS, FIRE WALLS AND FIRE SEALS FOR CONDITION						PKG		
71.025	PKG 4	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
REF:	See Workcard								
+ 71-20-00-01-01 (s)	LEFT ENGINE MOUNTS - PERFORM DETAILED INSPECTION OF LEFT ENGINE MOUNTS / ISOLATORS FOR CONDITION						PKG		
71.045	PKG 4	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
REF:	AMM 71-20-00								
+ 71-20-00-01-02 (s)	RIGHT ENGINE MOUNTS - PERFORM DETAILED INSPECTION OF RIGHT ENGINE MOUNTS / ISOLATORS FOR CONDITION						PKG		
71.045	PKG 4	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
REF:	AMM 71-20-00								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 71-21-11-01-01	ENGINE MOUNTS, LEFT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE FORWARD YOKE ASSEMBLY BOTTOM AND TOP CAP, LEFT								
71.070	REF: NTM 71-21-11	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 71-21-11-01-02	ENGINE MOUNTS, RIGHT - PERFORM SPECIAL DETAILED INSPECTION (EDDY CURRENT) OF THE FORWARD YOKE ASSEMBLY BOTTOM AND TOP CAP, RIGHT								
71.085	REF: NTM 71-21-11	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 71-21-12-01-01 (s)	ENGINE MOUNTS, LEFT - PERFORM DETAILED INSPECTION OF LEFT ENGINE MOUNTS, FORWARD MOUNT YOKE INCLUSIVE BOLTS AND SHOCK MOUNTS						PKG		
71.090	PKG 6 REF: AMM 05-25-72	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
71-21-12-01-02 (s)	ENGINE MOUNTS, RIGHT - PERFORM DETAILED INSPECTION OF RIGHT ENGINE MOUNTS, FORWARD MOUNT YOKE INCLUSIVE BOLTS AND SHOCK MOUNTS						PKG		
	PKG 6 REF:	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		
+ 71-21-12-02-01	ENGINE MOUNTS, LEFT - PERFORM DETAILED INSPECTION OF LEFT ENGINE MOUNTS, FORWARD MOUNT YOKE INCLUSIVE BOLTS AND SHOCK MOUNTS								
71.095	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 71-21-12-02-02	ENGINE MOUNTS, RIGHT - PERFORM DETAILED INSPECTION OF RIGHT ENGINE MOUNTS, FORWARD MOUNT YOKE INCLUSIVE BOLTS AND SHOCK MOUNTS								
71.095	REF: AMM 71-20-00	MOS HRS/MSC AFL	20000				27-FEB-2002 0 0	20000	
+ 71-21-13-01-01 (s)	ENGINE MOUNTS, LEFT - PERFORM DETAILED INSPECTION OF REAR YOKE ASSEMBLY INCLUDING BOLTS, LEFT						PKG		
71.075	PKG 6 REF: AMM 05-25-72	MOS HRS/MSC AFL	120	+6m			11-FEB-2011 5276.6 5873		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-21-13-01-02 (s)	ENGINE MOUNTS, RIGHT - PERFORM DETAILED INSPECTION OF REAR YOKE ASSEMBLY INCLUDING BOLTS, RIGHT PKG 6	MOS	120	+6m			PKG 11-FEB-2011 5276.6 5873		
	REF:	AFL					5873		
+ 71-21-13-02-01	ENGINE MOUNTS, LEFT - PERFORM DETAILED INSPECTION OF REAR YOKE ASSEMBLY INCLUDING BOLTS, LEFT	MOS					27-FEB-2002		
71.100	REF: AMM 71-20-10	HRS/MSC AFL	20000				0 0		20000
+ 71-21-13-02-02	ENGINE MOUNTS, RIGHT - PERFORM DETAILED INSPECTION OF REAR YOKE ASSEMBLY INCLUDING BOLTS, RIGHT	MOS					27-FEB-2002		
71.100	REF: AMM 71-20-10	HRS/MSC AFL	20000				0 0		20000
+ 71-21-14-01-01	ENGINE MOUNTS, LEFT - PERFORM DETAILED INSPECTION) OF REAR YOKE ASSEMBLY BRACKETS, LEFT	MOS					27-FEB-2002		
71.105	REF: AMM 71-20-10	HRS/MSC AFL	20000				0 0		20000
+ 71-21-14-01-02	ENGINE MOUNTS, RIGHT - PERFORM DETAILED INSPECTION OF REAR YOKE ASSEMBLY BRACKETS, RIGHT	MOS					27-FEB-2002		
71.105	REF: AMM 71-20-10	HRS/MSC AFL	20000				0 0		20000
71EN1	NO. 1 ENGINE								
71.EN1	4HFR34C768 CD-0233 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C				27-AUG-2012 5649 6013		
							TSO:5924.6 TSO:6011		
71EN2	NO. 2 ENGINE								
71.EN2	4HFR34C768 CD-0237 REF: GENERIC NO REF	MOS HRS/MSC AFL	E/C				27-AUG-2012 5649 6013		
							TSO:5934.7 TSO:6086		
ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B									
71-30-00-01-01	NO. 1 ENGINE - INNER CORE COWL DETAILED INSPECTION	MOS	120	+6m			16-APR-2008	16-APR-2018	16-OCT-2018
	REF:	HRS/MSC ENC					5086.9 5659		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
710000	NO. 1 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC - ENC					07-APR-2017 6379.7 6274		
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
71-30-00-01-01	NO. 2 ENGINE - INNER CORE COWL DETAILED INSPECTION REF:	MOS HRS/MSC ENC	120	+6m			16-APR-2008 5096.9 5734	16-APR-2018	16-OCT-2018
710000	NO. 2 ENGINE - COMPRESSOR WASH REF: EMM 71-00-00	MOS HRS/MSC - ENC					07-APR-2017 6281.9 6211		
CHAPTER 72 ENGINE									
+ 72-30-00-01-01 (s)	LEFT ENGINE FAN - PERFORM DETAILED INSPECTION OF LEFT ENGINE FAN ASSY FOR EVIDENCE OF DISTRESS OR CONTAMINATION PKG 3 REF: See Workcard	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367	PKG	
72.010									
+ 72-30-00-01-02 (s)	RIGHT ENGINE FAN - PERFORM DETAILED INSPECTION OF RIGHT ENGINE FAN ASSY FOR EVIDENCE OF DISTRESS OR CONTAMINATION PKG 3 REF: See Workcard	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367	PKG	
72.010									
+ 72-30-00-03-01 (s)	LEFT ENGINE FAN CASE - PERFORM DETAILED INSPECTION OF LEFT ENGINE FAN CASE AND INTAKE FOR INTEGRITY OF FAN EXIT STATOR, ABRADABLE LINING AND HONEYCOMB INTEGRITY PKG 2 REF: See Workcard	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425	PKG	
72.015									
+ 72-30-00-03-02 (s)	RIGHT ENGINE FAN CASE - PERFORM DETAILED INSPECTION OF RIGHT ENGINE FAN CASE AND INTAKE FOR INTEGRITY OF FAN EXIT STATOR, ABRADABLE LINING AND HONEYCOMB INTEGRITY PKG 2 REF: See Workcard	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425	PKG	
72.015									

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-30-00-07-01 (s)	LEFT ENGINE FAN CASE - PERFORM DETAILED INSPECTION OF LEFT ENGINE FAN CASE EXTERIOR						PKG		
72.025	PKG 4 REF: AMM 72-30-10	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 72-30-00-07-02 (s)	RIGHT ENGINE FAN CASE - PERFORM DETAILED INSPECTION OF RIGHT ENGINE FAN CASE EXTERIOR						PKG		
72.025	PKG 4 REF: AMM 72-30-10	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 72-32-00-03-01 (s)	LEFT ENGINE AGB POP-UP INDICATOR - PERFORM GENERAL VISUAL INSPECTION OF LEFT ENGINE AUXILIARY GEAR BOX (AGB) DIFFERENTIAL OIL OVER-PRESSURE POP-UP INDICATOR						PKG		
72.085	PKG 1 REF: AMM 79-10-02	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 72-32-00-03-02 (s)	RIGHT ENGINE AGB POP-UP INDICATOR - PERFORM GENERAL VISUAL INSPECTION OF RIGHT ENGINE AUXILIARY GEAR BOX (AGB) DIFFERENTIAL OIL OVER-PRESSURE POP-UP INDICATOR						PKG		
72.085	PKG 1 REF: AMM 79-10-02	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
72-50-00-01D-01	LEFT ENGINE HIGH PRESSURE (HP) TURBINE - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF 1ST STAGE HP TURBINE BLADES								
	REF: AMM 72-02-07	MOS HRS/MSC AFL	2000				01-OCT-2015 5924.6 6011	7924.6 8011	
72-50-00-01D-02	RIGHT ENGINE HIGH PRESSURE (HP) TURBINE - PERFORM SPECIAL DETAILED INSPECTION (BORESCOPE) OF 1ST STAGE HP TURBINE BLADES								
	REF: AMM 72-02-07	MOS HRS/MSC AFL	2000				01-OCT-2015 5934.7 6086	7934.7 8086	
+ 72-50-00-03-01 (s)	LEFT ENGINE EXHAUST - PERFORM DETAILED INSPECTION FROM REAR OF LEFT ENGINE OF TURBINE EXHAUST CASE AND EXHAUST CONE FOR EVIDENCE OF STRESS OR DAMAGE						PKG		
72.060	PKG 4 REF: AMM 78-20-05	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 72-50-00-03-02 (s)	RIGHT ENGINE EXHAUST - PERFORM DETAILED INSPECTION FROM REAR OF RIGHT ENGINE OF TURBINE EXHAUST CASE AND EXHAUST CONE FOR EVIDENCE OF STRESS OR DAMAGE						PKG		
72.060	PKG 4 REF: AMM 78-20-05	MOS HRS/MSC AFL	30	+2m			01-DEC-2017 6428.4 6367		
+ 72-50-00-14-01 (s)	LEFT ENGINE EMERGENCY FUEL SHUT-OFF - PERFORM DETAILED INSPECTION OF LEFT ENGINE EMERGENCY FUEL SHUT-OFF VALVE LINKAGE MECHANISM						PKG		
72.070	PKG 4 REF: AMM 73-10-19	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
72-50-00-14-02 (s)	RIGHT ENGINE EMERGENCY FUEL SHUT-OFF - PERFORM DETAILED INSPECTION OF RIGHT ENGINE EMERGENCY FUEL SHUT-OFF VALVE LINKAGE MECHANISM						PKG		
	PKG 4 REF:	MOS HRS/MSC AFL	30				01-DEC-2017 6428.4 6367		
+ 72-50-00-15-01 (s)	LEFT ENGINE EMERGENCY FUEL SHUT-OFF - PERFORM DETAILED INSPECTION OF LEFT ENGINE LP SHAFT SHEAR PROTECTION MECHANISM FOR OIL LEAKS						PKG		
72.075	PKG 4 REF: AMM 73-10-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
+ 72-50-00-15-02 (s)	RIGHT ENGINE EMERGENCY FUEL SHUT-OFF - PERFORM DETAILED INSPECTION OF RIGHT ENGINE LP SHAFT SHEAR PROTECTION MECHANISM FOR OIL LEAKS						PKG		
72.075	PKG 4 REF: AMM 73-10-20	MOS HRS/MSC AFL	30	+4m			01-DEC-2017 6428.4 6367		
ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B									
72-30-00-01-01 (s)	NO. 1 ENGINE - FAN ASSEMBLY DETAILED INSPECTION						PKG		
	PKG 3 REF:	MOS HRS/MSC ENC	15	+1m			01-DEC-2017 6459.5		
72-30-00-03-01	NO. 1 ENGINE - FAN CASE & INTAKE INSPECTION								
	REF:	MOS HRS/MSC ENC	12	+1m	-321		07-APR-2017 6369.7	07-APR-2018	M 07-MAY-2018

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-32-00-01-01	NO. 1 ENGINE - HP COMPRESSOR BORESCOPE INSPECTION	MOS					31-JUL-2007		
	REF:	HRS/MSC	6000	+400			5187	(11187) 11156	11587
		ENC					5715		
72-50-00-02B-01	NO. 1 ENGINE - LP TURBINE SECTION BORESCOPE INSPECTION	MOS					31-JUL-2007		
	REF:	HRS/MSC	6000	+400			5187	(11187) 11156	11587
		ENC					5715		
72-50-00-03-01 (s)	NO. 1 ENGINE - TURBINE EXHAUST CASE & CONE INSPECTION	MOS	30	+2m			21-MAY-2015		
	REF:	HRS/MSC					5924.6		
		ENC					6011		
72-50-00-14-01 (s)	NO. 1 ENGINE - EMERGENCY FUEL SHUT-OFF VALVE LINKAGE MECHANISM INSP	MOS	48	+4m			21-MAY-2015		
	REF:	HRS/MSC					5924.6		
		ENC					6011		
72-50-00-15-01 (s)	NO. 1 ENGINE - LP SHAFT SHEAR PROTECTION MECHANISM INSPECTION	MOS	48	+4m			21-MAY-2015		
	REF:	HRS/MSC					5924.6		
		ENC					6011		
720000	NO. 1 ENGINE - CENTRIFUGAL IMPELLER	MOS					06-MAR-2008		
	30B4796-01	HRS/MSC	-		TSN:0		5186.9		
	A0029YE0	ENC	6000		TSN:0		5715	(11715) 11836	
LIFE LIMIT	REF: See Workcard				TSN:0				
720005	NO. 1 ENGINE - FAN HUB	MOS					04-FEB-2002		
	30B4080-01	HRS/MSC	-		TSN:0		0		
	A000YP59	ENC	14000		TSN:0		0	(14000) 14121	
LIFE LIMIT	REF: See Workcard				TSN:0				
720010	NO. 1 ENGINE - HP COMPRESSOR (STAGE 1) ROTOR	MOS					04-FEB-2002		
	30B3951-01	HRS/MSC	-		TSN:0		0		
	A000YCDM	ENC	15000		TSN:0		0	(15000) 15121	
LIFE LIMIT	REF: See Workcard				TSN:0				

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720015	NO. 1 ENGINE - LP COMPRESSOR SHAFT 30B3897-01 57A103 REF: See Workcard	MOS HRS/MSC - ENC	- 30000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(30000) 30121
720025	NO. 1 ENGINE - OVERHAUL ENGINE REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0		(10000) 9969
720027	NO. 1 ENGINE - (AGB) ACCESSORY GEARBOX PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(10000) 9969
720030	NO. 1 ENGINE - HOT SECTION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	3000	+250			31-JUL-2007 5186.6 5715	(8186.6) 8155.6	8436.6
720060	NO. 1 ENGINE - HP TURBINE ROTOR REAR COVER 30B4012-01 A000X3X2 REF: See Workcard	MOS HRS/MSC - ENC	- 15000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(15000) 15121
720065	NO. 1 ENGINE - HP TURBINE ROTOR FRONT COVER 30B6202-01 A0029AP5 REF: See Workcard	MOS HRS/MSC - ENC	- 15000	TSN:0 TSN:0 TSN:0			08-MAR-2008 5186.9 5715		(20715) 20836
720070	NO. 1 ENGINE - 1ST-STAGE HP TURBINE DISK 30B6351-01 A002A5E1 REF: See Workcard	MOS HRS/MSC - ENC	- 15000	TSN:0 TSN:0 TSN:0			06-MAR-2008 5186.9 5715		(20715) 20836
720075	NO. 1 ENGINE - 2ND-STAGE HP TURBINE DISK 30B4542-01 A0010T57 REF: See Workcard	MOS HRS/MSC ENC	10000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(10000) 10121

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720080	NO. 1 ENGINE - 3RD-STAGE LP TURBINE DISK 30A2303 72B178 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(15000) 15121
720085	NO. 1 ENGINE - 4TH-STAGE LP TURBINE DISK 30A2304 73B975 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(15000) 15121
720090	NO. 1 ENGINE - 5TH-STAGE LP TURBINE DISK 30A2305 72B388 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(15000) 15121
720095	NO. 1 ENGINE - HP TURBINE ROTOR AIR SEAL 31B6205-01 WG001383 REF: See Workcard	MOS HRS/MSC ENC	15000	TSN:0 TSN:0 TSN:0			04-FEB-2002 0 0		(15000) 15121
720125	NO. 1 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES REF: EMM 72-00-00	MOS HRS/MSC ENC	1600		5186.9		06-MAR-2008 5186.9 5715		(6786.9) 6755.9 M
720135	NO. 1 ENGINE - BORESCOPE INSPECTION SECOND-STAGE HP TURBINE BLADES REF: EMM 72-00-00	MOS HRS/MSC ENC	2400				31-JUL-2007 5186.6 5715		(7586.6) 7555.6
720180	NO. 1 ENGINE - BORESCOPE INSPECTION HP TURBINE L SEAL REF: EMM 72-00-00	MOS HRS/MSC ENC	1200				31-JUL-2007 5187 5715		(6387) 6356
720190	NO. 1 ENGINE - BORESCOPE INSPECTION COMBUSTION CHAMBER LINER REF: EMM 72-00-00	MOS HRS/MSC ENC	6000				31-JUL-2007 5187 5715		(11187) 11156

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721122	NO. 1 ENGINE - VISUAL INSPECTION EXTERNAL OIL TUBES, INCLUDING NO. 4 BRG. TUBES, AGB COVER AND SEALS. REF: GENERIC NO REF	MOS HRS/MSC ENC	1000				01-DEC-2017 6459.5	(7459.5) 7428.5	
721123	NO. 1 ENGINE - VISUAL CHECK WIRING HARNESSSES FOR CONDITION AND SECURITY OF ACCESSIBLE HARNESSSES REF: GENERIC NO REF	MOS HRS/MSC ENC	800				04-MAR-2016 6090.5 6076	(6890.5) 6859.5	
721125	NO. 1 ENGINE - CHECK LP COMPRESSOR FAN BLADES FOR EROSION OF OUTER 3 INCHES OF THE LE REF: EMM 72-30-01	MOS HRS/MSC ENC	500				11-AUG-2016 6300.8 6168	(6800.8) 6769.8	
721126	NO. 1 ENGINE - VISUAL INSPECTION FAN AND NOSE CONE REF: EMM 72-30-01	MOS HRS/MSC ENC	1000				11-AUG-2016 6300.8 6168	(7300.8) 7269.8	
721127	NO. 1 ENGINE - VISUAL INSPECTION OUTER BYPASS DUCTS REF: EMM 72-70-01	MOS HRS/MSC ENC	2000				07-MAR-2008 5186.9 5715	(7186.9) 7155.9	
721128	NO. 1 ENGINE - VISUAL INSPECTION FAN SOUND ABSORBING LINER SEGMENT AND EXIT VANES REF: EMM 72-30-01	MOS HRS/MSC ENC	1000				11-AUG-2016 6300.8 6168	(7300.8) 7269.8	
721129	NO. 1 ENGINE - CHECK AGB HOUSING AND MOUNTS REF: GENERIC NO REF	MOS HRS/MSC ENC	2000				07-MAR-2008 5186.9 5715	(7186.9) 7155.9	
721130	NO. 1 ENGINE - VISUAL INSPECTION EXHAUST MIXER REF: GENERIC NO REF	MOS HRS/MSC ENC	2500				01-DEC-2017 6459.5	(8959.5) 8928.5	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721133 (s)	NO. 1 ENGINE - VISUAL INSPECTION FAN CASE EXTERIOR PKG 4	MOS HRS/MSC ENC	24				PKG 01-DEC-2017 6459.5		
	REF: EMM 72-30-01								
721134	NO. 1 ENGINE - VISUALLY CHECK FAN AREA FOR OIL LEAKS	MOS HRS/MSC ENC	500				01-DEC-2017 6459.5	(6959.5) 6928.5	
	REF: GENERIC NO REF								
+ 726001	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - AC GENERATOR (PMA)	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
	REF: GENERIC NO REF								
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
72-30-00-01-01 (s)	NO. 2 ENGINE - FAN ASSEMBLY DETAILED INSPECTION PKG 3	MOS HRS/MSC ENC	15	+1m			PKG 01-DEC-2017 6469.5		
	REF:								
72-30-00-03-01	NO. 2 ENGINE - FAN CASE & INTAKE INSPECTION	MOS HRS/MSC ENC	12	+1m	-321		07-APR-2017 6379.7 6274	07-APR-2018 M 07-MAY-2018	
	REF:								
72-32-00-01-01	NO. 2 ENGINE - HP COMPRESSOR BORESCOPE INSPECTION	MOS HRS/MSC ENC	6000	+400			01-AUG-2007 5197 5790	(11197) 11155.9 11597	
	REF:								
72-50-00-02B-01	NO. 2 ENGINE - LP TURBINE SECTION BORESCOPE INSPECTION	MOS HRS/MSC ENC	6000	+400			01-AUG-2007 5197 5790	(11197) 11155.9 11597	
	REF:								
72-50-00-03-01 (s)	NO. 2 ENGINE - TURBINE EXHAUST CASE & CONE INSPECTION	MOS HRS/MSC ENC	30	+2m			21-MAY-2015 5934.7 6086		
	REF:								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-50-00-14-01 (s)	NO. 2 ENGINE - EMERGENCY FUEL SHUT-OFF VALVE LINKAGE MECHANISM INSP	MOS	48	+4m			21-MAY-2015		
	REF:	HRS/MSC					5934.7		
		ENC					6086		
72-50-00-15-01 (s)	NO. 2 ENGINE - LP SHAFT SHEAR PROTECTION MECHANISM INSPECTION	MOS	48	+4m			21-MAY-2015		
	REF:	HRS/MSC					5934.7		
		ENC					6086		
720000	NO. 2 ENGINE - CENTRIFUGAL IMPELLER	MOS					08-MAR-2008		
	30B4796-01	HRS/MSC		TSN:0			1005.2		
	A002A5A9	ENC	-	TSN:0			1989		(7989) 8036
LIFE LIMIT	REF: See Workcard		6000	TSN:0					
720005	NO. 2 ENGINE - FAN HUB	MOS					24-JAN-2002		
	30B4080-01	HRS/MSC		TSN:0			0		
	A000Y08A	ENC	-	TSN:0			0		(14000) 14047
LIFE LIMIT	REF: See Workcard		14000	TSN:0					
720010	NO. 2 ENGINE - HP COMPRESSOR (STAGE 1) ROTOR	MOS					24-JAN-2002		
	30B3951-01	HRS/MSC		TSN:0			0		
	A000Y1A4	ENC	-	TSN:0			0		(15000) 15047
LIFE LIMIT	REF: See Workcard		15000	TSN:0					
720015	NO. 2 ENGINE - LP COMPRESSOR SHAFT	MOS					24-JAN-2002		
	30B3897-01	HRS/MSC		TSN:0			0		
	61A660	ENC	-	TSN:0			0		(30000) 30047
LIFE LIMIT	REF: See Workcard		30000	TSN:0					
720025	NO. 2 ENGINE - OVERHAUL ENGINE	MOS					24-JAN-2002		
		HRS/MSC	10000	TSI:0			0		(10000) 9958.9
	REF: GENERIC NO REF	ENC		TSI:0			0		
OVERHAUL				TSI:0					
720027	NO. 2 ENGINE - (AGB) ACCESSORY GEARBOX	MOS					24-JAN-2002		
	PN	HRS/MSC		TSN:0			0		(10000) 9958.9
	SN-UNKNOWN	ENC	10000	TSN:0			0		
OVERHAUL	REF: GENERIC NO REF			TSN:0					

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720030	NO. 2 ENGINE - HOT SECTION INSPECTION REF: EMM 72-00-00	MOS HRS/MSC ENC	3000	+250			01-AUG-2007 5196.6 5790	(8196.6) 8155.5	8446.6
720060	NO. 2 ENGINE - HP TURBINE ROTOR REAR COVER 30B4012-01 A0010WWP REF: See Workcard	MOS HRS/MSC ENC	- 15000				24-JAN-2002 0 0	(15000) 15047	
720065	NO. 2 ENGINE - HP TURBINE ROTOR FRONT COVER 30B6202-01 A0029DWY REF: See Workcard	MOS HRS/MSC ENC	- 15000				08-MAR-2008 1005.2 1989	(16989) 17036	
720070	NO. 2 ENGINE - 1ST-STAGE HP TURBINE DISK 30B6351-01 A002ACXF REF: See Workcard	MOS HRS/MSC ENC	- 15000				08-MAR-2008 1005.2 1989	(16989) 17036	
720075	NO. 2 ENGINE - 2ND-STAGE HP TURBINE DISK 30B4642-01 A0010T4F REF: See Workcard	MOS HRS/MSC ENC	- 10000				24-JAN-2002 0 0	(10000) 10047	
720080	NO. 2 ENGINE - 3RD-STAGE LP TURBINE DISK 30A2303 72B184 REF: See Workcard	MOS HRS/MSC ENC	- 15000				24-JAN-2002 0 0	(15000) 15047	
720085	NO. 2 ENGINE - 4TH-STAGE LP TURBINE DISK 30A2304 73B976 REF: See Workcard	MOS HRS/MSC ENC	- 15000				24-JAN-2002 0 0	(15000) 15047	
720090	NO. 2 ENGINE - 5TH-STAGE LP TURBINE DISK 30A2305 72B387 REF: See Workcard	MOS HRS/MSC ENC	- 15000				24-JAN-2002 0 0	(15000) 15047	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720095	NO. 2 ENGINE - HP TURBINE ROTOR AIR SEAL 31B6205-01 WG001587	MOS HRS/MSC ENC		TSN:0 TSN:0 TSN:0			24-JAN-2002 0 0		
LIFE LIMIT	REF: See Workcard		15000					(15000) 15047	
720125	NO. 2 ENGINE - BORESCOPE INSPECTION FIRST-STAGE HP TURBINE BLADES	MOS HRS/MSC ENC	1600				01-AUG-2007 5197 5790		(6797) 6755.9
	REF: EMM 72-00-00								
720135	NO. 2 ENGINE - BORESCOPE INSPECTION SECOND-STAGE HP TURBINE BLADES	MOS HRS/MSC ENC	2400				01-AUG-2007 5196.6 5790		(7596.6) 7555.5
	REF: EMM 72-00-00								
720180	NO. 2 ENGINE - BORESCOPE INSPECTION HP TURBINE L SEAL	MOS HRS/MSC ENC	1200				01-AUG-2007 5197 5790		(6397) 6355.9
	REF: EMM 72-00-00								
720190	NO. 2 ENGINE - BORESCOPE INSPECTION COMBUSTION CHAMBER LINER	MOS HRS/MSC ENC	6000				01-AUG-2007 5197 5790		(11197) 11155.9
	REF: EMM 72-00-00								
721122	NO. 2 ENGINE - VISUAL INSPECTION EXTERNAL OIL TUBES, INCLUDING NO. 4 BRG. TUBES, AGB COVER AND SEALS.	MOS HRS/MSC ENC	1000				01-DEC-2017 6428.4		(7428.4) 7387.3
	REF: GENERIC NO REF								
721123	NO. 2 ENGINE - VISUAL CHECK WIRING HARNESSSES FOR CONDITION AND SECURITY OF ACCESSIBLE HARNESSSES	MOS HRS/MSC ENC	800				04-MAR-2016 6100.6 6151		(6900.6) 6859.5
	REF: GENERIC NO REF								
721125	NO. 2 ENGINE - CHECK LP COMPRESSOR FAN BLADES FOR EROSION OF OUTER 3 INCHES OF THE LE	MOS HRS/MSC ENC	500				11-AUG-2016 6310.9 6244		(6810.9) 6769.8
	REF: EMM 72-30-01								

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
721126	NO. 2 ENGINE - VISUAL INSPECTION FAN AND NOSE CONE REF: EMM 72-30-01	MOS HRS/MSC ENC	1000				11-AUG-2016 6310.9 6244	(7310.9) 7269.8	
721127	NO. 2 ENGINE - VISUAL INSPECTION OUTER BYPASS DUCTS REF: EMM 72-70-01	MOS HRS/MSC ENC	2000				01-AUG-2007 5196.6 5790	(7196.6) 7155.5	
721128	NO. 2 ENGINE - VISUAL INSPECTION FAN SOUND ABSORBING LINER SEGMENT AND EXIT VANES REF: EMM 72-30-01	MOS HRS/MSC ENC	1000				07-APR-2017 6379.1 6274	(7379.1) 7338	
721129	NO. 2 ENGINE - CHECK AGB HOUSING AND MOUNTS REF: GENERIC NO REF	MOS HRS/MSC ENC	2000				01-AUG-2007 5196.6 5790	(7196.6) 7155.5	
721130	NO. 2 ENGINE - VISUAL INSPECTION EXHAUST MIXER REF: GENERIC NO REF	MOS HRS/MSC ENC	2500				01-DEC-2017 6469.5	(8969.5) 8928.4	
721133 (s)	NO. 2 ENGINE - VISUAL INSPECTION FAN CASE EXTERIOR PKG 4 REF: EMM 72-30-01	MOS HRS/MSC ENC	24				PKG 01-DEC-2017 6469.5		
721134	NO. 2 ENGINE - VISUALLY CHECK FAN AREA FOR OIL LEAKS REF: GENERIC NO REF	MOS HRS/MSC ENC	500				01-DEC-2017 6469.5	(6969.5) 6928.4	
+ 726001	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - AC GENERATOR (PMA) REF: GENERIC NO REF	MOS HRS/MSC ENC	10000				24-JAN-2002 0 0	(10000) 9958.9 M	

CHAPTER 73 ENGINE FUEL AND CONTROL

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 73-00-00-01-01 (s)	LEFT ENGINE FUEL LINES - PERFORM VISUAL CHECK OF LEFT ENGINE FUEL LINES AND COMPONENTS FOR LEAKS AND CONDITION - EXTERNAL						PKG		
73.010	PKG 3 REF: AMM 73-10-01	MOS HRS/MSC AFL	15	+2m			01-DEC-2017 6428.4 6367		
+ 73-00-00-01-02 (s)	RIGHT ENGINE FUEL LINES - PERFORM VISUAL CHECK OF RIGHT ENGINE FUEL LINES AND COMPONENTS FOR LEAKS AND CONDITION - EXTERNAL						PKG		
73.010	PKG 3 REF: AMM 73-10-01	MOS HRS/MSC AFL	15	+2m			01-DEC-2017 6428.4 6367		
73-00-00-03-01 (s)	DISCARD NO. 1 ENGINE FUEL PUMP FUEL FILTER						PKG		
73.015	PN PKG 3 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	15	+1m			01-DEC-2017 6428.4 6367		
73-00-00-03-02 (s)	DISCARD NO. 2 ENGINE FUEL PUMP FUEL FILTER						PKG		
73.020	PVP5055-00-03 PKG 3 01060009 REF: See Workcard	MOS HRS/MSC AFL	15	+1m			20-FEB-2019 6584.3 6425		
73-00-00-04-01 (s)	LEFT ENGINE CONDENSATION TRAPS - DRAIN LEFT ENGINE P1 CONDENSATION TRAPS						PKG		
73.025	PKG 2 REF: AMM 77-22-01	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
73-00-00-04-02 (s)	RIGHT ENGINE CONDENSATION TRAPS - DRAIN RIGHT ENGINE P1 CONDENSATION TRAPS						PKG		
73.025	PKG 2 REF: AMM 77-22-01	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
+ 73-00-00-06-01 (s)	LEFT ENGINE P3 CONDENSATION TRAPS - DRAIN LEFT ENGINE P3 CONDENSATION TRAPS						PKG		
73.065	PKG 1 REF: AMM 75-32-01	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		
+ 73-00-00-06-02 (s)	RIGHT ENGINE P3 CONDENSATION TRAPS - DRAIN RIGHT ENGINE P3 CONDENSATION TRAPS						PKG		
73.065	PKG 1 REF: AMM 75-32-01	DAYS HRS/MSC AFL	15	+2			13-JUN-2019 6590.1 6430		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-00-00-07-01 (s)	LEFT ENGINE P3 CONDENSATION TRAP - DETAILED INSPECTION OF LEFT ENGINE P3 CAP BLEED HOLE FOR BLOCKAGE						PKG		
73.066	PKG 2 REF: AMM 75-32-01	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
73-00-00-07-02 (s)	RIGHT ENGINE P3 CONDENSATION TRAP - DETAILED INSPECTION OF RIGHT ENGINE P3 CAP BLEED HOLE FOR BLOCKAGE						PKG		
73.067	PKG 2 REF: AMM 75-32-01	DAYS HRS/MSC AFL	225	+14			20-FEB-2019 6584.3 6425		
731062	NO. 2 ENGINE FUEL PUMP								
73.020	PVP5055-00-03 01060009 REF: See Workcard	MOS HRS/MSC AFL	O/C				20-FEB-2019 6584.3 6425		
ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B									
73-21-00-01-01	NO. 1 ENGINE - FADEC SOFTWARE MANDATORY RETROFIT FOR OPTION 040F036								
	30B3250-4, OPT 040F036 SN-UNKNOWN REF:	MOS HRS/MSC ENC	-		TSN:0 TSN:0 TSN:0		04-FEB-2002 0 0		
73-50-00-00-80	NO. 1 ENGINE - EEC								
	822823-4-008 01044419 REF:	MOS HRS/MSC ENC	O/C				10-JAN-2019		
+ 731002	NO. 1 ENGINE - OVERHAUL - FUEL PUMP								
OVERHAUL	PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	10000		TSI:0 TSI:0 TSI:0		04-FEB-2002 0 0	(10000) 9969 M	
+ 731003	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL WASTE EJECTOR TANK								
	REF: GENERIC NO REF	MOS HRS/MSC ENC	10000		TSI:0 TSI:0 TSI:0		04-FEB-2002 0 0	(10000) 9969 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731004	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE PRIMARY								
		MOS		TSI:0			04-FEB-2002		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
		ENC		TSI:0			0		
+ 731005	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL DUMP/START VALVE								
	PN	MOS		TSI:0			04-FEB-2002		
	SN-UNKNOWN	HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
	REF: EMM 73-10-05	ENC		TSI:0			0		
731010	NO. 1 ENGINE - FUEL FILTER								
	PN-UNKNOWN	MOS	12	TSO:0			11-AUG-2016	11-AUG-2017	
	SN-UNKNOWN	HRS/MSC		TSO:0			6203		
DISCARD	REF: EMM 73-10-03	ENC		TSO:0			6125		
+ 731013	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL FILTER BYPASS SWITCH								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
+ 731014	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE SECONDARY								
		MOS		TSI:0			04-FEB-2002		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
		ENC		TSI:0			0		
+ 731024	NO. 1 ENGINE - OVERHAUL - FUEL NOZZLE INLET								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
OVERHAUL	REF: EMM 73-10-04	ENC		TSI:0			0		
+ 731025	NO. 1 ENGINE - OVERHAUL - VALVE FUEL SHUTOFF								
		MOS		TSI:0			04-FEB-2002		
		HRS/MSC 10000		TSI:0			0	(10000) 9969 M	
OVERHAUL	REF: EMM 73-10-05	ENC		TSI:0			0		
731027	NO. 1 ENGINE - CHECK DRAIN MAST FOR LEAKS								
		MOS					07-MAR-2008		
		HRS/MSC 2000					5186.9	(7186.9) 7155.9	
	REF: GENERIC NO REF	ENC					5715		



Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731029 (s)	NO. 1 ENGINE - VISUAL INSPECTION EXTERNAL FUEL TUBES AND FUEL SYSTEM COMPONENTS PKG 4	MOS	24				PKG 01-DEC-2017 6459.5		
	REF: GENERIC NO REF	HRS/MSC ENC							
731030	NO. 1 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS					31-JUL-2007 5186.6 5715	(8186.6) 8155.6	
	REF: EMM 73-10-04	HRS/MSC ENC	3000						
+ 731035	NO. 1 ENGINE - DISCARD - FUEL SHUTOFF CABLE	MOS					04-FEB-2002		
	DISCARD	HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			0 0 0	(10000) 9969 M	
	REF: EMM 73-10-05								
732003	NO. 1 ENGINE - FUEL PUMP	MOS					04-FEB-2002		
	PN SN-UNKNOWN	HRS/MSC ENC	O/C	TSN:0 TSN:0 TSN:0			0 0 0		
	REF: EMM 73-10-02								
+ 732011	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - MOTIVE FLOW VALVE	MOS					04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			0 0 0	(10000) 9969 M	
+ 732012	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - EEC	MOS					04-FEB-2002		
	PN SN-UNKNOWN	HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			0 0 0	(10000) 9969 M	
	REF: GENERIC NO REF								
+ 732021	NO. 1 ENGINE - VISUALLY INSPECT/OVERHAUL - HMU	MOS					04-FEB-2002		
	OVERHAUL	HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			0 0 0	(10000) 9969 M	
	REF: See Workcard								
+ 733001	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL FLOW METER	MOS					04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			0 0 0	(10000) 9969 M	

ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-21-00-01-01	NO. 2 ENGINE - FADEC SOFTWARE MANDATORY RETROFIT FOR OPTION 040F036 30B3250-4, OPT 040F036 SN-UNKNOWN REF:	MOS HRS/MSC - ENC		TSN:0 TSN:0 TSN:0			24-JAN-2002 0 0		
73-50-00-00-80	NO. 2 ENGINE - EEC 822823-4-008 01044442 REF:	MOS HRS/MSC O/C ENC					10-JAN-2019		
+ 731002	NO. 2 ENGINE - OVERHAUL - FUEL PUMP PN SN-UNKNOWN REF: EMM 73-10-02	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
OVERHAUL									
+ 731003	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL WASTE EJECTOR TANK REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
+ 731004	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE PRIMARY REF: EMM 73-10-04	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
OVERHAUL									
+ 731005	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL DUMP/START VALVE PN SN-UNKNOWN REF: EMM 73-10-05	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
731010	NO. 2 ENGINE - FUEL FILTER PN-UNKNOWN SN-UNKNOWN REF: EMM 73-10-03	MOS HRS/MSC ENC	12	TSO:0 TSO:0 TSO:0			11-AUG-2016 6213.1 6200	11-AUG-2017	
DISCARD									
+ 731013	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL FILTER BYPASS SWITCH REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 731014	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE SECONDARY	MOS		TSI:0			24-JAN-2002		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9958.9 M	
+ 731024	NO. 2 ENGINE - OVERHAUL - FUEL NOZZLE INLET	MOS		TSI:0			24-JAN-2002		
OVERHAUL	REF: EMM 73-10-04	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9958.9 M	
+ 731025	NO. 2 ENGINE - OVERHAUL - VALVE FUEL SHUTOFF	MOS		TSI:0			24-JAN-2002		
OVERHAUL	REF: EMM 73-10-05	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9958.9 M	
731027	NO. 2 ENGINE - CHECK DRAIN MAST FOR LEAKS	MOS					01-AUG-2007		
	REF: GENERIC NO REF	HRS/MSC ENC	2000				5196.6 5790	(7196.6) 7155.5	
731029 (s)	NO. 2 ENGINE - VISUAL INSPECTION EXTERNAL FUEL TUBES AND FUEL SYSTEM COMPONENTS						PKG		
	PKG 4	MOS	24				01-DEC-2017		
	REF: GENERIC NO REF	HRS/MSC ENC					6469.5		
731030	NO. 2 ENGINE - CLEAN PRIMARY FUEL NOZZLES	MOS					01-AUG-2007		
	REF: EMM 73-10-04	HRS/MSC ENC	3000				5196.6 5790	(8196.6) 8155.5	
+ 731035	NO. 2 ENGINE - DISCARD - FUEL SHUTOFF CABLE	MOS		TSI:0			24-JAN-2002		
DISCARD	REF: EMM 73-10-05	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9958.9 M	
732003	NO. 2 ENGINE - FUEL PUMP						24-JAN-2002		
	PN	MOS		TSN:0					
	SN-UNKNOWN	HRS/MSC	O/C	TSN:0			0		
	REF: EMM 73-10-02	ENC		TSN:0			0		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 732011	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - MOTIVE FLOW VALVE								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
+ 732012	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - EEC								
	PN	MOS		TSI:0			24-JAN-2002		
	SN-UNKNOWN	HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
+ 732021	NO. 2 ENGINE - VISUALLY INSPECT/OVERHAUL - HMU								
	PN	MOS		TSI:0			24-JAN-2002		
	SN-UNKNOWN	HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	OVERHAUL	REF: See Workcard		TSI:0			0		
+ 733001	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - FUEL FLOW METER								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
CHAPTER 74 IGNITION									
+ 74-00-00-01-01 (s)	LEFT ENGINE IGNITION - PERFORM OPERATIONAL CHECK OF LEFT ENGINE IGNITERS FOR CONTINUOUS IGNITION						PKG		
	PKG 2	DAYS	225	+14			20-FEB-2019		
74.010		HRS/MSC					6584.3		
	REF: AMM 74-10-01	AFL					6425		
+ 74-00-00-01-02 (s)	RIGHT ENGINE IGNITION - PERFORM OPERATIONAL CHECK OF RIGHT ENGINE IGNITERS FOR CONTINUOUS IGNITION						PKG		
	PKG 2	DAYS	225	+14			20-FEB-2019		
74.010		HRS/MSC					6584.3		
	REF: AMM 74-10-01	AFL					6425		
74-00-00-02-01 (s)	LEFT ENGINE IGNITION - PERFORM DETAILED INSPECTION OF LEFT ENGINE SPARK IGNITERS						PKG		
	PKG 3	MOS	15				01-DEC-2017		
		HRS/MSC					6428.4		
	REF:	AFL					6367		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
74-00-00-02-02 (s)	RIGHT ENGINE IGNITION - PERFORM DETAILED INSPECTION OF RIGHT ENGINE SPARK IGNITERS PKG 3	MOS	15				PKG 01-DEC-2017 6428.4 6367		
	REF:	AFL					6367		
+ 742001 (s)	DETAILED INSPECTION NO. 1 ENGINE IGNITION - PERFORM DETAILED INSPECTION OF LEFT ENGINE SPARK IGNITERS PKG 3	MOS	15	+1m			PKG 01-DEC-2017 6428.4 6367		
74.030	REF:	AFL					6367		
+ 742002 (s)	DETAILED INSPECTION NO. 2 ENGINE IGNITION - PERFORM DETAILED INSPECTION OF RIGHT ENGINE SPARK IGNITERS PKG 3	MOS	15	+1m			PKG 01-DEC-2017 6428.4 6367		
74.030	REF:	AFL					6367		
ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B									
+ 741011	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION EXCITER BOX	MOS					04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC	10000		TSI:0		0		(10000) 9969 M
		ENC			TSI:0		0		
+ 741031	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION CABLES (INBOARD)	MOS					04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC	10000		TSI:0		0		(10000) 9969 M
		ENC			TSI:0		0		
+ 741032	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION CABLES (OUTBOARD)	MOS					04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC	10000		TSI:0		0		(10000) 9969 M
		ENC			TSI:0		0		
742001	NO. 1 ENGINE - INBOARD IGNITER PLUG PN	MOS					11-AUG-2016		
	SN-UNKNOWN	HRS/MSC	O/C		TSN:174		6300.8		
	REF: EMM 74-10-01	ENC			TSN:6300.8		6168		
					TSN:6168				

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742002	NO. 1 ENGINE - OUTBOARD IGNITER PLUG PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:174 TSN:6300.8 TSN:6168			11-AUG-2016 6300.8 6168		
742103 (s)	NO. 1 ENGINE - DETAILED INSPECTION IGNITERS PKG 3 REF: EMM 74-10-01	MOS HRS/MSC ENC	12				PKG 01-DEC-2017 6459.5		
742104 (s)	NO. 1 ENGINE - OPERATIONAL CHECK IGNITERS FOR CONTINUOUS IGNITION PKG 2 REF: EMM 74-10-01	MOS HRS/MSC ENC	6				PKG 20-FEB-2019 6441 6223		
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
+ 741011	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION EXCITER BOX REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0		(10000) 9958.9 M
+ 741031	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION CABLES (INBOARD) REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0		(10000) 9958.9 M
+ 741032	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - IGNITION CABLES (OUTBOARD) REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0		(10000) 9958.9 M
742001	NO. 2 ENGINE - INBOARD IGNITER PLUG PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:175 TSN:6310.9 TSN:6244			11-AUG-2016 6310.9 6244		
742002	NO. 2 ENGINE - OUTBOARD IGNITER PLUG PN SN-UNKNOWN REF: EMM 74-10-01	MOS HRS/MSC ENC	O/C	TSN:175 TSN:6310.9 TSN:6244			11-AUG-2016 6310.9 6244		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742103 (s)	NO. 2 ENGINE - DETAILED INSPECTION PKG 3 REF: EMM 74-10-01	IGNITERS MOS HRS/MSC ENC	12				PKG 01-DEC-2017 6469.5		
742104 (s)	NO. 2 ENGINE - OPERATIONAL CHECK PKG 2 REF: EMM 74-10-01	IGNITERS FOR CONTINUOUS IGNITION MOS HRS/MSC ENC	6				PKG 20-FEB-2019 6451.1 6299		
CHAPTER 75 AIR									
+ 75-00-00-05A-01 (s)	LEFT ENGINE P3 SOLENOID VALVE - RESTORATION (CLEAN) OF LEFT ENGINE BLEED-OFF VALVES SOLENOID P3 FILTER PKG 3 REF: AMM 75-31-14		15	+1m			PKG 01-DEC-2017 6428.4 6367		
75.050		MOS HRS/MSC AFL							
+ 75-00-00-05A-02 (s)	RIGHT ENGINE P3 SOLENOID VALVE - RESTORATION (CLEAN) OF RIGHT ENGINE BLEED-OFF VALVES SOLENOID P3 FILTER PKG 3 REF: AMM 75-31-14		15	+1m			PKG 01-DEC-2017 6428.4 6367		
75.050		MOS HRS/MSC AFL							
75-00-00-05B-01 (s)	LEFT ENGINE P3 SOLENOID VALVE - RESTORATION (CLEAN) OF LEFT ENGINE BLEED-OFF VALVES SOLENOID P3 FILTER PKG 4 REF:		30				PKG 01-DEC-2017 6428.4 6367		
		MOS HRS/MSC AFL							
75-00-00-05B-02 (s)	RIGHT ENGINE P3 SOLENOID VALVE - RESTORATION (CLEAN) OF RIGHT ENGINE BLEED-OFF VALVES SOLENOID P3 FILTER PKG 4 REF:		30				PKG 01-DEC-2017 6428.4 6367		
		MOS HRS/MSC AFL							
753021	NO. 1 ENGINE LEFT 2.5 COMPRESSOR BLEED VALVE 31B5759-01 AHX0104796 REF: See Workcard						09-MAY-2019 6590.1 6430		
75.020		MOS HRS/MSC AFL	O/C		TSO:0 TSO:0 TSO:0				

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753022	NO. 2 ENGINE LEFT 2.5 COMPRESSOR BLEED VALVE								
75.020	31B5759-01 AHX016267 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753025	NO. 1 ENGINE RIGHT 2.5 COMPRESSOR BLEED VALVE								
75.025	31B5759-01 AHX010796 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753026	NO. 2 ENGINE RIGHT 2.5 COMPRESSOR BLEED VALVE								
75.025	31B5759-01 AHX010284 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753031	NO. 1 ENGINE TOP 2.8 COMPRESSOR BLEED VALVE								
75.030	31B5756-01 AHX010933 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753032	NO. 2 ENGINE TOP 2.8 COMPRESSOR BLEED VALVE								
75.035	31B5756-01 AHX010898 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753035	NO. 1 ENGINE BOTTOM 2.8 COMPRESSOR BLEED VALVE								
75.030	31B5756-01 AHX010597 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		
753036	NO. 2 ENGINE BOTTOM 2.8 COMPRESSOR BLEED VALVE								
75.035	31B5756-01 AHX010930 REF: See Workcard	MOS HRS/MSC AFL	O/C	TSO:0 TSO:0 TSO:0			09-MAY-2019 6590.1 6430		

ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B

75-00-00-05A-01 (s)	NO. 1 ENGINE - CLEAN ENGINE BLEED-OFF VALVES SOLENOID P3 FLTR						PKG		
	PKG 3	MOS	15	+1m			01-DEC-2017		
	REF:	HRS/MSC					6459.5		
		ENC							

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
75-00-00-05B-01 (s)	NO. 1 ENGINE - CLEAN ENGINE BLEED-OFF VALVES SOLENOID P3 FILTER	MOS	30	+2m			21-MAY-2015 5924.6 6011		
	REF:	HRS/MSC ENC							
+ 751001	NO. 1 ENGINE - OVERHAUL - ANTI-ICING VALVE	MOS			TSI:0		04-FEB-2002		
	REF: EMM 75-10-01	HRS/MSC ENC	10000		TSI:0 TSI:0		0 0	(10000) 9969 M	
	OVERHAUL								
+ 753001	NO. 1 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES	MOS			TSI:0		04-FEB-2002		
	REF: EMM 75-30-01	HRS/MSC ENC	10000		TSI:0 TSI:0		0 0	(10000) 9969 M	
	OVERHAUL								
753003 (s)	NO. 1 ENGINE - REMOVE P3 AIR TUBE CAP AND INSPECT THE CAP BLEED HOLE FOR BLOCKAGE (POST-SBA25080 OR POST-SB25089)						PKG		
	PKG 2	MOS	6				20-FEB-2019 6441 6223		
	REF: EMM 75-30-03	HRS/MSC ENC							
753005 (s)	NO. 1 ENGINE - VISUAL CHECK P1 AIR TUBE AND DRAIN CONDENSATION TRAPS-CHECK FOR WEAR, CHAFING, CRACKS AND CORROSION.						PKG		
	PKG 2	MOS	6				20-FEB-2019 6441 6223		
	REF: GENERIC NO REF	HRS/MSC ENC							
+ 753014	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - LINEAR STATOR VANE ACTUATOR								
	PN	MOS			TSI:0		04-FEB-2002		
	SN-UNKNOWN	HRS/MSC	10000		TSI:0		0	(10000) 9969 M	
	REF: GENERIC NO REF	ENC			TSI:0		0		
753020	NO. 1 ENGINE - RESTORATION (CLEANING) COMPRESSOR BLEED SOLENOID VALVE OF BOV SOLENOID VALVE CARTRIDGE-SCREEN (POST-SB25090)								
	PN	MOS					31-JUL-2007		
	SN-UNKNOWN	HRS/MSC	5000				5186.6	(10186.6) 10155.6	
	REF: EMM 75-30-02	ENC					5715		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 753022	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - COMPRESSOR BOV SOLENOID PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
+ 754001	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - P3 TRANSDUCER REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
75-00-00-05A-01 (s)	NO. 2 ENGINE - CLEAN ENGINE BLEED-OFF VALVES SOLENOID P3 FLTR PKG 3 REF:	MOS HRS/MSC ENC	15	+1m			01-DEC-2017 6469.5		
75-00-00-05B-01 (s)	NO. 2 ENGINE - CLEAN ENGINE BLEED-OFF VALVES SOLENOID P3 FLTR REF:	MOS HRS/MSC ENC	30	+2m			21-MAY-2015 5934.7 6086		
+ 751001	NO. 2 ENGINE - OVERHAUL - ANTI-ICING VALVE OVERHAUL REF: EMM 75-10-01	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
+ 753001	NO. 2 ENGINE - OVERHAUL - COMPRESSOR BLEED VALVES OVERHAUL REF: EMM 75-30-01	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
753003 (s)	NO. 2 ENGINE - REMOVE P3 AIR TUBE CAP AND INSPECT THE CAP BLEED HOLE FOR BLOCKAGE (POST-SBA25080 OR POST-SB25089) PKG 2 REF: EMM 75-30-03	MOS HRS/MSC ENC	6				20-FEB-2019 6451.1 6299		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
753005 (s)	NO. 2 ENGINE - VISUAL CHECK CRACKS AND CORROSION.	P1 AIR TUBE AND DRAIN CONDENSATION TRAPS-CHECK FOR WEAR, CHAFING,					PKG		
	PKG 2	MOS	6				20-FEB-2019		
	REF: GENERIC NO REF	HRS/MSC					6451.1		
		ENC					6299		
+ 753014	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - LINEAR STATOR VANE ACTUATOR								
	PN	MOS		TSI:0			24-JAN-2002		
	SN-UNKNOWN	HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
753020	NO. 2 ENGINE - RESTORATION (CLEANING) COMPRESSOR BLEED SOLENOID VALVE OF BOV SOLENOID VALVE CARTRIDGE-SCREEN (POST-SB25090)								
	PN	MOS					01-AUG-2007		
	SN-UNKNOWN	HRS/MSC	5000				5196.6	(10196.6) 10155.5	
	REF: EMM 75-30-02	ENC					5790		
+ 753022	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - COMPRESSOR BOV SOLENOID								
	PN	MOS		TSI:0			24-JAN-2002		
	SN-UNKNOWN	HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
+ 754001	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - P3 TRANSDUCER								
		MOS		TSI:0			24-JAN-2002		
		HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
CHAPTER 76	ENGINE CONTROLS								
+ 76-10-00-01-01 (s)	THRUST LEVER (ENGINE CONTROL BOX) - PERFORM DETAILED INSPECTION OF GATE ASSEMBLIES FOR CONDITION AND SECURITY						PKG		
	PKG 3,4	MOS	15	+2m			01-DEC-2017		
76.015	REF:	HRS/MSC					6428.4		
		AFL					6367		
76-10-00-01-02	EJECTOR FLOW CONTROL VALVE #14HH								
	303556-03	MOS					14-FEB-2012		
	N0619	HRS/MSC	O/C				5538.2		
	REF:	AFL					5973		

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
---------	---------------------------------	------	----------	------------	-----	----------	------------	---------------------------	--------------

76-10-00-02-01 (s)	THRUST LEVER (ENGINE CONTROL BOX) - DISCARD OF THRUST LEVER ROLLER GUIDES FOR WEAR PKG 4	MOS	30				PKG 01-DEC-2017 6428.4 6367		
	REF: See Workcard	HRS/MSC AFL							

ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B

76-10-00-01-01 (s)	NO. 1 ENGINE - THRUST LEVER (ENGINE CONTROL BOX) GATE ASSEMBLIES INSPECTION PKG 4	MOS	24	+2m			PKG 01-DEC-2017 6459.5		
	REF:	HRS/MSC ENC							

76-10-00-02-01 (s)	NO. 1 ENGINE - THRUST LEVER (ENGINE CONTROL BOX) THRUST LEVER FOLLOWERS FOR WEAR REPLACEMENT PH4 SN-UNKNOWN	MOS	30	+2m			21-MAY-2015 5924.6 6011	21-NOV-2017	M 21-JAN-2018
	REF:	HRS/MSC ENC							

ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B

76-10-00-01-01 (s)	NO. 2 ENGINE - THRUST LEVER (ENGINE CONTROL BOX) GATE ASSEMBLIES INSPECTION PKG 4	MOS	24	+2m			PKG 01-DEC-2017 6469.5		
	REF:	HRS/MSC ENC							

76-10-00-02-01 (s)	NO. 2 ENGINE - THRUST LEVER (ENGINE CONTROL BOX) THRUST LEVER FOLLOWERS FOR WEAR REPLACEMENT PH4 SN-UNKNOWN	MOS	30	+2m			21-MAY-2015 5934.7 6086	21-NOV-2017	M 21-JAN-2018
	REF:	HRS/MSC ENC							

CHAPTER 77 ENGINE INDICATING

+ 77-00-00-02-01 (s)	LEFT ENGINE ITT SENSING SYSTEM - PERFORM FUNCTIONAL CHECK OF LEFT ENGINE ITT SENSING SYSTEM PKG 3	MOS	15	+1m			PKG 01-DEC-2017 6428.4 6367		
77.010	REF: AMM 77-20-01	HRS/MSC AFL							

+ 77-00-00-02-02 (s)	RIGHT ENGINE ITT SENSING SYSTEM - PERFORM FUNCTIONAL CHECK OF RIGHT ENGINE ITT SENSING SYSTEM PKG 3	MOS	15	+1m			PKG 01-DEC-2017 6428.4 6367		
77.010	REF: AMM 77-20-01	HRS/MSC AFL							

ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
771021	NO. 1 ENGINE - VISUAL CHECK P1/T1 SENSORS, N1,N2 SPEED SENSORS,T4.5 PROBES AND VIBRATION SENSOR FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS. REF: EMM 77-20-01	MOS HRS/MSC ENC	800				01-DEC-2017 6459.5	(7259.5) 7228.5	
771023 (s)	NO. 1 ENGINE - FUNCTIONAL CHECK ITT/T4.5 INDICATING SYSTEM PKG 3 REF: EMM 77-20-01	MOS HRS/MSC ENC	12				01-DEC-2017 6459.5		
+ 772001	NO. 1 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK - T4.5 HARNESSSES AND T4.5 TERMINAL BOX REF: EMM 77-20-01	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
+ 774001	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK OF THE ENGINE DIAGNOSTIC UNIT REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
771021	NO. 2 ENGINE - VISUAL CHECK P1/T1 SENSORS, N1,N2 SPEED SENSORS,T4.5 PROBES AND VIBRATION SENSOR FOR CONDITION OF ACCESSIBLE WIRING HARNESSSES AND SECURITY OF CONNECTORS. REF: EMM 77-20-01	MOS HRS/MSC ENC	800				01-DEC-2017 6469.5	(7269.5) 7228.4	
771023 (s)	NO. 2 ENGINE - FUNCTIONAL CHECK ITT/T4.5 INDICATING SYSTEM PKG 3 REF: EMM 77-20-01	MOS HRS/MSC ENC	12				01-DEC-2017 6469.5		
+ 772001	NO. 2 ENGINE - EXAMINE AND DO A FUNCTIONAL CHECK - T4.5 HARNESSSES AND T4.5 TERMINAL BOX REF: EMM 77-20-01	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 774001	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK OF THE ENGINE DIAGNOSTIC UNIT	MOS		TSI:0			24-JAN-2002		
		HRS/MSC	10000	TSI:0			0	(10000) 9958.9 M	
	REF: GENERIC NO REF	ENC		TSI:0			0		
CHAPTER 79 OIL									
+ 79-00-00-01-01 (s)	LEFT ENGINE OIL SYSTEM - CHECK LEFT ENGINE OIL LEVEL						PKG		
	PKG 1	DAYS	15	+2			13-JUN-2019		
79.010		HRS/MSC					6590.1		
	REF: AMM 12-15-10	AFL					6430		
+ 79-00-00-01-02 (s)	RIGHT ENGINE OIL SYSTEM - CHECK RIGHT ENGINE OIL LEVEL						PKG		
	PKG 1	DAYS	15	+2			13-JUN-2019		
79.010		HRS/MSC					6590.1		
	REF: AMM 12-15-10	AFL					6430		
+ 79-00-00-05-01 (s)	LEFT ENGINE OIL LINES - PERFORM DETAILED INSPECTION OF LEFT ENGINE OIL LINES IN FIRE ZONE						PKG		
	PKG 3	MOS	15	+1m			01-DEC-2017		
79.015		HRS/MSC					6428.4		
	REF: See Workcard	AFL					6367		
+ 79-00-00-05-02 (s)	RIGHT ENGINE OIL LINES - PERFORM DETAILED INSPECTION OF RIGHT ENGINE OIL LINES IN FIRE ZONE						PKG		
	PKG 3	MOS	15	+1m			01-DEC-2017		
79.015		HRS/MSC					6428.4		
	REF: See Workcard	AFL					6367		
79-00-00-09-01 (s)	DISCARD NO. 1 ENGINE OIL PUMP OIL FILTER						PKG		
	PN PKG 3	MOS	15	+1m			01-DEC-2017		
79.020		HRS/MSC					6428.4		
	REF: See Workcard	AFL					6367		
79-00-00-09-02 (s)	DISCARD NO. 2 ENGINE OIL PUMP OIL FILTER						PKG		
	PN PKG 3	MOS	15	+1m			01-DEC-2017		
79.020		HRS/MSC					6428.4		
	REF: See Workcard	AFL					6367		

ENGINE NO. 1 Model : PW306B Serial # CD-0233 Part # PW306B

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-00-00-05-01 (s)	NO. 1 ENGINE - OIL LINES IN FIRE ZONE INSPECTION PKG 3 REF:	MOS HRS/MSC ENC	15	+1m			PKG 01-DEC-2017 6459.5		
+ 792001	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK OF THE OIL FILTER BYPASS SWITCH REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
792002	NO. 1 ENGINE - VISUAL CHECK FUEL/OIL HEAT EXCHANGER FOR LEAKAGE AND SECURITY PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	60				04-FEB-2002 0 0	(10000) 9969 M	
792010	NO. 1 ENGINE - OIL FILTER ELEMENT PN-UNKNOWN SN-UNKNOWN REF: EMM 79-20-01	MOS HRS/MSC ENC	12	TSO:0 TSO:0 TSO:0			11-AUG-2016 6203 6125	11-AUG-2017	
+ 792012	NO. 1 ENGINE - VISUALLY INSPECT/FLUSH - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	
792020	NO. 1 ENGINE - VISUAL CHECK NO. 3 BEARING SCAVENGE OIL TUBE FOR LEAKAGE REF: EMM 79-20-03	MOS HRS/MSC ENC	1500				01-DEC-2017 6459.5	(7959.5) 7928.5	
792030 (s)	NO. 1 ENGINE - DETAILED INSPECTION OIL CONSUMPTION MONITORING AND OIL LEVEL CHECK PKG 1 REF: EMM 72-00-00	DAYS HRS/MSC ENC	14				PKG 13-JUN-2019		
+ 793002	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - LOW OIL PRESSURE SWITCH REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			04-FEB-2002 0 0	(10000) 9969 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793003	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - OIL TANK FILLER CAP	MOS		TSI:0			04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9969 M	
+ 793004	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - OIL TEMPERATURE SENSOR	MOS		TSI:0			04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9969 M	
+ 793010	NO. 1 ENGINE - DISCARD - CHIP DETECTOR	MOS		TSI:0			04-FEB-2002		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9969 M	
+ 793012	NO. 1 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL - DIFFERENTIAL OIL PRESSURE TRANSDUCER	MOS		TSI:0			04-FEB-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9969 M	
793020	NO. 1 ENGINE - OPERATIONAL CHECK CHIP DETECTOR	MOS					01-DEC-2017		
	REF: EMM 79-30-01	HRS/MSC ENC	2000				6459.5	(8459.5) 8428.5	
793021 (s)	NO. 1 ENGINE - VISUAL CHECK AGB/OIL OVERPRESSURE POP-UP INDICATOR FOR PROTRUDING POP-UP INDICATOR (RED BUTTON)						PKG		
	PKG 1	DAYS	14				13-JUN-2019		
	REF: EMM 79-30-03	HRS/MSC ENC							
ENGINE NO. 2 Model : PW306B Serial # CD-0237 Part # PW306B									
79-00-00-05-01 (s)	NO. 2 ENGINE - OIL LINES IN FIRE ZONE INSPECTION						PKG		
	PKG 3	MOS	15	+1m			01-DEC-2017		
	REF:	HRS/MSC ENC					6469.5		
+ 792001	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK OF THE OIL FILTER BYPASS SWITCH	MOS		TSI:0			24-JAN-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSI:0 TSI:0			0 0	(10000) 9958.9 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792002	NO. 2 ENGINE - VISUAL CHECK FUEL/OIL HEAT EXCHANGER FOR LEAKAGE AND SECURITY PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	60				24-JAN-2002 0 0	(10000) 9958.9 M	
792010	NO. 2 ENGINE - OIL FILTER ELEMENT PN-UNKNOWN SN-UNKNOWN REF: EMM 79-20-01	MOS HRS/MSC ENC	12	TSO:0 TSO:0 TSO:0			11-AUG-2016 6213.1 6200	11-AUG-2017	
+ 792012	NO. 2 ENGINE - VISUALLY INSPECT/FLUSH - FUEL/OIL HEAT EXCHANGER PN SN-UNKNOWN REF: EMM 79-20-02	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
792020	NO. 2 ENGINE - VISUAL CHECK NO. 3 BEARING SCAVENGE OIL TUBE FOR LEAKAGE REF: EMM 79-20-03	MOS HRS/MSC ENC	1500				01-DEC-2017 6469.5	(7969.5) 7928.4	
792030 (s)	NO. 2 ENGINE - DETAILED INSPECTION OIL CONSUMPTION MONITORING AND OIL LEVEL CHECK PKG 1 REF: EMM 72-00-00	DAYS HRS/MSC ENC	14				PKG 13-JUN-2019		
+ 793002	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - LOW OIL PRESSURE SWITCH REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
+ 793003	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - OIL TANK FILLER CAP REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	
+ 793004	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL CHECK - OIL TEMPERATURE SENSOR REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	TSI:0 TSI:0 TSI:0			24-JAN-2002 0 0	(10000) 9958.9 M	

Status Report

DORNIER 328-300 S/N 3209 (N430FJ): 6590.1 HRS, 6430 AFL as of 13-Aug-2019

Owner/Operator: DUNCAN AVIATION INCORPORATED - BATTLE CREEK

Report Date: 05-SEP-2019

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 793010	NO. 2 ENGINE - DISCARD - CHIP DETECTOR	MOS		TSl:0			24-JAN-2002		
DISCARD	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSl:0 TSl:0			0 0	(10000) 9958.9 M	
+ 793012	NO. 2 ENGINE - GENERAL VISUAL INSPECT/FUNCTIONAL - DIFFERENTIAL OIL PRESSURE TRANSDUCER	MOS		TSl:0			24-JAN-2002		
	REF: GENERIC NO REF	HRS/MSC ENC	10000	TSl:0 TSl:0			0 0	(10000) 9958.9 M	
793020	NO. 2 ENGINE - OPERATIONAL CHECK CHIP DETECTOR	MOS					01-DEC-2017		
	REF: EMM 79-30-01	HRS/MSC ENC	2000				6469.5	(8469.5) 8428.4	
793021 (s)	NO. 2 ENGINE - VISUAL CHECK AGB/OIL OVERPRESSURE POP-UP INDICATOR FOR PROTRUDING POP-UP INDICATOR (RED BUTTON)						PKG		
	PKG 1	DAYS	14				13-JUN-2019		
	REF: EMM 79-30-03	HRS/MSC ENC							
CHAPTER 80 STARTING									
+ 80-00-00-01-01	CHECK NO. 1 ENGINE AIR TURBINE STARTER OIL LEVEL	MOS					15-JAN-2016		
80.010	PN SN-UNKNOWN REF: AMM 12-14-10	HRS/MSC AFL	400	+20		-39.3	6139.5 6230	6500.2	6520.2
+ 80-00-00-01-02	CHECK NO. 2 ENGINE AIR TURBINE STARTER OIL LEVEL	MOS					15-JAN-2016		
80.010	PN SN-UNKNOWN REF: AMM 12-14-10	HRS/MSC AFL	400	+20		-39.3	6139.5 6230	6500.2	6520.2
80-00-00-02-01	CHANGE NO. 1 ENGINE AIR TURBINE STARTER OIL	MOS					08-APR-2013		
80.010	PN SN-UNKNOWN REF: AMM 12-14-11	HRS/MSC AFL	800	+100			5700.2 6053	6500.2	6600.2
80-00-00-02-02	CHANGE NO. 2 ENGINE AIR TURBINE STARTER OIL	MOS					08-APR-2013		
80.010	PN SN-UNKNOWN REF: AMM 12-14-11	HRS/MSC AFL	800	+100			5700.2 6053	6500.2	6600.2