

DUNCAN INTELLIGENCE

"Legendary People, Unforgettable Service"

UPDATE - 800XP BOLT HEAD INSPECTION

As you are aware, Raytheon Aircraft Company has issued Communique #51-02 dated August 23, 2000, informing all Hawker 800 and Hawker 800XP operators of the hydrogen embrittlement bolt condition originally reported in Communique #51-01 dated May 12, 2000.

We wanted to update you on this topic. To date, 12 aircraft and approximately 10,000 bolts have been inspected, revealing only 60 broken bolts. The primary objective of this investigation is to ensure that all of the potentially affected bolts are inspected. According to Communique #51-02, two Service Bulletins will be issued shortly dividing the affected aircraft into two groups: Group A having to accomplish the SB within 12 months and Group B having to accomplish it within 18 months. There are 103 affected aircraft, and so far only 12 have had their wings bolts inspected and/or replaced. That leaves 91 aircraft still needing to comply.

Given the number of affected aircraft and the limited number of service centers capable of accomplishing this Service Bulletin, securing **your preferred** input date will be difficult if scheduled at the last-minute.

Duncan Aviation is an Authorized Hawker Service Center. We have experienced the Hawker demate process, with our technicians having successfully completed the required inspection for the above mentioned Service Bulletin.

Please contact Dan Fuoco, at Duncan Aviation's Lincoln, Nebraska, facility (800.228.4277, ext. 1502) or Pete Kilmartin at our Battle Creek, Michigan, location (800.525.2376, ext. 8463) for a proposal, to schedule the work, or to discuss details about this important Service Bulletin.

**DUNCAN
AVIATION**



*For Hawker technical info, we have the experts with whom you should speak.
Our Hawker Teams consist of technicians with hundreds of combined years of experience.
Need technical advice? Call and ask for Duncan's Hawker Tech Reps in Lincoln or Battle Creek.*

*In Lincoln, NE, contact Dan Fuoco
at 800.228.4277*

*In Battle Creek, MI, contact Pete Kilmartin
at 800.525.2376*