

OWNER: FIRST SOUTHEAST AVIATION
ADDRESS: 4401 WEST KENNEDY BLVD
TAMPA FL 33609
PHONE: 727-639-0155
FAX: 813-639-1655

OPERATOR: ELITE AIR, INC.
ADDRESS: 100 2ND AVENUE SOUTH
ST. PETERSBURG FL 33701
PHONE: 727-507-7600
FAX: 727-507-7663

ANALYST: ERIC FOSTER
EMAIL: EFOSTER@CAMPSYSTEMS.COM

+1-316-928-7887 (DIRECT)
1-866-581-2267 (OFFICE)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (EFAX-CARDS)

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

Filter Criteria: Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

AIRCRAFT SERIAL/REGNO: 45-533/N173DS **MODEL:** LEARJET 75 **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES		LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE:	07-MAR-2016	794.3 A/C HRS	as of 05-JUN-2020	A/C HRS	as of ___/___/___
		521 AFL	as of 05-JUN-2020	AFL	as of ___/___/___
		361 APH	as of 26-MAY-2020	APH	as of ___/___/___
		479 APS	as of 26-MAY-2020	APS	as of ___/___/___

APU SERIAL/PART: P-572/3800726-1 **MODEL:** RE100 (CIMMS) **MANUFACTURER:** HONEYWELL

INSTALLED ON 13-NOV-2015		LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS		361 APU HRS	as of 26-MAY-2020	APU HRS	as of ___/___/___
0 APUS		479 APUS	as of 26-MAY-2020	APUS	as of ___/___/___

ENGINE NO. 1 SERIAL/PART: P-137284/3062075-1 **MODEL:** TFE731-40BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON 13-NOV-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	794.3 ENG. HRS	as of 05-JUN-2020	ENG. HRS	as of ___/___/___
0 ENC		521 ENC	as of 05-JUN-2020	ENC	as of ___/___/___

ENGINE NO. 2 SERIAL/PART: P-137283/3062075-1 **MODEL:** TFE731-40BR-1B **MANUFACTURER:** HONEYWELL

INSTALLED ON 13-NOV-2015		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	794.3 ENG. HRS	as of 05-JUN-2020	ENG. HRS	as of ___/___/___
0 ENC		521 ENC	as of 05-JUN-2020	ENC	as of ___/___/___



Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 05	TIME LIMITS/MAINTENANCE CHECKS							
0000001	12 MONTH SERVICING CHECKS							
	PKG 1	MOS	12				13-FEB-2020	28-FEB-2021
		HRS/MSC					746.3	14-MAR-2021
	REF: See Workcard	AFL					493	
0000002	36 MONTH ZONAL INSPECTIONS							
	PKG 2	MOS	36		-20		27-MAR-2019	31-MAR-2022
		HRS/MSC					588.8	14-APR-2022
	REF: See Workcard	AFL					384	
0000003	72 MONTH ZONAL INSPECTIONS							
	PKG 3	MOS	72				07-MAR-2016	31-MAR-2022
		HRS/MSC					0	14-APR-2022
	REF: See Workcard	AFL					0	
0000004	108 MONTH ZONAL INSPECTIONS							
	PKG 4	MOS	108				07-MAR-2016	31-MAR-2025
		HRS/MSC					0	14-APR-2025
	REF: See Workcard	AFL					0	
0000005	600 HOUR / 36 MONTH INSPECTIONS							
	PKG 5	MOS	36				17-NOV-2018	30-NOV-2021
		HRS/MSC	600				532.7	14-DEC-2021
	REF: See Workcard	AFL						1157.7

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
000006	1,200 HOUR / 72 MONTH INSPECTIONS							
	PKG 6	MOS	72			07-MAR-2016	31-MAR-2022	14-APR-2022
		HRS/MSC	1200	+14d/-14d		0	1200	1225
	REF: See Workcard	AFL		+25/-25		0		
000007	2,400 HOUR / 108 MONTH INSPECTIONS							
	PKG 7	MOS	108			07-MAR-2016	31-MAR-2025	14-APR-2025
		HRS/MSC	2400	+14d/-14d		0	2400	2425
	REF: See Workcard	AFL		+25/-25		0		
000008	4800 HOUR INSPECTIONS							
	PKG 8	MOS				07-MAR-2016		
		HRS/MSC	4800	-25		0	4800	
	REF: See Workcard	AFL				0		
000009	10000 HOUR INSPECTIONS							
	PKG 9	MOS				07-MAR-2016		
		HRS/MSC	10000	-25		0	10000	
	REF: See Workcard	AFL				0		
000010	RVSM INSPECTIONS							
	PKG 10	MOS	24			13-FEB-2020	28-FEB-2022	14-MAR-2022
		HRS/MSC		+14d/-14d		746.3		
	REF: See Workcard	AFL				493		



Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
000011	2400 HOUR - 4800 HOUR INITIAL INSPECTIONS								
	PKG 11	MOS					07-MAR-2016		
		HRS/MSC	4800	-25			0		4800
	REF: See Workcard	AFL					0		
000012	2400 HOUR - 10000 HOUR INITIAL INSPECTIONS								
	PKG 12	MOS					07-MAR-2016		
		HRS/MSC	10000	-25			0		10000
	REF: See Workcard	AFL					0		
000013	4800 HOUR - 10000 HOUR INITIAL INSPECTIONS								
	PKG 13	MOS					07-MAR-2016		
		HRS/MSC	10000	-25			0		10000
	REF: See Workcard	AFL					0		
000014	6000 HOUR - 10000 HOUR INITIAL INSPECTIONS								
	PKG 14	MOS					07-MAR-2016		
		HRS/MSC	10000	-25			0		10000
	REF: See Workcard	AFL					0		
ENGINE NO. 1 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-137284 Part # 3062075-1									
057110	NO. 1 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					13-FEB-2020		
		HRS/MSC	150	+100			746.3		(896.3) 896.3
	REF: LMM 72-00-00	ENC					493		996.3

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057120	NO. 1 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				28-OCT-2015		
		HRS/MSC	N/A			0		
	REF: LMM 72-00-00	ENC				0		
057130	NO. 1 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				17-NOV-2018		
		HRS/MSC	600	+50/-100	67.3	532.7	(1200) 1200	1250
	REF: LMM 72-00-00	ENC						
057140	NO. 1 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				13-FEB-2020		
		HRS/MSC	800	+50/-300		746.3	(1546.3) 1546.3	1596.3
	REF: LMM 72-00-00	ENC				493		
057150	NO. 1 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				28-OCT-2015		
		HRS/MSC	1200	+100/-200		0	(1200) 1200	1300
	REF: LMM 72-00-00	ENC				0		
057160	NO. 1 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				28-OCT-2015		
		HRS/MSC	1600	+50/-100		0	(1600) 1600	1650
	REF: LMM 72-00-00	ENC				0		

ENGINE NO. 2 Model : TFE731-20/-40/-60 (CIMMS) Serial # P-137283 Part # 3062075-1

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057110	NO. 2 ENGINE - 150 TO 250 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				13-FEB-2020		
		HRS/MSC	150	+100		746.3	(896.3) 896.3	996.3
	REF: LMM 72-00-00	ENC				493		
057120	NO. 2 ENGINE - 300 TO 440 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				23-OCT-2015		
		HRS/MSC	N/A			0		
	REF: LMM 72-00-00	ENC				0		
057130	NO. 2 ENGINE - 500 TO 650 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				17-NOV-2018		
		HRS/MSC	600	+50/-100	67.3	532.7	(1200) 1200	1250
	REF: LMM 72-00-00	ENC						
057140	NO. 2 ENGINE - 500 TO 850 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				13-FEB-2020		
		HRS/MSC	800	+50/-300		746.3	(1546.3) 1546.3	1596.3
	REF: LMM 72-00-00	ENC				493		
057150	NO. 2 ENGINE - 1000 TO 1300 HR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS							
	PKG 0	MOS				23-OCT-2015		
		HRS/MSC	1200	+100/-200		0	(1200) 1200	1300
	REF: LMM 72-00-00	ENC				0		



Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR	EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
057160	NO. 2 ENGINE - 1500 TO 1650 HOUR ROUTINE PERIODIC INSP PER MANUFACTURERS INSTRUCTIONS								
	PKG 0	MOS					23-OCT-2015		
	REF: LMM 72-00-00	HRS/MSC	1600				0	(1600) 1600	1650
		ENC					0		



Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 00	INFORMATION								
CA75-160608	REVIEW LEARJET 75 EINSPECTOR REVISION 08JUN2016								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CA75	HRS/MSC - AFL							
CA75-161207	REVIEW LEARJET 75 EINSPECTOR REVISION 2016.12.07								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CA75	HRS/MSC - AFL							
CA75-170110	REVIEW LEARJET 75 EINSPECTOR REVISION 2017.01.10								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CA75	HRS/MSC - AFL							
CA75-181109	REVIEW LEARJET 75 EINSPECTOR REVISION 2018.11.09								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CA75	HRS/MSC - AFL							
CA75-190429	REVIEW LEARJET 75 EINSPECTOR REV 2019.04.29								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF CA75	HRS/MSC - AFL							
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
EC04-180802	NO. 1 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	HRS/MSC - ENC							
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC04-180802	NO. 2 ENGINE - REVIEW TFE731-20/-40/-60 (CIMMS) LMM TR 5-17								
		MOS					(EBT)		
REQUIREMENT CHANGE FORMS	REF: RCF EC04-180802	HRS/MSC -							
		ENC							

CHAPTER 05 TIME LIMITS/MAINTENANCE CHECKS

050001	OBTAIN APU HOURS AND UPDATE CAMP								
		DAYS	30				26-MAY-2020	25-JUN-2020	
		HRS/MSC					787.8		
	REF:	AFL					517		

050002	CALIBRATE WEIGHT SCALE ONBOARD AIRCRAFT								
		MOS	12				17-JAN-2020	31-JAN-2021	
		HRS/MSC					725.4		
	REF:	AFL					477		

CHAPTER 08 LEVELING AND WEIGHING

082000	REWEIGH AIRCRAFT								
		MOS	36				17-NOV-2018	30-NOV-2021	
		HRS/MSC					532.7		
	REF: See Workcard	AFL							

CHAPTER 11 PLACARDS AND MARKINGS

1130000 (s)	CHECK BRIGHTNESS LEVEL OF ALL SELF-LUMINOUS PLACARDS.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 11-30-00	AFL					0		

CHAPTER 12 SERVICING

1210002 (s)	CHECK FLAP ACTUATORS - CHECK OIL LEVEL.						PKG		
	PKG 5	MOS	36	+14d/-14d			17-NOV-2018		
		HRS/MSC	600	+25/-25			532.7		
	REF: AMM 12-21-03	AFL							

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1210003 (s)	LUBRICATE FLAP ACTUATOR BALLNUT PKG 1 REF: AMM 12-21-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210004 (s)	LUBRICATE FLAP FLEXIBLE DRIVE SHAFTS - HAND LUBRICATE. PKG 8 REF: AMM 12-21-03	MOS HRS/MSC AFL	4800	+25/-25			PKG 07-MAR-2016 0 0		
1210005 (s)	LUBRICATE NOSE LANDING GEAR TRUNNION PIN PKG 1 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210006 (s)	LUBRICATE NOSE LANDING GEAR ACTUATOR ATTACH FITTING PKG 1 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210009 (s)	LUBRICATE NOSE GEAR DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210011 (s)	LUBRICATE MAIN LANDING GEAR ACTUATOR JOINTS PKG 1 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210012 (s)	LUBRICATE MAIN LANDING GEAR AXLE BEAM/PISTON JOINTS PKG 1 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1210013 (s)	LUBRICATE MAIN LANDING GEAR TORQUE LINKS PKG 1 REF: AMM 12-21-01	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210014 (s)	LUBRICATE MAIN LANDING GEAR DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210016 (s)	LUBRICATE PASSENGER/CREW DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210017 (s)	LUBRICATE PASSENGER/CREW DOOR PINS PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210018 (s)	LUBRICATE PASSENGER/CREW DOOR TENSION BOLTS PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210019 (s)	LUBRICATE EMERGENCY EXIT DOOR LATCHING MECHANISM PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210020 (s)	LUBRICATE EMERGENCY EXIT DOOR PINS PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1210021 (s)	LUBRICATE BAGGAGE COMPARTMENT DOOR LATCH PINS PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210022 (s)	LUBRICATE BAGGAGE COMPARTMENT DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210023 (s)	LUBRICATE OXYGEN SYSTEM SERVICING DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210024 (s)	LUBRICATE TOILET SERVICING DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210025 (s)	LUBRICATE PRESSURE REFUELING STATION DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210026 (s)	LUBRICATE FUSELAGE FUEL FILLER DOOR HINGE PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
1210027 (s)	LUBRICATE TAILCONE ACCESS DOOR PINS PKG 1 REF: AMM 12-21-02	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1210028 (s)	LUBRICATE TAILCONE ACCESS DOOR HINGE PKG 1	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
	REF: AMM 12-21-02	HRS/MSC AFL							
1210029 (s)	LUBRICATE MAIN LANDING GEAR TRUNNION PIN PKG 1	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
	REF: AMM 12-21-01	HRS/MSC AFL							
+ 1210060 (s)	MAIN LANDING GEAR UPLOCK ACTUATOR - LUBRICATE PKG 1	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
	REF: AMM 12-21-01	HRS/MSC AFL							
+ 1210061 (s)	NOSE GEAR SHOCK STRUT - SERVICE PKG 5	MOS	36	+14d/-14d			PKG 07-MAR-2016 0 0		
	REF: AMM 12-10-02	HRS/MSC AFL	600	+25/-25					
+ 1210062 (s)	MAIN GEAR SHOCK STRUT - SERVICE PKG 5	MOS	36	+14d/-14d			PKG 07-MAR-2016 0 0		
	REF: AMM 12-10-03	HRS/MSC AFL	600	+25/-25					
+ 1221037 (s)	LUBRICATE ROLLING SURFACES OF MAIN AND NOSE FLAP ROLLER TRACKS PKG 1	MOS	N/A				PKG 13-FEB-2020 746.3 493		
	REF: AMM 12-21-03	HRS/MSC AFL							
1221042 (s)	LUBRICATE HORIZONTAL STABILIZER UPPER AND LOWER TORQUE LINKS PKG 5	MOS	36	+14d/-14d			PKG 17-NOV-2018 532.7		
	REF: AMM 12-21-03	HRS/MSC AFL	600	+25/-25					

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
1227000 (s)	LUBRICATE EMERGENCY PARK BRAKE HANDLE SHAFT PKG 1	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
	REF: AMM 12-27-00	HRS/MSC AFL							
CHAPTER 21 AIR CONDITIONING									
212001	LH CHECK VALVE 6621000000-043 3323	MOS			N:0		07-MAR-2016 0 0		
	REF: AMM 21-20-03	HRS/MSC AFL	O/C		N:0 N:0				
212002	RH CHECK VALVE 6621000000-043 3377	MOS			N:0		07-MAR-2016 0 0		
	REF: AMM 21-20-03	HRS/MSC AFL	O/C		N:0 N:0				
2130000 (s)	INSPECT PRIMARY AND SECONDARY OUTFLOW VALVES PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016 0 0		
	REF: See Workcard	HRS/MSC AFL	1200	+25/-25					
2130001 (s)	REPLACE OUTFLOW VALVE AIR FILTER PKG 7	MOS	108	+14d/-14d			PKG 07-MAR-2016 0 0		
	REF: AMM 21-30-04	HRS/MSC AFL	2400	+25/-25					
2130002 (s)	** PRESSURIZATION CONTROL SYSTEM - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016 0 0		
CMR**	REF: AMM 21-30-00	HRS/MSC AFL	1200	+25/-25					
213001	LH EMERGENCY PRESSURIZATION VALVE 3291224-1 1508	MOS			N:0		07-MAR-2016 0 0		
	REF: AMM 21-31-01	HRS/MSC AFL	O/C		N:0 N:0				

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213002	RH EMERGENCY PRESSURIZATION VALVE 3291224-1 1509 REF: AMM 21-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
213003	CABIN PRESSURE CONTROLLER 6621300000-027 150-K0237 REF: AMM 21-30-03	MOS HRS/MSC AFL	O/C				28-APR-2016 23.3 15		
213031	PRIMARY OUTFLOW VALVE ASSY PN SN-UNKNOWN REF: AMM 21-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
213032	SECONDARY OUTFLOW VALVE ASSY PN SN-UNKNOWN REF: AMM 21-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
213055	ABSOLUTE BAROMETRIC PRESSURE SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
213056	ABSOLUTE BAROMETRIC PRESSURE (OPTION) SWITCH PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
213110	CABIN PRESSURE CHECK VALVE 130158-3-1 65-A2059 REF: AMM 21-30-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2140001	TEST/CLEAN LEFT OZONE CONVERTER PN SN-UNKNOWN REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			07-MAR-2016 0 0	3600	3625
2140001	TEST/CLEAN RIGHT OZONE CONVERTER PN SN-UNKNOWN REF: AMM 21-20-12	MOS HRS/MSC AFL	3600	+25/-25			07-MAR-2016 0 0	3600	3625
2140002	LEFT OZONE CONVERTER PN SN-UNKNOWN REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
2140002	RIGHT OZONE CONVERTER PN SN-UNKNOWN REF: AMM 21-20-12	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
2141001 (s)	VISUAL INSPECTION WATER SEPARATOR COALESCER BAG . CLEAN IF NECESSARY. PKG 1 REF: AMM 21-50-03	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
2145000 (s)	VISUAL INSPECTION ECS PLENUM ASSEMBLY CHECK VALVES . VERIFY FREEDOM OF MOVEMENT OF BUTTERFLY ASSEMBLY. PKG 7 REF: See Workcard	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
215001	ENVIRONMENTAL CONTROL UNIT 6621000000-089 827 REF: AMM 21-50-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
215003	WATER SEPARATOR ASSY 6621000000-031 533 REF: AMM 21-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
2150054	PERFORM COMPRESSOR DRIVE MOTOR WEAR INSPECTION ON BRUSHES PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	-					07-MAR-2016 0 0	
2150055	OVERHAUL COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	-					07-MAR-2016 0 0	
2150056 (s)	** AUXILIARY HEAT SYSTEM - PERFORM FUNCTIONAL TEST PKG 5 REF:	MOS HRS/MSC AFL	N/A					PKG 17-NOV-2018 532.7	
2150057 (s)	** AUXILIARY HEAT SYSTEM - PERFORM AUXILIARY HEATER ELECTRICAL AND TEMPERATURE SWITCH TEST PKG 6 REF:	MOS HRS/MSC AFL	N/A					PKG 07-MAR-2016 0 0	
2150059 (s)	CHECK AIR CONDITIONING SYSTEM - PERFORM LOAD SHED ASSEMBLY CHECK. PKG 6 REF:	MOS HRS/MSC AFL	N/A					PKG 07-MAR-2016 0 0	
215102	COMPRESSOR DRIVE MOTOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0				07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216008 (s)	INSPECT TEMPERATURE CONTROL SYSTEM - INSPECT AND CLEAN CABIN AND COCKPIT TEMPERATURE CONTROL VALVE SERVO AIR FILTERS. PKG 5	MOS	36	+14d/-14d			17-NOV-2018		
	REF: AMM 21-60-11	HRS/MSC AFL	600	+25/-25			532.7		
216001	TEMPERATURE, ECS CONTROLLER PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-60-10	AFL		N:0			0		
216013	LH / CABIN TEMPERATURE CONTROL VALVE 6621000000-047	MOS		N:0			07-MAR-2016		
	1490	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
216014	RH / COCKPIT TEMPERATURE CONTROL VALVE 6621000000-047	MOS		N:0			07-MAR-2016		
	1495	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
216025	TEMP SELECTOR PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-60-01	AFL		N:0			0		
216081	COCKPIT TEMPERATURE DUCT SENSOR PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-60-07	AFL		N:0			0		
216084	CABIN TEMPERATURE DUCT SENSOR PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 21-60-06	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 22	AUTO FLIGHT								
221002	ELEVATOR GSA 9000 SERVO ACTUATOR 011-02213-10 2JL005774 REF: AMM 22-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2210030 (s)	TENSION CHECK PITCH SERVO CABLES PKG 6 REF: AMM 22-10-03	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
2210031 (s)	TENSION CHECK ROLL SERVO CABLES PKG 6 REF: AMM 22-10-05	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
2210032 (s)	TENSION CHECK YAW SERVO CABLES PKG 6 REF: AMM 22-10-07	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
2210034 (s)	** AUTOPILOT AUTOTRIM FUNCTION AND MISTRIM ANNUNCIATION - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 22-10-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
2210036 (s)	** RUDDER BOOST - PERFORM THE FLAP POSITION FAIL CONTROL COMPARISON MONITOR CHECK PKG 6 REF: AMM 22-50-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
2210037	** AUTOPILOT PITCH SERVO GEARBOX - REPLACE 011-02214-10 2Q7005692 REF: AMM 22-10-03	MOS HRS/MSC AFL	240	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2036 14-APR-2036	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2210038	** AUTOPILOT ROLL SERVO GEARBOX - REPLACE 011-02214-10 2Q7005642 REF: AMM 22-10-04	MOS HRS/MSC AFL	240	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2036	14-APR-2036
CMR**									
2210039	** AUTOPILOT YAW SERVO GEARBOX - REPLACE 011-02214-11 2Q8005116 REF: AMM 22-10-07	MOS HRS/MSC AFL	240	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2036	14-APR-2036
CMR**									
221004	AILERON GSA 9000 SERVO ACTUATOR 011-02213-10 2KL005773 REF: AMM 22-10-04	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
221006	RUDDER GSA 9000 SERVO ACTUATOR 011-02213-10 2KL005728 REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
221008	PRIMARY AUTOPILOT TRIM, GTA 82 ADAPTER 011-00960-20 1A2000757 REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
221009	SECONDARY AUTOPILOT TRIM, GTA 82 ADAPTER 011-00960-20 1A2000756 REF: AMM 22-10-08	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
221040	GMC 7250 CONTROLLER 011-02544-01 26E015109 REF: AMM 22-10-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221061	YAW (SM-205) SERVO ASSY PN SN-UNKNOWN REF: AMM 22-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
CHAPTER 23 COMMUNICATIONS									
230001	UNILINK UL-701 TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
230002	CONFIGURATION (OPTION) MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
230003	CONFIGURATION MODULE P14126 1412614143 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
230004	CONFIGURATION (ACID #) MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
230005	SWIFT BROADBAND CONFIGURATION MODULE SBU MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
230006	SWIFT BROADBAND CONFIGURATION MODULE SBU (SOFTWARE OPT) MODULE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231000 (s)	** EMER COM SWITCH - PERFORM OPERATIONAL CHECK PKG 7	MOS	108	+14d/-14d			PKG	07-MAR-2016	
CMR**	REF: AMM 23-10-00	HRS/MSC AFL	2400	+25/-25			0 0		
231001	GMA 36 (LH) AUDIO PANEL 011-01793-00 1HF006557 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
231002	GMA 36 (RH) AUDIO PANEL 011-01793-00 1HF006577 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
231003	CLEARANCE DELIVERY SYSTEM ASSEMBLY SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
231011	NO. 2 KPA 1052 (OPTION) POWER AMPLIFIER 064-01072-0101 KPA1052-7236 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
231012	NO. 1 KPA 1052 (OPTION) POWER AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
231030	KRX 1053 NO 1 (OPTION) HF RECEIVER 064-01073-0102 KRX1053-7655 REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231031	KRX 1053 NO 2 (OPTION) HF RECEIVER PN SN-UNKNOWN REF: AMM 23-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231032	VHF COMM (OPTION) ANTENNA ASSY PN SN-UNKNOWN REF: AMM 23-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231033	UPPER VHF ANTENNA ASSY PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231034	LOWER VHF ANTENNA ASSY PN SN-UNKNOWN REF: AMM 34-51-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231035	AFT AIR TO GROUND ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231036	FWD AIR TO GROUND ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231037	FWD WIFI ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231038	MID WIFI ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231039	AFT WIFI ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231040	UCS 5000 SERVER P17000-001 1700000042 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2312003 (s)	PERFORM VISUAL INSPECTION HF ANTENNA - CHECK FOR PROPER TENSION OF HF ANTENNA WIRE. PKG 6 REF: AMM 23-12-06	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
231202	KAC 1052 NO 1 (OPTION) ANTENNA COUPLER 064-01074-0101 KAC1052-7198 REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231203	KAC 1052 NO 2 (OPTION) ANTENNA COUPLER PN SN-UNKNOWN REF: AMM 23-12-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231300	AIR TO GROUND (ATG 5000) TRANSCEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231301	IRIDIUM TRANSCEIVER 011-02268-01 2HU005195 REF: AMM 23-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231303	VHF DATALINK RADIO, GDR 66 UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231330	FWD IRIDIUM ANTENNA PN SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231331	AFT IRIDIUM ANTENNA PN SN-UNKNOWN REF: AMM 23-13-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231501	LH AIRCELL CORDED SMART PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
231502	RH AIRCELL CORDED SMART PHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233005	AUDIO POWER AMPLIFIER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233006	PASSENGER ADDRESS AMPLIFIER PN SN-UNKNOWN REF: AMM 23-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233101	LH NO.1 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233102	LH NO.2 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233103	LH NO.3 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233104	LH NO.4 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233105	LH NO.5 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233106	LH NO.6 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233107	LH NO.7 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233108	LH NO.8 CABIN WINDOW PANEL (LAV) PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233109	RH NO.1 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233110	RH NO.2 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233111	RH NO.3 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233112	RH NO.4 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233113	RH NO.5 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233114	RH NO.6 CABIN (EMERGENCY EXIT DOOR) WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233115	RH NO.7 CABIN WINDOW PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233116	RH NO.8 CABIN WINDOW PANEL (LAV) PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233117	SPEAKER KIT PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233118	SPEAKER KIT PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233119	SPEAKER KIT PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
233120	SPEAKER KIT PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233121	SPEAKER KIT PANEL PN SN-UNKNOWN REF: AMM 23-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2360020	FUNCTIONAL TEST AIRCRAFT STATIC DISCHARGERS REF: AMM 23-60-00	MOS HRS/MSC AFL	96 O/C	+14d/-14d			07-MAR-2016 0 0	31-MAR-2024	14-APR-2024
236004	2 CHANNEL SATELLITE DIGITAL AUDIO RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
236005	2 CHANNEL SATELLITE DIGITAL AUDIO (ID# CHANNEL 1) RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
236006	2 CHANNEL SATELLITE DIGITAL AUDIO (ID# CHANNEL 2) RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
236007	2-CHANNEL (OPTION) XM-RADIO INSTALLATION KIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
236010	XM WEATHER RADIO DATA PORT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237000 (s)	FUNCTIONAL TEST COCKPIT VOICE RECORDER PKG 6 REF: AMM 23-70-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
237001	COCKPIT VOICE (120 MIN) RECORDER 2100-1025-22 1082037 REF: AMM 23-70-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
237005	MULTI AXIS INERTIA SWITCH PN SN-UNKNOWN REF: AMM 23-70-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
237019	SURFACE MOUNT, BLK MICROPHONE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
237031	CVR PREAMPLIFIER PN SN-UNKNOWN REF: AMM 23-70-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
237032	MINI QUICK ACCESS RECORDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 24 ELECTRICAL POWER									
2420000	** LEFT ALTERNATOR - PERFORM BEARING REPLACEMENT 90278-2 1624 REF: AMM 24-20-01	MOS HRS/MSC AFL	1200	+25/-25			07-MAR-2016 0 0	1200	1225

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242000	** RIGHT ALTERNATOR - PERFORM BEARING REPLACEMENT								
	90278-2	MOS					07-MAR-2016		
	1622	HRS/MSC	1200	+25/-25			0	1200	1225
CMR**	REF: AMM 24-20-01	AFL					0		
242001	LH AC 5 KVA ALTERNATOR								
	90278-2	MOS		N:0			07-MAR-2016		
	1624	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-20-01	AFL		N:0			0		
242002	RH AC 5 KVA ALTERNATOR								
	90278-2	MOS		N:0			07-MAR-2016		
	1622	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-20-01	AFL		N:0			0		
242050	RC 25 AMP CIRCUIT AFT (OPTION) BREAKER								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
242052	NO. 1 REMOTE CONTROL CIRCUIT BREAKER								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
242054	NO. 2 REMOTE CONTROL CIRCUIT BREAKER								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
242055	RC 5 AMP REMOTE CIRCUITCB5035 (OPTION) BREAKER								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242056	RC 35 AMP REMOTE CIRCUIT CB5036 (OPTION) BREAKER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
242082	STATIC 1200 VA 115 VAC 60H INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			07-MAR-2016 0 0		
242083	STATIC 1200 VA 230 60H (OPTION) INVERTER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R	N:0 N:0 N:0			07-MAR-2016 0 0		
2430003	OVERHAUL LH STARTER/GENERATOR 6608458-013 P1160 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			07-MAR-2016 0 0	1200	1225
2430003	OVERHAUL RH STARTER/GENERATOR 6608458-013 P1159 REF: AMM 24-30-01	MOS HRS/MSC AFL	1200	+25/-25			07-MAR-2016 0 0	1200	1225
243001	LH STARTER/GENERATOR 6608458-013 P1160 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
243002	RH STARTER/GENERATOR 6608458-013 P1159 REF: AMM 24-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243003	APU STARTER/GENERATOR 6608458-010 Y01125 REF: AMM 49-40-01	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			18-JAN-2017 107.7 70		
243019	UPPER STARTING TURBINE LEAD ACID BATTERY RG-380E/40L 41032300 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m N:0 N:0 N:0			13-FEB-2020 746.3 493	29-FEB-2024	31-MAR-2024
LIFE LIMIT									
243020	LOWER STARTING TURBINE LEAD ACID BATTERY RG-380E/40L 40951533 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m N:0 N:0 N:0			13-FEB-2020 746.3 493	29-FEB-2024	31-MAR-2024
LIFE LIMIT									
2431003 (s)	** BATTERY TEMPERATURE CONTROL AND INDICATION - PERFORM INSPECTION CHECK PKG 7 REF: AMM 24-31-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
CMR**									
2431066	CAPACITY CHECK EMERGENCY BATTERY 100-2692-02 15033W0008 REF: CMM 24-30-17	DAYS HRS/MSC AFL	550 4000	+55/-55 +400/-400			27-SEP-2019 686.2 451	30-MAR-2021 4686.2	24-MAY-2021 5086.2
2431067	EMERGENCY BATTERY 100-2692-02 15033W0008 REF: AMM 24-32-01	MOS HRS/MSC AFL	O/C				23-OCT-2019 686.2 451		
2431068	CAPACITY CHECK LOWER STARTING TURBINE LEAD ACID BATTERY RG-380E/40L 40951533 REF: See Workcard	MOS HRS/MSC AFL	12 1000				13-FEB-2020 746.3 493	28-FEB-2021 1746.3	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2431068	CAPACITY CHECK UPPER STARTING TURBINE LEAD ACID BATTERY RG-380E/40L 41032300 REF: See Workcard	MOS HRS/MSC AFL	12 1000				13-FEB-2020 746.3 493	28-FEB-2021 1746.3	
244001	IN-SEAT (COCKPIT) (OPTION) INVERTER POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
244002	IN-SEAT (FWD CABIN) INVERTER POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
244003	IN-SEAT (AFT CABIN) INVERTER POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
244004	AUXILIARY CABIN OUTLET INVERTER (OPTION) POWER SUPPLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2450001 (s)	** AUXILIARY POWER SUPPLIES - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 24-00-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
2450002 (s)	** ELECTRICAL SYSTEM CONTROL - PERFORM OPERATIONAL CHECK PKG 6 REF: AMM 24-00-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2450023 (s)	** EMER BATT LOW AND GEN AMPS HIGH INDICATION - PERFORM OPERATIONAL CHECK						PKG		
	PKG 5	MOS	36	+14d/-14d			17-NOV-2018		
		HRS/MSC	600	+25/-25			532.7		
CMR**	REF: AMM 24-00-00	AFL							
2460001 (s)	** POWER DISTRIBUTION SYSTEM - PERFORM SQUAT SWITCH CHECK.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
CMR**	REF: AMM 24-60-00	AFL					0		
246001	23B001 (LH FWD) POWER DISTRIBUTION PANEL								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-60-02	AFL		N:0			0		
246002	23B001 (RH FWD) POWER DISTRIBUTION PANEL								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-60-02	AFL		N:0			0		
246003	AFT POWER DISTRIBUTION (LH AFT) PANEL								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-60-03	AFL		N:0			0		
246004	AFT POWER DISTRIBUTION (RH AFT) PANEL								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 24-60-03	AFL		N:0			0		
CHAPTER 25	EQUIPMENT/FURNISHINGS								
25-60-00/CT1	RENEWAL EMERGENCY LOCATOR TRANSMITTER BEACON REGISTRATION								
		MOS	24				24-MAR-2020	24-MAR-2022	
		HRS/MSC					787.8		
CUSTOMER CODE	REF:	AFL					517		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2510001 (s)	VISUAL INSPECTION CREW SEATS AND SEAT BELTS PKG 1 REF: AMM 25-10-50	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
2510003	HYDROSTATIC TEST CABIN FIRE EXTINGUISHER C352TS B-02761138 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			01-DEC-2015	31-DEC-2027	14-JAN-2028
2510003	HYDROSTATIC TEST COPILOT FIRE EXTINGUISHER A344T B-02759858 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			20-APR-2016	30-APR-2028	14-MAY-2028
2510003	HYDROSTATIC TEST PILOT FIRE EXTINGUISHER A344T B-02759862 REF: AMM 26-23-00	MOS HRS/MSC AFL	144	+14d/-14d			20-APR-2016	30-APR-2028	14-MAY-2028
251001	LH FLT DECK SIDEWALL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
251002	RH FLT DECK SIDEWALL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
251003	LH FLT DECK SIDEWALL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251004	RH FLT DECK SIDEWALL PANEL PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251005	COVER PN SN-UNKNOWN REF: AMM 25-10-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251007	FLT-DECK (LH) LWR SIDEWALL PANEL ASSY PN SN-UNKNOWN REF: AMM 25-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251008	FLT-DECK (RH) LWR SIDEWALL PANEL ASSY PN SN-UNKNOWN REF: AMM 25-10-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251009	PEDESTAL COVER ASSY PN SN-UNKNOWN REF: AMM 25-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251011	LH FLT DECK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251012	RH FLT DECK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251013	LH FLT DECK TOP CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251014	RH FLT DECK TOP CAP PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251101	LH FLT DECK TRIM TRIM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251102	RH FLT DECK TRIM TRIM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251201	FLT DECK CENTER POST PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251202	ENTRYWAY HEADLINER ASSY PN SN-UNKNOWN REF: AMM 25-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251203	CABIN DOOR-UPPER PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251204	CABIN DOOR-UPPER COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251205	LIGHT HOUSING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251206	BRKT-LIGHT HOUSING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251207	CABIN HEADLINER ASSY PN SN-UNKNOWN REF: AMM 25-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251303	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251304	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251305	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251306	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251307	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251308	OXYGEN LID COVER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251401	LH CABIN WINDOW PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251403	RH FWD CABIN WINDOW PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251405	RH AFT CABIN WINDOW PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251407	LH FWD WINDOW CLOSEOUT PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251409	ESC HATCH WINDOW PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251410	ESC HATCH ESCUTCHEON ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251421	LH CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251422	LH CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251423	LH CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251424	LH CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251426	CABIN DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251427	CABIN DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251428	CABIN DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251429	CABIN DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251513	CABIN (LH) FWD CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251515	CABIN (LH) AFT CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251517	CABIN (RH) FWD CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251519	CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251520	CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251521	CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251522	CONVENIENCE PANEL POD ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251523	CABIN (RH) AFT CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251531	CABIN TABLE (LEATHER) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251532	CABIN TABLE (VENEER) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251533	CABIN TABLE (VENEER) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251534	CABIN TABLE (VENEER) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251535	CABIN TABLE (VENEER W/INLAY) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251536	MID CABIN LH AIRCELL, USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251537	MID CABIN LH WIRELESS AIRCELL, USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251538	MID CABIN RH AIRCELL, 4.3-USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251539	MID CABIN RH WIRELESS AIRCELL, 4.3-USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251540	LH MID CABIN, BOX, USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251541	RH MID CABIN, BOX, 4.3 -HDMI (FWD) - USB (AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251542	LH FWD USB SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251543	RH FWD/LH AFT, USB SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251544	MID CABIN LH, USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251545	MID CABIN RH, 4.3-USB (FWD/AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251546	ESC HATCH SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251547	RH AFT SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251548	CABIN TABLE (VENEER) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251549	LH FWD USB-HDMI SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251550	RH FWD/LH AFT, HDMI SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251551	MID CABIN LH, HDMI (FWD) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251552	MID CABIN RH, 4.3-HDMI (FWD) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251553	MID CABIN LH, HDMI (AFT) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251554	MID CABIN LH AIRCELL, HDMI (FWD) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251555	MID CABIN LH AIRCELL, HDMI (AFT) SIDELEDGE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251556	MID CABIN LH WIRELESS AIRCELL, HDMI (FWD) SIDELEDGE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251557	MID CABIN LH WIRELESS AIRCELL, HDMI (AFT) SIDELEDGE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251558	MID CABIN RH AIRCELL, 4.3 HDMI (FWD) SIDELEDGE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251559	MID CABIN RH WIRELESS AIRCELL, 4.3 HDMI (FWD) SIDELEDGE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251560	ESC HATCH (LEATHER) TABLE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
251561	ESC HATCH (VENEER) TABLE ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251562	ESC HATCH (VENEER W/INLAY) TABLE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251601	COVER DOOR MECHANISM PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251602	ANGLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251603	BUMPER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251604	BUMPER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251611	IPOD DOCKING HARNESS PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251612	IPOD AUTHENTICATION DONGLE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251613	AFT 12" LCD BULKHEAD MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251613	FWD 12" LCD BULKHEAD MONITOR- LCD1209-001-001 000041 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				20-OCT-2018 507.9 328		
251614	#1 15" LCD BULKHEAD MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251614	#2 15" LCD BULKHEAD MONITOR- PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251615	FWD L/H LEARJET, 28 VDC RECT. EXIT SIGN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251615	LOWER LH FWD LEARJET, 28 VDC RECT. EXIT SIGN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251615	RH AFT LEARJET, 28 VDC RECT. EXIT SIGN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251615	UPPER LH FWD LEARJET, 28 VDC RECT. EXIT SIGN PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251616	BEZEL FOR MSP3009 1 BUTTON PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251617	BEZEL FOR MSP3009 5 BUTTON PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251618	BEZEL FOR SCW1010-001-000 RH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251619	BEZEL FOR SCW1010-002-000 LH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251631	MEMBRANE (DOOR/LIGHT) SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251632	MEMBRANE (LAVATORY) SWITCH PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251633	CORE MODULE TWO (LH FWD) PCU PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251634	CORE MODULE TWO (RH FWD) PCU PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251635	CORE MODULE TWO (LH AFT) PCU PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251636	CORE MODULE TWO (RH AFT) PCU PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251637	4.3" PASSENGER CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251638	4.3" PASSENGER CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251639	4.3" PASSENGER CONTROL UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251640	REMOTE MAINTENANCE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251651	LH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251652	LH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251653	LH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251654	LH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251655	RH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251656	RH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251657	RH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251658	RH SCROLL WHEEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251901	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251902	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251903	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251904	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251905	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251906	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251907	HEADPHONE-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251908	HEADPHONE-USB-HDMI JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
251909	ETHERNET-USB JACK PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252000 (s)	VISUAL INSPECTION PASSENGER SEAT AND SEAT BELTS PKG 1 REF: GENERIC NO REF	MOS HRS/MSC AFL	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
252003	ASHTRAY ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252004	ASHTRAY ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252005	FLT DECK CUP HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252006	FLT DECK CUP HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252007	FLT DECK CUP HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252008	FLT DECK CUP HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252011	(POS 1) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252012	(POS 2) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252013	(POS 3) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252014	(POS 4) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252015	(POS 5) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252016	(POS 6) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252017	(POS 7) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252018	(POS 8) PASSENGER SEAT ASSY PN SN-UNKNOWN REF: AMM 25-20-45	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252090	AC OUTLET UNIT WITH WHITE (LAV) LED PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252091	AC OUTLET UNIT WITH WHITE (LH FWD) LED PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252092	AC OUTLET UNIT WITH WHITE (RH FWD) LED PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252093	AC OUTLET UNIT WITH WHITE (LH AFT) LED PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252094	AC OUTLET UNIT WITH WHITE (RH AFT) LED PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252101	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252102	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252103	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252104	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252105	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252106	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252107	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252108	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252109	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252110	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252111	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252112	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252113	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252114	RH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252115	LH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252116	ESC HATCH WINDOW SHADE ASSY PN SN-UNKNOWN REF: AMM 25-20-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252210	BLU-RAY DISC PLAYER BDP3009-001-001 000346 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-DEC-2018 549.6 354		
252215	SEAT DISPLAY CONNECTION BRACKET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252216	SEAT DISPLAY CONNECTION BRACKET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252217	SEAT DISPLAY CONNECTION BRACKET PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252221	LH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252222	RH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252223	LH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252224	RH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252225	LH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252226	RH 7" SEAT TOUCH DISPLAY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252303	LH FWD HDMI (M70) SIDELEDGE ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252341	AFT ETHERNET DECODER UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252341	FWD ETHERNET DECODER UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252342	AFT ETHERNET ENCODER UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252342	FWD ETHERNET ENCODER UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252343	ETHERNET INTERFACE UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252401	LH FLT DECK HEADLINER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252402	RH FLT DECK HEADLINER ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252601	EXT RANGE O2 CLOSE OUT ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252701	LAV FLOOR CLOSEOUT ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252703	FLOOR CLOSEOUT PANEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252801	LH LAV CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252802	RH LAV CONVENIENCE PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
252803	LAV DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252804	LAV DOWNWASH LIGHT LENS PN SN-UNKNOWN REF: AMM 25-40-15	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252901	LH AFT WALL PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252903	RH AFT WALL PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252905	CENTER AFT WALL PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
252907	UPPER AFT WALL PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253042	WAVEJET MICROWAVE OVEN PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253101	FWD STORAGE (LH) CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253105	FWD STORAGE (LH) (W/GALLEY REST) CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253203	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253207	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253209	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253211	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253213	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253215	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253217	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253219	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253221	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253223	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253225	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253227	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253229	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253231	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253233	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253235	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253237	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253239	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253241	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253243	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253245	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253247	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253249	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253251	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253253	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253255	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253257	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253259	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253261	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253263	FWD GALLEY (RH) CABINET ASSY PN SN-UNKNOWN REF: AMM 25-30-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253301	TABLE STORAGE (LEATHER) CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253303	TABLE STORAGE (VENEER) CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253305	TABLE STORAGE (VENEER W/INLAY) CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253701	LH LAV WINDOW PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253702	RH LAV WINDOW PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-20	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253801	TOILET SHROUD ASSY PN SN-UNKNOWN REF: AMM 25-40-35	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253901	LH LAV SIDELEDGE ASSY PN SN-UNKNOWN REF: AMM 25-40-26	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253913	RH LAV SIDELEDGE ASSY PN SN-UNKNOWN REF: AMM 25-40-26	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253915	LH LAV DADO PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
253917	RH FWD LAV DADO PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
253919	RH AFT LAV DADO PANEL ASSY PN SN-UNKNOWN REF: AMM 25-40-25	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254001	LAV HEADLINER ASSY PN SN-UNKNOWN REF: AMM 25-40-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254002	LAV VANITY ASSY PN SN-UNKNOWN REF: AMM 25-40-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254003	LAV W/O SINK VANITY ASSY PN SN-UNKNOWN REF: AMM 25-40-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254004	LAV VANITY ASSY PN SN-UNKNOWN REF: AMM 25-40-40	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254007	LH AFT PARTITION ASSY PN SN-UNKNOWN REF: AMM 25-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254009	RH AFT PARTITION ASSY PN SN-UNKNOWN REF: AMM 25-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
254011	LH AFT (W/MONITOR) PARTITION ASSY PN SN-UNKNOWN REF: AMM 25-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254101	LAV PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254111	LAV SHELF ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
254112	FIRST AID KIT CABINET ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
255001	PILOT CONTROL WHEEL LIGHTED CHART HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
255002	CO-PILOT CONTROL WHEEL LIGHTED CHART HOLDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2560000	CLEAN CVR BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY. REF: AMM 25-61-01	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2020 746.3 493	28-FEB-2022	14-MAR-2022

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256000	CLEAN FDR BEACON SWITCH, PERFORM FUNCTIONAL TEST OF BEACON, AND PERFORM TEST OF ULB BATTERY.	MOS						07-MAR-2016	
N/A EQUIPMENT NOT INSTALLED	REF: AMM 25-61-01	HRS/MSC	N/A				0		
		AFL					0		
256001	PILOT SEAT ASSY 0820-0-L-1P00P1131 546 REF: AMM 25-10-50	MOS		N:0				07-MAR-2016	
		HRS/MSC	O/C	N:0			0		
		AFL		N:0			0		
256002	CO-PILOT SEAT ASSY 0820-0-R-1P00P1131 549 REF: AMM 25-10-50	MOS		N:0				07-MAR-2016	
		HRS/MSC	O/C	N:0			0		
		AFL		N:0			0		
256061	PILOT LIFE VEST 63600-501 L3066597 REF: AMM 25-60-01	MOS	120	N:0				07-MAR-2016	31-MAR-2026
OVERHAUL		HRS/MSC		N:0			0		
		AFL		N:0			0		
256062	CO-PILOT LIFE VEST 63600-501 L3066603 REF: AMM 25-60-01	MOS	120	N:0				07-MAR-2016	31-MAR-2026
OVERHAUL		HRS/MSC		N:0			0		
		AFL		N:0			0		
256063	NO. 1 LIFE VEST 63600-101 L3050691 REF: AMM 25-60-01	MOS	120	N:0				07-MAR-2016	31-MAR-2026
OVERHAUL		HRS/MSC		N:0			0		
		AFL		N:0			0		
256064	NO. 2 LIFE VEST 63600-101 L3050692 REF: AMM 25-60-01	MOS	120	N:0				07-MAR-2016	31-MAR-2026
OVERHAUL		HRS/MSC		N:0			0		
		AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256065	NO. 3 LIFE VEST 63600-101 L3050693 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256066	NO. 4 LIFE VEST 63600-101 L3050694 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256067	NO. 5 LIFE VEST 63600-101 L3050695 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256068	NO. 6 LIFE VEST 63600-101 L3050696 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256069	NO. 7 LIFE VEST 63600-101 L3050697 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256070	NO. 8 LIFE VEST 63600-101 L3050698 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									
256071	LAV LIFE VEST 63600-101 L3050699 REF: AMM 25-60-01	MOS HRS/MSC AFL	120	N:0 N:0 N:0			07-MAR-2016 0 0	31-MAR-2026	
OVERHAUL									

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256076	FIRST AID KIT 500939 030118007	MOS HRS/MSC AFL	DUE	0:0 0:0 0:0			22-APR-2020 787.8 517	30-APR-2021 M	
VENDOR RECOMMENDATION Expiry Date: 30-APR-2021 REF: GENERIC NO REF									
256100	COCKPIT VOICE RECORDER CVR PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2561001 (s)	INSPECT EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERIES. PERFORM FUNCTIONAL TEST OF ELT SYSTEM IN ACCORDANCE WITH FAR 91.207 (IF INSTALLED)						PKG 13-FEB-2020 746.3 493		
	PKG 1	MOS HRS/MSC AFL	12						
REF:									
+ 2561002	INSPECT CO-PILOT LIFE VEST 63600-501 L3066603	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
REF: AMM 25-60-01									
+ 2561002	INSPECT LAV LIFE VEST 63600-101 L3050699	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
REF: AMM 25-60-01									
+ 2561002	INSPECT NO. 1 LIFE VEST 63600-101 L3050691	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
REF: AMM 25-60-01									
+ 2561002	INSPECT NO. 2 LIFE VEST 63600-101 L3050692	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
REF: AMM 25-60-01									

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 2561002	INSPECT NO. 3 LIFE VEST 63600-101 L3050693 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT NO. 4 LIFE VEST 63600-101 L3050694 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT NO. 5 LIFE VEST 63600-101 L3050695 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT NO. 6 LIFE VEST 63600-101 L3050696 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT NO. 7 LIFE VEST 63600-101 L3050697 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT NO. 8 LIFE VEST 63600-101 L3050698 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
+ 2561002	INSPECT PILOT LIFE VEST 63600-501 L3066597 REF: AMM 25-60-01	MOS HRS/MSC AFL	12				21-FEB-2020	28-FEB-2021	
256101	CVR ACCOUSTIC UNDERWATER BEACON PN SN-UNKNOWN REF: AMM 25-61-01	MOS HRS/MSC AFL					07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256101	FDR ACCOUSTIC UNDERWATER BEACON PN SN-UNKNOWN REF: AMM 25-61-01	MOS HRS/MSC AFL	N/A	N:0 N:0 N:0			07-MAR-2016 0 0		
N/A EQUIPMENT NOT INSTALLED									
256109	C406-N ELT 453-5060 252-00136 REF: AMM 25-62-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
256109A	FUNCTIONAL CHECK C406-N ELT 453-5060 252-00136 REF: FAR 91.207	MOS HRS/MSC AFL	N/A				16-FEB-2018 315.5 198		
256109B	INSPECT C406-N ELT 453-5060 252-00136 REF: FAR 91.207	MOS HRS/MSC AFL	12				13-FEB-2020 746.3 493	28-FEB-2021	
256115	ELT 406 ANTENNA BLADE PN SN-UNKNOWN REF: AMM 25-62-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
256201	ELT BATTERY PN SN-UNKNOWN REF: FAR 91.207	MOS HRS/MSC AFL	DUE				20-MAR-2016	01-APR-2021 M	
2566001	REPLACE CVR ULB BATTERY. REF: AMM 25-61-01	MOS HRS/MSC AFL	72	+14d/-14d			07-MAR-2016 0 0	31-MAR-2022	14-APR-2022

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2566001	REPLACE FDR ULB BATTERY.	MOS					07-MAR-2016		
N/A EQUIPMENT NOT INSTALLED	REF: AMM 25-61-01	HRS/MSC AFL	N/A				0 0		
259072	DEFIBRILLATOR (AED)	MOS		N:0			07-MAR-2016		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: GENERIC NO REF								
EAI-206	ELITE AIR 6 MONTH SAFETY CHECK	MOS	6				27-APR-2020	31-OCT-2020	
	REF:	HRS/MSC AFL					787.8 517		
CHAPTER 26 FIRE PROTECTION									
052620	INSPECT MONTHLY PORTABLE FIRE EXTINGUISHERS	DAYS	30				26-MAY-2020	25-JUN-2020	
	REF:	HRS/MSC AFL					787.8 517		
2610001	VISUAL INSPECTION LEFT ENGINE HOT SECTION FIRE DETECTOR ELEMENT	MOS					07-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC AFL	3000	+100/-100			0 0	3000	3100
2610001	VISUAL INSPECTION RIGHT ENGINE HOT SECTION FIRE DETECTOR ELEMENT	MOS					07-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC AFL	3000	+100/-100			0 0	3000	3100
261057	FIRE DETECT CONTROL (NO 1) UNIT	MOS		N:0			07-MAR-2016		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	AFL		N:0			0		
	REF: AMM 26-11-01								

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261058	FIRE DETECT CONTROL (NO 2) UNIT PN SN-UNKNOWN REF: AMM 26-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
261069	ANTI-ICE LEAK DETECT (LH BLEED AIR) UNIT PN SN-UNKNOWN REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
261070	ANTI-ICE LEAK DETECT (RH BLEED AIR) UNIT PN SN-UNKNOWN REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
261071	ANTI-ICE LEAK DETECT UNIT PN SN-UNKNOWN REF: AMM 26-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
261075	FIRE/OVERHEAT DETECTOR PN SN-UNKNOWN REF: AMM 26-13-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2620000 (s)	** ENGINE FIRE EXTINGUISHING SYSTEM FIRE SWITCH - PERFORM FUNCTIONAL TEST PKG 8 REF: AMM 26-21-00	MOS HRS/MSC AFL	4800	+25/-25			PKG 07-MAR-2016 0 0		
2620001 (s)	** FIREWALL SHUT-OFF VALVES - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 26-21-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
2620006	HYDROSTATIC TEST NO. 1 33100021-1 67476B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			21-OCT-2015	31-OCT-2020	14-NOV-2020

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2620006	HYDROSTATIC TEST NO. 2 33100021-1 72631B1 REF: GENERIC NO REF	MOS HRS/MSC AFL	60	+14d/-14d			06-OCT-2015	31-OCT-2020	14-NOV-2020
2620007	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, LEFT SQUIB 30903856 1881TC REF: AMM 26-21-02	MOS HRS/MSC AFL	120	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2026	14-APR-2026
2620007	NO. 1/LEFT/LOWER FIRE EXTINGUISHER, RIGHT SQUIB 30903859 0208TD REF: AMM 26-21-02	MOS HRS/MSC AFL	120	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2026	14-APR-2026
2620007	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, LEFT SQUIB 30903856 1818TC REF: AMM 26-21-02	MOS HRS/MSC AFL	120	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2026	14-APR-2026
2620007	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER, RIGHT SQUIB 30903859 1095TE REF: AMM 26-21-02	MOS HRS/MSC AFL	120	+14d/-14d	N:0 N:0 N:0		07-MAR-2016 0 0	31-MAR-2026	14-APR-2026
2620009 (s)	INSPECT CABIN FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. C352TS PKG 1 B-02761138 REF: AMM 26-23-00	MOS HRS/MSC AFL	12	+14d/-14d			13-FEB-2020 746.3 493		
2620009 (s)	INSPECT COPILOT FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. A344T PKG 1 B-02759858 REF: AMM 26-23-00	MOS HRS/MSC AFL	12	+14d/-14d			13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2620009 (s)	INSPECT PILOT FIRE EXTINGUISHER FOR CONDITION AND DATE OF MANUFACTURE. CHECK OPERATING PRESSURE AND WEIGHT PER MAINTENANCE INSTRUCTIONS ON FIRE EXTINGUISHER BOTTLE. A344T PKG 1 B-02759862 REF: AMM 26-23-00	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
262001	NO. 1/LEFT/LOWER FIRE EXTINGUISHER BOTTLE 33100021-1 67476B1 REF: AMM 26-21-01	MOS			N:0		07-MAR-2016 0 0		
262002	NO. 2/RIGHT/UPPER FIRE EXTINGUISHER BOTTLE 33100021-1 72631B1 REF: AMM 26-21-01	MOS			N:0		07-MAR-2016 0 0		
2620021 (s)	NO. 1 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 1 REF: GENERIC NO REF	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
2620021 (s)	NO. 2 ENGINE FIRE EXTINGUISHER CONTAINER PLUMBING - PERFORM DETAILED INSPECTION PKG 1 REF: GENERIC NO REF	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
2620046 (s)	VISUAL INSPECTION NO. 1 ENGINE FIRE EXTINGUISHER DISCHARGE LINES PKG 6 REF: GENERIC NO REF	MOS	72	+14d/-14d			PKG 07-MAR-2016 0 0		
2620046 (s)	VISUAL INSPECTION NO. 2 ENGINE FIRE EXTINGUISHER DISCHARGE LINES PKG 6 REF: GENERIC NO REF	MOS	72	+14d/-14d			PKG 07-MAR-2016 0 0		
262040	WARNING HORN PN SN-UNKNOWN REF: AMM 26-13-02	MOS			N:0		07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262041	PILOT FIRE EXTINGUISHER A344T B-02759862 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-APR-2016 23.3 15		
262042	COPILOT FIRE EXTINGUISHER A344T B-02759858 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				28-APR-2016 23.3 15		
262051	CABIN FIRE EXTINGUISHER C352TS B-02761138 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:1 N:23.3 N:15			28-APR-2016 23.3 15		
262075	APU FIRE EXTINGUISHER CONTAINER 51600-2 0635 REF: AMM 26-22-01	MOS HRS/MSC AFL	O/C	N:0			28-APR-2016 23.3 15		
CHAPTER 27 FLIGHT CONTROLS									
2700000 (s)	AILERON CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES PKG 6 REF: AMM 27-00-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
2700001 (s)	RUDDER CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES PKG 6 REF: AMM 27-00-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
2700002 (s)	ELEVATOR CONTROL CABLE SYSTEM - WITH COCKPIT AND CABIN FLOORBOARDS REMOVED, PERFORM VISUAL INSPECTION OF CABLES PKG 6 REF: AMM 27-00-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2700003 (s)	VISUAL INSPECTION AILERON CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF CABLES WITHIN WING.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 27-00-00	AFL					0		
2700004 (s)	VISUAL INSPECTION RUDDER CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 27-00-00	AFL					0		
2700005 (s)	VISUAL INSPECTION ELEVATOR CONTROL CABLE SYSTEM - PERFORM VISUAL INSPECTION OF ACCESSIBLE UPPER AND LOWER CABLES.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 27-00-00	AFL					0		
2700006 (s)	VISUAL INSPECTION RUDDER AND ELEVATOR CONTROL CABLES AND ASSOCIATED PULLEYS, LOCATED IN AFT PRESSURE BULKHEAD SUPPORT CHANNEL - PERFORM VISUAL INSPECTION.						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 27-00-00	AFL					0		
2700007 (s)	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).						PKG		
	PKG 8	MOS					07-MAR-2016		
		HRS/MSC	4800				0		
CMR*	REF: AMM 27-00-00	AFL					0		
2700008 (s)	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).						PKG		
	PKG 8	MOS					07-MAR-2016		
		HRS/MSC	4800				0		
CMR*	REF: AMM 27-00-00	AFL					0		
2700009 (s)	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (FUSELAGE).						PKG		
	PKG 8	MOS					07-MAR-2016		
		HRS/MSC	4800				0		
CMR*	REF: AMM 27-00-00	AFL					0		



Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2700010 (s)	* ELEVATOR CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (AFT FUSELAGE).						PKG		
	PKG 8	MOS						07-MAR-2016	
		HRS/MSC	4800					0	
CMR*	REF: AMM 27-00-00	AFL						0	
2700012 (s)	* RUDDER CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (AFT FUSELAGE).						PKG		
	PKG 8	MOS						07-MAR-2016	
		HRS/MSC	4800					0	
CMR*	REF: AMM 27-00-00	AFL						0	
2700014 (s)	* AILERON CONTROL SYSTEM PRIMARY CABLES - REMOVE FROM AIRCRAFT AND PERFORM DETAILED VISUAL INSPECTION (WING).						PKG		
	PKG 8	MOS						07-MAR-2016	
		HRS/MSC	4800					0	
CMR*	REF: AMM 27-00-00	AFL						0	
2710003 (s)	TENSION CHECK AILERON CONTROL SYSTEM CABLES (LOCATED IN WING)						PKG		
	PKG 6	MOS	72	+14d/-14d				07-MAR-2016	
		HRS/MSC	1200	+25/-25				0	
	REF: AMM 27-10-00	AFL						0	
2710004 (s)	TENSION CHECK AILERON CONTROL SYSTEM CABLES (LOCATED IN FUSELAGE)						PKG		
	PKG 6	MOS	72	+14d/-14d				07-MAR-2016	
		HRS/MSC	1200	+25/-25				0	
	REF: AMM 27-10-00	AFL						0	
271045	LH INBOARD AILERON CONTROL CABLE ASSY								
	4527103077-013	MOS			N:0			07-MAR-2016	
	J64621	HRS/MSC	O/C		N:0			0	
	REF: AMM 27-10-05	AFL			N:0			0	
271046	RH INBOARD AILERON CONTROL CABLE ASSY								
	4527103076-017	MOS			N:0			07-MAR-2016	
	J38414	HRS/MSC	O/C		N:0			0	
	REF: AMM 27-10-05	AFL			N:0			0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271051	LH OUTBOARD UPPER AILERON CONTROL CABLE ASSY 4527103078-011 J62398 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
271052	RH OUTBOARD UPPER AILERON CONTROL CABLE ASSY 4527103078-011 J62398 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
271053	LH OUTBOARD LOWER AILERON CONTROL CABLE ASSY 4527103079-011 1242438-45 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
271054	RH OUTBOARD LOWER AILERON CONTROL CABLE ASSY 4527103079-011 J38510 REF: AMM 27-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2711001 (s)	** AILERON TRIM TAB CONTROL SYSTEM - PERFORM OPERATIONAL CHECK PKG 5 REF: AMM 27-10-04	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			17-NOV-2018 532.7		PKG
2712000 (s)	** ROLL DISCONNECT SWITCHES - PERFORM OPERATIONAL CHECK PKG 5 REF: AMM 27-60-09	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			17-NOV-2018 532.7		PKG
2720003 (s)	TENSION CHECK RUDDER CONTROL CABLES PKG 6 REF: AMM 27-20-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		PKG
2720004 (s)	VISUAL INSPECTION RUDDER PEDALS, PEDAL PUSHRODS, ADJUSTMENT ACTUATOR, AND SECTORS . CHECK DURING FULL TRAVEL OF RUDDER. PKG 6 REF:	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		PKG

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2720030	VISUAL INSPECTION RUDDER TORQUE TUBE AND SPINDLE - PERFORM DETAILED VISUAL INSPECTION. REF: AMM 27-20-01	MOS HRS/MSC AFL	72	+14d/-14d			07-MAR-2016 0 0	31-MAR-2022	14-APR-2022
272021	RUDDER TRIM TAB ACTUATOR ASSY 6627108000-003 750 REF: AMM 27-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
272022	AILERON TRIM TAB ACTUATOR ASSY PN SN-UNKNOWN REF: AMM 27-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
272031	LH LINEAR-RUDDER PEDAL ADJUST ACTUATOR PN SN-UNKNOWN REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
272032	RH LINEAR-RUDDER PEDAL ADJUST ACTUATOR PN SN-UNKNOWN REF: AMM 27-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2721001 (s)	** RUDDER TRIM SYSTEM - PERFORM OPERATIONAL CHECK PKG 5 REF: AMM 27-20-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
2730003 (s)	TENSION CHECK ELEVATOR CONTROL CABLES PKG 6 REF: AMM 27-30-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
273003	LH ELEVATOR CONTROL SYS PUSHROD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273004	RH ELEVATOR CONTROL SYS PUSHROD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273005	LH ELEVATOR CONTROL SYS PUSHROD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273006	RH ELEVATOR CONTROL SYS PUSHROD PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273063	LH ACTUATOR STICK SHAKER PN SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273064	RH ACTUATOR STICK SHAKER PN SN-UNKNOWN REF: AMM 27-31-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273075	LH ANGLE OF ATTACK TRANSMITTER PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273076	RH ANGLE OF ATTACK TRANSMITTER PN SN-UNKNOWN REF: AMM 27-31-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2731001 (s)	** PITCH TRIM - PERFORM OPERATIONAL CHECK OF ELEVATOR OVERRIDE ACTUATOR PKG 5 REF: AMM 27-30-14	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2731002 (s)	** ELEVATOR DISCONNECT SYSTEM - PERFORM OPERATIONAL CHECK PKG 5	MOS	36	+14d/-14d			PKG	17-NOV-2018	532.7
CMR**	REF: AMM 27-30-00	HRS/MSC AFL	600	+25/-25					
273101	LH STATIC (A20)(A21) INVERTER PN SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273102	RH STATIC (A20)(A21) INVERTER PN SN-UNKNOWN REF: AMM 27-31-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273201	ELEVATOR DISCONNECT CURRENT LIMITER PN SN-UNKNOWN REF: AMM 27-30-13	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273220	ELEVATOR AFT DISCONNECT ACTUATOR 6627300103-005 722 REF: AMM 27-30-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
273420	ELEVATOR OVERRIDE ACTUATOR ASSY PN SN-UNKNOWN REF: AMM 27-30-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2740003 (s)	** SECONDARY PITCH TRIM SYSTEM - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG	07-MAR-2016	0
CMR**	REF: See Workcard	HRS/MSC AFL	1200	+25/-25				0	0
2740004 (s)	** PRIMARY PITCH TRIM SYSTEM - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG	07-MAR-2016	0
CMR**	REF: See Workcard	HRS/MSC AFL	1200	+25/-25				0	0

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
2740032	HORIZONTAL STABILIZER ACTUATOR ASSY * HORIZONTAL STABILIZER ACTUATOR (6627401000-009) - PERFORM INSPECTION								
	6627401000-009	MOS					07-MAR-2016		
	B1032	HRS/MSC	1200				0		1200
CMR*	REF: AMM 27-40-02	AFL					0		
2740033	HORIZONTAL STABILIZER ACTUATOR ASSY * HORIZONTAL STABILIZER ACTUATOR (6627401000-009) - PERFORM DETAILED STRUCTURAL INSPECTION								
	6627401000-009	MOS					07-MAR-2016		
	B1032	HRS/MSC	2400				0		2400
CMR*	REF: AMM 27-40-02	AFL					0		
274011	HORIZONTAL STABILIZER ACTUATOR ASSY								
	6627401000-009	MOS		N:0			07-MAR-2016		
	B1032	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-40-02	AFL		N:0			0		
274051	HORIZ STAB ACTUATOR CONTROL BOX ASSY								
	6627401000-003	MOS		N:0			07-MAR-2016		
	789	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-40-03	AFL		N:0			0		
275001	FLAP CONTROL (J7) MODULE								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-02	AFL		N:0			0		
275020	LH OUTBD FLAP DRIVE ACTUATOR								
	6627503000-033	MOS		N:0			07-MAR-2016		
	2439	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-06	AFL		N:0			0		
275021	LH INBD FLAP DRIVE ACTUATOR								
	6627503000-031	MOS		N:0			07-MAR-2016		
	2443	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-50-06	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275022	RH FLAP DRIVE, INBD ACTUATOR 6627503000-031 2444 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275023	RH FLAP DRIVE, OTBD ACTUATOR 6627503000-033 2438 REF: AMM 27-50-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275057	FPU, FLAP POWER UNIT 6627503000-029 1775 REF: AMM 27-50-08	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275058	FLAP CONTROL UNIT FCU C144486-3-003 1829 REF: AMM 27-50-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275069	FLAP POSITION INDICATION UNIT C145159-1 1807 REF: AMM 27-50-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275081	LH ROTARY VAR DIFF TRANSFORMER 6627503000-019 1548 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
275082	RH ROTARY VAR DIFF TRANSFORMER 6627503000-019 A1549 REF: AMM 27-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2760001 (s)	** SPOILER ACTUATOR CHECK VALVE - PERFORM OPERATIONAL CHECK PKG 5 REF: AMM 27-60-04	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276002 (s)	** SPOILER SYSTEM - PERFORM SPOILER AUTHORITY WITH FLAPS CHECK PKG 5	MOS	36	+14d/-14d			PKG	17-NOV-2018	
CMR**	REF: AMM 27-60-00	HRS/MSC AFL	600	+25/-25			532.7		
276001	RH SPOILERON ACTUATOR ASSY PN SN-UNKNOWN REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
276002	LH SPOILERON ACTUATOR ASSY PN SN-UNKNOWN REF: AMM 27-60-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
+ 2760021	LEFT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			(EBT)	1200	1225
2760021	LEFT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			07-MAR-2016 0 0	1200 M	1225
+ 2760021	RIGHT SPOILER HYDRAULIC PRESSURE SWIVEL - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			(EBT)	1200	1225
+ 2760021	RIGHT SPOILER HYDRAULIC RETURN SWIVEL - REPLACE REF: GENERIC NO REF	MOS HRS/MSC AFL	1200	+25/-25			07-MAR-2016 0 0	1200 M	1225
276013	SPOILER SHUT-OFF VALVE ASSY PN SN-UNKNOWN REF: AMM 27-60-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276031	LH ROTARY VAR DIFF, SPOILER TRANSFORMER 3A2-249A A1421 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
276032	RH ROTARY VAR DIFF, SPOILER TRANSFORMER 3A2-249A A1420 REF: AMM 27-60-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
276073	SPOILERON COMPUTER PN SN-UNKNOWN REF: AMM 27-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
276076	ROTARY VAR DIFF CTL WHEEL TRANSFORMER 3G4-211A 7371530 REF: AMM 27-60-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 28	FUEL								
281001	LH BAY 1 FWD EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281002	RH BAY 1 EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281003	LH BAY 2 FWD EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281004	RH BAY 2 FWD EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281005	LH BAY 3 EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281006	RH BAY 3 EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281007	LH BAY 2 AFT EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281008	RH BAY 2 AFT EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281009	LH BAY 9 EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281010	RH BAY 9 EJECTOR SCAVENGE PUMP PN SN-UNKNOWN REF: AMM 28-12-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281051	LH MOTIVE FLOW CHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281052	RH MOTIVE FLOW CHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281102	FUSELAGE FUEL CELL BAG TANK PN SN-UNKNOWN REF: AMM 28-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281521	LH CHECK, FUEL TRANSFER VALVE PN SN-UNKNOWN REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
281522	RH CHECK, FUEL TRANSFER VALVE PN SN-UNKNOWN REF: AMM 28-12-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2820000 (s)	INSPECT LOW PRESSURE FUEL FILTER - REMOVE AND INSPECT FOR CONTAMINATION. CLEAN IF NECESSARY. PKG 6 REF: AMM 28-20-15	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
282011	SHUTOFF, REFUEL VALVE PN SN-UNKNOWN REF: AMM 28-20-10	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282031	CHECK, FUEL SUPPLY (LH) NO 1 VALVE PN SN-UNKNOWN REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282032	CHECK, FUEL SUPPLY (LH) NO 2 VALVE PN SN-UNKNOWN REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282033	CHECK, FUEL SUPPLY (RH) NO 1 VALVE PN SN-UNKNOWN REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282034	CHECK, FUEL SUPPLY (RH) NO 2 VALVE PN SN-UNKNOWN REF: AMM 28-20-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282037	SHUTOFF, FUEL SUPPLY (LH NO 1) VALVE ASSY PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282038	SHUTOFF, FUEL SUPPLY (LH NO 2) VALVE ASSY PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282039	SHUTOFF, FUEL SUPPLY (CTR) VALVE ASSY PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282040	RH SHUTOFF, FUEL SUPPLY VALVE ASSY PN SN-UNKNOWN REF: AMM 28-20-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282041	CONTROL, REFUELING PANEL ASSY PN SN-UNKNOWN REF: AMM 28-20-14	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282063	1/4" PRE CHECK VALVE PN SN-UNKNOWN REF: AMM 28-20-12	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282064	PILOT VALVE PN SN-UNKNOWN REF: AMM 28-20-11	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282075	LH MAIN EJECTOR PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282076	RH MAIN EJECTOR PUMP PN SN-UNKNOWN REF: AMM 28-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282087	LH STANDBY PUMP ASSY PN SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282088	RH STANDBY PUMP ASSY PN SN-UNKNOWN REF: AMM 28-20-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
282815	SHUTOFF, APU FUEL VALVE 7086048-1 1515028100223C REF: AMM 28-20-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2840003 (s)	** FUEL QUANTITY SIGNAL CONDITIONER - PERFORM FUNCTIONAL TEST TO VERIFY WEIGHT ON WHEELS (WOW) INPUTS PKG 6 REF: AMM 28-40-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0	PKG	
284001	LH FUEL (C1) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284002	LH FUEL (C2) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284003	LH FUEL (C3) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284004	LH FUEL (C4) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284005	LH FUEL (C5) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284006	LH FUEL (C15) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284008	RH FUEL (C8) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284009	RH FUEL (C9) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
284010	RH FUEL (C10) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284011	RH FUEL (C11) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284012	RH FUEL (C12) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284013	RH FUEL (C17) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284014	RH FUEL (C13) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284015	LH FUEL (C14) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284016	RH FUEL (C16) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284017	LH FUEL (C6) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
284033	FUSELAGE FUEL (C7) PROBE ASSY PN SN-UNKNOWN REF: AMM 28-40-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284104	FUEL QUANTITY SIGNAL CONDITIONER 6628408000-023 1313 REF: AMM 28-40-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 29	HYDRAULIC POWER								
2910005	REPLACE AUXILIARY HYDRAULIC FILTER MANIFOLD ELEMENTS REF: AMM 29-20-02	MOS HRS/MSC AFL	2400	+25/-25			07-MAR-2016 0 0	2400	2425
2910018	REPLACE MAIN HYDRAULIC FILTER MANIFOLD ELEMENTS REF: AMM 29-10-03	MOS HRS/MSC AFL	300	+25/-25			13-FEB-2020 746.3 493	1046.3	1071.3
291002	HYDRAULIC MAIN FILTER (A74) MANIFOLD PN SN-UNKNOWN REF: AMM 29-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
2910026 (s)	FUNCTIONAL TEST RELIEF FUNCTION OF THE PRESSURIZATION CONTROL MODULE PKG 6 REF: AMM 29-10-06	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
291033	RESERVOIR PRESSURIZATION CONTROL MODULE PN SN-UNKNOWN REF: AMM 29-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
291034	HYD RESERVOIR FLUID LEVEL SENSOR PN SN-UNKNOWN REF: AMM 29-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291045	LH ENGINE DRIVEN HYDRAULIC PUMP ASSY PN SN-UNKNOWN REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
291046	RH ENGINE DRIVEN HYDRAULIC PUMP ASSY PN SN-UNKNOWN REF: AMM 29-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
291057	MAIN HYD PRESSURE ACCUMULATOR PN SN-UNKNOWN REF: AMM 29-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
291069	THERMAL SHUTOFF VALVE PN SN-UNKNOWN REF: AMM 29-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
292011	AUXILIARY HYDRAULIC PUMP ASSY PN SN-UNKNOWN REF: AMM 29-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
293001	CONTROL BOX ASSY PN SN-UNKNOWN REF: AMM 29-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
293011	HYDRAULIC PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
293012	HYDRAULIC PRESSURE TRANSDUCER PN SN-UNKNOWN REF: AMM 29-30-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 30	ICE AND RAIN PROTECTION								
3010000 (s)	** WING/STAB ANTI-ICE SWITCH - PERFORM OPERATIONAL CHECK						PKG		
	PKG 5	MOS	36	+14d/-14d				17-NOV-2018	
		HRS/MSC	600	+25/-25				532.7	
CMR**	REF: AMM 30-10-00	AFL							
3010006 (s)	** ANTI-ICE MANIFOLD - PERFORM BORESCOPE INSPECTION						PKG		
	PKG 6	MOS	72	+14d/-14d				07-MAR-2016	
		HRS/MSC	1200	+25/-25				0	
CMR**	REF: AMM 30-10-07	AFL						0	
301006	VERTICAL STABILIZER ANTI ICE PANEL								
	PN	MOS			N:0			07-MAR-2016	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: GENERIC NO REF	AFL			N:0			0	
301063	LH SHUTOFF, PRESSURE REGULATING VALVE								
	PN	MOS			N:0			07-MAR-2016	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: AMM 30-10-01	AFL			N:0			0	
301064	RH SHUTOFF, PRESSURE REGULATING VALVE								
	PN	MOS			N:0			07-MAR-2016	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: AMM 30-10-01	AFL			N:0			0	
301065	LH SHUTOFF, PRESSURE REGULATING (L17) VALVE								
	PN	MOS			N:0			07-MAR-2016	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: AMM 30-10-01	AFL			N:0			0	
301066	RH SHUTOFF, PRESSURE REGULATING (L18) VALVE								
	PN	MOS			N:0			07-MAR-2016	
	SN-UNKNOWN	HRS/MSC	O/C		N:0			0	
	REF: AMM 30-10-01	AFL			N:0			0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3020000 (s)	** NACELLE ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016		
CMR**	REF: AMM 30-20-00	HRS/MSC AFL	1200	+25/-25			0 0		
3020005	LEFT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.	MOS					13-FEB-2020		
CMR*	REF: AMM 30-20-00	HRS/MSC AFL	250				746.3 493	996.3	
3020005	RIGHT * ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS.	MOS					13-FEB-2020		
CMR*	REF: AMM 30-20-00	HRS/MSC AFL	250				746.3 493	996.3	
+ 3020006	LEFT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					07-MAR-2016		
NOT APPLICABLE	REF: AMM 30-20-00	HRS/MSC AFL	N/A				0 0		
+ 3020006	RIGHT ENGINE INLET ANTI-ICE TUBE ASSEMBLY FROM THE AFT INLET BULKHEAD CONNECTION POINT FORWARD TO SPRAY RING CONNECTION, PERFORM DETAILED VISUAL/BORESCOPE INSPECTION OF THE WELDS INSIDE AND OUTSIDE OF THE TUBE AT BOTH FORWARD AND AFT ENDS	MOS					07-MAR-2016		
NOT APPLICABLE	REF: AMM 30-20-00	HRS/MSC AFL	N/A				0 0		
3030000 (s)	** PITOT-STATIC HEAT SYSTEM - PERFORM OPERATIONAL CHECK PKG 7	MOS	108	+14d/-14d			PKG 07-MAR-2016		
CMR**	REF: See Workcard	HRS/MSC AFL	2400	+25/-25			0 0		
3040000 (s)	** WINDSHIELD ANTI-ICE SYSTEM - PERFORM FUNCTIONAL TEST OF THE WINDSHIELD ANTI-ICE SYSTEM PKG 5	MOS	36	+14d/-14d			PKG 17-NOV-2018		
CMR**	REF: AMM 30-40-00	HRS/MSC AFL	600	+25/-25			532.7		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
304021	WINDSHIELD ANTI-ICE CONTROLLER 90825-9 1055 REF: AMM 30-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
308005	ICE DETECTOR PROBE PN SN-UNKNOWN REF: AMM 30-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 31 INDICATING/RECORDING SYSTEMS									
310002 (s)	** ELECTRONIC FLIGHT INSTRUMENT SYSTEM - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 31-60-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
313001	FLIGHT DATA RECORDER PN SN-UNKNOWN REF: AMM 31-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
313003	TRIAxIAL ACCELEROMETER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
313019	FDR INERTIA SWITCH PN SN-UNKNOWN REF: AMM 31-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314011	DATA CONCENTRATION, GSD 41 (#1) UNIT 011-01457-00 16906543 REF: AMM 31-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314012	DATA CONCENTRATION, GSD 41 (#2) UNIT 011-01457-00 16906544 REF: AMM 31-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314023	LH INTEGRATED AV, NAV/COM GIA 63W UNIT 011-01105-40 2DC002166 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314024	RH INTEGRATED AV, NAV/COM GIA 63W UNIT 011-01105-40 2DC002049 REF: AMM 31-41-01	MOS HRS/MSC AFL	O/C				28-APR-2016 23.3 15		
314051	I/O, ENGINE AND AIRFRAME, GEA71 (PILOT) UNIT 011-00831-00 46721204 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314052	I/O, ENGINE AND AIRFRAME, GEA71 (CENTER RH) UNIT 011-00831-00 46721211 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314053	I/O, ENGINE AND AIRFRAME, GEA71 (CENTER LH) UNIT 011-00831-00 46721198 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
314054	I/O, ENGINE AND AIRFRAME, GEA71 (CO-PILOT) UNIT 011-00831-00 46721203 REF: AMM 31-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3151002 (s)	** AURAL WARNING - PERFORM INSPECTION CHECK PKG 5 REF: AMM 31-51-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3151003 (s)	** TAKEOFF CONFIGURATION WARNING - PERFORM INSPECTION CHECK PKG 5	MOS	36	+14d/-14d			PKG	17-NOV-2018	
CMR**	REF: AMM 31-51-00	HRS/MSC AFL	600	+25/-25			532.7		
316001	(PILOT) GDU 1400W COLOR W SCR N LDSCAPE DISPLAY 011-01910-30 1F1305085 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
316002	CO-PILOT GDU 1400W COLOR W SCR N LDSCAPE DISPLAY 011-01910-30 1F1305086 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
316003	(MFD) GDU 1400W COLOR W SCR N LDSCAPE DISPLAY 011-01910-30 1F1305084 REF: AMM 31-60-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
316005	LH TOUCHSCREEN, GTC 570 CONTROLLER 011-01924-10 1MB501161 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C				10-JUN-2017 168.9 112		
316006	RH TOUCHSCREEN, GTC 570 CONTROLLER 011-01924-10 1MB505939 REF: AMM 31-60-02	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			04-JUL-2017 174.4 117		
316007	LH BACKUP, GCU 275 CONTROLLER 011-01983-01 1U7105974 REF: AMM 31-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
316008	RH BACKUP, GCU 275 CONTROLLER 011-01983-01 1U7105975 REF: AMM 31-60-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316091	AFIS DATA TRANSFER (OPTION) UNIT								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
CHAPTER 32 LANDING GEAR									
321001	LH MLG GEAR INSTALLATION								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
3210015 (s)	CORROSION INSPECTION NOSE LANDING GEAR AND WHEEL WELL						PKG		
	PKG 1	MOS	12	+14d/-14d			13-FEB-2020		
		HRS/MSC					746.3		
	REF: GENERIC NO REF	AFL					493		
321002	RH MLG GEAR INSTALLATION								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
321011	LH MLG SHOCK STRUT CYLINDER ASSY								
	200-0201-005	MOS		N:0			07-MAR-2016		
	H0873	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-10-01	AFL		N:0			0		
321012	RH MLG SHOCK STRUT CYLINDER ASSY								
	200-0201-006	MOS		N:0			07-MAR-2016		
	H0885	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-10-01	AFL		N:0			0		
321073	LH DISPLACEMENT MLG ACTUATOR TUBE								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321074	RH DISPLACEMENT MLG ACTUATOR TUBE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321085	LH FWD MLG TRUNNION ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321086	RH FWD MLG TRUNNION ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321087	LH AFT MLG TRUNNION ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321088	RH AFT MLG TRUNNION ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321301	LH OUTBD MLG DOOR ASSY 4552803003-003 680 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321302	LH INBD MLG DOOR ASSY 4552803004-005 680 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
321303	RH INBD MLG DOOR ASSY 4552803004-006 680 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321304	RH OUTBD MLG DOOR ASSY 4552803003-004 680 REF: AMM 52-80-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3220003	REPLACE NOSE GEAR SHOCK STRUT - RETAINER RING LOCKSCREW. REF:	MOS HRS/MSC AFL	600	+25/-25			17-NOV-2018 532.7	1132.7	1157.7
3220007	LEFT * MAIN LANDING GEAR AXLE - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (P/N 200-0203-001) REF: AMM 32-10-01	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220007	RIGHT * MAIN LANDING GEAR AXLE - PERFORM MAIN LANDING GEAR AXLE BEAM ASSEMBLY BORESCOPE INSPECTION (P/N 200-0203-001) REF: AMM 32-10-01	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220009	* NOSE LANDING GEAR STRUT ASSEMBLY - REPLACE 2342100-037 82 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000				07-MAR-2016 0 0	20000	
322001	NOSE GEAR STEERING AND STRUT ASSY PN SN-UNKNOWN REF: AMM 32-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3220010	* NOSE LANDING GEAR ACTUATOR ASSEMBLY - REPLACE 6632201000-005 TASV916 REF: AMM 32-32-01	MOS HRS/MSC AFL	20000				07-MAR-2016 0 0	20000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220011	* NOSE LANDING GEAR ACTUATOR UPPER PIN - REPLACE 4532302043-007 9	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-32-01	AFL	20000	N:0			0	20000	
3220012	LEFT * MAIN LANDING GEAR STRUT ASSEMBLY - REPLACE 200-0200-013 H1880	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220012	RIGHT * MAIN LANDING GEAR STRUT ASSEMBLY - REPLACE 200-0200-014 H1878	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220013	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR, EXCLUDING THE END CAP - REPLACE 200-0300-003 H0752	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220013	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR, EXCLUDING THE END CAP - REPLACE 200-0300-004 H1748	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220014	LEFT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE 200-0325-101 CPS01C3251	MOS HRS/MSC	96	N:47 N:746.3			13-FEB-2020 746.3	31-MAR-2024	
CMR*	REF: AMM 32-31-01	AFL		N:493			493		
3220014	RIGHT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE 200-0325-101 CPS01C3250	MOS HRS/MSC	96	N:47 N:746.3			13-FEB-2020 746.3	31-MAR-2024	
CMR*	REF: AMM 32-31-01	AFL		N:493			493		
3220016	INSPECT NOSE LANDING GEAR STRUT ASSEMBLY - PERFORM SPECIAL DETAILED INSPECTION. REF: GENERIC NO REF	MOS HRS/MSC AFL					07-MAR-2016 0 0	10000	10025
			10000	+25/-25					

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220017	VISUAL INSPECTION NOSE LANDING GEAR TRUNNION AXLE	MOS					07-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025
3220018	NDT INSPECT LMLG SPECIAL DETAILED INSPECTION ON SHOCK STRUT	MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
	REF: GENERIC NO REF	HRS/MSC					0		
		AFL	6600	+25/-25			0	6600	6625
3220018	NDT INSPECT RMLG SPECIAL DETAILED INSPECTION ON SHOCK STRUT	MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
	REF: GENERIC NO REF	HRS/MSC					0		
		AFL	6600	+25/-25			0	6600	6625
3220019	NDT INSPECT NOSE LANDING GEAR ACTUATOR ATTACHMENT PIN - REMOVE PIN AND PERFORM MAGNETIC PARTICLE INSPECTION.	MOS					07-MAR-2016		
	REF: NDT PART 7 / 32-30-02	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025
322002	NOSE GEAR CYLINDER ASSY	MOS					07-MAR-2016		
	2342102-003	HRS/MSC			N:0		0		
	T1066	O/C			N:0		0		
	REF: AMM 32-20-01	AFL			N:0		0		
3220020	* MAIN LANDING GEAR TRUNNION FITTINGS ON MID AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION	MOS					07-MAR-2016		
	REF: NDT PART 6 / 32-11-00	HRS/MSC					0		
CMR*		AFL	10000				0	10000	
3220022	NDT INSPECT LEFT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.	MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
	REF: See Workcard	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025
3220022	NDT INSPECT LEFT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.	MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
	REF: See Workcard	HRS/MSC					0		
		AFL	10000	+25/-25			0	10000	10025

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220022	NDT INSPECT RIGHT AFT MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								
		MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
		HRS/MSC					0		
	REF: See Workcard	AFL	10000	+25/-25			0	10000	10025
3220022	NDT INSPECT RIGHT FORWARD MAIN LANDING GEAR TRUNNION PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								
		MOS	96	+14d/-14d			07-MAR-2016	31-MAR-2024	14-APR-2024
		HRS/MSC					0		
	REF: See Workcard	AFL	10000	+25/-25			0	10000	10025
3220023	LEFT AFT * MAIN LANDING GEAR TRUNNION PIN - REPLACE								
	200-0213-103	MOS		N:0			07-MAR-2016		
	CPS01C1728	HRS/MSC		N:0			0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220023	LEFT FORWARD * MAIN LANDING GEAR TRUNNION PIN - REPLACE								
	200-0212-103	MOS		N:0			07-MAR-2016		
	H1463	HRS/MSC		N:0			0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220023	RIGHT AFT * MAIN LANDING GEAR TRUNNION PIN - REPLACE								
	200-0213-103	MOS		N:0			07-MAR-2016		
	H1277	HRS/MSC		N:0			0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220023	RIGHT FORWARD * MAIN LANDING GEAR TRUNNION PIN - REPLACE								
	200-0212-103	MOS		N:0			07-MAR-2016		
	CPS01C1728	HRS/MSC		N:0			0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220024	LEFT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION.								
	200-0217-101	MOS	48				13-FEB-2020	29-FEB-2024	
	H3020	HRS/MSC					746.3		
CMR*	REF: NDT PART 7 / 32-30-01	AFL					493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220024	LEFT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION. 200-0325-101 CPS01C3251 REF: NDT PART 7 / 32-30-01	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
CMR*									
3220024	RIGHT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION. 200-0217-101 CPS01C3678 REF: NDT PART 7 / 32-30-01	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
CMR*									
3220024	RIGHT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM MAGNETIC PARTICLE INSPECTION. 200-0325-101 CPS01C3250 REF: NDT PART 7 / 32-30-01	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
CMR*									
3220028	LEFT * NOSE LANDING GEAR TRUNNION PIN - REPLACE 2342108-003 MTI-653 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000		N:0 N:0 N:0		07-MAR-2016 0 0	20000	
CMR*									
3220028	RIGHT * NOSE LANDING GEAR TRUNNION PIN - REPLACE 2342108-003 MTI-652 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000		N:0 N:0 N:0		07-MAR-2016 0 0	20000	
CMR*									
3220029	* NOSE LANDING GEAR TRUNNION AXLE - REPLACE 2342110-003 R1216 REF: AMM 32-20-01	MOS HRS/MSC AFL	20000		N:0 N:0 N:0		07-MAR-2016 0 0	20000	
CMR*									
322003	NOSE LANDING GEAR PISTON 2342104-003 E-254 REF: AMM 32-32-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
CMR*									

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220035	LEFT * MAIN LANDING GEAR SHOCK STRUT PISTON - REPLACE 200-0202-003 H1922	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220035	RIGHT * MAIN LANDING GEAR SHOCK STRUT PISTON - REPLACE 200-0202-003 H2193	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220036	LEFT * MAIN LANDING GEAR AXLE BEAM - REPLACE 200-0203-001 H1681	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220036	RIGHT * MAIN LANDING GEAR AXLE BEAM - REPLACE 200-0203-001 H1665	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220037	LEFT * MAIN LANDING GEAR SHOCK STRUT LINK - REPLACE 200-0204-001 PRE13C-1946	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220037	RIGHT * MAIN LANDING GEAR SHOCK STRUT LINK - REPLACE 200-0204-001 PRE13C-1945	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-10-01	AFL	10000	N:0			0	10000	
3220038	LEFT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE 200-0217-101 H3020	MOS HRS/MSC	96	N:47 N:746.3			13-FEB-2020 746.3	31-MAR-2024	
CMR*	REF: AMM 32-31-01	AFL		N:493			493		
3220038	RIGHT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE 200-0217-101 CPS01C3678	MOS HRS/MSC	96	N:47 N:746.3			13-FEB-2020 746.3	31-MAR-2024	
CMR*	REF: AMM 32-31-01	AFL		N:493			493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322004	NOSE GEAR STEERING AND STRUT INSTL BRACKET 2342111-005 R765 REF: AMM 32-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
322005	NOSE LANDING GEAR FORK 2342116-004 R1085 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3220101	LEFT AFT * MAIN LANDING GEAR LINK PIN - REPLACE 200-0214-101 H2896 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	
3220101	LEFT FORWARD * MAIN LANDING GEAR LINK PIN - REPLACE 200-0214-101 H2897 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	
3220101	RIGHT AFT * MAIN LANDING GEAR LINK PIN - REPLACE 200-0214-101 CPS01C-3321 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	
3220101	RIGHT FORWARD * MAIN LANDING GEAR LINK PIN - REPLACE 200-0214-101 CPS01C-3322 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	
3220102	LEFT * MAIN LANDING GEAR PISTON PIN - REPLACE 200-0215-101 H1416 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	
3220102	RIGHT * MAIN LANDING GEAR PISTON PIN - REPLACE 200-0215-101 CPS01C-1659 REF: AMM 32-10-01	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2016 0 0	10000	

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220103	LEFT * MAIN LANDING GEAR ACTUATOR PISTON - REPLACE 200-0301-103 PRE13C-2470	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220103	RIGHT * MAIN LANDING GEAR ACTUATOR PISTON - REPLACE 200-0301-103 PRE13C-2575	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220104	LEFT * MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE 200-0302-101 PRE13C-1935	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220104	RIGHT * MAIN LANDING GEAR ACTUATOR CYLINDER - REPLACE 200-0302-101 PRE13C-2004	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220105	LEFT * MAIN LANDING GEAR ACTUATOR END CAP - REPLACE PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	2387	N:0			0	2387	
3220105	RIGHT * MAIN LANDING GEAR ACTUATOR END CAP - REPLACE PN SN-UNKNOWN	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	2387	N:0			0	2387	
3220106	LEFT * MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE 200-0304-001 KAL02U-H2225	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	
3220106	RIGHT * MAIN LANDING GEAR ACTUATOR HOUSING - REPLACE 200-0304-001 KAL02U-H2232	MOS HRS/MSC		N:0 N:0			07-MAR-2016 0		
CMR*	REF: AMM 32-31-01	AFL	17000	N:0			0	17000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220109	VISUAL INSPECTION NOSE LANDING GEAR ACTUATOR ASSEMBLY - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.	MOS HRS/MSC AFL	10000	+25/-25			07-MAR-2016 0 0	10000	10025
	REF: GENERIC NO REF								
3220111	VISUAL INSPECTION LEFT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.	MOS HRS/MSC AFL	96 10000	+14d/-14d +25/-25			07-MAR-2016 0 0	31-MAR-2024 10000	14-APR-2024 10025
	REF: AMM 32-31-01								
3220111	VISUAL INSPECTION RIGHT MAIN LANDING GEAR SIDE-STAY ACTUATOR - DISASSEMBLE ACTUATOR AND PERFORM DETAILED VISUAL INSPECTION.	MOS HRS/MSC AFL	96 10000	+14d/-14d +25/-25			07-MAR-2016 0 0	31-MAR-2024 10000	14-APR-2024 10025
	REF: AMM 32-31-01								
3220116	LEFT * MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE	PN SN-UNKNOWN AFL	10000		N:0 N:0 N:0		07-MAR-2016 0 0	10000	
	REF: AMM 32-10-01								
3220116	RIGHT * MAIN LANDING GEAR SHOCK STRUT CYLINDER - REPLACE	PN SN-UNKNOWN AFL	10000		N:0 N:0 N:0		07-MAR-2016 0 0	10000	
	REF: AMM 32-10-01								
3220126	LEFT * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING - REPLACE	4532103041-013 102927/1-05 AFL	20000		N:0 N:0 N:0		07-MAR-2016 0 0	20000	
	REF: AMM 32-31-01								
3220126	RIGHT * MAIN LANDING GEAR SIDE-STAY ACTUATOR FITTING - REPLACE	4532103041-014 37766/8-02 AFL	20000		N:0 N:0 N:0		07-MAR-2016 0 0	20000	
	REF: AMM 32-31-01								

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220135	LEFT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION 200-0217-101 H3020 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220135	LEFT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION 200-0325-101 CPS01C3251 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220135	RIGHT * MAIN LANDING GEAR ACTUATOR LOWER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION 200-0217-101 CPS01C3678 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220135	RIGHT * MAIN LANDING GEAR ACTUATOR UPPER PIN - REPLACE * MAIN LANDING GEAR SIDE-STAY ACTUATOR PIN - PERFORM DETAILED VISUAL INSPECTION 200-0325-101 CPS01C3250 REF: GENERIC NO REF	MOS HRS/MSC AFL	48				13-FEB-2020 746.3 493	29-FEB-2024	
3220139	LEFT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-2868 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0	5000	
3220139	LEFT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-2904 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0	5000	
3220139	RIGHT FORWARD LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-3038 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0	5000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220139	RIGHT FORWARD UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103201-001 CMI-3044 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0		5000
3220140	LEFT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI-1538 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0		5000
3220140	RIGHT AFT UPPER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103202-001 CMI-1536 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0		5000
3220141	LEFT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI-123 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0		5000
3220141	RIGHT AFT LOWER * MAIN LANDING GEAR TRUNNION SHEAR PIN 4532103203-001 CMI-888 REF: AMM 57-10-05	MOS HRS/MSC AFL	5000	N:0 N:0 N:0			07-MAR-2016 0 0		5000
3220146	LEFT * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE. REF: NDT PART 4 / 32-10-01	MOS HRS/MSC AFL	4800				07-MAR-2016 0 0		4800
3220146	RIGHT * MAIN LANDING GEAR SHOCK STRUT CYLINDER (P/N 200-0201-109 AND 200-0201-110) - PERFORM ULTRASONIC INSPECTION OF THE FORGING PARTING LINE. REF: NDT PART 4 / 32-10-01	MOS HRS/MSC AFL	4800				07-MAR-2016 0 0		4800

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3220148 (s)	CORROSION INSPECTION MAIN LANDING GEAR AND WHEEL WELLS PKG 1	MOS	12	+14d/-14d			PKG 13-FEB-2020 746.3 493		
	REF: GENERIC NO REF	HRS/MSC AFL							
3220149	LEFT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE (P/N 200-0300-005, -006) PN	MOS		N:0			07-MAR-2016 0		
	SN-UNKNOWN	HRS/MSC		N:0			0		
	REF: AMM 32-31-01	AFL	17000	N:0			0		17000
3220149	RIGHT * MAIN LANDING GEAR SIDE BRACE ACTUATOR ASSEMBLY - REPLACE (P/N 200-0300-005, -006) PN	MOS		N:0			07-MAR-2016 0		
	SN-UNKNOWN	HRS/MSC		N:0			0		
	REF: AMM 32-31-01	AFL	17000	N:0			0		17000
322095	LH NOSE GEAR DOOR ASSY 455280001-009	MOS		N:0			07-MAR-2016 0		
	709	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-81-01	AFL		N:0			0		
322096	RH NOSE GEAR DOOR ASSY 455280002-009	MOS		N:0			07-MAR-2016 0		
	708	HRS/MSC	O/C	N:0			0		
	REF: AMM 52-81-01	AFL		N:0			0		
322098	AXLE 2342117-002	MOS		N:0			07-MAR-2016 0		
	R1451	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
322121	NLG UPLOCK PN	MOS		N:0			07-MAR-2016 0		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-32-02	AFL		N:0			0		
3230001 (s)	** LANDING GEAR - PERFORM EMERGENCY GEAR EXTENSION FUNCTIONAL TEST PKG 5	MOS	36	+14d/-14d			PKG 17-NOV-2018 532.7		
		HRS/MSC	600	+25/-25					
CMR**	REF: AMM 32-33-00	AFL							

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323001	LEFT MLG SIDE BRACE ACTUATOR ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
323002	RIGHT MLG SIDE BRACE ACTUATOR ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
323037	MLG (LH) INBOARD DOOR UPLOCK 6632303004-005 2488 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
323038	MLG (RH) INBOARD DOOR UPLOCK 6632303004-006 2490 REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3231024	LEFT * MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS - REPLACE REF: AMM 32-31-02	MOS HRS/MSC AFL	2400				07-MAR-2016 0 0	2400	
3231024	RIGHT * MAIN LANDING GEAR INBOARD DOOR ACTUATOR (P/N 7469-1) CAP SCREWS - REPLACE REF: AMM 32-31-02	MOS HRS/MSC AFL	2400				07-MAR-2016 0 0	2400	
323220	LH DOWN AND LOCK SWITCH 604HE162 2199 REF: AMM 32-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
323221	RH DOWN AND LOCK SWITCH 604HE162 2198 REF: AMM 32-60-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323735	CONTROL, MANIFOLD, LANDING GEAR VALVE PN SN-UNKNOWN REF: AMM 32-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3240004 (s)	** EMERGENCY/PARKING BRAKE POSITION INDICATING SWITCH - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 32-42-01	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
3240005 (s)	** BRAKE HYDRAULIC FUSES - PERFORM FUNCTIONAL TEST PKG 6 REF: AMM 32-41-09	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
3240006 (s)	** BRAKE SHUTTLE MODULE - PERFORM FUNCTIONAL TEST PKG 6 REF: AMM 32-41-04	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
3240007 (s)	** BRAKE SHUTTLE VALVES - PERFORM FUNCTIONAL TEST PKG 7 REF: AMM 32-42-04	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
3240008 (s)	** EMERGENCY/PARKING BRAKE CONTROL SYSTEM - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 32-42-02	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
3240009 (s)	** BRAKE PRESSURE TRANSDUCERS - PERFORM FUNCTIONAL TEST PKG 8 REF: AMM 32-41-08	MOS HRS/MSC AFL	4800	+25/-25			PKG 07-MAR-2016 0 0		
324001	NO. 1 (LH OB) MLG WHEEL ASSY 3-1545-1 3985 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				21-MAR-2018 336.6 210		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324001A	NON DESTRUCTIVE TEST LH OB MAIN LANDING GEAR WHEEL REFER TO GOODRICH PUBLICATION NO. 3-1545-1 3-1545-1 3985 REF: GENERIC NO REF	MOS HRS/MSC AFL	T/C						
324002	NO. 2 (LH IB) MLG WHEEL ASSY 3-1545-1 3984 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C				21-MAR-2018 336.6 210		
324002A	NON DESTRUCTIVE TEST LH IB MAIN LANDING GEAR WHEEL REFER TO GOODRICH PUBLICATION NO. 3-1545-1 3-1545-1 3984 REF: GENERIC NO REF	MOS HRS/MSC AFL	T/C						
324003	NO. 3 (RH IB) MLG WHEEL ASSY 3-1545-1 3749 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			01-OCT-2018 493.7 318		
324003A	NON DESTRUCTIVE TEST RH IB MAIN LANDING GEAR WHEEL REFER TO GOODRICH PUBLICATION NO. 3-1545-1 3-1545-1 3749 REF: GENERIC NO REF	MOS HRS/MSC AFL	T/C				01-OCT-2018 493.7 318		
324004	NO. 4 (RH OB) MLG WHEEL ASSY 3-1545-1 3968 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			11-OCT-2018 493.7 318		
324004A	NON DESTRUCTIVE TEST RH OB MAIN LANDING GEAR WHEEL REFER TO GOODRICH PUBLICATION NO. 3-1545-1 3-1545-1 3968 REF: GENERIC NO REF	MOS HRS/MSC AFL	T/C				11-OCT-2018 493.7 318		
324005	NOSE GEAR WHEEL ASSY 9544207-5 AIR-7095 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C				17-NOV-2018 532.7		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324006	NO. 1 WHEEL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324007	NO. 2 WHEEL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324008	NO. 3 WHEEL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324009	NO. 4 WHEEL TRANSDUCER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324021	NO. 1 (LH OB) MLG TIRE 226K08-4 81372719 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2019 711.6 469		
324022	NO. 2 (LH IB) MLG TIRE 226K08-4 91212640 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2019 711.6 469		
324023	NO. 3 (RH IB) MLG TIRE 226K08-4 81412726 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2019 711.6 469		
324024	NO. 4 (RH OB) MLG TIRE 226K08-4 91242390 REF: AMM 32-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-DEC-2019 711.6 469		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324025	NOSE GEAR TIRE 031-613-8 8061S00499 REF: AMM 32-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				11-DEC-2019 711.6 469	
324061	LH ANTI-SKID VALVE PN SN-UNKNOWN REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324062	RH ANTI-SKID VALVE PN SN-UNKNOWN REF: AMM 32-41-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324097	BCU, BRAKE CONTROL UNIT PN SN-UNKNOWN REF: AMM 32-41-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324111	(LH OUTBD) MLG GEAR BRAKE ASSY PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324112	(LH INBD) MLG GEAR BRAKE ASSY PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324113	(RH INBD) MLG GEAR BRAKE ASSY PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
324114	(RH OUTBD) MLG GEAR BRAKE ASSY PN SN-UNKNOWN REF: AMM 32-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324201	SHUTTLE, BRAKE (LH OTBD) VALVE PN SN-UNKNOWN REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324202	SHUTTLE, BRAKE (LH INBD) VALVE PN SN-UNKNOWN REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324203	SHUTTLE, BRAKE (RH INBD) VALVE PN SN-UNKNOWN REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324204	SHUTTLE, BRAKE (RH OTBD) VALVE PN SN-UNKNOWN REF: AMM 32-42-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324205	L/H MLG O/B BRAKE SWIVEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324206	R/H MLG I/B BRAKE SWIVEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324207	L/H MLG I/B BRAKE SWIVEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324208	R/H MLG O/B BRAKE SWIVEL PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324805	BRAKE ACCUMULATOR ASSY PN SN-UNKNOWN REF: AMM 32-42-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
324806	EMERGENCY PARKING BRAKE VALVE ASSY PN SN-UNKNOWN REF: AMM 32-42-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325011	NOSE WHEEL STEERING SERVO ACTUATOR JR5208C C0787 REF: AMM 32-50-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325021	NOSE WHEEL STEER GEARBOX 2W3-201D 752 REF: AMM 32-50-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325031	NOSE WHEEL STEERING COMPUTER PN SN-UNKNOWN REF: AMM 32-50-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325041	LH NWS TRANSDUCER PN SN-UNKNOWN REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325042	RH NWS TRANSDUCER PN SN-UNKNOWN REF: AMM 32-50-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
325054	LH ACTUATOR, INBD DOOR, MAIN LANDING GEAR ACTUATOR PN SN-UNKNOWN REF: AMM 32-31-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325055	RH ACTUATOR, INBD DOOR, MAIN LANDING GEAR ACTUATOR								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 32-31-02	AFL		N:0			0		
3260005 (s)	LUBRICATE NOSE LANDING GEAR SQUAT SWITCH ROTATING DISC ASSEMBLY						PKG		
	PKG 1	MOS	12	+14d/-14d			13-FEB-2020		
		HRS/MSC					746.3		
	REF: AMM 12-21-01	AFL					493		
CHAPTER 33 LIGHTS									
330000	PULSE LIGHT 2401S CONTROL UNIT								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
3310000 (s)	OPERATIONAL CHECK FLIGHT COMPARTMENT LIGHTING						PKG		
	PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
		HRS/MSC	1200	+25/-25			0		
	REF: AMM 33-10-00	AFL					0		
331001	CENTER SWITCH PANEL OVERLAY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-10-05	AFL		N:0			0		
331002	CO-PILOTS INBOARD SWITCH PANEL OVERLAY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-10-05	AFL		N:0			0		
331003	FLIGHT CONTROL SWITCH PANEL OVERLAY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 33-10-05	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331004	PILOTS CB DS85 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331005	CO-PILOT SIDE CB PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331005-DS58	PRESSURIZATION PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331006	PILOTS SW PANEL BLANK OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331007	ENGINE CONTROL DS65 PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331008	ELECTRICAL PANEL DS85 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331009	OVERHEAD LIGHTING PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331010	CABIN POWER DS64 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331011	DU REVERSION PANEL DS165 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331012	ENVIROMENTAL CONTROL DS163 PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331013	FLIGHT CONTROL DS67 PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331014	COCKPIT LIGHTS PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331015	GEAR/HYD PANEL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331016	APU CONTROL OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331017	THROTTLE QUAD A72 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
331018	CO-PILOTS C/B DS84 OVERLAY PN SN-UNKNOWN REF: AMM 33-10-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331020	DIMMER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3320000 (s)	OPERATIONAL CHECK PASSENGER COMPARTMENT LIGHTING PKG 6 REF: AMM 33-20-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0	PKG	
3340000 (s)	OPERATIONAL CHECK EXTERIOR LIGHTING SYSTEMS PKG 6 REF: AMM 33-40-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0	PKG	
334001	LEFT LED WING TIP POSITION LIGHT ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
334002	WHITE NAV LIGHT ASSY PN SN-UNKNOWN REF: AMM 33-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
334332	(LWR) ANTI-COLLISION/STROBE LIGHT ASSY PN SN-UNKNOWN REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
334333	(UPR) ANTI-COLLISION/STROBE LIGHT ASSY GE16386-12-1 3158949 REF: AMM 33-40-01	MOS HRS/MSC AFL	O/C				21-FEB-2019 573.6 371		
3350003 (s)	OPERATIONAL CHECK EMERGENCY LIGHTING SYSTEM PKG 6 REF: AMM 33-50-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0	PKG	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 34	NAVIGATION								
340001	UPDATE DATABASE JEPPESEN CHARTS	DAYS	14				27-MAY-2020	10-JUN-2020	
CUSTOMER CODE	REF:	HRS/MSC							
		AFL							
340001-RVSM	CHECK RVSM HEIGHT MONITORING	MOS	24				31-MAR-2020	31-MAR-2022	
		HRS/MSC	1000				787.8	1787.8	
	REF: FAR AGHME	AFL					517		
340002	UPDATE DATABASE NAVIGATION DATA	DAYS	28				26-MAY-2020	23-JUN-2020	
CUSTOMER CODE	REF:	HRS/MSC					787.8		
		AFL					517		
341001	LH GDC7400 ELSP AIR DATA COMPUTER								
	011-02337-01	MOS		N:0			07-MAR-2016		
	1U6100962	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-17-01	AFL		N:0			0		
341001A	TEST/INSPECT LH GDC7400 ELSP AIR DATA COMPUTER (91.411)								
	011-02337-01	MOS	24				13-FEB-2020	28-FEB-2022	
	1U6100962	HRS/MSC							
	REF: See Workcard	AFL							
341002	RH GDC7400 ELSP AIR DATA COMPUTER								
	011-02337-01	MOS		N:0			07-MAR-2016		
	1U6100960	HRS/MSC	O/C	N:0			0		
	REF: AMM 34-17-01	AFL		N:0			0		
341002A	TEST/INSPECT RH GDC7400 ELSP AIR DATA COMPUTER (91.411)								
	011-02337-01	MOS	24				13-FEB-2020	28-FEB-2022	
	1U6100960	HRS/MSC							
	REF: See Workcard	AFL							

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341073	FWD RADIO ALTIMETER ANTENNA PN SN-UNKNOWN REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
341074	AFT RADIO ALTIMETER ANTENNA PN SN-UNKNOWN REF: AMM 34-14-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
3411000 (s)	VISUAL INSPECTION PITOT-STATIC PROBES - PERFORM VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS PKG 6 REF: AMM 34-11-01	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
3411052 (s)	VERIFY PITCH, ROLL, AND YAW ALIGNMENT OF PRIMARY PITOT-STATIC PROBES PKG 10 REF: AMM 34-11-01	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2020 746.3 493		
3411053	LH PITOT-STATIC PROBE PN SN-UNKNOWN REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025
3411054	RH PITOT-STATIC PROBE PN SN-UNKNOWN REF: AMM 34-11-01	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025
3411060 (s)	FUNCTIONAL TEST AIR DATA SYSTEM PKG 10 REF: See Workcard	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3411062 (s)	VISUAL INSPECTION PITOT-STATIC PROBE - PERFORM DETAILED VISUAL INSPECTION. ENSURE DRAIN HOLES ARE CLEAR OF OBSTRUCTIONS. PKG 10 REF: AMM 34-11-01	MOS HRS/MSC AFL	24	+14d/-14d			13-FEB-2020 746.3 493	PKG	
341110	STANDBY PITOT-STATIC PROBE PN SN-UNKNOWN REF: AMM 34-11-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
341110A	TEST/INSPECT PITOT/STATIC SYSTEM REF: See Workcard	MOS HRS/MSC AFL	24		-8		11-OCT-2019 681 448	31-OCT-2021	
341401	ALT-4000 ALTIMETER 822-0615-207 4ND1X REF: AMM 34-14-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
341401A	TEST/INSPECT ALT-4000 ALTIMETER 822-0615-207 4ND1X REF: GENERIC NO REF	MOS HRS/MSC AFL	A/R				02-OCT-2017		
341901	TOTAL AIR TEMPERATURE SENSOR PN SN-UNKNOWN REF: AMM 34-17-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342103	STANDBY COMPASS WITH LIGHT ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342103A	CALIBRATION CHECK STANDBY COMPASS WITH LIGHT ASSY (FAR 25.1327) PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
342401	ELECTRONIC STANDBY INSTRUMENT GH-3900 SYSTEM 9200-34400-0201 1372 REF: AMM 34-24-01	MOS HRS/MSC AFL	O/C				02-OCT-2019 681 448		
342401A	FUNCTIONAL TEST ELECTRONIC STANDBY INSTRUMENT GH-3900 SYSTEM (91.411) 9200-34400-0201 1372 REF: See Workcard	MOS HRS/MSC AFL	24				13-FEB-2020 746.3 493	28-FEB-2022	
342402	3100 MAGNETOMETER 9200-21200-0102 80114 REF: AMM 34-24-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342601	LH GMU 44 MAGNETOMETER 011-00870-10 1CM016173 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342602	RH GMU 44 MAGNETOMETER 011-00870-10 1CM016170 REF: AMM 34-26-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342605	LH GRS 7800 COMPUTER 011-02278-00 25M000662 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
342606	RH GRS 7800 COMPUTER 011-02278-00 25M000667 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
343005	MARKER BEACON ANTENNA PN SN-UNKNOWN REF: AMM 34-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
343030	ANTENNA (DIPLEXER) COUPLER PN SN-UNKNOWN REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
343031	ANTENNA (DIPLEXER) COUPLER PN SN-UNKNOWN REF: AMM 34-51-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344111	UPPER TCAS ANTENNA PN SN-UNKNOWN REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344112	LOWER TCAS ANTENNA PN SN-UNKNOWN REF: AMM 34-43-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344143	TCAS II, GTS 8000 PROCESSOR 011-02571-00 28P006161 REF: AMM 34-43-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344209	ANTENNA (LIGHTNING SENSOR OPTION) ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344211	WEATHER RADAR ANTENNA 117-00254-01 986 REF: AMM 34-42-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
344212	WEATHER, BASE, GWX 70 RADAR 011-01768-00 1DP006396 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345013	DUAL ADF, ANT-462B ANTENNA PN SN-UNKNOWN REF: AMM 34-57-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345037	ATC LOWER NO 2 ANTENNA PN SN-UNKNOWN REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345038	ATC LOWER NO 1 ANTENNA PN SN-UNKNOWN REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345049	DME NO 1 ANTENNA PN SN-UNKNOWN REF: AMM 34-55-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345050	DME NO 2 ANTENNA PN SN-UNKNOWN REF: AMM 34-55-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345083	LH VOR/ILS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345084	RH VOR/ILS ANTENNA PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345260	PHASING COUPLER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345501	DME (DME-4000) TRANSCEIVER 822-1466-001 44V59R REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345502	DME (DME-4000) TRANSCEIVER PN SN-UNKNOWN REF: AMM 34-55-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345601	LH GTX 3000 TRANSPONDER 011-01997-00 20S007224 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345601A	TEST/INSPECT LH GTX 3000 TRANSPONDER 011-01997-00 20S007224 REF: See Workcard	MOS HRS/MSC AFL	24				13-FEB-2020	28-FEB-2022	
345602	RH GTX 3000 TRANSPONDER 011-01997-00 20S007229 REF: AMM 34-56-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345602A	TEST/INSPECT RH GTX 3000 TRANSPONDER 011-01997-00 20S007229 REF: See Workcard	MOS HRS/MSC AFL	24				13-FEB-2020	28-FEB-2022	
345605	ATC UPPER NO 1 ANTENNA PN SN-UNKNOWN REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345606	ATC UPPER NO 2 ANTENNA PN SN-UNKNOWN REF: AMM 34-56-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345701	ADF (#1) RECEIVER PN SN-UNKNOWN REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
345702	ADF (#2) RECEIVER PN SN-UNKNOWN REF: AMM 34-57-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
346090	DATA MANAGEMENT (OPTION) UNIT PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
347510	LH GPS WAASXM ANTENNA 013-00245-00 13366 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
347511	RH GPS WAASXM ANTENNA 013-00245-00 13378 REF: AMM 34-53-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 35	OXYGEN								
3500024	HYDROSTATIC TEST PORTABLE OXYGEN DOT 3AA1800 (OPTION) CYLINDER (IF INSTALLED). PN SN-UNKNOWN REF: AMM 35-00-01	MOS HRS/MSC AFL	-						
N/A EQUIPMENT NOT INSTALLED									
350230	PRESSURE INDICATOR PN SN-UNKNOWN REF: AMM 35-00-05	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3510002 (s)	** OXYGEN SYSTEM - PERFORM OPERATIONAL CHECK PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016		
CMR**	REF: AMM 35-00-00	HRS/MSC AFL	1200	+25/-25			0 0		
3510003 (s)	** CABIN LOW PRESSURE OXYGEN DISTRIBUTION FLEX HOSES - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016		
CMR**	REF: AMM 35-20-00	HRS/MSC AFL	1200	+25/-25			0 0		
3510008	CREWMEMBER PBE PN SN-UNKNOWN	MOS							
NOT INSTALLED	REF: AMM 25-60-00	HRS/MSC AFL	-						
351001	PILOT CREW OXYGEN MASK 6635000000-059 S101695	MOS		N:0			07-MAR-2016		
	REF: AMM 35-10-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
3510013	** OXYGEN CYLINDER AND REMOTE OXYGEN FILL VALVES - PERFORM PERIODIC CHECK	MOS					07-MAR-2016		
CMR**	REF: AMM 35-00-01	HRS/MSC AFL	1500	+25/-25			0 0	1500	1525
3510014 (s)	** OXYGEN SYSTEM ALTITUDE COMPENSATING REGULATOR - PERFORM FUNCTIONAL TEST PKG 6	MOS	72	+14d/-14d			PKG 07-MAR-2016		
CMR**	REF: AMM 35-20-00	HRS/MSC AFL	1200	+25/-25			0 0		
351002	CO-PILOT CREW OXYGEN MASK 6635000000-059 S101743	MOS		N:0			07-MAR-2016		
	REF: AMM 35-10-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
3510022	OVERHAUL OXYGEN CYLINDER REGULATOR	MOS					07-MAR-2016		
	REF: AMM 35-00-02	HRS/MSC AFL	4800	+25/-25			0 0	4800	4825

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3510024	OVERHAUL CO-PILOT CREW OXYGEN MASK 6635000000-059 S101743 REF: AMM 35-10-01	MOS HRS/MSC AFL	72	+14d/-14d			07-MAR-2016 0 0	31-MAR-2022	14-APR-2022
3510024	OVERHAUL PILOT CREW OXYGEN MASK 6635000000-059 S101695 REF: AMM 35-10-01	MOS HRS/MSC AFL	72	+14d/-14d			07-MAR-2016 0 0	31-MAR-2022	14-APR-2022
3510025	HYDROSTATIC TEST 40 CU FT, W/GAUGE CYLINDER (PER DOT 3HT-1850). 6635000000-139 C16020431 REF: AMM 35-00-01	MOS HRS/MSC AFL	36	+14d/-14d			16-NOV-2018	30-NOV-2021	14-DEC-2021
3510026 (s)	** OXYGEN CYLINDER LOW PRESSURE RELIEF VALVE - PERFORM FUNCTIONAL TEST PKG 8 REF: AMM 35-00-00	MOS HRS/MSC AFL	4800	+25/-25			PKG 07-MAR-2016 0 0		
3510029	40 CU FT, W/GAUGE CYLINDER 6635000000-139 C16020431 REF: AMM 35-00-01 LIFE LIMIT Manufacture Date: 01-DEC-2015	MOS HRS/MSC AFL	288	+14d/-14d			17-NOV-2018 532.7	31-DEC-2039	14-JAN-2040
352011	OXYGEN CONTROL VALVE PN SN-UNKNOWN REF: AMM 35-20-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
353001	PORTABLE OXYGEN DOT 3AA1800 (OPTION) CYLINDER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C						

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353005	INTERCOSTAL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 36 PNEUMATIC									
3610000 (s)	** BLEED AIR SYSTEM - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 36-10-00	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
3610001 (s)	** PYLON OVERHEAT THERMOSTAT AND ELECTRICAL SYSTEM - PERFORM FUNCTIONAL TEST PKG 5 REF: AMM 36-20-01	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
+ 3610048	LEFT HP BLEED MANIFOLD ASSEMBLY - PERFORM VISUAL INSPECTION. REF: GENERIC NO REF	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
3610048	RIGHT HP BLEED MANIFOLD ASSEMBLY - PERFORM VISUAL INSPECTION. REF: GENERIC NO REF	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
361006	LH HIGH PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361006	RH HIGH PRESSURE SWITCH PN SN-UNKNOWN REF: AMM 36-10-06	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
3610061 (s)	CLEAN HIGH PRESSURE BLEED AIR SHUT-OFF VALVE IN-LINE FILTER PKG 5 REF: AMM 36-10-02	MOS HRS/MSC AFL	36 600	+14d/-14d +25/-25			PKG 17-NOV-2018 532.7		
361031	ECS, DUAL CHANNEL CONTROLLER 6636108500-003 14 REF: AMM 36-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361040	CHECK VALVE PN SN-UNKNOWN REF: AMM 36-10-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361050	SHUTOFF, BLEED AIR VALVE 3876322-1 550 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361053	LH ECS SHUTOFF VALVE 6621000000-061 1488 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361054	RH ECS SHUTOFF VALVE 6621000000-061 1496 REF: AMM 36-10-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361055	LH SHUTOFF, BUTTERFLY, 2.0 DIA VALVE 6621000000-092 1596 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361056	RH SHUTOFF, BUTTERFLY, 2.0 DIA VALVE 6621000000-092 1597 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361215	LH HP MANIFOLD ASSY PN SN-UNKNOWN REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361216	RH HP MANIFOLD ASSY PN SN-UNKNOWN REF: AMM 36-10-07	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361301	CHECK - APU VALVE PN SN-UNKNOWN REF: AMM 36-10-09	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361302	LH CHECK - SERVO AIR VALVE PN SN-UNKNOWN REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361303	RH CHECK - SERVO AIR VALVE PN SN-UNKNOWN REF: AMM 36-15-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
361501	PRESSURE SERVO AIR REGULATOR 6600245-004 1638 REF: AMM 36-15-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 38	WATER/WASTE								
381009	FWD HEATED DRAIN MAST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
381010	AFT HEATED DRAIN MAST PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
383001	TOILET ASSY PN SN-UNKNOWN REF: AMM 38-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
383002	TIMER BOX ASSY PN SN-UNKNOWN REF: AMM 38-30-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
383005	WATER TANK ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
383006	AFT HOT LIQUID CONTAINER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 45	CENTRAL MAINT SYSTEM								
454502	WIFI DATA LINK 011-01746-00 1EJ005735 REF: AMM 45-45-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
454503	L-BAND ANTENNA PN SN-UNKNOWN REF: AMM 45-45-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 46	INFORMATION SYSTEMS								

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
462001	XM GRAPHICAL WEATHER RECEIVER 011-00986-00 47708632 REF: AMM 46-20-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
462002	GDL69A RECEIVER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 49 AIRBORNE AUXILIARY POWER									
4900002 (s)	FUNCTIONAL TEST AUXILIARY POWER UNIT FIRE EXTINGUISHER CONTAINER WIRING PKG 6 REF: AMM 26-22-00	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
4900003	OVERHAUL APU STARTER/GENERATOR (REPLACE BRUSHES) 6608458-010 Y01125 REF: See Workcard	MOS HRS/MSC AFL APH	1200	+25/-25			18-JAN-2017 107.7 70 67	1267	1292
4900006	VISUAL INSPECTION APU STARTER/GENERATOR GEAR BOX DRIVE SPLINES 6608458-010 Y01125 REF: GENERIC NO REF	MOS HRS/MSC AFL	C/C				18-JAN-2017 107.7 70		
4900011 (s)	** APU GENERATOR - PERFORM OVERVOLTAGE PROTECTION CHECK. PKG 6 REF: AMM 49-40-01	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
4900014	HYDROSTATIC TEST APU FIRE EXTINGUISHER CONTAINER 51600-2 0635 REF: AMM 26-22-01	MOS HRS/MSC AFL	60	+14d/-14d			22-DEC-2015	31-DEC-2020	14-JAN-2021

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
4900015	APU FIRE EXTINGUISHER CONTAINER CARTRIDGE 30600-22 LOT 105 REF: AMM 26-22-01	MOS HRS/MSC AFL	144	+14d/-14d	N:8		28-APR-2016 23.3 15	31-AUG-2027	14-SEP-2027
LIFE LIMIT									
491011	APU MAINTENANCE CONTROL PANEL 7088001-2 DC555 REF: AMM 49-60-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
491020	APU CTRL PANEL ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
495001	LH TAILCONE FAN PN SN-UNKNOWN REF: AMM 49-50-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
495002	ACCESS DOOR TAILCONE FAN PN SN-UNKNOWN REF: AMM 49-50-01	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2016 0 0		
49APU1 49.APU1	APU 3800726-1 P-572 REF: AMM 49-10-01	MOS HRS/MSC AFL	E/C						
APU Model : RE100 (CIMMS) Serial # P-572 Part # 3800726-1									
4900004	APU - ENGINE OIL FILTER PN-UNKNOWN SN-UNKNOWN REF: AMM 49-90-04	MOS HRS/MSC APUS	750		N:0 N:0 N:0		18-JAN-2017 67 80	817	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
4900005	APU - ENGINE FUEL FILTER PN SN-UNKNOWN REF: AMM 49-30-03	MOS HRS/MSC APUS	750	N:0 N:0 N:0			12-OCT-2015 0 0	750	
4900008	APU - INSPECT APU ENGINE CHIP DETECTOR FOR CONTAMINATION REF: AMM 49-90-05	MOS HRS/MSC APUS	750				12-OCT-2015 0 0	750	
4900009	APU - PERFORM APU ENGINE OIL CHANGE REF:	MOS HRS/MSC APUS	750				12-OCT-2015 0 0	750	
4900018	APU - AUXILIARY POWER UNIT TURBINE ROTOR PN SN-UNKNOWN REF: AMM 49-10-01	MOS HRS/MSC APUS	4000	N:0 N:0 N:0			12-OCT-2015 0 0	4000	
4900020	APU - AUXILIARY POWER UNIT COMPRESSOR ROTOR 3822523-003 14-162053-07607 REF: AMM 49-10-01	MOS HRS/MSC APUS	12000	N:0 N:0 N:0			12-OCT-2015 0 0	12000	
+ 491000	APU - DOWNLOAD APU ECU (TIMES/CYCLES) REF:	MOS HRS/MSC APUS	A/R				12-OCT-2015 0 0		
493011	APU - APU PRESSURIZING VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
493021	APU - APU FILTER BYPASS VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
493031	APU - APU PRESSURE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
493041	APU - APU DIFFERENTIAL PRESSURE VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
493051	APU - APU FUEL PUMP PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
493061	APU - APU DIFFERENTIAL PRESSURE INDICATOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
493071	APU - APU ASSEMBLY, FUEL CONTROL 3883900-1 1502025 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
494001	APU - (LOW VOLTAGE) IGNITION UNIT 3888000-7 J15390472 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
494011	APU - APU IGNITION EXCITER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	
494021	APU - APU LOW VOLTAGE IGNITER PLUG PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0				12-OCT-2015 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494031	APU - APU IGNITION LEAD PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
494060	APU - APU GROUND CONTROL UNIT CHANGE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
495001	APU - APU ISOLATION VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
496001	APU - APU REMOTELY LOCATED (ECU) CONTROLLER 2119560-3 44-N0112 REF:	MOS HRS/MSC APUS	O/C				20-DEC-2016 64 71		
496010	APU - APU FUEL LINE REPLACE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
496011	APU - APU FUEL SHUTOFF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
496021	APU - APU FLOW DIVIDER VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
496031	APU - APU FUEL SOLENOID VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
496041	APU - APU - BLEED AIR SHUTOFF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
497001	APU - APU SPEED SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
497011	APU - APU EGT THERMOCOUPLE 3876315-2 00152 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			04-JAN-2017 67 80		
499025	APU - APU ASSEMBLY, LUBE OIL-PUMP 3881825-1 P-2104 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499037	APU - APU LOW OIL PRESSURE SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499048	APU - INLET TEMP SENSOR PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499049	APU - APU OIL TEMPERATURE BULB PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499061	APU - APU OIL LEVEL SENSOR 3876318-3 1516222101596 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
499071	APU - APU ULTIMATE RELIEF VALVE PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499081	APU - APU MANIFOLD AND PRIMARY ATOMIZER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
499082	APU - APU MANIFOLD AND SECONDARY ATOMIZER PN SN-UNKNOWN REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			12-OCT-2015 0 0		
CHAPTER 52 DOORS									
5210003 (s)	VISUAL INSPECTION EXTERNAL LOWER PASSENGER/CREW DOOR CABLES - PERFORM VISUAL INSPECTION OF VISIBLE PORTION OF CABLES AND HANDLE AREA. PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
5210006 (s)	VISUAL INSPECTION UPPER PASSENGER/CREW DOOR VENT DOOR SPRINGS PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
5210008 (s)	PERFORM OPERATIONAL CHECK - EMERGENCY EXIT DOOR INTERNAL AND EXTERNAL HANDLE LATCHING MECHANISM. PKG 6 REF: AMM 52-20-07	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			07-MAR-2016 0 0		
5210009 (s)	* EMERGENCY EXIT DOOR RETAINERS - PERFORM VISUAL INSPECTION. INSPECT DOOR STOP FITTINGS ON EMERGENCY EXIT DOOR FRAMES IN FLANGE RADII. (F.S. 374 AND 394). PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
521001	UPPER PASSENGER/CREW DOOR ASSY 4552101000-005 W684 REF: AMM 52-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
5210010	* LOWER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				07-MAR-2016 0 0	9600	
5210011	* UPPER AND LOWER PASSENGER DOOR LATCH PINS - PERFORM VISUAL INSPECTION. INSPECT BOLTS AND DOOR END RIB STRUCTURE AT LOCK PINS. REF: GENERIC NO REF	MOS HRS/MSC AFL	9600				07-MAR-2016 0 0	9600	
5210012 (s)	* LOWER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT PIANO HINGE LUGS AND FASTENERS. PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5210013 (s)	* UPPER AND LOWER PASSENGER DOOR LATCH ARMS AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5210014 (s)	* UPPER PASSENGER DOOR TENSION FITTINGS - PERFORM VISUAL INSPECTION. INSPECT THE FOLLOWING: A. TENSION STUDS AT RETAINING FLANGES. B. RADII AROUND FLANGE PERIPHERY. PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5210015 (s)	* EMERGENCY EXIT DOOR - PERFORM VISUAL INSPECTION. PAY PARTICULAR ATTENTION TO FLANGES AND FASTENER HOLES OF DOOR STOP FITTINGS. PKG 14 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5210016 (s)	* UPPER PASSENGER DOOR HINGE - PERFORM VISUAL INSPECTION. INSPECT UPPER SURFACE OF HINGE FINGERS AT BASE OF LUG. PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5210017	* UPPER PASSENGER DOOR TENSION BOLTS, BOLT RETAINERS, TENSION FITTINGS, AND DOOR ATTACHMENTS - PERFORM VISUAL INSPECTION	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	9600				0 0	9600	
521002	LOWER PASSENGER/CREW DOOR ASSY 4552100050V109-001 W669	MOS		N:0			07-MAR-2016		
	REF: AMM 52-10-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
+ 5210053	CABIN DOOR HANDLE - REPLACE	MOS					07-MAR-2016		
	REF: GENERIC NO REF	HRS/MSC AFL	N/A				0 0		
+ 5210055 (s)	CABIN DOOR HANDLE RAMP ROLLER WHEEL - LUBRICATE PKG 6	MOS	72	+14d/-14d			07-MAR-2016		
	REF:	HRS/MSC AFL	1200	+25/-25			0 0		
522001	EMERGENCY EXIT DOOR ASSY 4552200076-V44-001 L533	MOS		N:0			07-MAR-2016		
	REF: AMM 52-20-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
523001	TAILCONE BAGGAGE DOOR ASSY 12045-558V3-001 535	MOS		N:0			07-MAR-2016		
	REF: AMM 52-30-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5240004 (s)	INSPECT AVIONIC ACCESS DOORS - PERFORM AVIONICS DOOR GAP AND MISMATCH INSPECTION PKG 10 REF: AMM 52-40-01	MOS HRS/MSC AFL	24	+14d/-14d			PKG 13-FEB-2020 746.3 493		
524001	TAILCONE ACCESS DOOR ASSY 4552405151-017 5514 REF: AMM 52-40-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
CHAPTER 53 FUSELAGE									
530001	FUSELAGE ASSEMBLY 4553000010-001 L533 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
5310001 (s)	* LONGERON, INTERNAL (BETWEEN F.S. 384 AND F.S. 433) - PERFORM VISUAL INSPECTION PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5310002 (s)	* FLIGHT DECK LONGERON (F.S. 149 - F.S. 196) - PERFORM VISUAL INSPECTION. INSPECT FLIGHT DECK LONGERON STIFFENERS, WEBS, AND CUTOUS PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5310003 (s)	* AFT PRESSURE BULKHEAD SUPPORT POST (F.S. 457) - PERFORM EDDY CURRENT INSPECTION. PKG 9 REF: NDT PART 6 / 53-30-18	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5310004 (s)	* AFT PRESSURE BULKHEAD FRAME PERIPHERY - PERFORM EDDY CURRENT INSPECTION. PKG 13 REF: NDT PART 6 / 53-30-21	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5310005 (s)	* FUSELAGE FUEL CELL CANTED BULKHEAD (F.S. 495) - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION TO MAIN CROSS MEMBER. INSPECT FLANGES AND ATTACHMENTS FOR CRACKING. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5310006 (s)	* FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-07	HRS/MSC AFL	10000				0 0		
5310007 (s)	* AFT PRESSURE BULKHEAD BOTTOM SHEAR DIAPHRAGM - PERFORM DETAILED VISUAL INSPECTION. INSPECT BULKHEAD POST ATTACHMENT FASTENER HOLES AND CONTROL CABLE SLOT. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5310017 (s)	* AFT PRESSURE BULKHEAD BOTTOM CROSSMEMBER (F.S. 457) - PERFORM DETAILED VISUAL INSPECTION. INSPECT TEE-SECTION AT F.S. 457 FLANGE AT ATTACHMENT TO PRESSURE FLOOR PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5310018 (s)	* AFT PRESSURE BULKHEAD PANEL FACING SHEETS (F.S. 457) - PERFORM VISUAL INSPECTION - INSPECT BOTH FRONT AND AFT OF FACING SHEETS. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5310023 (s)	VISUAL INSPECTION FORWARD AND AFT FUEL CELL BAY STRUCTURE, ANGLE REINFORCEMENT, STRINGER 1, LH & RH - PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS. PKG 9	MOS					PKG	07-MAR-2016	
	REF: GENERIC NO REF	HRS/MSC AFL	10000	+25/-25			0 0		
5310025 (s)	VISUAL INSPECTION AFT FUSELAGE KEELBEAM LONGERON (LH & RH, BL 5.15, FS 466.30 - 495.12) AND AFT FUSELAGE KEELBEAM LOWER FRAME (FS 466.30, BL 9.55 LH THRU BL 9.55 RH)- PERFORM DETAILED VISUAL INSPECTION OF HI-LITE COLLARS. PKG 9	MOS					PKG	07-MAR-2016	
	REF: GENERIC NO REF	HRS/MSC AFL	10000	+25/-25			0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5310027 (s)	* AFT PRESSURE BULKHEAD TOP MOUNTING STRUCTURE - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG		
		HRS/MSC	10000				07-MAR-2016		
CMR*	REF: NDT PART 6 / 53-30-17	AFL					0		
							0		
5311002	* NOSE LANDING GEAR ACTUATOR ATTACHMENT ON FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. INSPECT ACTUATOR ATTACHMENT BRACKET LUGS, RADII, AND FASTENER HOLES.	MOS							
		HRS/MSC					07-MAR-2016		
CMR*	REF: NDT PART 6 / 32-12-00	AFL	10000				0		10000
							0		
5311004	* NOSE LANDING GEAR TRUNNION FITTINGS - PERFORM VISUAL INSPECTION OF THE TRUNNION FITTINGS AND ATTACHMENT BOLTS.	MOS							
		HRS/MSC					07-MAR-2016		
CMR*	REF: GENERIC NO REF	AFL	10000				0		10000
							0		
5311005	* NOSE LANDING GEAR TRUNNION FITTINGS AND SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION OF THE TRUNNION SUPPORT STRUCTURE AT THE FORWARD PRESSURE BULKHEAD FLANGE.	MOS							
		HRS/MSC					07-MAR-2016		
CMR*	REF: NDT PART 6 / 32-12-05	AFL	10000				0		10000
							0		
5313001 (s)	CHECK FORWARD FUSELAGE SKIN - PERFORM PITOT-STATIC PROBE ZONE SKIN CONTOUR CHECK. PKG 10	MOS	24	+14d/-14d			PKG		
		HRS/MSC					13-FEB-2020		
	REF: AMM 53-00-01	AFL					746.3		
							493		
5314000 (s)	* EMERGENCY EXIT DOOR SKIN CUTOUT CORNERS AND DOUBLERS (F.S. 370 - F.S. 398) - PERFORM EDDY CURRENT INSPECTION. PKG 11	MOS							
		HRS/MSC	4800				07-MAR-2016		
CMR*	REF: NDT PART 6 / 53-30-01	AFL					0		
							0		
5320001 (s)	* FUSELAGE PRESSURE FLOOR STEP (F.S. 433 - F.S. 457) - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS							
		HRS/MSC	10000				07-MAR-2016		
CMR*	REF: NDT PART 6 / 53-20-01	AFL					0		
							0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323021 (s)	* EXTERNAL LONGERON, FASTENER LOCATIONS, AND AREA AROUND WING ATTACHMENTS - PERFORM VISUAL INSPECTION - INSPECT LONGERON BETWEEN F.S. 398 AND F.S. 486, STRINGER 13 LHS & RHS. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0	0	
5323022 (s)	* NOSE LANDING GEAR AFT WHEELBOX CLOSING STRUCTURE (F.S. 150 TO F.S.162) - PERFORM VISUAL INSPECTION - INSPECT THE FOLLOWING: A. PANEL. B. CHANNEL STIFFENERS. C. SUPPORT ANGLE. D. ANGLE STIFFENER. E. ZEE STIFFENER. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0	0	
5323023 (s)	* DRAG LINK ATTACHMENT LUG - PERFORM VISUAL INSPECTION PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0	0	
5323024 (s)	* FUSELAGE SKIN CUT-OUTS ABOVE FUEL CELL - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-12	HRS/MSC AFL	10000				0	0	
5323025 (s)	* FORWARD/AFT WHEELBOX JOINT (F.S. 150) - PERFORM VISUAL INSPECTION - INSPECT SPLICE STRAP AFT OF FORWARD PRESSURE BULKHEAD AT INTERSECTION OF ATTACHMENT ANGLE AND FLIGHT DECK LONGERON. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0	0	
5323026 (s)	* UPPER AND LOWER PASSENGER/CREW DOOR SKIN CUTOUT CORNERS (F.S. 224 - F.S. 256) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN AT CORNERS OF PASSENGER/CREW DOOR CUTOUT. PKG 11	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-02	HRS/MSC AFL	4800				0	0	
5323027 (s)	* FUSELAGE FRAME AT F.S. 412 - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-20	HRS/MSC AFL	10000				0	0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323028 (s)	* FUSELAGE TO WING ATTACH FITTINGS - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-16	HRS/MSC AFL	10000				0 0		
5323029 (s)	* MACHINED SPAR FRAMES SYSTEMS CUTOUTS (F.S. 398, F.S. 412, F.S. 432, F.S. 466) - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-15	HRS/MSC AFL	10000				0 0		
5323032	* EXTERIOR CABIN WINDOW COAMINGS (UNPAINTED) - PERFORM EDDY CURRENT INSPECTION.	MOS	24				13-FEB-2020	28-FEB-2022	
CMR*	REF: NDT PART 6 / 56-20-01	HRS/MSC AFL	2400				746.3 493	3146.3	
5323033 (s)	* FUSELAGE SKIN AT EMERGENCY DOOR EGRESS LIGHT AND WING INSPECTION LIGHT - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-40-02	HRS/MSC AFL	10000				0 0		
5323034 (s)	* UPPER AND LOWER COUPE RAIL AND CENTER POST/WINDSHIELD RETAINER ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-03	HRS/MSC AFL	10000				0 0		
5323037 (s)	* WINDSHIELD COUPE RAIL TIE ROD BRACKET - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-09	HRS/MSC AFL	10000				0 0		
5323038 (s)	* WINDSHIELD CENTER POST TO UPPER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 14	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-22	HRS/MSC AFL	10000				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323047 (s)	* PRESSURE CABIN FUSELAGE CROWN SKIN - PERFORM EDDY CURRENT INSPECTION. PKG 12	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-10-04	HRS/MSC AFL	10000				0 0		
5323048 (s)	* FUSELAGE (PRESSURE CABIN) - PERFORM EDDY CURRENT INSPECTION. INSPECT PRESSURE CABIN SKIN (LONGITUDINAL SKIN CRACKING). PKG 14	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-05	HRS/MSC AFL	10000				0 0		
5323049 (s)	* FUSELAGE SKIN AT UPPER AND LOWER COUPE RAIL RUN-OUT JOINTS - PERFORM EDDY CURRENT INSPECTION PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-11	HRS/MSC AFL	10000				0 0		
5323050 (s)	* AFT POST/WINDSHIELD RETAINER ATTACHMENT - WITH HEADLINER REMOVED, PERFORM EDDY CURRENT INSPECTION. INSPECT WINDSHIELD AFT POST AT WINDSHIELD RETAINER FASTENER HOLES. PKG 14	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-04	HRS/MSC AFL	10000				0 0		
5323051 (s)	* LONGITUDINAL JOINTS INSIDE PRESSURE CABIN (F.S. 220 - F.S. 457) AND SKIN WITHIN ONE STRINGER BAY OF JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN FASTENER HOLES ALONG JOINTS AT STRINGER 10 LH & RH AND STRINGER 2 RH AND STRINGER 18 RH. PKG 14	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-05	HRS/MSC AFL	10000				0 0		
5323053 (s)	* FRAME ATTACHMENTS TO UPPER AND LOWER COUPE RAILS (F.S. 171 TO F.S. 204) - PERFORM VISUAL INSPECTION - INSPECT THE FOLLOWING: A. FRAME ATTACHMENTS TO LOWER COUPE RAILS AT F.S. 171, F.S. 182, F.S. 196 AND F.S. 204. B. FRAME ATTACHMENTS TO UPPER COUPE RAIL PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5323055	* TIE-ROD ASSEMBLY (F.S. 162) (TITANIUM ENDS) - PERFORM VISUAL INSPECTION - INSPECT TIE-ROD ENDS, TIE-ROD TUBES, AND TIE-ROD BOLTS. MOS							07-MAR-2016	
CMR*	REF: AMM 53-10-04	HRS/MSC AFL	9600				0 0	9600	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323057 (s)	* PRESSURE CABIN SKIN AT FUSELAGE STATION 451 - PERFORM EDDY CURRENT INSPECTION. PKG 12	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-06	HRS/MSC AFL	10000				0 0		
5323058 (s)	* FUSELAGE SKIN AT F.S. 504 - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-13	HRS/MSC AFL	10000				0 0		
5323059 (s)	* STRINGER TO FRAME JOINTS (F.S. 162 TO F.S. 213) - PERFORM EDDY CURRENT INSPECTION. INSPECT SKIN, STRINGERS, AND FRAMES AT JOINTS. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-05	HRS/MSC AFL	10000				0 0		
5323068 (s)	* STRINGER 1RH BETWEEN F.S. 533 AND F.S. 543 - PERFORM VISUAL INSPECTION - INSPECT STRINGER 1 FLANGE AND SKIN ALONG STRINGER 1 BETWEEN F.S. 533 AND F.S. 543. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5323069 (s)	* CIRCUMFERENTIAL SKIN JOINT AT FORWARD PRESSURE BULKHEAD - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 53-30-08	HRS/MSC AFL	10000				0 0		
5323073 (s)	* FUSELAGE BOTTOM SKIN PANEL - PERFORM VISUAL INSPECTION - INSPECT CORNER RADIUS AT JUNCTION OF EXTERNAL LONGERON AND MID SPAR FRAME (F.S. 435). PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5323074 (s)	* AUXILIARY SKIN PANEL - PERFORM VISUAL INSPECTION - INSPECT CORNER RADIUS AT JUNCTION OF KEEL BEAM AND REAR SPAR FRAME (F.S. 466). PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5323081	* TIE-ROD FORK ENDS (TITANIUM, P/N R24889) - PERFORM FLUORESCENT PENETRANT INSPECTION.								
		MOS					07-MAR-2016		
		HRS/MSC	9600				0		9600
CMR*	REF: NDT PART 8 / 53-10-01	AFL					0		
5323092	* EXTERIOR CABIN WINDOW COAMINGS (PAINTED) - PERFORM EDDY CURRENT INSPECTION.								
		MOS	96				07-MAR-2016		31-MAR-2024
		HRS/MSC	4800				0		4800
CMR*	REF: NDT PART 6 / 56-20-01	AFL					0		
5323164 (s)	* FUSELAGE SKIN AND DOUBLER AROUND ECS DUCT CUTOUT - PERFORM EDDY CURRENT INSPECTION.						PKG		
	PKG 9	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: NDT PART 6 / 53-40-01	AFL					0		
5323165 (s)	* WINDSHIELD CENTER POST TO LOWER COUPE RAIL JOINT ATTACHMENT - PERFORM EDDY CURRENT INSPECTION.						PKG		
	PKG 9	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: NDT PART 6 / 53-30-10	AFL					0		
5323166	* EXTERNAL SKIN CUT-OUTS/PENETRATIONS (PRESSURE CABIN) - PERFORM DETAILED VISUAL INSPECTION. INSPECT SKIN AND DOUBLERS AT ANTENNAS, ELECTRICAL COMPONENTS, AND ACCESS PANELS (EXCLUDING PITOT/STATIC PROBES, AOA STALL VANES, AND WING INSPECTION LIGHT).								
		MOS	144				07-MAR-2016		31-MAR-2028
		HRS/MSC	10000				0		10000
CMR*	REF: GENERIC NO REF	AFL					0		
5323168	* LH AND RH LOWER COUPE RAIL RADIUS/WINDSCREEN RETAINER ATTACH - PERFORM EDDY CURRENT INSPECTION (P/N'S 4553130001-802 THRU 4553130001-809)								
		MOS					07-MAR-2016		
		HRS/MSC	N/A				0		
	REF: GENERIC NO REF	AFL					0		
+ 5323173	* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION								
		MOS					07-MAR-2016		
		HRS/MSC	N/A				0		
CMR*	REF: GENERIC NO REF	AFL					0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 5323174	* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
+ 5323175	* SKIN CUT-OUT FOR IRIDIUM ANTENNAS, FS 283.88 TO FS 308.39 - PERFORM EDDY CURRENT INSPECTION	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	N/A					0 0	
5331021 (s)	* FORWARD CANTED BULKHEAD (F.S. 630) - PERFORM VISUAL INSPECTION - INSPECT AT FRONT SPAR UPPER ATTACHMENT FASTENERS.						PKG		
	PKG 13	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000					0 0	
5331022 (s)	* MID CANTED BULKHEAD (F.S. 657) - PERFORM VISUAL INSPECTION AT MID SPAR UPPER ATTACHMENT FASTENERS.						PKG		
	PKG 9	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000					0 0	
5331023 (s)	* AFT CANTED BULKHEAD (F.S. 682) - PERFORM VISUAL INSPECTION - INSPECT AT REAR SPAR ATTACHMENT FASTENERS.						PKG		
	PKG 9	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000					0 0	
5331024 (s)	* VERTICAL STABILIZER FRONT SPAR ROOT BULKHEAD ATTACHMENT (F.S. 630) - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 9	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000					0 0	
5331025 (s)	* VERTICAL STABILIZER MID SPAR ROOT BULKHEAD ATTACHMENT (F.S. 657) - PERFORM VISUAL INSPECTION - INSPECT MID SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES.						PKG		
	PKG 9	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000					0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5331026 (s)	* VERTICAL STABILIZER REAR SPAR ROOT BULKHEAD ATTACHMENT (F.S. 682) - PERFORM VISUAL INSPECTION - INSPECT REAR SPAR ROOT BULKHEAD ATTACHMENT AT FASTENER HOLES. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5350000 (s)	* BOTTOM KEEL BEAM END PADS (F.S. 384 - F.S. 486) - INSPECT END PADS AROUND BOLT HOLES AND IN RADII AT F.S. 433. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
535001	RADOME ASSEMBLY 6634408000-005 783	MOS		N:0				07-MAR-2016	
	REF: AMM 53-50-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
535601	LH DELTA FIN ASSY 4555501000-017 A 0447	MOS		N:0				07-MAR-2016	
	REF: AMM 53-56-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
535602	RH DELTA FIN ASSY 4555501000-018 A0463	MOS		N:0				07-MAR-2016	
	REF: AMM 53-56-01	HRS/MSC AFL	O/C	N:0 N:0			0 0		
5360001 (s)	VISUAL INSPECTION DELTA FINS - WITH DELTA FINS REMOVED, VISUALLY INSPECT THE FOLLOWING: A. DELTA FIN AFT SPAR. B. DELTA FIN SUPPORT ANGLE. C. INSPECT STIFFENERS CONNECTING TO ATTACH FITTINGS. PKG 9	MOS					PKG	07-MAR-2016	
	REF: GENERIC NO REF	HRS/MSC AFL	10000	+25/-25			0 0		
5360006 (s)	NDT INSPECT DELTA FIN ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
	REF: NDT PART 8 / 53-10-02	HRS/MSC AFL	10000	+25/-25			0 0		

CHAPTER 54 NACELLES/PYLONS

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5410002 (s)	VISUAL INSPECTION PYLONS - INSPECT HILITE COLLARS COMMON TO MAIN ENGINE BEAM EXTERNAL TO FUSELAGE. PKG 7	MOS	108	+14d/-14d			07-MAR-2016		
	REF: AMM 54-00-01	HRS/MSC AFL	2400	+25/-25			0		0
545001	LH FIREWALL ASSY PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 54-50-01	AFL		N:0			0		
5450011 (s)	* DRAG STRUT ATTACHMENT FITTINGS - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					07-MAR-2016		
	REF: NDT PART 6 / 53-10-03	HRS/MSC AFL	10000				0		0
5450012 (s)	* FRAMES 39/40 (F.S. 512/518) AT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. INSPECT OUTER FLANGE AND FRAME WEB AT ENGINE BEAM ATTACHMENT. PKG 13	MOS					07-MAR-2016		
	REF: NDT PART 6 / 54-50-03	HRS/MSC AFL	10000				0		0
5450015 (s)	* FORWARD ENGINE BEAM, SPAR CAP, AND WEB - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					07-MAR-2016		
	REF: NDT PART 6 / 54-50-05	HRS/MSC AFL	10000				0		0
5450016 (s)	* FORWARD ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					07-MAR-2016		
	REF: NDT PART 6 / 54-50-02	HRS/MSC AFL	10000				0		0
5450017 (s)	LEFT * FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS					07-MAR-2016		
	REF: NDT PART 8 / 53-40-01	HRS/MSC AFL	10000				0		0

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5450017 (s)	RIGHT * FORWARD ENGINE BEAM TO FRAME ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 53-40-01	HRS/MSC AFL	10000				0 0		
5450018 (s)	LEFT * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 71-20-01	HRS/MSC AFL	10000				0 0		
5450018 (s)	RIGHT * FORWARD ENGINE MOUNT ATTACHMENT BOLTS - PERFORM FLUORESCENT LIQUID PENETRANT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 71-20-01	HRS/MSC AFL	10000				0 0		
5450019 (s)	* AFT ENGINE BEAM ATTACHMENT TO FRAMES - PERFORM VISUAL INSPECTION - INSPECT AFT ENGINE BEAM ATTACHMENT TO FRAMES. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
545002	RH FIREWALL ASSY PN SN-UNKNOWN	MOS			N:0			07-MAR-2016	
	REF: AMM 54-50-01	HRS/MSC AFL	O/C		N:0 N:0		0 0		
5450020 (s)	LEFT * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 54-30-01	HRS/MSC AFL	10000				0 0		
5450020 (s)	RIGHT * AFT ENGINE BEAM TO FRAME ATTACHMENT BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 54-30-01	HRS/MSC AFL	10000				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5450021 (s)	LEFT * ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 71-20-03	AFL					0		
5450021 (s)	RIGHT * ENGINE AFT ISOLATOR MOUNT FITTINGS - PERFORM LIQUID PENETRANT INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 71-20-03	AFL					0		
5450022 (s)	LEFT * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 7 / 71-20-01	AFL					0		
5450022 (s)	RIGHT * AFT ENGINE MOUNT TO END FITTING ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 7 / 71-20-01	AFL					0		
5450023 (s)	LEFT * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 54-30-02	AFL					0		
5450023 (s)	RIGHT * ENGINE TO AFT ENGINE MOUNT ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 54-30-02	AFL					0		
5450024 (s)	* FUSELAGE FRAMES AT FS 543.55 AND 546.15 TO AFT ENGINE BEAM ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 53-30-14	AFL					0		
5450025 (s)	* FORWARD ENGINE BEAM AND FRAMES AT ATTACH HOLES - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 54-50-03	AFL					0		

?-Insufficient Information +-Task exists in Inspection Manual (s)-Suppressed Requirement (EBT)-Estimated Base Time *-Estimated Due (New Requirement) (EFF)-Effective C/W

(ENG/APU) = Engine/APU Units

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5450026 (s)	LEFT * ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION						PKG		
	PKG 13	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: NDT PART 6 / 54-50-01	AFL					0		
5450026 (s)	RIGHT * ENGINE DRAG STRUT - PERFORM EDDY CURRENT INSPECTION.						PKG		
	PKG 13	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: NDT PART 6 / 54-50-01	AFL					0		
5450029 (s)	* AFT ENGINE BEAM - PERFORM VISUAL INSPECTION. INSPECT UPPER CAPPING PLATE, AROUND FASTENER HOLES IN THE CAPPING PLATE, AND CHANNEL FLANGE.						PKG		
	PKG 13	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: GENERIC NO REF	AFL					0		
5450030 (s)	* AFT ENGINE BEAM END FITTING - PERFORM EDDY CURRENT INSPECTION						PKG		
	PKG 13	MOS					07-MAR-2016		
		HRS/MSC	10000				0		
CMR*	REF: NDT PART 6 / 54-50-04	AFL					0		
5450054	VISUAL INSPECTION LEFT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.								
		MOS					07-MAR-2016		
		HRS/MSC	6000	+100/-100			0	6000	6100
	REF: GENERIC NO REF	AFL					0		
5450054	VISUAL INSPECTION RIGHT FORWARD ENGINE BEAM AND BEAM FITTING - PERFORM VISUAL INSPECTION, PAYING PARTICULAR ATTENTION OF THE FOLLOWING: A. UPPER CAPPING PLATE AT FASTENER HOLES, AND CHANNEL FLANGE AT FASTENER HOLES. B. BOLT HOLES, ESPECIALLY UPPER BOLT HOLE ON AFT FLANGE.								
		MOS					07-MAR-2016		
		HRS/MSC	6000	+100/-100			0	6000	6100
	REF: GENERIC NO REF	AFL					0		
CHAPTER 55	STABILIZERS								
5510000 (s)	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT FITTING - PERFORM EDDY CURRENT INSPECTION.						PKG		
	PKG 8	MOS					07-MAR-2016		
		HRS/MSC	4800				0		
CMR*	REF: NDT PART 6 / 55-10-01	AFL					0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5510002 (s)	VISUAL INSPECTION ELEVATOR HINGES ON HORIZONTAL STABILIZER - INSPECT HINGE LUGS ON HORIZONTAL TAIL SIDE OF JOINT. INSPECT HILITE COLLARS AT BL 0.0 AND OUTBOARD ELEVATOR HINGE. PKG 7 REF: AMM 55-10-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
5510003 (s)	VISUAL INSPECTION VISUAL INSPECTION VERTICAL STABILIZER PIVOT FITTING - PERFORM VISUAL INSPECTION. INSPECT HI-LITE COLLARS COMMON TO THE PIVOT FITTING (MID SPAR, AFT SPAR, TOP PLATE, AND UP/DOWN SPRING BRACKET) PKG 6 REF: GENERIC NO REF	MOS HRS/MSC AFL	72 1200	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
5510004 (s)	* RUDDER HINGE FITTINGS - PERFORM VISUAL INSPECTION - CONTROL SURFACE REMOVAL NOT REQUIRED. PKG 9 CMR* REF: GENERIC NO REF	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5510005 (s)	* HORIZONTAL STABILIZER REAR SPAR CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR CAP AND WEB AT CENTER SPLICE. PKG 11 CMR* REF: NDT PART 6 / 55-10-05	MOS HRS/MSC AFL	4800				PKG 07-MAR-2016 0 0		
5510006 (s)	* VERTICAL STABILIZER FRONT SPAR AND MID SPAR - PERFORM RADIOGRAPHIC INSPECTION. PKG 9 CMR* REF: NDT PART 2 / 55-30-01	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5510007 (s)	* VERTICAL STABILIZER SKIN AND LOWER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION. PKG 9 CMR* REF: NDT PART 6 / 55-30-06	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5510008 (s)	* HORIZONTAL STABILIZER PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION PKG 9 CMR* REF: See Workcard	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5510009 (s)	* HORIZONTAL STABILIZER MID SPAR UPPER CAP B.L. 0.0 TO B.L. 4.0 - PERFORM X-RAY INSPECTION. PKG 12	MOS					PKG 07-MAR-2016		
CMR*	REF: NDT PART 2 / 55-10-03	HRS/MSC AFL	10000				0 0		
5510010	* HORIZONTAL STABILIZER AFT ROOT RIB - PERFORM EDDY CURRENT INSPECTION. INSPECT AFT ROOT RIB INTERNAL BETWEEN MID SPAR AND AFT SPAR AND UPPER AND LOWER SKINS EXTERNAL AT ATTACHMENT FASTENERS.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-10-03	HRS/MSC AFL	4800				0 0	4800	
5510011	* HORIZONTAL STABILIZER MID SPAR AND REAR SPAR UPPER FLANGE AT ROOT RIB - PERFORM RADIOGRAPHIC INSPECTION.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 2 / 55-10-01	HRS/MSC AFL	10000				0 0	10000	
5510014 (s)	* VERTICAL STABILIZER PIVOT FITTING BOTTOM PLATE - PERFORM DETAILED VISUAL INSPECTION. INSPECT AFT PORTION OF BOTTOM PLATE THROUGH LIGHTENING HOLE IN TOP PLATE, FORWARD PORTION OF BOTTOM PLATE THROUGH TOP PLATE CUTOUTS, AND BOTTOM OF OUTSIDE EXPOSED SURFACE OF PIVOT FITTING PKG 9	MOS					PKG 07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5510015 (s)	* VERTICAL STABILIZER PIVOT FITTING TOP PLATE - PERFORM EDDY CURRENT INSPECTION. PKG 11	MOS					PKG 07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-30-02	HRS/MSC AFL	4800				0 0		
5510016 (s)	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION FORWARD RADIUS - PERFORM EDDY CURRENT INSPECTION. INSPECT PIVOT FITTING AT TOWER SECTION RADIUS, PIVOT FITTING AND TOP PLATE AROUND ADJACENT FASTENERS, AND PIVOT FITTING SIDES AT TOWER SECTION RADIUS. PKG 11	MOS					PKG 07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-30-03	HRS/MSC AFL	4800				0 0		
5510017 (s)	* VERTICAL STABILIZER PIVOT FITTING TOWER SECTION - PERFORM EDDY CURRENT INSPECTION. PKG 12	MOS					PKG 07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-30-05	HRS/MSC AFL	10000				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5510018 (s)	* VERTICAL STABILIZER PIVOT FITTING LUGS - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 55-30-04	AFL					0		
5510019 (s)	* ELEVATOR HINGES ON HORIZONTAL STABILIZER - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 55-20-02	AFL					0		
5510020 (s)	* HORIZONTAL MID SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 55-10-07	AFL					0		
5510021 (s)	* HORIZONTAL MID SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM DETAILED VISUAL INSPECTION. PKG 9	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: GENERIC NO REF	AFL					0		
5510023 (s)	* HORIZONTAL STABILIZER ACTUATOR VERTICAL TAIL ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 8	MOS HRS/MSC	4800				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 55-30-01	AFL					0		
5510024 (s)	* ELEVATOR CONTROL HORN - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 55-20-01	AFL					0		
5510033 (s)	* HORIZONTAL STABILIZER ACTUATOR ATTACHMENT BOLTS - PERFORM LIQUID PENETRANT INSPECTION. PKG 8	MOS HRS/MSC	4800				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 27-40-01	AFL					0		
+ 5510034	HORIZONTAL STABILIZER PRIMARY AND SECONDARY BOLTS AND BUSHINGS - PERFORM DETAILED INSPECTION	MOS HRS/MSC	4800	+25/-25			(EBT)	4800	4825
	REF: GENERIC NO REF	AFL							

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
551005	HORIZONTAL STABILIZER ASSY 4555101001V46-001 A0424 REF: AMM 27-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
5510069 (s)	* HORIZONTAL STABILIZER MID SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 11 REF: NDT PART 6 / 55-10-02	MOS HRS/MSC AFL	4800					07-MAR-2016 0 0	
5510070 (s)	* HORIZONTAL STABILIZER FRONT SPAR - PERFORM RADIOGRAPHIC INSPECTION. PKG 9 REF: NDT PART 2 / 55-10-02	MOS HRS/MSC AFL	10000					07-MAR-2016 0 0	
5510073 (s)	* HORIZONTAL REAR SPAR UPPER CAP - PERFORM EDDY CURRENT INSPECTION. PKG 9 REF: NDT PART 6 / 55-10-07	MOS HRS/MSC AFL	10000					07-MAR-2016 0 0	
5510074 (s)	* HORIZONTAL STABILIZER REAR SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT REAR SPAR CAP AND FASTENERS. PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000					07-MAR-2016 0 0	
5510075 (s)	* HORIZONTAL STABILIZER OUTBOARD SPARS AND SKINS OUTBOARD OF CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT SPAR CAPS AND FASTENERS PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000					07-MAR-2016 0 0	
5510076 (s)	* HORIZONTAL STABILIZER FRONT SPAR FROM CANTED RIB #2 TO CANTED RIB #3 - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR CAP AND FASTENERS. PKG 9 REF: GENERIC NO REF	MOS HRS/MSC AFL	10000					07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5510082 (s)	* HORIZONTAL STABILIZER REAR SPAR FLANGE ROOT RIB ATTACHMENT - PERFORM EDDY CURRENT INSPECTION. PKG 11	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-10-04	HRS/MSC AFL	4800				0 0		
5510091	* HORIZONTAL STABILIZER HINGE PRIMARY AND SECONDARY PIVOT PIN INSTALLATION AND ATTACHING HARDWARE - PERFORM DETAILED VISUAL INSPECTION.	MOS					17-NOV-2018		
CMR*	REF: AMM 55-10-00	HRS/MSC AFL	625				532.7	1157.7	
5510092 (s)	* HORIZONTAL STABILIZER UPPER SPAR SPLICE DOUBLER - PERFORM EDDY CURRENT INSPECTION PKG 12	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-10-06	HRS/MSC AFL	10000				0 0		
5510093 (s)	VISUAL INSPECTION HORIZONTAL STABILIZER - PERFORM VISUAL INSPECTION OF HI-LITE COLLARS IN THE FOLLOWING AREAS: - FORWARD SPAR TO BL 0.0 RIB. - CENTER SPAR TO BL 0.0 RIB. - CENTER SPAR SPLICE PLATE. - AFT SPAR SPLICE PLATE. - ROOT RIBS AT BL 3.70 (RIGHT AND LEFT). - UPPER PKG 7	MOS	108	+14d/-14d			07-MAR-2016		
	REF: AMM 55-00-01	HRS/MSC AFL	2400	+25/-25			0 0		
5510094 (s)	BORESCOPE INSPECTION LOWER BRACKET, HORIZONTAL STABILIZER TRIM ACTUATOR - PERFORM BORESCOPE INSPECTION OF HI-LITE COLLARS COMMON TO RIB# 6 AND MID SPAR. PKG 7	MOS	108	+14d/-14d			07-MAR-2016		
	REF: AMM 55-10-00	HRS/MSC AFL	2400	+25/-25			0 0		
5520001 (s)	* ELEVATOR HINGE ATTACH BOLT - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 9	MOS					07-MAR-2016		
CMR*	REF: NDT PART 7 / 27-30-01	HRS/MSC AFL	10000				0 0		
5520003 (s)	* ELEVATOR FRONT SPAR - PERFORM VISUAL INSPECTION - INSPECT SPAR CAP AT FASTENER HOLES. PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5520004 (s)	* ELEVATOR RIB #1 CAP- PERFORM VISUAL INSPECTION OF RIB #1 CAP CROSS SECTION AND RIB CAP FLANGES AT TORQUE TUBE. PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5520021 (s)	* ELEVATOR HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-30-07	HRS/MSC AFL	10000				0 0		
5520022 (s)	* ELEVATOR HINGE PRIMARY AND SECONDARY ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION. PKG 9	MOS					07-MAR-2016		
CMR*	REF: See Workcard	HRS/MSC AFL	10000				0 0		
552031	LH ELEVATOR ASSEMBLY 4555201005-011 A0431 REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
552032	RH ELEVATOR ASSEMBLY 4555201005-012 A0431 REF: AMM 27-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
553000	TAILCONE/VERTICAL STABILIZER ASSY 4555301001-001 A0421 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
553001	BULLET FAIRING SKIN ASSY INSTALLATION PN SN-UNKNOWN REF: AMM 55-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
5530011	* VERTICAL STABILIZER SKIN AND UPPER AFT SPAR CAP - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 55-30-06	HRS/MSC AFL	9600				0 0	9600	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5540000 (s)	* RUDDER RIB CAP (F.S. 698) - PERFORM VISUAL INSPECTION - INSPECT AROUND FASTENER HOLES AND LIGHTENING HOLES. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5540001 (s)	* RUDDER SPAR - PERFORM DETAILED VISUAL INSPECTION. INSPECT SPAR CAPS AND FASTENERS. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5540002	* RUDDER ATTACH BOLT - PERFORM LIQUID PENETRANT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 8 / 55-30-02	HRS/MSC AFL	9600				0 0	9600	
554005	RUDDER ASSEMBLY 4555401000-025 A0430 REF: AMM 27-20-01	MOS					PKG	07-MAR-2016	
		HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
CHAPTER 56 WINDOWS									
5600002 (s)	** WINDSHIELD - PERFORM RAIN REMOVAL COATING EFFECTIVENESS TEST. PKG 1	MOS	12	+14d/-14d			PKG	13-FEB-2020	
CMR**	REF: AMM 56-10-01	HRS/MSC AFL					746.3 493		
5600010 (s)	* CABIN WINDOWS (INCLUDING THE EMERGENCY EXIT WINDOW) - PERFORM DETAILED VISUAL INSPECTION. PKG 8	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	4800				0 0		
5600012	LEFT * WINDSHIELDS - PERFORM BOLT HOLE INSPECTION PKG 8	MOS					PKG	07-MAR-2016	
CMR*	REF: AMM 56-10-01	HRS/MSC AFL	4800				0 0	4800	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5600012	RIGHT * WINDSHIELDS - PERFORM BOLT HOLE INSPECTION	MOS					07-MAR-2016		
CMR*	REF: AMM 56-10-01	HRS/MSC AFL	4800				0 0	4800	
561001	LH WINDSHIELD ASSY 6656100001-001 2727	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
REF: AMM 56-10-01									
561002	RH WINDSHIELD ASSY 6656100001-002 2690	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
REF: AMM 56-10-01									
561003	EMERGENCY EXIT WINDOW-CABIN PN SN-UNKNOWN	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
REF: AMM 52-20-06									
CHAPTER 57	WINGS								
5710001 (s)	* WING DRAG LINK ATTACH FITTING - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 12	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
CMR*	REF: NDT PART 7 / 57-30-02								
5710002	* WING BOX MID SPAR LOWER CAP, OUTBOARD OF JOINT AT WS 137 BETWEEN RIB# 7 AND 8 - PERFORM DETAILED VISUAL INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS.	MOS HRS/MSC AFL	6448				07-MAR-2016 0 0	6448	
CMR*	REF: GENERIC NO REF								
5710004	* WING CENTER SECTION REAR SPAR - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP FROM CENTER LINE TO WS 33.	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0	10000	
CMR*	REF: NDT PART 6 / 57-20-02								

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710005 (s)	* WING CENTER SECTION SPAR UPPER CAPS - PERFORM VISUAL INSPECTION - INSPECT FRONT, MID, AND REAR SPAR UPPER CAPS FROM CENTERLINE TO SKIN TERMINATION AT WS 33. PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
5710006	* WING CENTER SECTION FORWARD AND AFT RIBS AT WS 6 AND FORWARD RIBS AT WS 17 - PERFORM EDDY CURRENT INSPECTION.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-06	HRS/MSC AFL	10000				0 0	10000	
5710007 (s)	* WING TO FUSELAGE ATTACH FITTINGS AND LINKS - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-12	HRS/MSC AFL	10000				0 0		
5710008	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP AND LOWER SKIN PANELS BETWEEN WS 99 AND WS 137.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 4 / 57-30-03	HRS/MSC AFL	6730				0 0	6730	
5710009	* WING BOX MID SPAR LOWER CAP JOINT AT WS 137 - PERFORM X-RAY INSPECTION. INSPECT MID SPAR CENTER/OUTER JOINT.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 2 / 57-10-02	HRS/MSC AFL	6730				0 0	6730	
571001	WING ASSEMBLY 4557000004-001	MOS		N:0			07-MAR-2016		
	680	HRS/MSC	O/C	N:0			0		
	REF: AMM 57-10-00	AFL		N:0			0		
5710010	* WING BOX REAR SPAR LOWER CAP INBOARD OF JOINT AT WS 81 - PERFORM ULTRASONIC INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN SKIN TERMINATION AT WS 48 AND CLOSING RIB AT WS 60.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 4 / 57-30-01	HRS/MSC AFL	6943				0 0	6943	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710011	* WING BOX REAR SPAR LOWER CAP JOINT AT WS 81 - PERFORM X-RAY INSPECTION. INSPECT CENTER AND OUTER REAR SPARS, LOWER SPLICE PLATE, AND LOWER SKIN BETWEEN WS 60 AND WS 90.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 2 / 57-10-03	HRS/MSC AFL	10000				0 0	10000	
5710012	* WING BOX REAR SPAR LOWER CAP OUTBOARD OF JOINT AT WS 81 TO RIB# 6 - PERFORM DETAILED VISUAL INSPECTION. INSPECT OUTER REAR SPAR LOWER CAP AND AFT LOWER SKIN PANEL OUTBOARD OF REAR SPLICE AT WS 90.	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	6859				0 0	6859	
5710013	* WING BOX REAR SPAR LOWER CAP SKIN TERMINATION AT MS 48 - PERFORM EDDY CURRENT INSPECTION. INSPECT REAR SPAR LOWER CAP BETWEEN WS 33 AND WS 48.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-20-04	HRS/MSC AFL	7885				0 0	7885	
5710014	* WING BOX REAR SPAR FLAP TRACK CUT-OUTS - PERFORM EDDY CURRENT INSPECTION. INSPECT FLAP TRACK CUT-OUTS AT WS 65, WS 126, AND WS 184 ON REAR SPAR.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-20-01	HRS/MSC AFL	9903				0 0	9903	
5710015 (s)	* WING REAR SPAR AT AILERON HINGE - PERFORM EDDY CURRENT INSPECTION.						PKG		
CMR*	PKG 13 REF: NDT PART 6 / 57-10-20	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5710016	* WING BOX BASIC SKIN/STRINGER, LOWER SKIN - PERFORM VISUAL INSPECTION - INSPECT OUTBOARD WING FORWARD AND AFT LOWER SKIN PANELS AND STRINGERS.	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	7312				0 0	7312	
5710017	* WING BOX BASIC SKIN/STRINGER AT STRINGER RUN-OUT, LOWER SKIN - PERFORM VISUAL INSPECTION - INSPECT STRINGER RUN-OUTS IN FORWARD AND AFT LOWER SKIN PANELS.	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0	10000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710018	* WING LOWER SKIN AT MID SPAR SPAN WISE JOINT - PERFORM EDDY CURRENT INSPECTION.								
		MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-09	HRS/MSC	10000				0		10000
		AFL					0		
5710019 (s)	* WING BOX, UPPER SKIN, SKIN/STRINGER AND SPAR CAPS - PERFORM VISUAL INSPECTION - INSPECT UPPER WING SPAR CAPS, SKIN PANEL, AND STRINGERS OF OUTER WING.						PKG		
	PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC	10000				0		
		AFL					0		
5710020 (s)	* WING BOX RIBS - PERFORM VISUAL INSPECTION - INSPECT ALL WING BOX RIBS EXCEPT CLOSING RIB BETWEEN FRONT AND MID SPARS AND CLOSING RIB BETWEEN MID AND REAR SPAR.						PKG		
	PKG 9	MOS					07-MAR-2016		
CMR*	REF: GENERIC NO REF	HRS/MSC	10000				0		
		AFL					0		
5710021	* CENTER SECTION MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT MID SPAR FROM CENTER-LINE SPLICE PLATE TO SKIN TERMINATION AT MS 33.								
		MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-02	HRS/MSC	10000				0		10000
		AFL					0		
5710022	* CENTER SECTION MID SPAR CENTER-LINE JOINT - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER MID SPAR (CENTER-LINE TO WS 17), LOWER SPLICE PLATE, AND CENTER MID SPAR JOINT FITTING LOWER CAP.								
		MOS					07-MAR-2016		
CMR*	REF: See Workcard	HRS/MSC	7974				0		7974
		AFL					0		
5710023	* CENTER SECTION FRONT SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION. INSPECT CENTER WING FRONT SPAR LOWER CAP BETWEEN SKIN TERMINATIONS (WS 31 LEFT TO WS 31 RIGHT).								
		MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-03	HRS/MSC	10000				0		10000
		AFL					0		
5710024 (s)	* WING REAR SPAR SIDE STAY FITTING SUPPORT STRUCTURE - EDDY CURRENT INSPECTION.						PKG		
	PKG 13	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-20-06	HRS/MSC	10000				0		
		AFL					0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710025	* WING FRONT SPAR LOWER CAP FROM WS 33.0 TO WS 60.0 - PERFORM RADIOGRAPHIC INSPECTION.								
CMR*	REF: NDT PART 2 / 57-10-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0	10000	
5710026	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION. INSPECT MID SPAR LOWER CAP OUTBOARD OF ROOT RIB AT WS 33 TO WS 99.								
CMR*	REF: NDT PART 4 / 57-30-03	MOS HRS/MSC AFL	8242				07-MAR-2016 0 0	8242	
5710028	* WING BOX MID SPAR LOWER CAP, SKIN TERMINATION AT WS 33 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION. INSPECT MID SPAR LOWER CAP UNDERNEATH ROOT RIB (WS 33) AT POINT OF SKIN TERMINATION.								
CMR*	REF: NDT PART 6 / 57-10-11	MOS HRS/MSC AFL	7811				07-MAR-2016 0 0	7811	
5710029 (s)	* WING MID SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION.								
CMR*	REF: NDT PART 6 / 57-10-07	PKG 9 MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5710030 (s)	* WING REAR SPAR VERTICAL WEB - PERFORM EDDY CURRENT INSPECTION.								
CMR*	REF: NDT PART 6 / 57-20-05	PKG 9 MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
5710031	* WING BOX SKIN ACCESS COVER HOLES - PERFORM EDDY CURRENT INSPECTION. INSPECT ACCESS HOLES IN FORWARD AND AFT LOWER SKIN PANELS.								
CMR*	REF: NDT PART 6 / 57-30-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0	10000	
5710032	* WING RIB UPPER AFT FLANGE FILLET RADIUS AT WS 33.0 - PERFORM ULTRASONIC INSPECTION.								
CMR*	REF: NDT PART 4 / 57-30-02	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0	10000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710033 (s)	* WING ACCESS HOLE IN CLOSING RIB BETWEEN MID SPAR AND REAR SPAR - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-05	HRS/MSC AFL	10000				0 0		
5710034	* WING BOX JOINT TO WINGLET - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-13	HRS/MSC AFL	6451				0 0	6451	
5710035 (s)	* WING LOWER SKIN AT DRAIN HOLE - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-30-02	HRS/MSC AFL	10000				0 0		
5710037	* WING BOX FRONT SPAR LOWER CAP - PERFORM VISUAL INSPECTION - INSPECT FRONT SPAR LOWER CAP AND LOWER FORWARD SKIN OUTBOARD OF MID-SPAR STATION (MS) 55. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	8780				0 0	8780	
5710039 (s)	* WINGLET SKIN - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-18	HRS/MSC AFL	10000	+25/-25			0 0		
5710083 (s)	* FLAP BOX STRUCTURE - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-40-02	HRS/MSC AFL	10000				0 0		
5710084 (s)	NDT INSPECT SPOILER, CENTER HINGE SPOILER SIDE - PERFORM EDDY CURRENT INSPECTION. PKG 11	MOS					PKG	07-MAR-2016	
	REF: NDT PART 6 / 57-40-01	HRS/MSC AFL	4800	+25/-25			0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710085 (s)	NDT INSPECT SPOILER UPPER SKIN - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
	REF: NDT PART 6 / 57-10-16	HRS/MSC AFL	10000	+25/-25			0 0		
5710086 (s)	NDT INSPECT SPOILER BOLTS AND HINGE PINS - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
	REF: NDT PART 7 / 27-10-01	HRS/MSC AFL	10000	+25/-25			0 0		
5710121	* WING BOX MID SPAR, OUTBOARD OF RIB #8 - PERFORM VISUAL INSPECTION AT WS 156 AND OUTBOARD TO WS 260.	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	8107				0 0	8107	
5710122	* WING BOX REAR SPAR, OUTBOARD OF RIB #6 - PERFORM VISUAL INSPECTION AT WS 118 AND OUTBOARD TO WS 260.	MOS						07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0	10000	
5710123	* WING BOX MID SPAR LOWER CAP - PERFORM EDDY CURRENT INSPECTION AT TRUNNION FITTING.	MOS						07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-01	HRS/MSC AFL	7167				0 0	7167	
5710124 (s)	* AILERON DRIVE SUPPORT - PERFORM ULTRASONIC INSPECTION. PKG 8	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 4 / 27-10-01	HRS/MSC AFL	4800				0 0		
5710137	* MID SPAR AT RIB #2 NEAR WS 48 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.	MOS						07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-11A	HRS/MSC AFL	8242				0 0	8242	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710138	* MID SPAR AT RIB #3 NEAR WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-10-11A	HRS/MSC AFL	8242				0 0		8242
5710139	* FORWARD FLANGE FASTENERS AT REAR SPAR BETWEEN WS 52 AND WS 60 - PERFORM BOLT HOLE EDDY CURRENT INSPECTION.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 6 / 57-20-03	HRS/MSC AFL	6943				0 0		6943
5710172	* WING BOX MID SPAR LOWER CAP - PERFORM ULTRASONIC INSPECTION AT TRUNNION FITTING.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 4 / 57-10-00	HRS/MSC AFL	7167				0 0		7167
5710176	* WING MID SPAR (CENTER SECTION) LOWER CAP AND CENTER JOINT FITTING - PERFORM ULTRASONIC INSPECTION.	MOS					07-MAR-2016		
CMR*	REF: NDT PART 4 / 57-30-05	HRS/MSC AFL	10000				0 0		10000
5710181 (s)	* WING DRAG LINK TUBE - PERFORM MAGNETIC PARTICLE INSPECTION.						PKG		
CMR*	PKG 12 REF: NDT PART 7 / 57-30-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5710182 (s)	* WING DRAG LINK ATTACH BOLTS - PERFORM LIQUID PENETRANT INSPECTION.						PKG		
CMR*	PKG 12 REF: NDT PART 8 / 57-10-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5710183 (s)	* WING DRAG LINK CLEVIS - PERFORM MAGNETIC PARTICLE INSPECTION.						PKG		
CMR*	PKG 12 REF: NDT PART 7 / 57-10-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5710184 (s)	* WING ATTACH BOLTS - PERFORM FLUORESCENT PENETRANT INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 8 / 57-10-02	AFL					0		
5710185 (s)	* WING ATTACH LINKS - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 7 / 57-10-03	AFL					0		
5710186 (s)	* WING ATTACH FITTINGS AT MID SPAR AND REAR SPAR - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 13	MOS HRS/MSC	10000				PKG 07-MAR-2016 0		
CMR*	REF: NDT PART 7 / 57-10-02	AFL					0		
+ 5710190	LEFT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS HRS/MSC	96	+14d/-14d			07-MAR-2016 0	07-MAR-2024	21-MAR-2024
	REF: GENERIC NO REF	AFL					0		
+ 5710190	RIGHT WING CENTER SECTION (PANELS 510AC, 510BC, 510BL AND 610BR REMOVED AND PANELS 510AL, 610AR, 720BL, AND 730BR LOWERED) - PERFORM VISUAL INSPECTION. INSPECT STRUCTURE FOR CORROSION OR DETERIORATION OF PROTECTIVE TREATMENT.	MOS HRS/MSC	96	+14d/-14d			07-MAR-2016 0	07-MAR-2024	21-MAR-2024
	REF: GENERIC NO REF	AFL					0		
5730014 (s)	LUBRICATE AILERON BRUSH SEALS PKG 1	MOS HRS/MSC	12	+14d/-14d			PKG 13-FEB-2020 746.3		
	REF: AMM 12-21-03	AFL					493		
573090	LH WINGLET ASSY 4557300201-001	MOS HRS/MSC	O/C		N:0		07-MAR-2016 0		
	REF: AMM 57-30-01	AFL			N:0		0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573092	RH WINGLET ASSY 4557300201-002 W096 REF: AMM 57-30-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574001	WING TEMP (MT42) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574002	WING TEMP (MT43) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574003	WING TEMP (MT44) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574004	WING TEMP (MT45) SENSOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574005	LH INBD LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574007	RH INBD LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574011	LH INBD LEADING EDGE ACCESS SECTION PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
574013	RH INBD LEADING EDGE ACCESS SECTION PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574033	LH CTR LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574035	RH CTR LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574039	LH OUTBD LEADING EDGE ACCESS SECTION PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574041	RH OUTBD LEADING EDGE ACCESS SECTION PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574050	LH OTBD ACCESS LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
574051	RH OTBD LEADING EDGE ASSY PN SN-UNKNOWN REF: AMM 57-40-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
5750002 (s)	* FLAP FRONT SPAR CUTOUTS - PERFORM EDDY CURRENT INSPECTION. PKG 12	MOS HRS/MSC	10000				07-MAR-2016 0		
CMR*	REF: NDT PART 6 / 57-10-15	AFL					0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5750003 (s)	* FLAP NOSE ROLLER RIBS - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-14	HRS/MSC AFL	10000				0 0		
5750004 (s)	* FLAP ACTUATOR SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-21	HRS/MSC AFL	10000				0 0		
5750005 (s)	* FLAP MAIN TRACK HINGE FITTINGS, TRACK, AND FLAP BOX SIDES - PERFORM VISUAL INSPECTION. INSPECT MAIN TRACK HINGE FITTINGS ON TRACK AND FLAP BOX SIDES. PKG 12	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
575001	LH FLAP ASSY 4557500006-009 680 REF: AMM 27-50-01	MOS						07-MAR-2016	
		HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
575002	RH FLAP ASSY 4557500006-010 680 REF: AMM 27-50-01	MOS						07-MAR-2016	
		HRS/MSC AFL	O/C	N:0 N:0 N:0			0 0 0		
5750048 (s)	* FLAP TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 7 / 57-71-01	HRS/MSC AFL	10000				0 0		
5750049 (s)	* FLAP NOSE ROLLER TRACKS - PERFORM MAGNETIC PARTICLE INSPECTION WITH FLAPS REMOVED. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 7 / 57-10-04	HRS/MSC AFL	10000				0 0		
5750051	* FLAP MAIN TRACK ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED. PKG 9	MOS						07-MAR-2016	
CMR*	REF: AMM 27-50-01	HRS/MSC AFL	10000				0 0	10000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5750052	* FLAP NOSE ROLLERS - PERFORM VISUAL INSPECTION WITH FLAPS REMOVED.								
CMR*	REF: See Workcard	MOS HRS/MSC AFL	7200				07-MAR-2016 0 0	7200	
5750053 (s)	* FLAP TRACK SUPPORT RIBS - PERFORM EDDY CURRENT INSPECTION.						PKG		
CMR*	REF: NDT PART 6 / 57-10-17	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5750068 (s)	* FLAP FRONT SPAR RIB SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION						PKG		
CMR*	REF: NDT PART 6 / 57-10-26	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5760000 (s)	* AILERON ACTUATOR HINGE FITTING - PERFORM EDDY CURRENT INSPECTION.						PKG		
CMR*	REF: NDT PART 6 / 57-10-25	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5760001 (s)	* AILERON SKIN - PERFORM EDDY CURRENT INSPECTION.						PKG		
CMR*	REF: NDT PART 6 / 57-10-19	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5760002 (s)	* AILERON BALANCE TAB HINGE FITTINGS - PERFORM EDDY CURRENT INSPECTION.						PKG		
CMR*	REF: NDT PART 6 / 57-60-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5760003 (s)	* AILERON TRIM AND BALANCE TAB FRONT SPARS - PERFORM RADIOGRAPHIC INSPECTION.						PKG		
CMR*	REF: NDT PART 2 / 57-60-01	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		
5760004 (s)	* AILERON BOLTS - PERFORM MAGNETIC PARTICLE INSPECTION (NAS6204-16H)						PKG		
CMR*	REF: See Workcard	MOS HRS/MSC AFL	10000				07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
5760005 (s)	* AILERON HINGE LUGS AND FITTINGS - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-24	HRS/MSC AFL	10000				0 0		
5760006 (s)	* AILERON BASIC STRUCTURE - PERFORM VISUAL INSPECTION PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: GENERIC NO REF	HRS/MSC AFL	10000				0 0		
576001	LH AILERON ASSEMBLY 4557600003-001	MOS						07-MAR-2016	
	680	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-02	AFL		N:0			0		
5760014 (s)	* AILERON HINGE SUPPORT STRUCTURE - PERFORM EDDY CURRENT INSPECTION. PKG 9	MOS					PKG	07-MAR-2016	
CMR*	REF: NDT PART 6 / 57-10-23	HRS/MSC AFL	10000				0 0		
576002	RH AILERON ASSEMBLY 4557600003-002	MOS						07-MAR-2016	
	680	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-10-02	AFL		N:0			0		
5770000 (s)	NDT INSPECT SPOILER HINGE ASSEMBLIES AND ACTUATOR FITTING - PERFORM EDDY CURRENT INSPECTION. PKG 13	MOS					PKG	07-MAR-2016	
	REF: NDT PART 6 / 57-10-22	HRS/MSC AFL	10000	+25/-25			0 0		
577001	LH SPOILERON ASSY 4557700003-043	MOS						07-MAR-2016	
	680	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-01	AFL		N:0			0		
577002	RH SPOILERON ASSY 4557700003-044	MOS						07-MAR-2016	
	680	HRS/MSC	O/C	N:0			0		
	REF: AMM 27-60-01	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 71	POWER PLANT								
711004	TEST LEFT ENGINE ENGINE INLETS - PERFORM TAP-TEST.								
		MOS					07-MAR-2016		
		HRS/MSC	3000	+100/-100			0	3000	3100
	REF: AMM 71-10-01	AFL					0		
711004	TEST RIGHT ENGINE ENGINE INLETS - PERFORM TAP-TEST.								
		MOS					07-MAR-2016		
		HRS/MSC	3000	+100/-100			0	3000	3100
	REF: AMM 71-10-01	AFL					0		
711001	LH UPPER ENGINE COWL ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-02	AFL		N:0			0		
711002	RH UPPER ENGINE COWL ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-02	AFL		N:0			0		
711003	LH LOWER ENGINE COWL ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-02	AFL		N:0			0		
711004	RH LOWER ENGINE COWL ASSY								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-10-02	AFL		N:0			0		
711101	LH FWD ENGINE MOUNT								
	4571200011-003	MOS		N:0			07-MAR-2016		
	CDF1620	HRS/MSC	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711102	RH FWD ENGINE MOUNT 4571200011-003 CDF1631 REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
7120001 (s)	LEFT * FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION. PKG 13 REF: NDT PART 6 / 71-10-01	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
7120001 (s)	RIGHT * FORWARD ENGINE MOUNT - PERFORM EDDY CURRENT INSPECTION. PKG 13 REF: NDT PART 6 / 71-10-01	MOS HRS/MSC AFL	10000				PKG 07-MAR-2016 0 0		
+ 7120004	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025
+ 7120004	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025
7120004	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING REF: AMM 71-20-00	MOS HRS/MSC AFL	15000	+25/-25			07-MAR-2016 0 0	15000	15025
+ 7120004	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR HOUSING PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025
+ 7120004	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR HOUSING PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	15000	+25/-25	N:0 N:0 N:0		07-MAR-2016 0 0	15000	15025

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7120004	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR HOUSING	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	15000	+25/-25			0	15000	15025
+ 7120006	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
+ 7120006	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
+ 7120006	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
+ 7120006	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
+ 7120006	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
+ 7120006	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	N/A	N:0			0		
	REF:	AFL		N:0			0		
712005	NO. 1 AFT ENGINE ISOLATOR	MOS		N:0			07-MAR-2016		
	PN SN-UNKNOWN	HRS/MSC AFL	O/C	N:0			0		
	REF: AMM 71-20-00	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712006	NO. 2 AFT ENGINE ISOLATOR PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
+ 7120069	NO. 1 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
+ 7120069	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
7120069	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
+ 7120069	NO. 2 ENGINE AFT ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
+ 7120069	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100
7120069	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM VISUAL INSPECTION OF ISOLATOR AND ASSOCIATED PARTS REF: AMM 71-20-00	MOS HRS/MSC AFL	3000	+100/-100			07-MAR-2016 0 0	3000	3100

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712007	NO. 1 FORWARD UPPER ENGINE ISOLATOR PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
+ 7120070	REPLACE NO. 1 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100 N:0 N:0			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
+ 7120070	REPLACE NO. 1 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100 N:0 N:0			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
7120070	REPLACE NO. 1 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS MOS HRS/MSC REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
+ 7120070	REPLACE NO. 2 ENGINE AFT ENGINE MOUNT ISOLATOR METAL MESH ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100 N:0 N:0			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
+ 7120070	REPLACE NO. 2 ENGINE FORWARD LOWER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100 N:0 N:0			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
7120070	REPLACE NO. 2 ENGINE FORWARD UPPER ENGINE MOUNT ISOLATOR BONDED MOUNTING ELEMENTS MOS HRS/MSC REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100			07-MAR-2016 0 0	6000	6100
LIFE LIMIT									
+ 7120073	NO. 1 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS MOS HRS/MSC REF: AMM 71-20-00	MOS HRS/MSC AFL	6000	+100/-100			07-MAR-2016 0 0	6000	6100

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 7120073	NO. 1 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120073	NO. 1 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
+ 7120073	NO. 2 ENGINE AFT ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
+ 7120073	NO. 2 ENGINE FORWARD LOWER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120073	NO. 2 ENGINE FORWARD UPPER ISOLATOR - PERFORM INSPECTION OF ISOLATOR AND ASSOCIATED PARTS	MOS					07-MAR-2016		
	REF: AMM 71-20-00	HRS/MSC AFL	6000	+100/-100			0 0	6000	6100
7120074	* NO. 1 AFT ENGINE MOUNT BOLT - REPLACE	MOS					07-MAR-2016		
CMR*	REF: AMM 71-20-00	HRS/MSC AFL	E/C				0 0		
7120074	* NO. 2 AFT ENGINE MOUNT BOLT - REPLACE	MOS					07-MAR-2016		
CMR*	REF: AMM 71-20-00	HRS/MSC AFL	E/C				0 0		
712008	NO. 2 FORWARD UPPER ENGINE ISOLATOR	PN					07-MAR-2016		
	SN-UNKNOWN	MOS					0		
	REF: AMM 71-20-00	HRS/MSC AFL	O/C				0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712009	NO. 1 FORWARD LOWER ENGINE ISOLATOR PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
712010	NO. 2 FORWARD LOWER ENGINE ISOLATOR PN SN-UNKNOWN REF: AMM 71-20-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
716005	LH NACELLE INLET ASSY PN SN-UNKNOWN REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
716006	RH NACELLE INLET ASSY PN SN-UNKNOWN REF: AMM 71-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
71EN1 71.EN1	NO. 1 ENGINE 3062075-1 P-137284 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
71EN2 71.EN2	NO. 2 ENGINE 3062075-1 P-137283 REF: AMM 71-00-01	MOS HRS/MSC AFL	E/C						
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
710100	NO. 1 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY 3060757-3 15-150262-40305 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 710130 (s)	NO. 1 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
+ 710140 (s)	NO. 1 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B) PKG 0 REF: See Workcard	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
+ 714010 (s)	NO. 1 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
+ 715010 (s)	NO. 1 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
710100	NO. 2 ENGINE - MAIN ENGINE WIRING HARNESS ASSEMBLY 3060757-3 15-150262-40304 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		
+ 710130 (s)	NO. 2 ENGINE - INSPECT TAILPIPE/LPT3 ROTOR ASSEMBLY-VISUALLY INSPECT FOR FOREIGN OBJECT DAMAGE, THERMAL DISTRESS, AND LEAKS. PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
+ 710140 (s)	NO. 2 ENGINE - INSPECT INLET/FAN AREA - INSPECT FOR FOREIGN OBJECT DAMAGE AND LEAKAGE (REFER TO PARAGRAPH 4.B) PKG 0 REF: See Workcard	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 714010 (s)	NO. 2 ENGINE - CHECK ELECTRICAL WIRES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY AND DAMAGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		
+ 715010 (s)	NO. 2 ENGINE - CHECK PLUMBING LINES AND CONNECTIONS - VISUALLY INSPECT FOR SECURITY, LOOSE OR BROKEN CLAMPS OR BRACKETS, LEAKS, CRACKS, CUTS, OR RUBBING PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	850	-350			PKG 13-FEB-2020 746.3 493		

CHAPTER 72 ENGINE
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1

72-AS-720005	NO. 1 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			28-OCT-2015 0 0	(3000) 3000	3100
72-AS-720006 (s)	NO. 1 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			28-OCT-2015 0 0		
72-AS-720007	NO. 1 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS REF: LMM 72-00-00	MOS HRS/MSC ENC	6000	+200			28-OCT-2015 0 0	(6000) 6000	6200
72-AS-720008 (s)	NO. 1 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS REF: See Workcard	MOS HRS/MSC ENC	6000	+200/-200			28-OCT-2015 0 0		
72-AS-720010	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP) REF: LMM 72-00-00	MOS HRS/MSC ENC	A/R				20-APR-2016 16.8 11		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720011	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)	MOS						20-APR-2016	
	REF: LMM 73-21-02	HRS/MSC ENC	A/R					16.8 11	
720110	NO. 1 ENGINE - ACCESSORY GEARBOX	MOS		N:0				28-OCT-2015	
	3060827-4	HRS/MSC	O/C	N:0				0	
	S-4402	ENC		N:0				0	
	REF: LMM 72-60-02								
720244	NO. 1 ENGINE - NO. 6 CARBON SEAL ASSEMBLY	MOS		N:0				28-OCT-2015	
	3071383-2	HRS/MSC	O/C	N:0				0	
	15-150211-00297	ENC		N:0				0	
	REF: GENERIC NO REF								
720245	NO. 1 ENGINE - NO. 6 BEARING ASSEMBLY	MOS		N:0				28-OCT-2015	
	358750-2	HRS/MSC	O/C	N:0				0	
	15-162111-06632	ENC		N:0				0	
	REF: GENERIC NO REF								
722001	NO. 1 ENGINE - FAN INLET HOUSING ASSEMBLY	MOS		N:0				28-OCT-2015	
	PN	HRS/MSC	O/C	N:0				0	
	SN-UNKNOWN	ENC		N:0				0	
	REF: GENERIC NO REF								
723002	NO. 1 ENGINE - NO. 3 CARBON SEAL ASSEMBLY	MOS		N:0				28-OCT-2015	
	3060150-3	HRS/MSC	O/C	N:0				0	
	14-169020-01899	ENC		N:0				0	
	REF: LMM 72-30-01								
+ 723010 (s)	NO. 1 ENGINE - CHECK CARBON SEAL HEALTH	MOS					PKG	28-OCT-2015	
	PKG 0	HRS/MSC	1600	+50/-100				0	
	REF: LMM 72-00-00	ENC						0	
723011	NO. 1 ENGINE - NO. 4 CARBON SEAL RUNNER	MOS		N:0				28-OCT-2015	
	3075639-2	HRS/MSC	O/C	N:0				0	
	15-162397-09413	ENC		N:0				0	
	REF: GENERIC NO REF								

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723012	NO. 1 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
723013	NO. 1 ENGINE - NO. 5 CARBON SEAL RUNNER 3075633-2 15-162397-08111 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
723014	NO. 1 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
723081	NO. 1 ENGINE - ROTATING, AIR 2ND STAGE SEAL 3074108-2 14-169025-00021 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725007	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			28-OCT-2015 0 0		
725010	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 14-156103-00507 LIFE LIMIT	MOS HRS/MSC ENC		N:0 N:0 N:0			28-OCT-2015 0 0		(12000) 12000
725017	NO. 1 ENGINE - HPT SHROUD SLEEVE PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725020	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060611-1 14-156103-00339 LIFE LIMIT	MOS HRS/MSC ENC		N:0 N:0 N:0			28-OCT-2015 0 0		(12000) 12000

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725021	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER								
	PN	MOS		N:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725022	NO. 1 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD								
	PN	MOS		N:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725030	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC								
	3060671-2	MOS		N:0			28-OCT-2015		
	14-156103-00126	HRS/MSC		N:0			0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000)	12000
725031	NO. 1 ENGINE - 3RD-STAGE LTP BLADES								
	PN	MOS		N:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725040	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC								
	3060841-1	MOS		N:0			28-OCT-2015		
	15-162246-02668	HRS/MSC		N:0			0		
LIFE LIMIT	REF: LMM 72-50-07	ENC	10000	N:0			0	(10000)	10000
725045	NO. 1 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY								
	PN	MOS		N:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
REF:		ENC		N:0			0		
725050	NO. 1 ENGINE - FAN DISC								
	3060287-2	MOS		N:0			28-OCT-2015		
	1518244917018	HRS/MSC		N:0			0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	20000	N:0			0	(20000)	20000
725060	NO. 1 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC								
	3060372-1	MOS		N:0			28-OCT-2015		
	14-162045-01539	HRS/MSC		N:0			0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	10000	N:0			0	(10000)	10000

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725070	NO. 1 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075839-1 15-162045-00593	MOS HRS/MSC		N:0 N:0			28-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20000	
725071	NO. 1 ENGINE - COMBUSTION LINER 3060766-1 15-3300-02911	MOS HRS/MSC	O/C	N:0 N:0			28-OCT-2015 0		
	REF: LMM 72-40-03	ENC		N:0			0		
725080	NO. 1 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 14-162045-00550	MOS HRS/MSC		N:0 N:0			28-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20000	
725081	NO. 1 ENGINE - OUTER TRANSITION LINER 3060573-2 15-3300-02550	MOS HRS/MSC	O/C	N:0 N:0			28-OCT-2015 0		
	REF: LMM 72-40-03	ENC		N:0			0		
725090	NO. 1 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 14-162053-02148	MOS HRS/MSC		N:0 N:0			28-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-30-04	ENC	20000	N:0			0	(20000) 20000	
725110	NO. 1 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 15P79432	MOS HRS/MSC	O/C	N:0 N:0			28-OCT-2015 0		
	REF: See Workcard	ENC		N:0			0		
725120	NO. 1 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 1518244916039	MOS HRS/MSC		N:0 N:0			28-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-50-06	ENC	8000	N:0			0	(8000) 8000	
725130	NO. 1 ENGINE - FAN SPINNER 3060156-2 15-5060-00118	MOS HRS/MSC		N:0 N:0			28-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-70-01	ENC	20000	N:0			0	(20000) 20000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725140	NO. 1 ENGINE - FAN DRIVE SHAFT 3060180-2 1415611408777 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725141	NO. 1 ENGINE - FAN ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
CUSTOMER CODE									
725160	NO. 1 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 15-162246-01725 REF: LMM 72-70-03	MOS HRS/MSC ENC	7000	N:0 N:0 N:0			28-OCT-2015 0 0	(7000) 7000	
LIFE LIMIT									
725170	NO. 1 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 15P80849 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725180	NO. 1 ENGINE - COMBUSTION PLENUM CASE 3060534-4 15-3300-02057 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725210	NO. 1 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 14-182449-13528 REF: GENERIC NO REF	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			28-OCT-2015 0 0	(10000) 10000	
LIFE LIMIT									
725220	NO. 1 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-8 15-3300-02025 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725230	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 15-3300-02772 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725240	NO. 1 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-11 15-3300-02325 REF: LMM 72-50-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725250	NO. 1 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 15-1034-46753 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725260	NO. 1 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-3 15-1034-46935 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
725270	NO. 1 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 15-3300-02450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726005	NO. 1 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 15P81361 REF: LMM 72-60-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726010	NO. 1 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726011	NO. 1 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726012	NO. 1 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726013	NO. 1 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726014	NO. 1 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726015	NO. 1 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726016	NO. 1 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
726017	NO. 1 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727001	NO. 1 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727005	NO. 1 ENGINE - UPPER FAN DUCT ASSEMBLY 3061300-7 15-181898-01313 REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727006	NO. 1 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727010 (s)	NO. 1 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200			PKG 28-OCT-2015 0 0		
727101	NO. 1 ENGINE - NO. 1 CARBON SEAL ASSEMBLY 3060457-1 15-152826-14446 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727102	NO. 1 ENGINE - NO. 1 CARBON SEAL RUNNER 3075657-1 15-162397-04283 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727103	NO. 1 ENGINE - NO. 1 BEARING ASSEMBLY 3061510-1 15-162111-07431 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727105	NO. 1 ENGINE - RING GEAR 3060277-4 1415611408828 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727107	NO. 1 ENGINE - SUN GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727203	NO. 1 ENGINE - NO. 3 BALL BEARING 3060212-1 15-162255-19291 REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727210	NO. 1 ENGINE - PLANET HOUSING ASSEMBLY 3060121-8 1516224301338 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727210-1	NO. 1 ENGINE - NO. 1 PLANET GEAR ASSEMBLY 3060129-7 15P81362 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727210-2	NO. 1 ENGINE - NO. 2 PLANET GEAR ASSEMBLY 3060129-7 15P81363 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727210-3	NO. 1 ENGINE - NO. 3 PLANET GEAR ASSEMBLY 3060129-7 15P81364 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727210-4	NO. 1 ENGINE - NO. 4 PLANET GEAR ASSEMBLY 3060129-7 15P81365 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
727210-5	NO. 1 ENGINE - NO. 5 PLANET GEAR ASSEMBLY 3060129-7 15P81366 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
72-AS-720005	NO. 2 ENGINE - INSPECT MAJOR PERIODIC PER MANUFACTURERS INSTRUCTIONS 3060129-7 15P81366 REF: LMM 72-00-00	MOS HRS/MSC ENC	3000	+100			23-OCT-2015 0 0	(3000) 3000	3100
72-AS-720006 (s)	NO. 2 ENGINE - INSPECT COMB CHAMBER PLENUM CASE INSP PER MANUFACTURERS INSTRUCTIONS 3060129-7 15P81366 REF: GENERIC NO REF	MOS HRS/MSC ENC	3000	+100/-100			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-AS-720007	NO. 2 ENGINE - INSPECT COMPRESSOR ZONE PER MANUFACTURERS INSTRUCTIONS	MOS					23-OCT-2015		
	REF: LMM 72-00-00	HRS/MSC	6000	+200			0	(6000) 6000	6200
		ENC					0		
72-AS-720008 (s)	NO. 2 ENGINE - INSPECT AGB PER MANUFACTURERS INSTRUCTIONS	MOS					23-OCT-2015		
	REF: See Workcard	HRS/MSC	6000	+200/-200			0		
		ENC					0		
72-AS-720010	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (BASELINE/SPECIAL REQUIREMENT) (SOAP)	MOS					20-APR-2016		
	REF: LMM 72-00-00	HRS/MSC	A/R				16.8		
		ENC					11		
72-AS-720011	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT (25-HR INITIAL)	MOS					20-APR-2016		
	REF: LMM 73-21-02	HRS/MSC	A/R				16.8		
		ENC					11		
720110	NO. 2 ENGINE - ACCESSORY GEARBOX	MOS					23-OCT-2015		
	3060827-4	HRS/MSC	O/C	N:0			0		
	S-4396	ENC		N:0			0		
	REF: LMM 72-60-02			N:0			0		
720244	NO. 2 ENGINE - NO. 6 CARBON SEAL ASSEMBLY	MOS					23-OCT-2015		
	3071383-2	HRS/MSC	O/C	N:0			0		
	15-150211-00294	ENC		N:0			0		
	REF: GENERIC NO REF			N:0			0		
720245	NO. 2 ENGINE - NO. 6 BEARING ASSEMBLY	MOS					23-OCT-2015		
	358750-2	HRS/MSC	O/C	N:0			0		
	15-162111-06633	ENC		N:0			0		
	REF: GENERIC NO REF			N:0			0		
722001	NO. 2 ENGINE - FAN INLET HOUSING ASSEMBLY	MOS					23-OCT-2015		
	PN	HRS/MSC	O/C	N:0			0		
	SN-UNKNOWN	ENC		N:0			0		
	REF: GENERIC NO REF			N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723002	NO. 2 ENGINE - NO. 3 CARBON SEAL ASSEMBLY 3060150-3 14-169020-01873 REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
+ 723010 (s)	NO. 2 ENGINE - CHECK CARBON SEAL HEALTH PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1600	+50/-100			PKG 23-OCT-2015 0 0		
723011	NO. 2 ENGINE - NO. 4 CARBON SEAL RUNNER 3075639-2 15-162397-09416 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
723012	NO. 2 ENGINE - NO. 4 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
723013	NO. 2 ENGINE - NO. 5 CARBON SEAL RUNNER 3075633-2 15-162397-08109 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
723014	NO. 2 ENGINE - NO. 5 CARBON SEAL ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
723081	NO. 2 ENGINE - ROTATING, AIR 2ND STAGE SEAL 3074108-2 14-169025-00020 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725007	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) NOZZLE ASSEMBLY PN SN-UNKNOWN REF: LMM 72-50-07	MOS HRS/MSC ENC	A/R	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725010	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060625-1 14-156103-00539	MOS HRS/MSC		N:0 N:0			23-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000) 12000	
725017	NO. 2 ENGINE - HPT SHROUD SLEEVE PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
CUSTOMER CODE	REF: LMM 72-50-07	ENC		N:0			0		
725020	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060611-1 12-156103-00794	MOS HRS/MSC		N:0 N:0			23-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000) 12000	
725021	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE RETAINER PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725022	NO. 2 ENGINE - 2ND-STAGE LPT NOZZLE SHROUD PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725030	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE TURBINE (LPT) DISC 3060671-2 14-156103-00144	MOS HRS/MSC		N:0 N:0			23-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-50-04	ENC	12000	N:0			0	(12000) 12000	
725031	NO. 2 ENGINE - 3RD-STAGE LTP BLADES PN SN-UNKNOWN	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
CUSTOMER CODE	REF: LMM 72-50-04	ENC		N:0			0		
725040	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) DISC 3060555-5 15-162246-02669	MOS HRS/MSC		N:0 N:0			23-OCT-2015 0		
LIFE LIMIT	REF: LMM 72-50-07	ENC	10000	N:0			0	(10000) 10000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725045	NO. 2 ENGINE - HIGH PRESSURE TURBINE (HPT) ASSY PN SN-UNKNOWN REF:	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725050	NO. 2 ENGINE - FAN DISC 3060287-2 1518244917007 LIFE LIMIT REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			23-OCT-2015 0 0	(20000) 20000	
725060	NO. 2 ENGINE - 1ST-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060372-1 14-162045-01540 LIFE LIMIT REF: LMM 72-30-04	MOS HRS/MSC ENC	10000	N:0 N:0 N:0			23-OCT-2015 0 0	(10000) 10000	
725070	NO. 2 ENGINE - 2ND-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075839-1 15-162045-00405 LIFE LIMIT REF: LMM 72-30-04	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			23-OCT-2015 0 0	(20000) 20000	
725071	NO. 2 ENGINE - COMBUSTION LINER 3060766-1 15-3300-02959 REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725080	NO. 2 ENGINE - 3RD-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3060374-1 14-162045-00692 LIFE LIMIT REF: LMM 72-30-04	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			23-OCT-2015 0 0	(20000) 20000	
725081	NO. 2 ENGINE - OUTER TRANSITION LINER 3060573-2 15-3300-02468 REF: LMM 72-40-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725090	NO. 2 ENGINE - 4TH-STAGE LOW PRESSURE COMPRESSOR (LPC) DISC 3075326-5 14-162053-02144 LIFE LIMIT REF: LMM 72-30-04	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			23-OCT-2015 0 0	(20000) 20000	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725110	NO. 2 ENGINE - LOW PRESSURE COMPRESSOR TIE ROD 3074744-1 15P79431 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725120	NO. 2 ENGINE - HIGH PRESSURE COMPRESSOR ROTOR IMPELLER 3060371-1 1518244917037 REF: LMM 72-50-06	MOS HRS/MSC ENC	8000	N:0 N:0 N:0			23-OCT-2015 0 0	(8000) 8000	
725130	NO. 2 ENGINE - FAN SPINNER 3060156-2 15-5060-00134 REF: LMM 72-70-01	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			23-OCT-2015 0 0	(20000) 20000	
725140	NO. 2 ENGINE - FAN DRIVE SHAFT 3060180-2 1415611408769 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725141	NO. 2 ENGINE - FAN ROLLER BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725160	NO. 2 ENGINE - FORWARD ROTOR HIGH PRESSURE SEAL 3060698-1 15-162246-01735 REF: LMM 72-70-03	MOS HRS/MSC ENC	7000	N:0 N:0 N:0			23-OCT-2015 0 0	(7000) 7000	
725170	NO. 2 ENGINE - HIGH PRESSURE SHOULDERED SHAFT 3060366-3 15P80850 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
725180	NO. 2 ENGINE - COMBUSTION PLENUM CASE 3060534-4 15-3300-02133 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210	NO. 2 ENGINE - HIGH PRESSURE TURBINE FORWARD SEAL PLATE 3060514-1 15-182449-15286	MOS HRS/MSC		N:0 N:0			23-OCT-2015 0		
LIFE LIMIT	REF: GENERIC NO REF	ENC	10000	N:0			0	(10000) 10000	
725220	NO. 2 ENGINE - TURBINE INTERSTAGE TRANSITION DUCT 3060694-8 15-3300-02015	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: GENERIC NO REF	ENC		N:0			0		
725230	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE SEAL SUPPORT 3060693-1 15-3300-02776	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: LMM 72-50-04	ENC		N:0			0		
725240	NO. 2 ENGINE - LOW PRESSURE TURBINE (LPT) 1 NOZZLE ASSEMBLY 3060666-11 15-3300-01930	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: LMM 72-50-04	ENC		N:0			0		
725250	NO. 2 ENGINE - FORWARD SHAFT HIGH PRESSURE TURBINE (HPT) COUPLING 3060502-2 15-1034-47278	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: GENERIC NO REF	ENC		N:0			0		
725260	NO. 2 ENGINE - AFT HIGH PRESSURE TURBINE (HPT) SHAFT COUPLING 3060599-3 15-1034-47311	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: GENERIC NO REF	ENC		N:0			0		
725270	NO. 2 ENGINE - NOZZLE LOW PRESSURE TURBINE (LPT) (A5) SEAL 3073765-12 15-3300-02932	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: GENERIC NO REF	ENC		N:0			0		
726005	NO. 2 ENGINE - TRANSFER GEARBOX ASSEMBLY 3070093-16 15P81360	MOS HRS/MSC	O/C	N:0 N:0			23-OCT-2015 0		
	REF: LMM 72-60-03	ENC		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726010	NO. 2 ENGINE - FORWARD OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726011	NO. 2 ENGINE - AFT OIL PUMP SPUR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726012	NO. 2 ENGINE - FORWARD ALTERNATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726013	NO. 2 ENGINE - AFT ALTERNATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726014	NO. 2 ENGINE - FORWARD AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726015	NO. 2 ENGINE - AFT AIR-OIL SEPARATOR ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726016	NO. 2 ENGINE - FORWARD STARTER/GENERATOR SPU ANNULAR BALL BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
726017	NO. 2 ENGINE - AFT STARTER/GENERATOR SPU ANNULAR BEARING PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727001	NO. 2 ENGINE - BYPASS FAN STATOR PN SN-UNKNOWN REF: LMM 72-70-04	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727005	NO. 2 ENGINE - UPPER FAN DUCT ASSEMBLY 3061300-7 15-181898-01309 REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727006	NO. 2 ENGINE - LOWER FAN DUCT ASSEMBLY PN SN-UNKNOWN REF: LMM 72-70-05	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727010 (s)	NO. 2 ENGINE - INSPECT BYPASS STATOR VANE ASSEMBLY. PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1200	+100/-200				PKG 23-OCT-2015 0 0	
727101	NO. 2 ENGINE - NO. 1 CARBON SEAL ASSEMBLY 3060457-1 15-152826-12534 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727102	NO. 2 ENGINE - NO. 1 CARBON SEAL RUNNER 3075657-1 15-162397-04302 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727103	NO. 2 ENGINE - NO. 1 BEARING ASSEMBLY 3061510-1 15-162111-07427 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727105	NO. 2 ENGINE - RING GEAR 3060277-4 1415611408831 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
727107	NO. 2 ENGINE - SUN GEAR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727203	NO. 2 ENGINE - NO. 3 BALL BEARING 3060212-1 15-162255-15916 REF: LMM 72-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210	NO. 2 ENGINE - PLANET HOUSING ASSEMBLY 3060121-8 15162243569 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210-1	NO. 2 ENGINE - NO. 1 PLANET GEAR ASSEMBLY 3060129-7 15P81229 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210-2	NO. 2 ENGINE - NO. 2 PLANET GEAR ASSEMBLY 3060129-7 15P81231 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210-3	NO. 2 ENGINE - NO. 3 PLANET GEAR ASSEMBLY 3060129-7 15P812355 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210-4	NO. 2 ENGINE - NO. 4 PLANET GEAR ASSEMBLY 3060129-7 15P81356 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
727210-5	NO. 2 ENGINE - NO. 5 PLANET GEAR ASSEMBLY 3060129-7 15P81359 REF: LMM 72-72-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CHAPTER 73	ENGINE FUEL AND CONTROL								
733013	FUEL FLOW, DUAL CONVERTER								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 73-31-02	AFL		N:0			0		
733031	ELECTRICAL RESISTANCE (FUEL - LH) TEMPERATURE BULB								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 73-31-03	AFL		N:0			0		
733032	ELECTRICAL RESISTANCE (FUEL - RH) TEMPERATURE BULB								
	PN	MOS		N:0			07-MAR-2016		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: AMM 73-31-03	AFL		N:0			0		
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
730110	NO. 1 ENGINE - FUEL CONTROL UNIT								
	3070800-47	MOS		N:0			28-OCT-2015		
	20569	HRS/MSC	O/C	N:0			0		
	REF: LMM 73-20-01	ENC		N:0			0		
730120 (s)	NO. 1 ENGINE - REPLACE FUEL FILTER ELEMENT						PKG		
	PKG 0	MOS					17-NOV-2018		
		HRS/MSC	600	+50/-100			532.7		
	REF: See Workcard	ENC							
730130	NO. 1 ENGINE - ENGINE FUEL PUMP ASSEMBLY								
	3060760-4	MOS		N:0			28-OCT-2015		
	3707	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		
731001	NO. 1 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY								
	PN	MOS		N:0			28-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: LMM 73-21-02	ENC		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-1	NO. 1 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00434 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-10	NO. 1 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00435 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-11	NO. 1 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00436 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-12	NO. 1 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00437 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-2	NO. 1 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00444 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-3	NO. 1 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00445 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-4	NO. 1 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00448 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-5	NO. 1 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00450 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-6	NO. 1 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00451 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-7	NO. 1 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00456 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-8	NO. 1 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00460 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731005-9	NO. 1 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00467 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731015	NO. 1 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731110	NO. 1 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 19087 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
731120	NO. 1 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 3893 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
732102	NO. 1 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732120 (s)	NO. 1 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			PKG 17-NOV-2018 532.7		
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
730110	NO. 2 ENGINE - FUEL CONTROL UNIT 3070800-47 20573 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		
730120 (s)	NO. 2 ENGINE - REPLACE FUEL FILTER ELEMENT PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			PKG 17-NOV-2018 532.7		
730130	NO. 2 ENGINE - ENGINE FUEL PUMP ASSEMBLY 3060760-4 3709 REF: See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		
731001	NO. 2 ENGINE - MOTIVE FLOW FUEL PUMP ASSEMBLY PN SN-UNKNOWN REF: LMM 73-21-02	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		
731005-1	NO. 2 ENGINE - NO. 1 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00447 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		
731005-10	NO. 2 ENGINE - NO. 10 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00449 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-11	NO. 2 ENGINE - NO. 11 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00659 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-12	NO. 2 ENGINE - NO. 12 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00661 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-2	NO. 2 ENGINE - NO. 2 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00662 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-3	NO. 2 ENGINE - NO. 3 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00666 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-4	NO. 2 ENGINE - NO. 4 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00669 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-5	NO. 2 ENGINE - NO. 5 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00670 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-6	NO. 2 ENGINE - NO. 6 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00671 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-7	NO. 2 ENGINE - NO. 7 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00677 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731005-8	NO. 2 ENGINE - NO. 8 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00679 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731005-9	NO. 2 ENGINE - NO. 9 FUEL MANIFOLD NOZZLE ASSEMBLY 3060540-2 15-163498-00691 REF: LMM 73-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731015	NO. 2 ENGINE - FUEL PUMP PRESSURE DIFFERENTIAL INDICATOR PN SN-UNKNOWN REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731110	NO. 2 ENGINE - PRESSURE LIMITER (PCD) VALVE 3070685-11 19086 REF: LMM 73-20-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
731120	NO. 2 ENGINE - FUEL FLOW DIVIDER/DRAIN VALVE 394476-2 3892 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
732102	NO. 2 ENGINE - RELIEF VALVE PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
732120 (s)	NO. 2 ENGINE - INSPECT MOTIVE FLOW FUEL PUMP DRIVE SPLINE PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			PKG 17-NOV-2018 532.7		

CHAPTER 74 IGNITION

ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
740110	NO. 1 ENGINE - IGNITION UNIT 3061186-1 J15360004 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
740130	NO. 1 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG 3060722-12 S15250003 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
+ 740140 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: See Workcard	MOS HRS/MSC ENC	1600	+50/-100			28-OCT-2015 0 0	PKG	
740150	NO. 1 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG 3060722-12 S15250003 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
+ 740160 (s)	NO. 1 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD PKG 0 REF: LMM 74-00-01	MOS HRS/MSC ENC	1600	+50/-100			28-OCT-2015 0 0	PKG	
742011	NO. 1 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD 3060722-11 S15200002 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
742012	NO. 1 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD 3060722-12 S15250003 REF: LMM 74-00-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
742020	NO. 1 ENGINE - IGNITION EXCITER PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
740110	NO. 2 ENGINE - IGNITION UNIT								
	3061186-1	MOS		N:0			23-OCT-2015		
	J15360002	HRS/MSC	O/C	N:0			0		
	REF: LMM 74-00-01	ENC		N:0			0		
740130	NO. 2 ENGINE - 5 O'CLOCK IGNITER (#1 POSITION) PLUG								
	3060722-12	MOS		N:0			23-OCT-2015		
	S15320001	HRS/MSC	O/C	N:0			0		
	REF: LMM 74-00-01	ENC		N:0			0		
+ 740140 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 5 O'CLOCK IGNITER PLUG AND LEAD						PKG		
	PKG 0	MOS					23-OCT-2015		
		HRS/MSC	1600	+50/-100			0		
	REF: See Workcard	ENC					0		
740150	NO. 2 ENGINE - 7 O'CLOCK IGNITER (#2 POSITION) PLUG								
	3060722-12	MOS		N:0			23-OCT-2015		
	S15320001	HRS/MSC	O/C	N:0			0		
	REF: LMM 74-00-01	ENC		N:0			0		
+ 740160 (s)	NO. 2 ENGINE - REMOVE AND INSPECT 7 O'CLOCK IGNITER PLUG AND LEAD						PKG		
	PKG 0	MOS					23-OCT-2015		
		HRS/MSC	1600	+50/-100			0		
	REF: LMM 74-00-01	ENC					0		
742011	NO. 2 ENGINE - NO. 1 IGNITION (IPC 20 REFERENCE) LEAD								
	3060722-11	MOS		N:0			23-OCT-2015		
	S15220002	HRS/MSC	O/C	N:0			0		
	REF: LMM 74-00-01	ENC		N:0			0		
742012	NO. 2 ENGINE - NO. 2 IGNITION (IPC 25 REFERENCE) LEAD								
	3060722-12	MOS		N:0			23-OCT-2015		
	S15320001	HRS/MSC	O/C	N:0			0		
	REF: LMM 74-00-01	ENC		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
742020	NO. 2 ENGINE - IGNITION EXCITER								
	PN	MOS		N:0			23-OCT-2015		
	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		

CHAPTER 75 AIR

ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1

754210	NO. 1 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								
	3070816-14	MOS		N:0			28-OCT-2015		
	1516901724722	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

761310	NO. 1 ENGINE - SURGE BLEED VALVE								
	978812-7-1	MOS		N:0			28-OCT-2015		
	15032	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1

754210	NO. 2 ENGINE - INLET PRESSURE AND TEMPERATURE SENSOR								
	3070816-14	MOS		N:0			23-OCT-2015		
	1516901724721	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

761310	NO. 2 ENGINE - SURGE BLEED VALVE								
	978812-7-1	MOS		N:0			23-OCT-2015		
	15039	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	ENC		N:0			0		

CHAPTER 76 ENGINE CONTROLS

7600001 (s)	FUNCTIONAL TEST THRUST LEVER CONTROL MODULE						PKG		
	PKG 7	MOS	108	+14d/-14d			07-MAR-2016		
		HRS/MSC	2400	+25/-25			0		
	REF: AMM 76-10-02	AFL					0		

761001	RH DIGITAL ENGINE ELECTRONIC CONTROL								
	2118882-1008	MOS		N:0			07-MAR-2016		
	85-BP0166	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761002	LH DIGITAL ENGINE ELECTRONIC CONTROL 2118882-1008 95-BP0171 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
761003	L/H THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
761004	R/H THROTTLE CABLE PN SN-UNKNOWN REF: AMM 76-10-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
761005	THRUST LEVER CONTROL MODULE PN SN-UNKNOWN REF: AMM 76-10-02	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
761320	NO. 1 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 14358 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
761330	NO. 1 ENGINE - ENGINE (DEEC) COMPUTER 2118882-8001 95-BP0171 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
761330A	NO. 1 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-8001 95-BP0171 REF: See Workcard	MOS HRS/MSC ENC					21-FEB-2020 764.6 504	(544) 544	554
CUSTOMER CODE			40	+10					
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761320	NO. 2 ENGINE - SOLENOID CONTROLLER VALVE 109696-6-1 14356 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
761330	NO. 2 ENGINE - ENGINE (DEEC) COMPUTER 2118882-8001 85-BP0166 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
761330A	NO. 2 ENGINE - DOWNLOAD ENGINE (DEEC) COMPUTER ECTM 2118882-8001 85-BP0166 REF: See Workcard	MOS HRS/MSC ENC	40	+10			21-FEB-2020 764.6 504	(544) 544	554

CHAPTER 77 ENGINE INDICATING

774001	ENGINE VIBRATION SIGNAL CONDITIONER BOX PN SN-UNKNOWN REF: AMM 77-41-01	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
774010	TAILCONE/VERT STAB ASSY RELAY BOX PN SN-UNKNOWN REF: AMM 77-41-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
7741000 (s)	FUNCTIONAL TEST ENGINE VIBRATION MONITORING SYSTEM PKG 7 REF: AMM 77-41-00	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
774103	GSC46 (PRIMARY) SIGNAL CONDITIONER 013-00337-10 471 REF: AMM 77-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
774104	GSC46 (SECONDARY) SIGNAL CONDITIONER 013-00337-10 476 REF: AMM 77-41-04	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
770101	NO. 1 ENGINE - N1 MONOPOLE 3060714-5 15910300145 REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
770110	NO. 1 ENGINE - N1 LEAD MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
771210	NO. 1 ENGINE - N1 COMPENSATOR 3060735-3 1416909401104 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
771220	NO. 1 ENGINE - N2 MONOPOLE 3070722-8 15910300566 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
772210	NO. 1 ENGINE - ITT HARNESS ASSEMBLY 3060763-3 1416901740813 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
770101	NO. 2 ENGINE - N1 MONOPOLE 3060714-5 15910300142 REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
770110	NO. 2 ENGINE - N1 LEAD MONOPOLE PN SN-UNKNOWN REF: LMM 77-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
771210	NO. 2 ENGINE - N1 COMPENSATOR 3060735-2 1216909400189 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
771220	NO. 2 ENGINE - N2 MONOPOLE 3070722-8 15910300565 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
772210	NO. 2 ENGINE - ITT HARNESS ASSEMBLY 3060763-3 1516901740896 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
CHAPTER 78	EXHAUST								
7830007	CHECK THRUST REVERSER - PERFORM CONDUCTIVITY CHECK OF RH THRUST REVERSER DOOR SKIN AND COWL ADJACENT TO APU EXHAUST. REF: NDT PART 6 / 78-30-01	MOS HRS/MSC AFL APH	1200	+25/-25			07-MAR-2016 0 0 0	1200	1225
783001	LEFT THRUST REVERSER ASSY PN SN-UNKNOWN REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
783001A	LEFT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783002	RIGHT THRUST REVERSER ASSY PN SN-UNKNOWN REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
783002A	RIGHT INBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
783003A	LEFT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: AMM 78-31-00	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
783004A	RIGHT OUTBOARD THRUST REVERSER ACTUATOR PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2016 0 0		
7830078 (s)	** THRUST REVERSER SYSTEM THROTTLE RETARD ACTUATOR - PERFORM OPERATIONAL CHECK PKG 7 REF: AMM 78-32-40	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
7830081 (s)	NDT INSPECT LEFT ENGINE THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 7 REF: NDT PART 7 / 78-30-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		
7830081 (s)	NDT INSPECT RIGHT ENGINE THRUST REVERSERS - REMOVE LINK ROD ASSEMBLIES AND PERFORM MAGNETIC PARTICLE INSPECTION. PKG 7 REF: NDT PART 7 / 78-30-01	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 07-MAR-2016 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
7830082 (s)	NDT INSPECT LEFT ENGINE THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES. PKG 7 REF: See Workcard	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 0 0	07-MAR-2016 0 0	
7830082 (s)	NDT INSPECT RIGHT ENGINE THRUST REVERSERS - REMOVE THRUST REVERSER DOOR ASSEMBLIES AND PERFORM EDDY CURRENT INSPECTION OF PIVOT FITTING AND DOOR HINGES. PKG 7 REF: See Workcard	MOS HRS/MSC AFL	108 2400	+14d/-14d +25/-25			PKG 0 0	07-MAR-2016 0 0	
783101	LEFT THRUST REVERSER ISOLATION VALVE PN SN-UNKNOWN REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0	07-MAR-2016 0 0	
783102	RIGHT THRUST REVERSER ISOLATION VALVE PN SN-UNKNOWN REF: AMM 78-30-02	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0	07-MAR-2016 0 0	
783301	LEFT THRUST REVERSER CONTROL UNIT LJ7836706-3 942 REF: AMM 78-33-10	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0	07-MAR-2016 0 0	
783302	RIGHT THRUST REVERSER CONTROL UNIT LJ7836706-3 940 REF: AMM 78-33-10	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		0 0 0	07-MAR-2016 0 0	
CHAPTER 79 OIL									
793011	ELECTRICAL RESISTANCE (OIL - LH) TEMPERATURE BULB MS28034-3 252451 REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		13-FEB-2020 746.3 493		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
793012	ELECTRICAL RESISTANCE (OIL - RH) TEMPERATURE BULB PN SN-UNKNOWN REF: AMM 79-30-03	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2016 0 0	
ENGINE NO. 1 Model : TFE731-40BR-1B Serial # P-137284 Part # 3062075-1									
790110	NO. 1 ENGINE - OIL PUMP 3060785-3 1516225400196 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				28-OCT-2015 0 0	
790130 (s)	NO. 1 ENGINE - ANALYSIS OIL AND FILTER (SOAP) PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100				PKG 13-FEB-2020 746.3 493	
790140 (s)	NO. 1 ENGINE - PERFORM OIL CHANGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200				PKG 28-OCT-2015 0 0	
790150 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100				PKG 17-NOV-2018 532.7	
790160 (s)	NO. 1 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 0 REF: See Workcard	MOS HRS/MSC ENC	150	+100				PKG 13-FEB-2020 746.3 493	
791001	NO. 1 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				28-OCT-2015 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792002	NO. 1 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792005	NO. 1 ENGINE - OIL TANK ASSEMBLY PN SN-UNKNOWN REF: LMM 79-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792008	NO. 1 ENGINE - OIL FLOW REDUCTION VALVE 3060769-1 15-182215-12703 REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792011	NO. 1 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792012	NO. 1 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792020	NO. 1 ENGINE - OIL CHECK VALVE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792220	NO. 1 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-4 2418 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792230	NO. 1 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 3848 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792240	NO. 1 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 3946 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792250	NO. 1 ENGINE - PRESSURE BREATHER VALVE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
792260	NO. 1 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 14218 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
793064	NO. 1 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
793310	NO. 1 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
+ 793315 (s)	NO. 1 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH PKG 0 REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100/-200			28-OCT-2015 0 0		
793316	NO. 1 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		
793320	NO. 1 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY 3060709-4 3899 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			28-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
ENGINE NO. 2 Model : TFE731-40BR-1B Serial # P-137283 Part # 3062075-1									
790110	NO. 2 ENGINE - OIL PUMP 3060785-3 1516225400195 REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
790130 (s)	NO. 2 ENGINE - ANALYSIS OIL AND FILTER (SOAP) PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	150	+100			PKG 13-FEB-2020 746.3 493		
790140 (s)	NO. 2 ENGINE - PERFORM OIL CHANGE PKG 0 REF: LMM 72-00-00	MOS HRS/MSC ENC	1200	+100/-200			PKG 23-OCT-2015 0 0		
790150 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION AND PERFORM RESISTANCE CHECK PKG 0 REF: See Workcard	MOS HRS/MSC ENC	600	+50/-100			PKG 17-NOV-2018 532.7		
790160 (s)	NO. 2 ENGINE - INSPECT CHIP DETECTOR FOR CONTAMINATION PKG 0 REF: See Workcard	MOS HRS/MSC ENC	150	+100			PKG 13-FEB-2020 746.3 493		
791001	NO. 2 ENGINE - ENGINE OIL CHIP DETECTOR PN SN-UNKNOWN REF: LMM 79-10-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		
792002	NO. 2 ENGINE - AIR BREATHER VALVE ASSEMBLY CHANGE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			23-OCT-2015 0 0		

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792005	NO. 2 ENGINE - OIL TANK ASSEMBLY PN SN-UNKNOWN REF: LMM 79-10-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792008	NO. 2 ENGINE - OIL FLOW REDUCTION VALVE 3060769-1 15-182215-12733 REF: LMM 79-20-08	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792011	NO. 2 ENGINE - FUEL/OIL VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792012	NO. 2 ENGINE - OIL TEMPERATURE REGULATOR PN SN-UNKNOWN REF: LMM 79-20-03	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792020	NO. 2 ENGINE - OIL CHECK VALVE ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792220	NO. 2 ENGINE - UPPER OIL COOLER ASSEMBLY 160552-4 2408 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792230	NO. 2 ENGINE - LOWER LEFT OIL COOLER ASSEMBLY 160554-5 3821 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792240	NO. 2 ENGINE - LOWER RIGHT OIL COOLER ASSEMBLY 160554-6 3912 REF: LMM 79-20-10	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792250	NO. 2 ENGINE - PRESSURE BREATHER VALVE PN SN-UNKNOWN REF: LMM 79-20-02	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
792260	NO. 2 ENGINE - OIL TEMPERATURE CONTROL VALVE 158465-6 14234 REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
793064	NO. 2 ENGINE - TEMP BULB PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
793310	NO. 2 ENGINE - OIL FILTER BYPASS VALVE PN SN-UNKNOWN REF: LMM 79-30-01	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
+ 793315 (s)	NO. 2 ENGINE - CHECK OIL FILTER BYPASS VALVE CIRCUIT/THERMAL LOCKOUT SWITCH PKG 0 REF: LMM 79-30-01	MOS HRS/MSC ENC	1200	+100/-200				PKG 23-OCT-2015 0 0	
793316	NO. 2 ENGINE - THERMO LOCKOUT VALVE SWITCH ASSEMBLY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	
793320	NO. 2 ENGINE - FUEL HEATER / OIL COOLER ASSEMBLY 3060709-4 3926 REF: LMM 79-20-07	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0				23-OCT-2015 0 0	

CHAPTER 99 OPTIONAL KITS

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9900023	GVI OVERWEIGHT LANDING (WEIGHT IN EXCESS OF MAXIMUM LANDING WEIGHT) INSPECTION. REF: EMP 9900023	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900024	GVI HARD LANDING INSPECTION. REF: EMP 9900024	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900025	GVI SEVERE TURBULENCE AND/OR MANEUVERS INSPECTION. REF: EMP 9900025	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900026	UNSCHEDULED ENGINE CHANGE INSPECTION REF: EMP 9900026	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900027	DVI HIGH ENERGY STOP (LANDING AND REJECTED TAKEOFF). REF: EMP 9900027	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900028	OP/CK THRUSTS REVERSER INSPECTION. REF: See Workcard	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900029	GVI OVERSPEED RECOVERY LANDING GEAR INSPECTION (LANDING GEAR EXTENSION AT HIGH SPEED). REF: EMP 9900029	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900030	GVI LIGHTNING STRIKE INSPECTION. REF: EMP 9900030	MOS HRS/MSC - AFL						07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9900031	GVI HIGH GROUND WIND GUST INSPECTION. REF: EMP 9900031	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900032	GVI HEAT DAMAGE INSPECTION. REF: EMP 9900032	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900033	F/C NACELLE HEAT FAIL MESSAGE INSPECTION. REF: EMP 9900033	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900034	DVI ELEVATOR DISCONNECT INSPECTION. REF: See Workcard	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900035	GVI WING FLAP SYSTEM OVERSPEED CHECK. REF: See Workcard	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900036	NDT INSPECT PRESSURE CABIN SKIN THICKNESS MEASUREMENTS. REF: See Workcard	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900037	GVI VOLCANIC ASH INSPECTION AND MAINTENANCE PROCEDURES REF: EMP 9900037	MOS HRS/MSC - AFL						07-MAR-2016 0 0	
9900038	GVI INSPECTION OF AIRCRAFT OPERATIONS IN SALT INFLUENCED ENVIRONMENTS. REF: See Workcard	MOS HRS/MSC - AFL						07-MAR-2016 0 0	

Status Report

LEARJET 75 S/N 45-533 (N173DS): 794.3 HRS, 521 AFL as of 05-Jun-2020

Owner: FIRST SOUTHEAST AVIATION Operator: ELITE AIR, INC.

Report Date: 05-JUN-2020

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
9910000 (s)	GVI ENGINE ZONAL INSPECTION PKG 2 REF: EMP 9910000	MOS HRS/MSC AFL	36	+14d/-14d			PKG 27-MAR-2019 588.8 384		
9910001 (s)	GVI EXTERIOR AIRCRAFT ZONAL INSPECTION. PKG 2 REF: EMP 9910001	MOS HRS/MSC AFL	36	+14d/-14d			PKG 27-MAR-2019 588.8 384		
9910002 (s)	GVI LANDING GEAR ZONAL INSPECTION. PKG 2 REF: EMP 9910002	MOS HRS/MSC AFL	36	+14d/-14d			PKG 27-MAR-2019 588.8 384		
9910003 (s)	GVI AFT FUSELAGE ZONAL INSPECTION. PKG 3 REF: EMP 9910003	MOS HRS/MSC AFL	72	+14d/-14d			PKG 07-MAR-2016 0 0		
9910004 (s)	GVI NOSE ZONAL INSPECTION. PKG 3 REF: EMP 9910004	MOS HRS/MSC AFL	72	+14d/-14d			PKG 07-MAR-2016 0 0		
9910005 (s)	GVI WING ZONAL INSPECTION. PKG 3 REF: EMP 9910005	MOS HRS/MSC AFL	72	+14d/-14d			PKG 07-MAR-2016 0 0		
9910006 (s)	GVI COCKPIT ZONAL INSPECTION. PKG 4 REF: EMP 9910006	MOS HRS/MSC AFL	108	+14d/-14d			PKG 07-MAR-2016 0 0		
9910007 (s)	GVI FUSELAGE ZONAL INSPECTION. PKG 4 REF: EMP 9910007	MOS HRS/MSC AFL	108	+14d/-14d			PKG 07-MAR-2016 0 0		