



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
051233N	INSPECT CONCORDE BATTERY INSPECTION	KCRQ	MTH	29-May-2018		12		31-May-2019	-3 m 5 d
			HRS	8334.1		600		8934.1	541.63
			LDG	5614					Over Due
052513	INSPECT GALY/VANTY 300 HRS	CRQ	MTH	16-Aug-2018					
			HRS	8346.4		300		8646.4	253.93
			LDG	5621					
053424A	INSPECT EGPWS 12 MO		MTH	15-Feb-2017		36		29-Feb-2020	5 m 24 d
			HRS	8195.5		1200		9395.5	1003.03
			LDG	5532					
053460	INSPECT BFG ADI-330	CRQ	MTH	07-Jul-2016		36		31-Jul-2019	-1 m 5 d
			HRS	8069.5		1200		9269.5	877.03
			LDG	5456					
			ACH	4258.7					Over Due
053462	INSPECT GPS NAV		MTH	15-Feb-2017		36		29-Feb-2020	5 m 24 d
			HRS	8195.5		1200		9395.5	1003.03
			LDG	5532					
053463	INSPECT RDR-2100		MTH	15-Feb-2017		36		29-Feb-2020	5 m 24 d
			HRS	8195.5		1200		9395.5	1003.03
			LDG	5532					
053464	INSPECT NAV DATA UPDATE	KCRQ	DAYS	23-May-2019		DUE		20-Jun-2019	-2 m 16 d
			HRS	8392.9		DUE			
			LDG	5654		DUE			
						DUE			Over Due
059983G	INSPECT CVR 9000 HRS		MTH	04-Dec-2008					
			HRS	6645		9000		15645	7252.53
059983I	INSPECT IHAS 1200H/36M		MTH	15-Feb-2017		36		29-Feb-2020	5 m 24 d
			HRS	8195.5		1200		9395.5	1003.03
			LDG	5532					
5-12-01 051201	PHASE 1	KCRQ	MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
			HRS	8346.4		300		8646.4	253.93
			LDG	5621					
5-12-02 051202	PHASE 2	KCRQ	MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
			HRS	8346.4		300		8646.4	253.93
			LDG	5621					
5-12-03 051203	PHASE 3	KCRQ	MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
			HRS	8346.4		300		8646.4	253.93
			LDG	5621					
5-12-04 051204	PHASE 4	KCRQ	MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
			HRS	8346.4		300		8646.4	253.93
			LDG	5621					
5-12-05 051205	PHASE 5	KGJT	MTH	08-Jun-2017		36		30-Jun-2020	9 m 25 d
			HRS	8250.1		1200		9450.1	1057.63
			LDG	5563					
			ACH	4320.4					
5-12-08	PHASE 8 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KCRQ	MTH	07-Mar-2019		6			
			HRS	8387.9					
			LDG	5647					
A262003 AFT 051208 : A	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ	MTH	07-Mar-2019		6		30-Sep-2019	25 d
			A352TS						
			X561984						
A262003 FORWARD 051208 : F	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ	MTH	07-Mar-2019		6		30-Sep-2019	25 d
			A352TS						
			X571070						



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-0B 051200B	PHASE B	KGJT		MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		150		8400.1	7.63
5-12-11	PHASE 11 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	CRQ		MTH 14-May-2019 HRS LDG		6			
B342004 051211	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY	KCRQ	501-1228-04 12500	LEAD ACID PS835 BATTERY PACK: PHASE 11 MTH 14-May-2019 HRS 8392 LDG 5651		6		30-Nov-2019	2 m 25 d
5-12-12	PHASE 12			MTH HRS		3600		10887.13	2494.67
5-12-13 051213	PHASE 13	MCO		MTH 02-Nov-2003 HRS 5039		5000		10039	1646.53
5-12-14 051214	PHASE 14	*CF		MTH 22-Nov-1986 HRS 0		10000		10000	1607.53
5-12-15 051215	PHASE 15	*CF		MTH 22-Nov-1986 HRS 0		10000		10000	1607.53
5-12-16 051216	PHASE 16	*CF		MTH 22-Nov-1986 HRS 0		10000		10000	1607.53
5-12-17 051217	PHASE 17	*CF		MTH 22-Nov-1986 HRS 0		10000		10000	1607.53
5-12-18 051218	PHASE 18	KCRQ		MTH 16-Aug-2018 HRS 8346.4 LDG 5621		12		31-Aug-2019	-5 d
									Over Due
5-12-20	PHASE 20 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KGJT		MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH		24			
A341006 051220	CHECK STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	KGJT		MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
									Over Due
B341003 LEFT 051220 : L-ALT	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	4016341-905 6110287	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
									Over Due
B341003 NO. 1 051220 : ADC	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	7024900-30302 05011012	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
									Over Due
B341003 STANDBY 051220 : STDBY	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	570-24929-013 2288	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
									Over Due



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B341003 STANDBY <i>051220 : ADC#2</i>	CALIBRATION TEST ADC/ALTIMETER -- : PHASE 20	KGJT	70251N02D04 040413500	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341004 LEFT <i>051220 : L-ALT</i>	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	4016341-905 6110287	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341004 STANDBY <i>051220 : STDBY</i>	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	570-24929-013 2288	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341005 LEFT <i>051220 : L</i>	LEAK TEST STATIC SYSTEM: PHASE 20	KGJT		MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341005 RIGHT <i>051220 : R</i>	LEAK TEST STATIC SYSTEM: PHASE 20	KGJT		MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341107 LEFT <i>051220 : L-ALT</i>	CHECK ALTIMETER (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	KGJT	4016341-905 6110287	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341107 NO. 1 <i>051220 : ADC</i>	CHECK AIR DATA COMPUTER (AIRPLANES CERTIFIED FOR RVSM) : PHASE 20	KGJT	7024900-30302 05011012	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341107 STANDBY <i>051220 : STDBY</i>	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT	570-24929-013 2288	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B341107 STANDBY <i>051220 : ADC#2</i>	CHECK ADC/ALTIMETER -- (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	KGJT	70251N02D04 040413500	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
5-12-21	PHASE 21 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	KGJT		MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
A237003 051221 : CVR	INSPECT COCKPIT VOICE RECORDER	KGJT	UNDERWATER LOCATOR BEACON : PHASE 21 DK100 DV15665	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B237004 051221 : CVR	OPERATIONAL TEST COCKPIT VOICE RECORDER	KGJT	UNDERWATER LOCATOR BEACON : PHASE 21 DK100 DV15665	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B345001 LEFT 051221	CALIBRATION TEST TRANSPONDER	KGJT	TRANSPONDER SYSTEM: PHASE 21 622-1270-001 28045	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B345001 RIGHT 051221 : R	CALIBRATION TEST TRANSPONDER	KGJT	TRANSPONDER SYSTEM: PHASE 21 622-1270-001 28174	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
5-12-22	PHASE 22 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 28-Feb-2018		36			
B326003 051222 : GEAR	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22	CRQ	212940-2 2262	MTH 28-Feb-2018		36		28-Feb-2021	17 m 23 d
5-12-23	PHASE 23 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			KGJT MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		60			
B262002 AFT 051223 : ATR	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	KGJT	C352TS A-40842642	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		60		30-Jun-2022	33 m 25 d
B262002 FORWARD 051223 : FTR	HYDROSTATIC TEST ENGINE FIRE EXTINGUISHER : PHASE 23	KGJT	898066-2 16439C1	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		60		30-Jun-2022	33 m 25 d
5-12-26 051226	PHASE 26	KGJT		MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		24 3000		30-Jun-2019 11250.1	-2 m 5 d 2857.63 Over Due
5-12-30 051230 : ACM	PHASE 30	KCRQ		MTH 02-Dec-2017 HRS 8295.5 LDG 5592 ACH 4334.4		600		8895.5	503.03
5-12-32 051232	PHASE 32			MTH 22-Nov-1986 LDG 0		15000		15000	9340
5-12-33 051233	PHASE 33			MTH 22-Nov-1986 LDG 0		15000		15000	9340
5-12-40 051240	PHASE 40 NOT USED	*CF		MTH 22-Nov-1986		A/R			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-43 051243	PHASE 43 NOT USED			MTH 22-Nov-1986		A/R			
		*CF							
5-12-47	PHASE 47 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)			MTH 22-Nov-1986		144			
B262003 AFT 051247 : A	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	CRQ	A352TS X561984	MTH 09-Dec-2009		144		31-Dec-2021	27 m 26 d
B262003 FORWARD 051247 : F	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : PHASE 47	CRQ	A352TS X571070	MTH 09-Dec-2009		144		31-Dec-2021	27 m 26 d
5-12-48	PHASE 48 (PLEASE REFER TO INDIVIDUAL SUBTASKS FOR DUE TIMES)	CRQ		MTH 27-Jan-2016 HRS 8044.6 LDG 5434		72			
B262004 AFT 051248 : A	INSPECT PORTABLE FIRE EXTINGUISHER	KCRQ	FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48 A352TS X561984	MTH 27-Jan-2016 HRS 8044.6 LDG 5434		72		31-Jan-2022	28 m 26 d
B262004 FORWARD 051248 : F	INSPECT PORTABLE FIRE EXTINGUISHER	KCRQ	FIRE EXTINGUISHERS-EMPTY, FOR DAMAGE AND RECHARGE: PHASE 48 A352TS X571070	MTH 27-Jan-2016 HRS 8044.6 LDG 5434		72		31-Jan-2022	28 m 26 d
5-12-49 051249	PHASE 49	KGJT		MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		36 1200		30-Jun-2020 9450.1	9 m 25 d 1057.63
5-12-52 051252	PHASE 52	KCRQ		MTH 16-Aug-2018 HRS 8346.4 LDG 5621	-47	12		30-Jun-2019	-2 m 5 d
5-12-53 051253	PHASE 53	KCRQ		MTH 16-Feb-2017 HRS 8195.5 LDG 5532 ACH 4258.7		72 2400		28-Feb-2023 10595.5	41 m 23 d 2203.03
5-12-54	PHASE 54			MTH 22-Nov-1986 HRS 0		13200		13200	4807.53
5-12-55	PHASE 55			MTH 22-Nov-1986 HRS 0		15600		15600	7207.53
5-12-56	PHASE 56			MTH 22-Nov-1986 HRS 0		15600		15600	7207.53
5-12-57	PHASE 57			MTH HRS		10000		10000	1607.53
5-12-58	PHASE 58	KCRQ		MTH 16-Aug-2018 HRS 8346.4 LDG 5621		300		8646.4	253.93
5-12-59	PHASE 59	CRQ		MTH 04-Mar-2016 HRS 8053.8 LDG 5441 ACH 4258.7		500		4758.7	405.5
5-12-MA	PHASE MA	KCRQ		MTH 19-Oct-2017 HRS 8286.5 LDG 5582 ACH 4334.4		300		8586.5	194.03
5-12-MB	PHASE MB			MTH 22-Nov-1986 LDG 0		10000		10000	4340
050001 E1	ENGINE OVERTEMPERATURE					A/R			
050001 E2	ENGINE OVERTEMPERATURE					A/R			

Over Due



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
050002 E1	ENGINE OVERSPEED					A/R			
050002 E2	ENGINE OVERSPEED					A/R			
050003 E1	ENGINE IMMERSION IN WATER					A/R			
050003 E2	ENGINE IMMERSION IN WATER					A/R			
050004 E1	ENGINE DROPPED DURING HANDLING					A/R			
050004 E2	ENGINE DROPPED DURING HANDLING					A/R			
050005 E1	FOREIGN OBJECT DAMAGE (FOD)					A/R			
050005 E2	FOREIGN OBJECT DAMAGE (FOD)					A/R			
050006 E1	LOSS OF OIL					A/R			
050006 E2	LOSS OF OIL					A/R			
050007 E1	ENGINE WINDMILLING					A/R			
050007 E2	ENGINE WINDMILLING					A/R			
050008 E1	LIGHTNING STRIKE					A/R			
050008 E2	LIGHTNING STRIKE					A/R			
050009 E1	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT					A/R			
050009 E2	ENGINE EXPOSED TO FIRE EXTINGUISHING AGENT					A/R			
050010 E1	HEAVY / HARD LANDING					A/R			
050010 E2	HEAVY / HARD LANDING					A/R			
050011 E1	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH					A/R			
050011 E2	AIRCRAFT FLOWN THROUGH A CLOUD OF VOLCANIC ASH					A/R			
050012 E1	ENGINE WITH HIGH TURBINE BLADE DISTRESS					A/R			
050012 E2	ENGINE WITH HIGH TURBINE BLADE DISTRESS					A/R			
050013 E1	STARTER GENERATOR FAIL INDICATION					A/R			
050013 E2	STARTER GENERATOR FAIL INDICATION					A/R			
050014 E1	HYDRAULIC PUMP FAILURE					A/R			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
050014 E2	HYDRAULIC PUMP FAILURE					A/R			
057110 E1	MINOR INSPECTION	KCRQ	MTH	26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
057110 E2	MINOR INSPECTION	KCRQ	MTH	26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
129999	INSPECT AIRCRAFT SURVEY TOL		MTH	11-Oct-1996 HRS 3507		O/C			
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)		AE13083-5 LOT 0610358544	MTH	10-Jul-2010	120		31-Jul-2020	10 m 26 d
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)		AE13083-5 LOT 0610358544	MTH	10-Jul-2010	120		31-Jul-2020	10 m 26 d
B350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER ASSEMBLY DOT 3HT 1850 OR DOT 3FC1850 OR MANUFACTURED UNDER DOT-SP-8162.	CRQ	176176-64 633812	MTH	07-Jul-2016	36		31-Jul-2019	-1 m 5 d
									Over Due
710000 E1	TURBINE WASH					A/R			
710000 E2	TURBINE WASH					A/R			
710010 E1	OVERHAUL		MTH	25-Jan-2007 HRS 5947 LDG 3893		3500		(9208)9447	1054.53
710010 E2	OVERHAUL		MTH	29-Oct-2010 HRS 7278.13 LDG 4824		3500		(10556)10778.13	2385.67
710020 E1	HOT SECTION INSPECTION	KCRQ	MTH	14-Dec-2012 HRS 7747.7 LDG 5205		1800		(9307.5)9547.7	1155.23
710020 E2	HOT SECTION INSPECTION	MCO	MTH	29-Oct-2010 HRS 7278.13 LDG 4817		1800		(8856)9078.13	685.67
710030 E1	INSPECT INTERMEDIATE CASE FOR CORROSION					A/R			
710030 E2	INSPECT INTERMEDIATE CASE FOR CORROSION					A/R			
720010 E1	OIL ANALYSIS					A/R			
720010 E2	OIL ANALYSIS					A/R			
725040 E1	REPLACE HIGH TURBINE BLADES GYH		MTH	25-Jan-2007 HRS 5947		O/C			
725040 E2	REPLACE HIGH TURBINE BLADES		MTH	30-Sep-2010 HRS 7278.13 LDG 4817		O/C			
731025 E1	VISUALLY INSPECT FUEL-OIL COOLER		UA530768-4 2827	HRS	240.13	A/R		(9207)9447.13	1054.67
731025 E2	VISUALLY INSPECT FUEL-OIL COOLER		UA560768-4 3279	HRS	222.13	A/R		(10556)10778.13	2385.67



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731035 E1	VISUALLY INSPECT MOTIVE FLOW VALVE			2524995 A70503	HRS 240.13		1800		(9207)9447.13	1054.67
731035 E2	VISUALLY INSPECT MOTIVE FLOW VALVE			2524995-1 A90627	HRS 222.13		1800		(10556)10778.13	2385.67
731090 E1	VISUALLY INSPECT FLOW DIVIDER VALVE			25607-2 2910	HRS 240.13		1800		(9207)9447.13	1054.67
731090 E2	VISUALLY INSPECT FLOW DIVIDER VALVE			25607-2 3316	HRS 222.13		1800		(10556)10778.13	2385.67
741030 E1 LOWER	VISUAL INSPECT IGNITION EXCITER KCRQ			9049770-3 NNA06465140	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
741030 E1 UPPER	VISUAL INSPECT IGNITION EXCITER KCRQ			9049770-3 NNA06465140	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
741030 E2 LOWER	VISUAL INSPECT IGNITION EXCITER KCRQ			NB01201 R7153	MTH 26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
741030 E2 UPPER	VISUAL INSPECT IGNITION EXCITER KCRQ			NB01201 K8974	MTH 26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
792010 E1	CHANGE OIL CRQ				MTH 19-Aug-2010 HRS 7180 LDG 4760		O/C			
792010 E2	CHANGE OIL CRQ				MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
211002	EMERGENCY PRESSURIZATION VALVE *CF			228455 8AB13	MTH 22-Nov-1986		O/C			
212002	AVIONICS COOLNG FAN -- CRQ			19A608 N/A	MTH 07-Feb-2011 HRS 7327.5 LDG 4860		O/C	0 0		
212003	BLOWER 9912070-1	SDF		19A2338 2338	MTH 22-Dec-1999 HRS 4305		O/C	0		
212004	CABIN OVERHEAD FAN 9912323-2	KGJT		BC61A-901-2 1856A	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		1000	0	9250.1	857.63
212005 LEFT	CABIN DIVIDER BLOWER 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
212005 RIGHT	CABIN DIVIDER BLOWER 5515129-4	*CF		WS2107F30 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
212009	CABIN UNDERFLOOR ACTUATOR *CF			NYLC50466 656	MTH 22-Nov-1986		O/C			
212010	DOOR ACTUATOR MOTOR ASSY 9910059-3	*CF		5A3032 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
212027 212006	DEFOG FAN CRQ			5703-4 1329	MTH 19-Apr-2010 HRS 7061		3500	0	10561	2168.53
213001	CABIN PRESS INDICATOR 3001J14	*CF		C668511-0102 18222	MTH 22-Nov-1986		O/C			
213002	OUTFLOW VALVE CONTROLLER GSO			130356-15 601244	MTH 31-Oct-1997 HRS 3811		O/C	0		
213003	CABIN RATE OF CLIMB INDICATOR 35060-1128	*CF		C668513-0101 W14317H	MTH 22-Nov-1986		O/C			
213007 LEFT	OUTFLOW VALVE *CF			103576-36 451674	MTH 22-Nov-1986		O/C			
213007 RIGHT	OUTFLOW VALVE *CF			103576-36 421273	MTH 22-Nov-1986		O/C			
213009 LEFT	BLEED AIR FLOW CONTROL VALVE KGJT			1988-00-1 3232A	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C	0 0		
213009 RIGHT	BLEED AIR FLOW CONTROL VALVE 9912162-1	*CF		34E16-4 5860674	MTH 22-Nov-1986		O/C			
213013	PNEUMATIC RELAY *CF			130358-1 941466	MTH 22-Nov-1986		O/C			
215001	REFRIGERATION PACKAGE *CF			738443-1 860520	MTH 22-Nov-1986		O/C			
215004	AIR CYCLE MACHINE 9912069-1	GSO		738384-26P1 860111	MTH 15-Aug-2000 HRS 4418		5000	4418	5000	-3392.47
RECOMMENDED ECONOMIC OVERHAUL PERIOD DEFINED BY HAMILTON STANDARD.										Over Due
215005	BYPASS VALVE 9912069-1	*CF		754751-2 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
215014 Z	AIR COND MOTOR -- Z	MCO		1250151 SN-UNKNOWN	MTH 12-Nov-1993 HRS 2565		O/C	0		
215015	COMPRESSOR DRIVE MOTOR			PN SN-UNKNOWN	MTH 22-Nov-1986		O/C	0		
215016 215016Z : ZPHYR	COMPRESSOR SDF			1250160 SN-UNKNOWN	MTH 21-Aug-1997 HRS 3746		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
215017Z Z	AIR COND CONDENSOR - Z	MCO		125400-16 SN-UNKNOWN	MTH 12-Nov-1993 HRS 2565		O/C	0		
215022 AFT	AIRCONDITION EVAPORATOR AFT	MCO		1250240-3 SN-UNKNOWN	MTH 12-Nov-1993 HRS 2565		O/C	0		
<i>215022Z : ZPHYR</i>										
215023 FORWARD	AIRCONDITION EVAPORATOR FORWARD	MCO		1250240-1 SN-UNKNOWN	MTH 12-Nov-1993 HRS 2565		O/C	0		
<i>215023Z : ZPHYR</i>										
216002	TEMP CONTROL UNIT 9912069-22	CRQ		754661-5 GH57407	MTH 22-Feb-2008 HRS 6313		O/C	0		
216003	DUCT TEMP SENSOR 9912069-14	MCO		754691-3 03041734	MTH 02-Nov-2003 HRS 5039		O/C	0		
216004	CABIN TEMP SENSOR 9912069-15	*CF		754681-1 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
216005	CENTRIFUGAL BLOWER *CF			3A1003-10 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
216006	CABIN TEMPERATURE INDICATOR *CF			0221-003 48547	MTH 22-Nov-1986		O/C			
217001	WATER SEPARATOR 9912069-13	*CF		738386-3 860643	MTH 22-Nov-1986		O/C			
221008	AUTOPILOT COMPUTER SP-200	CRQ		4008519-945 84091524	MTH 20-Sep-2007 HRS 6102		O/C	3874		
221009	AUTOPILOT CONTROLLER PC-500			4018639-909 87012873	MTH 11-Apr-2008 HRS 6369		O/C	2193		
221010 AFT	AILERON AUTOPILOT SERVO SM-200	*CF		4006719-906 86072700	MTH 22-Nov-1986		O/C			
221010 FORWARD	ELEVATOR AUTOPILOT SERVO SM-200	MCO		4006719-914 80014549	MTH 01-Jun-1994 HRS 2800		O/C	0		
221010 MID	RUDDER AUTOPILOT SERVO SM-200	*CF		4006719-906 86042591	MTH 22-Nov-1986		O/C			
230010 237001	COCKPIT VOICE RECORDER GA-100	ICT		GA100-0000 1029	MTH 19-Aug-1991 HRS 1935		O/C	0		
230017 237010	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON CRQ			DK100 DV15665	MTH 01-May-2014 HRS 7931.8 LDG 5349		72	2	31-Mar-2020	6 m 26 d
232002 NO. 2	COMM ANTENNA NO. 2	KCRQ		CI 211 434630	MTH 10-Oct-2013 HRS 7870.8 LDG 5304		O/C			
232003 NO. 1	COMM ANTENNA NO. 1	KCRQ		VFS10-90-7 1712	MTH 02-Aug-2016 HRS 8075.4 LDG 5459 ACH 4258.7		O/C	0 0		
232004	AIRBIRNE COMMUNICATION TRANSCEIVER RT-18E	*CF		400-0125 1118	MTH 22-Nov-1986		O/C			
232005 CABIN	CONTROL PHONE CABIN	*CF		400-0123 1164	MTH 22-Nov-1986		O/C			
232006	COCKPIT CONTROL	*CF		400-0124 1170	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
232007	AIRBORNE COMMUNICATION ANTENNA *CF			121-0011 509501	MTH 22-Nov-1986		O/C			
232010 BOTTOM	NO.2 COMM TRANSCEIVER VHF-22A	KCRQ		622-6152-001 22150	MTH 14-Sep-2017 HRS 8282 LDG 5580		O/C	781		
232010 TOP	NO.1 COMM TRANSCEIVER VHF-22A	KCRQ		622-6152-001 22208	MTH 14-Sep-2017 HRS 8282 LDG 5580		O/C	781		
232011 LEFT	COMM CONTROL CTL-22	KCRQ		622-6520-005 4364	MTH 29-Nov-2017 HRS 8291.2 LDG 5588		O/C			
232011 RIGHT	COMM CONTROL CTL-22	KCRQ		622-6520-005 4365	MTH 29-Nov-2017 HRS 8291.2 LDG 5588		O/C	2928.2		
235001 LEFT	AUDIO AMPLIFIER	KCRQ		5640-1 531	MTH 14-Sep-2017 HRS 8282 LDG 5580		O/C	7748.2		
235001 RIGHT	AUDIO AMPLIFIER	KCRQ		5640-1 647	MTH 14-Sep-2017 HRS 8282 LDG 5580		O/C	7748.2		
237006	REMOTE MIKE --	ICT		93-A055-95 1064	MTH 19-Aug-1991 HRS 1935		O/C	0		
237014	HEADS UP CHECKLIST -- MKE			HUC/G-1-GPE 363	MTH 30-Oct-1992 HRS 2155		O/C	0		
242001 BOTTOM	NO.2 AC INVERTER	AZO		SPC38B 1282	MTH 16-Mar-1989 HRS 926		O/C	0		
242001 TOP	NO.1 AC INVERTER	AZO		SPC38B 1283	MTH 16-Mar-1989 HRS 926		O/C	0		
243001 LEFT	STARTER/GENERATOR	CRQ		9912125-3EX 98064	MTH 01-May-2014 HRS 7931.8 LDG 5349		1000	0	8931.8	539.33
243001 RIGHT	STARTER/GENERATOR	KCRQ		23085-004-1 98060	MTH 20-Dec-2012 HRS 7748.2 LDG 5206		1000	0 0 0	8748.2	355.73
243003 LEFT	GENERATOR CONTROL UNIT	CRQ		51539-006F 94401B	MTH 16-Apr-2009 HRS 6753		O/C	0		
243003 RIGHT	GENERATOR CONTROL UNIT	CRQ		51539-006F 3454AB	MTH 16-Apr-2009 HRS 6753		O/C	4132		
243004 LEFT	AMMETER	*CF		C662501-0104 246	MTH 22-Nov-1986		O/C			
243004 RIGHT	AMMETER	*CF		C662501-0104 248	MTH 22-Nov-1986		O/C			
243005	VOLTMETER	MCO		C662502-0101 1770	MTH 10-Apr-2002 HRS 4735		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
243007	BATTERY	KGJT		RG-380E/44 40870557	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		O/C	0 0		
243008	BATTERY TEMPERATURE MODULE	GSO		1529-1 1477	MTH 31-Oct-1997 HRS 3811		O/C	0		
243009	BATTERY TEMPERATURE GAGE			1229-1 1369	MTH 22-Nov-1986		O/C			
243011	CURRENT VOLTAGE CONTROLLER	AZO		1301-1 1495	MTH 28-Apr-1987 HRS 196		O/C	0		
243012	CURRENT SENSOR	AZO		1302-1 1239A	MTH 21-Jan-1987 HRS 41		O/C	0		
243013	BATT DISCONNECT K69 RELAY			A876K SN-UNKNOWN	MTH 22-Nov-1986		O/C			
243014 243010	BATTERY TEMPERATURE SENSOR			1166-1 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
243015 243010 : G	TEMPERATURE SENSOR GAGE			1166-1 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
245001 CENTER	5 VOLT LIGHT DIMMER	MCO		273-1 2762	MTH 01-Jun-1994 HRS 2800		O/C	0		
245001 LEFT	5 VOLT LIGHT DIMMER			1505-1 4429	MTH 22-Nov-1986		O/C			
245001 RIGHT	5 VOLT LIGHT DIMMER	ICT		273-1 2068	MTH 17-Oct-1993 HRS 2560		O/C	0		
245003 LEFT	START K7 RELAY			A703C SN-UNKNOWN	MTH 22-Nov-1986		O/C			
245003 RIGHT	START K8 RELAY			A703C SN-UNKNOWN	MTH 22-Nov-1986		O/C			
245004 LEFT	POWER K13 RELAY			A703P SN-UNKNOWN	MTH 22-Nov-1986		O/C			
245004 RIGHT	POWER K12 RELAY			A703P SN-UNKNOWN	MTH 22-Nov-1986		O/C			
256002	LOCATOR BEACON TRANSMITTER	CRQ		3000-11 328134	MTH 01-Sep-2015 HRS 8009.6 LDG 5403		O/C	1561.6		
256003	REPLACE LOCATOR BEACON TRANSMITTER BATTERY	KGJT		2020 2020-REV-A	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4220.4		24	0	30-Jun-2019	-2 m 5 d
256004 LEFT	LOCATOR BEACON ANTENNA	CRQ		ELT10-177-1 1251	MTH 27-May-2008 HRS 6435		O/C	0		Over Due
256004 RIGHT	LOCATOR BEACON ANTENNA			ELT10-177-2 700	MTH 22-Nov-1986		O/C			
256010 NO. 10	LIFE PRESERVER	KCRQ		PO1074-209 11111430069	MTH 01-Mar-2012 HRS 7586.7 LDG 5068		120	3	31-Dec-2021	27 m 26 d
256010 NO. 11	LIFE PRESERVER --	KCRQ		PO1074-209 11111430076	MTH 01-Mar-2012 HRS 7586.7 LDG 5068		120	3	31-Dec-2021	27 m 26 d



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
256010 NO. 1	LIFE PRESERVER	KGJT		PO1074-209 15060950118	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		120	0	30-Jun-2027	93 m 25 d
256010 NO. 2	LIFE PRESERVER	CRQ		PO1074-209 1512150017	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		120	0 0 0	30-Apr-2025	67 m 25 d
256010 NO. 3	LIFE PRESERVER	CRQ		PO1074-209 1512150018	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		120	0 0 0	30-Apr-2025	67 m 25 d
256010 NO. 4	LIFE PRESERVER	CRQ		PO1074-209 1512150019	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		120	0 0 0	30-Apr-2025	67 m 25 d
256010 NO. 5	LIFE PRESERVER	CRQ		PO1074-209 1512150020	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		120	0 0 0	30-Apr-2025	67 m 25 d
256010 NO. 6	LIFE PRESERVER	CRQ		PO1074-209 1512150021	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		120	0 0 0	30-Apr-2025	67 m 25 d
256010 NO. 7	LIFE PRESERVER	KCRQ		PO1074-209 11111430073	MTH 01-Mar-2012 HRS 7586.7 LDG 5068		120	3	31-Dec-2021	27 m 26 d
256010 NO. 8	LIFE PRESERVER	KCRQ		PO1074-209 11111430074	MTH 01-Mar-2012 HRS 7586.7 LDG 5068		120	3	31-Dec-2021	27 m 26 d
256010 NO. 9	LIFE PRESERVER	KCRQ		PO1074-209 11111430075	MTH 01-Mar-2012 HRS 7586.7 LDG 5068		120	3	31-Dec-2021	27 m 26 d
261001 LEFT	ENGINE FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
261001 RIGHT	ENGINE FIRE DETECTOR SENSOR 9912036-3	*CF		244-18882 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
261002 LEFT	FIRE DETECTION CONTROL UNIT 9912036-2	*CF		377-02808 8623022	MTH 22-Nov-1986		O/C			
261002 RIGHT	FIRE DETECTION CONTROL UNIT 9912036-2	*CF		377-02808 8623019	MTH 22-Nov-1986		O/C			
262001 AFT	ENGINE FIRE EXTINGUISHER CRQ			C352TS A-40842642	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		O/C	0 0 0		
262001 FORWARD	ENGINE FIRE EXTINGUISHER 9912048-3	SDF		898066-2 16439C1	MTH 12-Feb-2003 HRS 4910		O/C	0		
262002 AFT	PORTABLE FIRE EXTINGUISHER CRQ			A352TS X561984	MTH 31-Dec-2009 HRS 6919 LDG 4602		O/C	0 0 0		
262002 FORWARD	PORTABLE FIRE EXTINGUISHER CRQ			A352TS X571070	MTH 31-Dec-2009 HRS 6919 LDG 4602		O/C	0 0 0		
262101 AFT LEFT 262003 : AL	FIRE EXTINGUISHER CARTRIDGE KCRQ			M873364-1 01234	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		180		31-May-2026	80 m 26 d
Manufacture Date: 11-May-2011										
262101 AFT RIGHT 262003 : AR	FIRE EXTINGUISHER CARTRIDGE KCRQ			M873364-1 02135	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		180		31-May-2026	80 m 26 d
Manufacture Date: 11-May-2011										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
262101 FORWARD LEFT 262003 : FL Manufacture Date: 10-Mar-2010	FIRE EXTINGUISHER CARTRIDGE			AE13083-5 LOT 0610358544	MTH 10-Jul-2010 HRS 7115 LDG 4716		120	0	31-Mar-2020	6 m 26 d
262101 FORWARD RIGHT 262003 : FR Manufacture Date: 10-Mar-2010	FIRE EXTINGUISHER CARTRIDGE			AE13083-5 LOT 0610358544	MTH 10-Jul-2010 HRS 7115 LDG 4716		120		31-Mar-2020	6 m 26 d
271001	AILERON TRIM TAB ACTUATOR KGJT			6660361-18 4901	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C			
272001	RUDDER TRIM TAB ACTUATOR 5565450-71 *CF			5565450-71 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
273002	ELECTRIC ELEVATOR TRIM ACTUATOR SDF			44430-3657 T617	MTH 22-Dec-1999 HRS 4305		O/C	0		
273003 LEFT	ELEVATOR TRIM TAB ACTUATOR MCO			5565450-899 SN-UNKNOWN	MTH 10-Apr-2002 HRS 4735		O/C	0		
273003 RIGHT	ELEVATOR TRIM TAB ACTUATOR 5565450-80 MCO			5565450-98 SN-UNKNOWN	MTH 10-Apr-2002 HRS 4735		O/C	0		
275001	FLAP CONTROL VALVE *CF			66720 244	MTH 22-Nov-1986		O/C			
275003 LEFT	FLAP ACTUATOR 9912007-1 *CF			55800-1 390	MTH 22-Nov-1986		O/C			
275003 RIGHT	FLAP ACTUATOR 9912007-1 *CF			55800-1 391	MTH 22-Nov-1986		O/C			
275004 LEFT WING LEFT INBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 LEFT WING LEFT OUTBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 LEFT WING RIGHT INBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 LEFT WING RIGHT OUTBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 RIGHT WING LEFT INBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 RIGHT WING LEFT OUTBOARD	-AFT FLAP ROLLER KCRQ			CC50380 N/A	MTH 15-Nov-2011 HRS 7510.7 LDG 4997		5000	0	9997	4337
275004 RIGHT WING RIGHT INBOARD	-AFT FLAP ROLLER KCRQ			CC50380 SN-UNKNOWN	MTH 16-Aug-2018 HRS 8346.4 LDG 5621		5000	0	10621	4961
275004 RIGHT WING RIGHT OUTBOARD	-AFT FLAP ROLLER KCRQ			CC50380 SN-UNKNOWN	MTH 16-Aug-2018 HRS 8346.4 LDG 5621		5000	0	10621	4961
276001 LEFT	SPEED BRAKES ACTUATOR 6527550-1 *CF			50115-1 148	MTH 22-Nov-1986		O/C			
276001 RIGHT	SPEED BRAKES ACTUATOR 6527550-1 *CF			50115-1 255	MTH 22-Nov-1986		O/C			
276002	SPEED BRAKE VALVE *CF			66720 239	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
276003	SPEED BRAKE SAFETY VALVE *CF			2710972 1321	MTH 22-Nov-1986		O/C			
282001 LEFT	MOTOR DRIVEN FUEL PUMP 9912017-2	CRQ		1C7-12 7AR56	MTH 30-Jan-2008 HRS 6276		O/C	0		
282001 RIGHT	MOTOR DRIVEN FUEL PUMP 9912017-2	*CF		1C7-12 SN-UNKNOWN	MTH 23-Nov-1986		O/C			
284001 LEFT	LOW LEVEL FUEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
284001 RIGHT	LOW LEVEL FUEL SWITCH *CF			L15H-3 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
284002 LEFT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 15205T	MTH 22-Nov-1986		O/C			
284002 RIGHT	FUEL QUANTITY COMPENSATOR 9912019-4	*CF		300047-13001 15194T	MTH 22-Nov-1986		O/C			
284007	FUEL QUANTITY INDICATOR 9912147-12	GSO		VSDL-OC403D-1 51	MTH 09-Mar-2007 HRS 5986		O/C	0		
291001	HYDRAULIC RESERVOIR ASSEMBLY 9912052-12	MCO		7140-7 732	MTH 06-Dec-2004 HRS 5363		O/C	0		
291002 LEFT	ENGINE HYDRAULIC PUMP 9912062-4	CRQ		24195-LAA 6123	MTH 13-Nov-2013 HRS 7888 LDG 5319		O/C	0 0		
291002 RIGHT	ENGINE HYDRAULIC PUMP 9912062-4	CRQ		24195-LAA 5184	MTH 13-Nov-2013 HRS 7888 LDG 5319		O/C	0 0		
291005 LEFT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	CRQ		3520020100-4 2215	MTH 13-Nov-2013 HRS 7888 LDG 5319		O/C			
291005 RIGHT	HYDRAULIC W/FLOW DETECTOR CHECK VALVE 9912194-3	CRQ		3520020100-4 5184	MTH 13-Nov-2013 HRS 7888 LDG 5319		O/C			
291007 LEFT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
291007 RIGHT	HYDRAULIC FIREWALL SHUTOFF VALVE *CF			149145 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
291012	HYDRAULIC BY-PASS VALVE *CF			2710971 811	MTH 22-Nov-1986		O/C			
301001 AFT	ANTI-ICE PUMP KCRQ			XA9511A010 IRM0883/A277-87	MTH 29-Aug-2012 HRS 7699.2 LDG 5162		O/C	0 0		
301001 FORWARD	ANTI-ICE PUMP *CF			XA9511C005 J6986	MTH 22-Nov-1986		O/C			
301002 LEFT	LOW PRESSURE SWITCH *CF			PO67B078 C45085	MTH 22-Nov-1986		O/C			
301002 RIGHT	LOW PRESSURE SWITCH *CF			PO67B078 T43384	MTH 22-Nov-1986		O/C			
301003	ANTI-ICE TANK ASSY *CF			6514007-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
301004	ANTI-ICE FLUID INDICATOR *CF			19-435-02 SN-UNKNOWN	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301005 LEFT	SURF SOLENOID VALVE *CF			FV137 K15784	MTH 22-Nov-1986		O/C			
301005 RIGHT	SURF SOLENOID VALVE *CF			FV137 K18884	MTH 22-Nov-1986		O/C			
301005	SOLENOID VALVE *CF			FV137 T139184	MTH 22-Nov-1986		O/C			
301006 LEFT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3717 853U17	MTH 22-Nov-1986		O/C			
301006 LEFT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3715 854D15	MTH 22-Nov-1986		O/C			
301006 RIGHT INBOARD	HORIZONTAL STABILIZER PANEL *CF			D3718 86C18	MTH 22-Nov-1986		O/C			
301006 RIGHT OUTBOARD	HORIZONTAL STABILIZER PANEL *CF			D3716 854G16	MTH 22-Nov-1986		O/C			
301007 LEFT NO.1	WING PANEL *CF			D3709 86V9	MTH 22-Nov-1986		O/C			
301007 LEFT NO.2	WING PANEL *CF			D3731 86C7	MTH 22-Nov-1986		O/C			
301007 LEFT NO.3	WING PANEL *CF			D3729 86R5	MTH 22-Nov-1986		O/C			
301007 LEFT NO.4	WING PANEL *CF			D3703 86S3	MTH 22-Nov-1986		O/C			
301007 LEFT NO.5	WING PANEL *CF			D3701 86M1	MTH 22-Nov-1986		O/C			
301007 RIGHT NO.1	WING PANEL *CF			D3710 86T10	MTH 22-Nov-1986		O/C			
301007 RIGHT NO.2	WING PANEL *CF			D3732 852Z8	MTH 22-Nov-1986		O/C			
301007 RIGHT NO.3	WING PANEL *CF			D3730 86R6	MTH 22-Nov-1986		O/C			
301007 RIGHT NO.4	WING PANEL *CF			D3704 86Q4	MTH 22-Nov-1986		O/C			
301007 RIGHT NO.5	WING PANEL *CF			D3702 86F2	MTH 22-Nov-1986		O/C			
301008 LEFT	FAIRING PANEL *CF			D3714 86X14	MTH 22-Nov-1986		O/C			
301008 RIGHT	FAIRING PANEL *CF			D3713 86R13	MTH 22-Nov-1986		O/C			
301009 LEFT	SURF PROPORTIONER *CF			PU306DW38 D6086	MTH 22-Nov-1986		O/C			
301009 RIGHT	SURF PROPORTIONER *CF			PU306DW38 A9686	MTH 22-Nov-1986		O/C			
301010	ENGINE PROPORTIONER *CF			PU306DC39 A5186	MTH 22-Nov-1986		O/C			
301011	HOR/STB PROPORTIONER *CF			PU306DT41 M1985	MTH 22-Nov-1986		O/C			
301012	ICE DETECTOR	MCO		871DN1 0210	MTH 06-Dec-2004 HRS 5363		O/C	0		
301013 <i>301016</i>	SURF PUMP CHECK VALVE *CF			FV121 C41385	MTH 22-Nov-1986		O/C			
301014 LEFT	FAIRING PANEL PRESSURE SWITCH MCO			PO67L015 AST02H069	MTH 02-Nov-2003 HRS 5039		O/C	0		
301014 LEFT INBOARD	FAIRING PANEL PRESSURE SWITCH *CF			PO67L015 H7186	MTH 22-Nov-1986		O/C			
301014 RIGHT	FAIRING PANEL PRESSURE SWITCH MCO			PO67L015 J2187	MTH 05-Jan-1996 HRS 3336		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
301014 RIGHT INBOARD	FAIRING PANEL PRESSURE SWITCH FXE			PO67L015 A3187	MTH 05-Jan-1996 HRS 3335		O/C	0		
301016 LEFT	WING PANEL PRESSURE SWITCH *CF			PO67LC035 B10886	MTH 22-Nov-1986		O/C			
301016 RIGHT	WING PANEL PRESSURE SWITCH *CF			PO67LC035 C18585	MTH 22-Nov-1986		O/C			
301017 LEFT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 A24186	MTH 22-Nov-1986		O/C			
301017 LEFT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 D10786	MTH 22-Nov-1986		O/C			
301017 RIGHT INBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 A24786	MTH 22-Nov-1986		O/C			
301017 RIGHT OUTBOARD	HORIZONTAL STABILIZER PRESSURE SWITCH *CF			PO67L015 A25886	MTH 22-Nov-1986		O/C			
301018 <i>301015 : PUMP</i>	ENGINE PUMP CHECK VALVE *CF			FV147 H7786	MTH 22-Nov-1986		O/C			
301019 LEFT	SURF TEE CHECK VALVE *CF			FV147 L3885	MTH 22-Nov-1986		O/C			
301019 RIGHT	SURF TEE CHECK VALVE *CF			FV147 L3985	MTH 22-Nov-1986		O/C			
301020	SURF INBD CHECK VALVE *CF			FV147 L4485	MTH 22-Nov-1986		O/C			
301021	SURF TO ENGINE CHECK VALVE *CF			FV147 L4585	MTH 22-Nov-1986		O/C			
302003 LEFT	ENGINE BLEED AIR VALVE 9912402-16	KGJT		1946-00-16 5213C	MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		O/C	0 0		
302003 RIGHT	ENGINE BLEED AIR VALVE 9912086-7	GSO		67410-1 1571	MTH 31-Oct-1997 HRS 3811		O/C	0		
302004 LEFT	ANTI ICE TEMP SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
302004 RIGHT	ANTI ICE TEMP SWITCH *CF			21548-2-19-6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303001 LEFT	PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303001 RIGHT	PITOT TUBE *CF			PH502 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303002 LEFT	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303002 RIGHT <i>303003 : RT</i>	CO-PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303003 LEFT	CO-PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
303003 RIGHT <i>303002 : RB</i>	PILOT STATIC PORT *CF			CM2933-7 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
304001	HOT AIR TEMPERATURE MONITOR- 5514120	*CF		1169-1 1521	MTH 22-Nov-1986		O/C			
304002	HEAT EXCHANGER 9912041-4	*CF		10663A 283	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
304005	TEMPERATURE CONTROL VALVE 9912085-1	*CF		27241287 7AB45	MTH 22-Nov-1986		O/C			
304006	TEMPERATURE CONTROLLER 9912085-2	*CF		27231272 11AA60	MTH 22-Nov-1986		O/C			
304009	WINDSHIELD BLEED AIR VALVE 9912086-4	CRQ		67410-2 970BCDEGK	MTH 07-Sep-2007		O/C			
312001 RIGHT	CLOCK	KGJT		811B A42567	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C	0 0		
312003 LEFT <i>312001 : L</i>	DIGITAL CLOCK	MCO		811B24A 36923	MTH 06-Dec-2004 HRS 5363		O/C	0		
313001	FLIGHT HOURMETER 85071	MCO		C664503-0104 SN-UNKNOWN	MTH 08-Feb-1994 HRS 2651		O/C	0		
313003	ACCELEROMETER AG-222	*CF		7000992 4807	MTH 22-Nov-1986		O/C			
321001 LEFT	MAIN LANDING GEAR ASSY 6641000	KGJT		6641000-3 121	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		25800	5340	25800	20140
321002 RIGHT	MAIN LANDING GEAR ASSY 6641000	*CF		6641000-4 121	MTH 22-Nov-1986 LDG 0		25800	0	25800	20140
321003 LEFT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0	980	21500	980	21500	15840
321003 RIGHT MAIN LANDING GEAR	TORQUE LINK BOLT	*CF		5541220-2 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0	980	21500	980	21500	15840
322001	NOSE LANDING GEAR ASSY 6642000-2	*CF		6642000-2 33	MTH 22-Nov-1986 LDG 0		23900	0	23900	18240
322002	NOSE GEAR SHIMMY DAMPER KGJT			5543001-8 01928-3-8	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C			
322004	NOSE LANDING GEAR FORK *CF			5542300-2 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		13800	0	13800	8140
322005	NOSE GEAR ACTUATOR FITTING *CF			5511169-1 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		23900	0	23900	18240
322006 LEFT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-1 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		11600	0	11600	5940
322006 RIGHT	NOSE GEAR TRUNNION SUPPORT ASSEMBLY 5513056-5	*CF		6613056-2 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		11600	0	11600	5940
322007	NOSE GEAR TRUNNION *CF			5542301-9 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		23900	0	23900	18240
322008	NOSE LANDING GEAR PISTON WELD ASSEMBLY *CF			6642100-2 SN-UNKNOWN	MTH 22-Nov-1986 LDG 0		13800	0	13800	8140
323001 LEFT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-1	MCO		1523100-3 51	MTH 06-Dec-2004 HRS 5363 LDG 3545		25800	2981	26364	20704
323002 RIGHT MAIN LANDING GEAR	SIDE BRACE ACTUATOR 9912111-2	*CF		1523100-4 49	MTH 22-Nov-1986 LDG 0		25800	0	25800	20140
323003 NOSE LANDING GEAR	ACTUATOR 9912120-1	*CF		1523200-3 21	MTH 22-Nov-1986 LDG 0		23900	0	23900	18240



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
323004 LEFT	LANDING GEAR UPLOCK ACTUATOR 5527500	*CF		5527504-2 SN-UNKNOWN	MTH 04-Nov-1986		O/C			
323004 NOSE	LANDING GEAR UPLOCK ACTUATOR 5527500-2	*CF		5527504-2 SN-UNKNOWN	MTH 04-Nov-1986		O/C			
323004 RIGHT	LANDING GEAR UPLOCK ACTUATOR 5517000	*CF		5527504-2 SN-UNKNOWN	MTH 04-Nov-1986		O/C			
323006	EMERGENCY GEAR AIR BOTTLE 9912103-3	SCF		212940-2 2262	MTH 02-Jul-2002 HRS 4793		288	2	31-May-2026	80 m 26 d
323007	GEAR CONTROL VALVE 70	*CF		66710	MTH 22-Nov-1986		O/C			
323008	DUMP VALVE	*CF		AS19400-1 1336	MTH 22-Nov-1986		O/C			
323019	EMERGENCY AIR BOTTLE GAGE *CF			2341128 SN-UNKNOWN	MTH 22-Nov-1986		O/C	0		
324001 LEFT	MAIN WHEEL ASSEMBLY 9912222-2	KGJT		40-202 362	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C			
324001 RIGHT	MAIN WHEEL ASSEMBLY 9912222-2	CRQ		40-202 L453	MTH 04-Feb-2014 HRS 7907.4 LDG 5334		O/C	0	0	
324002	NOSE WHEEL ASSEMBLY KCRQ			9544207-2 JUN81-11	MTH 29-Nov-2017 HRS 8295.5 LDG 5592 ACH 4334.4		O/C			
324003 LEFT	BRAKE ASSEMBLY	CRQ		30-161A 1076	MTH 13-Apr-2016 HRS 8063.2 LDG 5447		O/C	0	0	0
324004 RIGHT	BRAKE ASSEMBLY	CRQ		030-16101 1044	MTH 20-May-2016 HRS 8063.2 LDG 5447		O/C	7	0	
324005 LEFT	MAIN TIRE	KCRQ		220K28-1 63462827	MTH 16-Aug-2018 HRS 8346.4 LDG 5621		O/C	0	0	
324005 RIGHT	MAIN TIRE	KCRQ		220K28-1 63472644	MTH 16-Aug-2018 HRS 8346.4 LDG 5621		O/C	0	0	
324006	NOSE TIRE	KCRQ		184F08-1 62362789	MTH 29-Nov-2017 HRS 8295.5 LDG 5592 ACH 4334.4		O/C	0	0	
324011 LEFT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		12A085-11 2983	MTH 22-Nov-1986		O/C			
324011 RIGHT	(PILOT SIDE) MASTER BRAKE CYLINDER 9912050-11	*CF		12A085-11 2986	MTH 22-Nov-1986		O/C			
324012 LEFT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 3070	MTH 22-Nov-1986		O/C			
324012 RIGHT	(COPILOT SIDE) MASTER BRAKE CYLINDER 9912050-12	*CF		12A085-12 3075	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
324014	EMERGENCY AIR BRAKE VALVE 9912105-1	*CF		53640 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
324019	BRAKE PRESSURE PUMP ASSY 9912166-2	*CF		634343 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
324020	BRAKE CONTROL BOX 9912305-6	DPA		42-707-1 338	MTH 04-Mar-1991 HRS 1772		O/C	0		
324021	POWER BRAKE ANTI-SKID VALVE 9912305-7	*CF		38-707-1 304	MTH 22-Nov-1986		O/C			
324023	ACCUMULATOR	*CF		57C57652 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
324024 LEFT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 1690	MTH 22-Nov-1986		O/C			
324024 RIGHT	WHEEL TRANSDUCER 9912305-2	*CF		40-955 1693	MTH 22-Nov-1986		O/C			
324025	PRESSURE SWITCH 38-581501	*CF		1206P27 1298	MTH 22-Nov-1986		O/C			
324026	POWER BRAKE ASSEMBLY MOTOR MKE			30-2 2440	MTH 23-Oct-1992 HRS 2145 LDG 1436		O/C	0		
324101	PARKING BRAKE VALVE 9914263-1	AZO		20800-6 1418	MTH 08-Aug-1989 HRS 1111		O/C	0		
325001	BUNGEE ASSEMBLY 5565624-18	*CF		5565624-18 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
326002 LEFT	M/G UP & LOCKED SWITCH CRQ			65-430087 SN-UNKNOWN	MTH 20-May-2016 HRS 8063.2 LDG 5447		O/C	0 0		
326002 RIGHT	M/G UP & LOCKED SWITCH MKE			65430087 SN-UNKNOWN	MTH 23-Dec-1992 HRS 2228 LDG 1488		O/C	0		
326003 LEFT	M/G DOWN & LOCK SWITCH FXE			602EN16-6B SN-UNKNOWN	MTH 14-Apr-1995 LDG 2000		O/C	0		
326003 RIGHT	M/G DOWN & LOCK SWITCH 9912053-13	*CF		1CH106-6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
326004	N/G DOWN & LOCK SWITCH *CF			1CH106-6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
326005	N/G UP&LOCKED SWITCH *CF			CM3597-1 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
331001	ANNUNCIATOR PANEL -- 9912119-8	GSO		950D-0240-008 104	MTH 31-Oct-1997 HRS 3811		O/C	3811		
331011	EL PANEL-115V INVERTER *CF			EM2044-1 763	MTH 22-Nov-1986		O/C			
332002 AFT	INDIRECT LIGHTING INVERTER MCO			18.996 6996	MTH 01-Nov-1996 HRS 3535		O/C	0		
332002 FORWARD	INDIRECT LIGHTING INVERTER MKE			18.994 3538	MTH 29-Jun-1993 HRS 2487		O/C	0		
334002	VERT FIN ANTI-COLLISION LIGHT ASSEMBLY MCO			30-2140-5 0156	MTH 06-Dec-2004 HRS 5363		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
334003 LEFT	STROBE LIGHT POWER SUPPLY 9910368-2	MKE		60-2799-1 2190	MTH 29-Jun-1993 HRS 2487		O/C	0		
334003 RIGHT	STROBE LIGHT POWER SUPPLY 9910368-2	CRQ		60-2799-1 10161	MTH 05-Jun-2014 HRS 7967.1 LDG 5362		O/C	0		
334004 RIGHT	STROBE LITE TUBE	GYH		31-3172-11 APS20542	MTH 23-Feb-2006 HRS 5712		O/C	0		
335001	EMERGENCY BATTERY PACK 5518109	*CF		24621-3 SN-UNKNOWN	MTH 22-Nov-1986		O/C	0		
341001 LEFT	AIR SPEED INDICATOR	MCO		C661063-0105 208	MTH 12-Nov-1993 HRS 2565		O/C	0		
341001 RIGHT	AIR SPEED INDICATOR	GSO		C661063-0105 147	MTH 31-Oct-1997 HRS 3811		O/C	0		
341002 STANDBY	ALTIMETER			570-24929-013 2288	MTH 22-Nov-1986		O/C	0		
341004	OAT GAUGE 162BL507D	MKE		C668510-0401 1746	MTH 23-Dec-1992 HRS 2228		O/C	0		
341005	OVERSPEED WARNING SWITCH 9912076-12	KGJT		D2RA45C-24 301	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		O/C	0		
341010	AOA INDICATOR	DPA		SLZ9987 CR1350C	MTH 06-Feb-1989 HRS 877		O/C	0		
341011	STALL WARNING COMPUTER	MKE		SLZ7695 AE1127A	MTH 08-Jan-1993 HRS 2275		O/C	0		
341012	AOA POTENTIOMETER 5518132-1	*CF		MOD202-5K SN-UNKNOWN	MTH 22-Nov-1986		O/C			
341013	AOA TRANSMITTER	KCQR		SLZ7306 LS1638	MTH 07-Sep-2018 HRS 8363.4 LDG 5632		O/C			
341014	AOA TRANSMITTER INDEXER	*CF		SLZ9374 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
341018	V NAV CONTROL DISPLAY VN-800	KCRQ		7000472-901 84100447	MTH 12-Sep-2013 HRS 7870.8 LDG 5304		O/C			
341019 LEFT	ALTIMETER BA-141	CRQ		4016341-905 6110287	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		O/C			
341019 RIGHT <i>341002 : R</i>	RIGHT ALTIMETER	CRQ		70251N02D04 040413500	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		O/C			
341020	V-NAV COMPUTER CONTROL VN-212	MCO		4020571-904 87122143	MTH 02-Nov-2003 HRS 5039		O/C	3703		
341023	TRUE AIR SPEED IND -- DS-125A	*CF		7002638-902 84040351	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
341024	TAS TEMPERATURE PROBE *CF			102AU1AF 59040	MTH 22-Nov-1986		O/C			
342001	MAGNETIC COMPASS C2400-L4V2W-5B	KCRQ		C660501-0301 SN-UNKNOWN	MTH 08-May-2012 HRS 7641.7 LDG 5110		O/C	0 0 0		
342002	TURN AND BANK INDICATOR CRQ			C661004-0101 457	MTH 27-May-2008 HRS 6435		O/C	0		
342003 RIGHT	HORIZON GYRO 1U149-002-2	KCRQ		C661056-0202 A12518H	MTH 27-Aug-2018 HRS 8355.1 LDG 5625		O/C	0		
342021 LEFT	VERTICAL SPEED INDICATOR *CF			C661006-0101 W14030H	MTH 22-Nov-1986		O/C			
342021 RIGHT	VERTICAL SPEED INDICATOR *CF			C661006-0101 W13929H	MTH 22-Nov-1986		O/C			
342041	FLIGHT DIRECTOR COMPUTER FZ-500	CRQ		4018369-905 82013310	MTH 25-Mar-2010 HRS 7029		O/C		4737	
342042 LEFT	AP/FD MODE SELECTOR MS-205	KCRQ		4020570-903 86011503	MTH 29-Nov-2017 HRS 8291.2 LDG 5588		O/C		8291.2 5588	
342043 LEFT	VERTICAL GYRO VG-14A	PBI		7000622-901 98128774	MTH 05-Aug-2000 HRS 4415		O/C		39	
342044 LEFT	RATE GYRO RG-204	*CF		7007453-903 86050674	MTH 22-Nov-1986		O/C			
342046 NO. 1 342048	AIR DATA COMPUTER AZ-252	KCRQ		7024900-30302 05011012	MTH 23-Oct-2012 HRS 7722.6 LDG 5183		O/C			
342047 LEFT	ADI INDICATOR AD-650	MKE		7000466-951 84082261	MTH 08-Jan-1993 HRS 2275		O/C		0	
342048 STANDBY	ADC/ALTIMETER --	CRQ		70251N02D04 040413500	MTH 07-Feb-2011 HRS 7327.5 LDG 4860		O/C	0 0		
342049 LEFT	DIR GYRO SYN COMPASS C-14D	KGJT		4020577-3 80011536	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		O/C	0	8218.4	
342049 RIGHT	DIR GYRO SYN COMPASS C-14D	KGJT		4020577-3 90064648	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		O/C	0	3553	
342050 LEFT	FLUX VALVE FX-220	MCO		2594484 90129332	MTH 06-Dec-2004 HRS 5363		O/C		175	
342050 RIGHT	FLUX VALVE FX-220	KCRQ		2594484 98012659	MTH 10-Apr-2017 HRS 8218.4 LDG 5547 ACH 4258.7		O/C			
342052	REMOTE COMPENSATOR CS-412	*CF		2593379-1 86048412	MTH 22-Nov-1986		O/C			

NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items.



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
342053 LEFT	HSI INDICATOR RD-650A	KCRQ		7000469-909 86102304	MTH 17-May-2013 HRS 7842.5 LDG 5282		O/C			
342053 RIGHT	HSI INDICATOR RD-450	*CF		7002493-903 86030619	MTH 22-Nov-1986		O/C			
342063	REMOTE HDG CONTROL MKE			4026206-9232 84092545	MTH 30-Oct-1992 HRS 2155		O/C	0		
342064	STANDBY GYRO POWER SUPPLY PS-835	KCRQ		501-1228-04 12500	MTH 22-Aug-2017 HRS 8279.7 LDG 5578 ACH 4332.1		O/C			
342065	STAND-BY GYRO	CMH		501-1566-10 1196	MTH 20-Feb-1997 HRS 3606		O/C	0		
342072	JET STATIC CONVERTER *CF			501-1318-01 2223	MTH 22-Nov-1986		O/C			
344004	RADAR RECEIVER/TRANSMITTER ART-2100	KCRQ		071-01550-0101 1208	MTH 29-Apr-2011 HRS 7375.8 LDG 4896		O/C	523.8		
344005	RADAR ANTENNA AA-2012V	MCO		071-01549-0200 5479	MTH 06-Dec-2004 HRS 5363		O/C	0		
344006	WEATHER RADAR MODULE -- KAC0501	MCO		071-00159-0111 3700	MTH 06-Dec-2004 HRS 5363		O/C	0		
344011	DATA NAV COMPUTER IZ-1002	CMH		M1585397-5 1281	MTH 20-Feb-1997 HRS 3606		O/C	0		
344012	EGPWS MODULE KAC0502	MCO		071-00158-0211 3963	MTH 06-Dec-2004 HRS 5363		O/C	0		
344013	TRAFFIC MODULE KAS0503	MCO		071-00166-0411 3440	MTH 06-Dec-2004 HRS 5363		O/C	0		
344021 LEFT	TAWS/RMI INDICATOR RMI-30	SDF		622-4938-004 7031	MTH 22-Dec-1999 HRS 4305		O/C	4305		
344021 RIGHT	TAWS/RMI INDICATOR RMI-30	MKE		622-4938-004 8992	MTH 08-Jan-1993 HRS 2275		O/C	0		
344022	RADIO ALTIMETER TRANSCEIVER ALT-55	MCO		622-2855-001 7336	MTH 01-Jun-1994 HRS 2800		O/C	0		
344025	GPS RCVR/DSPY --	MCO		13824-12-0211 2480323	MTH 12-Nov-1993 HRS 2565		O/C	0		
344030	KEYBOARD -- WN-900	CMH		M1585245 1846	MTH 20-Feb-1997 HRS 3606		O/C	0		
344031	DATA NAV CONTROL -- IC-1003	CMH		M1585399-2 1053	MTH 20-Feb-1997 HRS 3606		O/C	0		
344040	STORMSCOPE PROCESSOR CRQ			78-8047-0978-6 R1P05600722	MTH 05-Sep-2007 HRS 6102		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
344041	STORMSCOPE DISPLAY CRQ			78-8047-0977-8 R1D05600722	MTH 05-Sep-2007 HRS 6102		O/C	0		
344042	STORMSCOPE ANTENNA MCO			78-8060-5860-4 5300131	MTH 12-Nov-1993 HRS 2565		O/C	0		
345004 AFT	TRANSPONDER ANTENNA *CF			DMN150-2 29423	MTH 22-Nov-1986		O/C			
345004 FORWARD	TRANSPONDER ANTENNA *CF			DMN150-2 29446	MTH 22-Nov-1986		O/C			
345007 LEFT	DME ANTENNA 85226	MCO		DMNI50-2-2 90452	MTH 06-Dec-2004 HRS 5363		O/C	0		
345007 RIGHT	DME ANTENNA *CF			DMNI50-2 29444	MTH 22-Nov-1986		O/C			
345010	NAV ANTENNA *CF			DMN4-17-1B 28954	MTH 22-Nov-1986		O/C			
345011 RIGHT	ADF RECEIVER ADF-60A	SDF		622-2362-001 17586	MTH 23-Feb-2001 HRS 4482		O/C	4477		
345012	ADF CONTROL CTL-62	*CF		622-6522-005 2565	MTH 22-Nov-1986		O/C			
345014 LEFT	ADF LOOP ANTENNA APA-80	*CF		622-2363-001 19347	MTH 22-Nov-1986		O/C			
345017	MARKER BEACON ANTENNA *CF			16D00400-2 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
345018	GLIDESCOPE ANTENNA *CF			RGS1048 9789	MTH 22-Nov-1986		O/C			
345032 BOTTOM	NO.2 NAVIGATION TRANSCEIVER VIR-32	MCO		622-6137-001 12036	MTH 06-Dec-2004 HRS 5363		O/C	36		
345032 TOP	NO.1 NAVIGATION TRANSCEIVER VIR-32	MKE		622-6137-001 5627	MTH 30-Oct-1992 HRS 2155		O/C	0		
345033 BOTTOM	NAVIGATION NO. 2 CONTROL UNIT CTL-32	SDF		622-6521-013 4148	MTH 08-Jun-2001 HRS 4562		O/C	4562		
345033 TOP	NAVIGATION NO. 1 CONTROL UNIT CTL-32	KGJT		622-6521-013 4613	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C			
345034 LEFT	TRANSPONDER TDR-90	CRQ		622-1270-001 28045	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		O/C			
345034 RIGHT	TRANSPONDER TDR-90	CRQ		622-1270-001 28174	MTH 03-Apr-2015 HRS 7982.4 LDG 5385		O/C			
345035 LEFT	DME INDICATOR IND-42A	SDF		622-6524-001 SN-UNKNOWN	MTH 16-Jan-2002 HRS 4717		O/C	0		
345035 RIGHT	DME INDICATOR IND-42A	PBI		622-6524-001 4265	MTH 26-Feb-2002 HRS 4720		O/C	2562		
345036 LEFT	DME INTERROGATOR DME-42	KGJT		622-6263-001 1337	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
345036 RIGHT	DME INTERROGATOR DME-42	SDF		622-6263-001 1756	MTH 23-Feb-2001 HRS 4482		O/C	628		
345039 NO. 1	CONTROL ADF ADAPTER CAD-62	*CF		622-6590-001 3638	MTH 22-Nov-1986		O/C			
345039 NO. 2	CONTROL ADF ADAPTER CAD-62	*CF		622-6590-001 2495	MTH 22-Nov-1986		O/C			
345039	CONTROL TRANSPONDER ADAPTER CAD-62	ICT		622-6590-001 3900	MTH 12-Dec-1986 HRS 3		O/C	0		
345040	TRANSPONDER CONTROL CTL-92	SDF		622-6523-005 9276	MTH 11-Sep-2003 HRS 5013		O/C	0		
345053	VLF ANTENNA	CMH		11455-2 SN-UNKNOWN	MTH 20-Feb-1997 HRS 3606		O/C	0		
345057 345054 : GNS-X	GNS CONTROL DISPLAY GNS-XLS	KGJT	7	17960-0102-0002 M1095	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		O/C	0 0		
345057A	GNS BATTERY PACK --	MCO		10648-1 1640	MTH 18-Nov-1993 HRS 2565		O/C	0		
345066	DATA INTERFACE UNIT --	ICT		21105-2-03 1461	MTH 26-Aug-1992 HRS 2074		O/C	0		
345067	MEMORY MODULE --	ICT		22150-1-03 257	MTH 26-Aug-1992 HRS 2074		O/C	0		
345096	GPS SENSOR ANTENNA --	KCRQ		S67-1575-39 492-43744	MTH 14-Sep-2017 HRS 8282 LDG 5580 ACH 4332.1		O/C	0 0		
345099	GPS RPU --	ICT		10050-6-5M-1110 3179	MTH 09-Jan-1994 HRS 2621		O/C	393		
346007	GPS (TRIMBLE) ANT --	MCO		16248-20 3109877	MTH 12-Nov-1993 HRS 2565		O/C	0		
346010	ARGUS MOVING MAP --	MCO		7000-10-27 71223	MTH 12-Nov-1993 HRS 2565		O/C	0		
346093 NO. 2	GPS ANTENNA --	MCO		011-00147-00 60006111	MTH 06-Dec-2004 HRS 5363		O/C	0		
346098	GPS RECEIVER GPS-400	KCRQ		011-00504-10 45900060	MTH 04-Jun-2013 HRS 7845.6 LDG 5284		O/C			
347007 BOTTOM	TAS ANTENNA	MCO		071-01599-0100 09224	MTH 06-Dec-2004 HRS 5363		O/C	0		
347007 TOP	TAS ANTENNA	MCO		071-01599-0100 010777	MTH 06-Dec-2004 HRS 5363		O/C	0		
347009	MULTI-FUNCTIN DISPLAY --	MCO		066-01178-2101 1179	MTH 06-Dec-2004 HRS 5363		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
351001	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 W16730H	MTH 22-Nov-1986		O/C	0		
351004 LEFT	CREW OXYGEN MASK 9914067-41	KCRQ		MC10-15-109 57795	MTH 16-Mar-2017 HRS 8203.3 LDG 5536 ACH 4258.7		72	4	30-Nov-2022	38 m 25 d
351004 RIGHT	CREW OXYGEN MASK	KCRQ		MC10-15-109 14836	MTH 04-Jun-2013 HRS 7845.6 LDG 5284		O/C	3 0		
351005	OXYGEN REGULATOR	AZO		172170-01 677	MTH 08-Aug-1989 HRS 1111		O/C	0		
351006	OXYGEN CYLINDER ASSEMBLY ZC369-64			176176-64 633812	MTH 10-Jun-2010 HRS 7113 LDG 4713		288	146	30-Apr-2022	31 m 25 d
361003	PNEUMATIC REGULATOR 9912043-2	*CF		38E85-5C RF1424	MTH 22-Nov-1986		O/C			
361005 RIGHT	GYRO PRESSURE GAGE	*CF		C668515-0101 W15992H	MTH 22-Nov-1986		O/C			
361006 BOTTOM	FORWARD INST BA PRESS REGULATOR	GSO		3H64-4 SN-UNKNOWN	MTH 31-Oct-1997 HRS 3811		O/C	0		
361006 TOP	FORWARD INST BA PRESS REGULATOR	*CF		3H64-4 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
361007	PRESSURE DOOR SEAL HOSE	*CF		CM2939-4-15 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
383002	TOILET PUMP	ICT		17000-382 3624	MTH 19-Aug-1991 HRS 1935		O/C	0		
521001	CABIN DOOR SEAL 9912075-4	MCO		S15501-4 SN-UNKNOWN	MTH 06-Dec-2004 HRS 5363		O/C	0		
526001	CABIN DOOR STEP 6519009	*CF		6519009-44 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
561001 LEFT	MAIN WINDSHIELD ASSY, (LH) 9912064-11	MCO		E149000-9 6267	MTH 08-Feb-2001 HRS 4477		O/C	0		
561002 RIGHT	MAIN WINDSHIELD ASSY, (LH)	KGJT		9912064-16 2702	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C	0 0		
561003	FOUL WEATHER WINDOW	CRQ		5511275-17 IJ01-01	MTH 20-May-2016 HRS 8063.2 LDG 5447		O/C	0 0		
561005 LEFT INBOARD	FLIGHT COMPARTMENT WINDOW	*CF		5511285-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
561005 LEFT OUTBOARD	FLIGHT COMPARTMENT WINDOW	*CF		5511285-3 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
561005 RIGHT INBOARD	FLIGHT COMPARTMENT WINDOW	GYH		5511285-6 62406	MTH 21-Dec-2006 HRS 5918		O/C	0		
561005 RIGHT OUTBOARD	FLIGHT COMPARTMENT WINDOW	KGJT		PAS5511285-78 18964	MTH 26-Mar-2014 HRS 7917.9 LDG 5340		O/C	0 0		
562001 LEFT NO. 1	CABIN WINDOW	*CF		5591005-6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
562001 LEFT NO. 2	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 LEFT NO. 3	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 LEFT NO. 4	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 LEFT NO. 5	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 LEFT NO. 6	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 1	CABIN EMERGENCY DOOR WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 2	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 3	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 4	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 5	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
562001 RIGHT NO. 6	CABIN WINDOW 5591005-5	*CF		5591005-5 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
575001 LEFT INBOARD	FLAP --	ICT		6525130-21 89C	MTH 24-Jan-1992 HRS 1994		O/C	0		
575003 RIGHT INBOARD	FLAP --	ICT		6525130-22 85C	MTH 24-Jan-1992 HRS 1994		O/C	0		
712001 LEFT	AFT ENGINE ISOLATOR 9912455-2	GYH		LM420SA6 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		3500	0	9447	1054.53
712001 RIGHT	AFT ENGINE ISOLATOR 9912172-7	KCRQ		LM420SA23 NSN	MTH 28-Oct-2010 HRS 7278.1 LDG 4824		3500	0	10778.1	2385.63
712002 LEFT BOTTOM	FWD ENGINE ISOLATOR 9912172-9	GYH		LM420SA31 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		3500	0	9447	1054.53
712002 LEFT TOP	FWD ENGINE ISOLATOR 9912172-8	GYH		LM420SA30 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		3500	0	9447	1054.53
712002 RIGHT BOTTOM	FWD ENGINE ISOLATOR 9912172-9	KCRQ		LM420SA31 NSN	MTH 28-Oct-2010 HRS 7278.1 LDG 4824		3500	0	10778.1	2385.63
712002 RIGHT TOP	FWD ENGINE ISOLATOR 9912172-8	KCRQ		LM420SA30 NSN	MTH 28-Oct-2010 HRS 7278.1 LDG 4824		3500	0	10778.1	2385.63
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE 3018700			JT15D-4B 102257	MTH 25-Jan-2007 HRS 5947		E/C	0		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE 3018700	KCRQ		JT15D-4B 102227	MTH 29-Oct-2010 HRS 7278.1 LDG 4824		E/C	7056		
722001 E1	OIL PUMP	GYH		3104289-06 OPO951	MTH 25-Jan-2007 HRS 5947		O/C	0		
722001 E2	OIL PUMP	PRI		3104267-01 1L704	MTH 16-Jan-1997 HRS 3596		O/C	0		
723001 E1	ENGINE FAN --	GYH		3018020 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		O/C	3479		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
723001 E2	ENGINE FAN --	PRI		3018020 SN-UNKNOWN	MTH 16-Jan-1997 HRS 3596		O/C	0		
723010 E1	CENTRIFUGAL IMPELLER	GYH		3032899 8B491	MTH 25-Jan-2007 HRS 5947 LDG 3892		8200	3865	(8200)8227	2567
723010 E2	CENTRIFUGAL IMPELLER			3035865 5C395	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		8200	7056 4664	(8200)8353	2693
723020 E1	LOW PRESSURE BOOST COMPRESSOR HUB	GYH		3021112 2R128	MTH 25-Jan-2007 HRS 5947 LDG 3892		14000	3865	(14000)14027	8367
723020 E2	LOW PRESSURE BOOST COMPRESSOR HUB			3021112 8P772	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		14000	7056 4664	(14000)14153	8493
723030 E1	LOW PRESSURE COMPRESSOR HUB	GYH		3018018 9R675	MTH 25-Jan-2007 HRS 5947 LDG 3892		13750	3865	(13750)13777	8117
723030 E2	LOW PRESSURE COMPRESSOR HUB			3018018 3R913	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		13750	7056 9328	(9086)9239	3579
725010 E1	HIGH PRESSURE TURBINE ROTOR DISK	GYH		3023411 2F855	MTH 25-Jan-2007 HRS 5947 LDG 3892		14000	3865	(14000)14027	8367
725010 E2	HIGH PRESSURE TURBINE ROTOR DISK			3023411 A001HYF8	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		14000	0 0	(18664)18817	13157
725020 E1	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK	GYH		3022212 3M240	MTH 25-Jan-2007 HRS 5947 LDG 3892		14000	3865	(14000)14027	8367
725020 E2	SECOND STAGE LOW PRESSURE TURBINE ROTOR DISK	PRI		3022212 6R646	MTH 16-Jan-1997 HRS 3596 LDG 2365		14000	2365	(13948)14000	8340
725030 E1	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK	GYH		3036113 8R188	MTH 25-Jan-2007 HRS 5947 LDG 3892		14000	3865	(14000)14027	8367
725030 E2	THIRD STAGE LOW PRESSURE TURBINE ROTOR DISK			3036113 8R181	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		14000	7056 4664	(14000)14153	8493
725071 E1	COMBUSTION LINER	GYH		3105143-01 8C477	MTH 25-Jan-2007 HRS 5947		O/C	3479		
725071 E2	COMBUSTION LINER	PRI		3105143-01 8C413	MTH 16-Jan-1997 HRS 3596		O/C	0		
731004 LEFT	LOW FUEL PRESSURE SWITCH 9912033-1	*CF		1103P92 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
731004 RIGHT	LOW FUEL PRESSURE SWITCH 9912033-2	GSO		1103P0448 3687	MTH 10-Jun-1999 HRS 4139		O/C	0		
732002	ENGINE SYNC CONTROL 5560001	GSO		213787 2341229 //J	MTH 09-Mar-2007 HRS 5986		O/C	0		
732003	ENGINE SYNC ACTUATOR SDF			5485-066 1043837	MTH 25-Apr-2002 HRS 4745		O/C	0		
733002	FUEL FLOW INDICATOR 9912147-16	ICT		VSDL-OC208E 383	MTH 12-Dec-1986 HRS 3		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
731010 E1	FUEL PUMP 3031632	GYH		025493-402-05 2874	MTH 25-Jan-2007 HRS 5947		O/C	0		
731010 E2	FUEL PUMP 3031632			025493-402-05 2975	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		
731020 E1	FUEL-OIL COOLER 3015303	GYH		UA530768-4 2827	MTH 25-Jan-2007 HRS 5947		O/C	0		
731020 E2	FUEL-OIL COOLER			UA560768-4 3279	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		
731030 E1	MOTIVE FLOW VALVE 3017930	GYH		2524995 A70503	MTH 25-Jan-2007 HRS 5947		O/C	0		
731030 E2	MOTIVE FLOW VALVE 3017930			2524995-1 A90627	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		
731040 E1	FLOW DIVIDER VALVE 3024476	GYH		25607-2 2910	MTH 25-Jan-2007 HRS 5947		O/C	0		
731040 E2	FLOW DIVIDER VALVE 3024476			25607-2 3316	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		
732004 E1	SOLENOID FUEL VALVE 3029591	GYH		3244758-1 93J129	MTH 25-Jan-2007 HRS 5947		O/C	0		
732004 E2	SOLENOID FUEL VALVE 3029591	PRI		3244758-1 SN-UNKNOWN	MTH 16-Jan-1997 HRS 3596		O/C	0		
732010 E1	FUEL CONTROL UNIT 3030251	GYH		3244759-3 A58622	MTH 25-Jan-2007 HRS 5947		O/C	0		
732010 E2	FUEL CONTROL UNIT 3030251			3244759-3 A92585	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 3519 0		
733010 E1	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 1015A	MTH 12-Dec-1986		O/C			
733010 E2	FUEL FLOW TRANSMITTER 9912031-6			3268014-0201 847A	MTH 12-Dec-1986		O/C			
741010 E1 LOWER	IGNITION EXCITER 3041641-01	GYH		9049770-3 NNA06465140	MTH 25-Jan-2007 HRS 5947		O/C	0		
741010 E2 LOWER	IGNITION EXCITER	PRI		NB01201 R7153	MTH 16-Jan-1997 HRS 3596		O/C	0		
741015 E1 UPPER	IGNITION EXCITER 3041641-01	GYH		9049770-3 NNA06465140	MTH 25-Jan-2007 HRS 5947		O/C	0		
741015 E2 UPPER	IGNITION EXCITER 3033378	PRI		NB01201 K8974	MTH 16-Jan-1997 HRS 3596		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
742010 E1 OUTBOARD	IGNITER PLUG	KCRQ		FHE-246-4 NSN	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		O/C	0 0		
742010 E2 OUTBOARD	IGNITER PLUG	KCRQ		FHE-246-4 SN-UNKNOWN	MTH 29-Aug-2012 HRS 7699.2 LDG 5162		O/C	0 0 0		
742020 E1 INBOARD	IGNITER PLUG 3030595	CRQ		FHE-246-4 SN-UNKNOWN	MTH 04-Mar-2016 HRS 8053.8 LDG 5441		O/C	0 0		
742020 E2 INBOARD	IGNITER PLUG 3030595	KCRQ		FHE-246-4 N/A	MTH 16-Aug-2018 HRS 8346.17		O/C	0 0		
742030 E1 SHORT	IGNITER LEAD	GYH		53067-21 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		O/C		2923	
742030 E2 SHORT	IGNITER LEAD	MCO		53067-21 SN-UNKNOWN	MTH 02-Nov-2003 HRS 5039		O/C	0		
742040 E1 LONG	IGNITER LEAD	GYH		53067-38.5 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		O/C	534		
742040 E2 LONG	IGNITER LEAD	PRI		53067-38.5 SN-UNKNOWN	MTH 16-Jan-1997 HRS 3596		O/C	0		
750010 E1	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531	GYH		KW15632 3614	MTH 25-Jan-2007 HRS 5947		O/C	0		
750010 E2	LOW PRESSURE COMPRESSOR ANTI-ICING SOLENOID VALVE 3018531 3097				MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		
761005	SOLENOID ASSEMBLY 9912110-1	*CF		U-183238-001 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
771001 LEFT BOTTOM	TACH N2 GENERATOR 9912034-1	MKE		22A623 34656	MTH 29-Jun-1993 HRS 2487		O/C	2487		
771001 LEFT TOP	TACH N1 GENERATOR 9912034-1	MKE		22A623 34529	MTH 29-Jun-1993 HRS 2487		O/C	2487		
771001 RIGHT BOTTOM	TACH N2 GENERATOR 9912034-1	MKE		22A623 34538	MTH 29-Jun-1993 HRS 2487		O/C	2487		
771001 RIGHT TOP	TACH N1 GENERATOR 9912034-1	MKE		22A623 34541	MTH 29-Jun-1993 HRS 2487		O/C	2487		
771002	N2 TURBINE RPM INDICATOR 9912147-25	SDF		DDL-OC110A 49BAC	MTH 14-Dec-1998 HRS 4069		O/C	548		
771003	N1 FAN RPM INDICATOR 9912147-24	SDF		VSDL-OC410AD 10EA	MTH 09-Aug-2003 HRS 5006		O/C	0		
772003 772001	ITT INDICATOR 9912147-34	GSO		VSDL-OC419L 195AB	MTH 14-Jun-1999 HRS 4139		O/C	0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
781001 LEFT	EXHAUST NOZZLE CONE *CF			9912110-6-S6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
781001 RIGHT	EXHAUST NOZZLE CONE *CF			9912110-6-S6 SN-UNKNOWN	MTH 22-Nov-1986		O/C			
783001 LEFT	THRUST REVERSER ASSEMBLY 9912110-1 *CF			202-0000-1 RC1770	MTH 22-Nov-1986		O/C			
783001 RIGHT	THRUST REVERSER ASSEMBLY 9912110-1 *CF			202-0000-3 RC1767	MTH 22-Nov-1986		O/C			
783002 RIGHT	CONTROL VALVE *CF			65680 851	MTH 22-Nov-1986		O/C			
783003 LEFT	THREE WAY VALVE *CF			13027-4 1696	MTH 22-Nov-1986		O/C			
783003 RIGHT	THREE WAY VALVE *CF			13027-4 1625	MTH 22-Nov-1986		O/C			
783005 LEFT	THRUST REVERSER DOOR 9912110-1 *CF			202-0001-501 RC17662	MTH 22-Nov-1986		O/C			
783005 RIGHT	THRUST REVERSER DOOR 9912110-1 *CF			202-0001-502 RC17671	MTH 22-Nov-1986		O/C			
783006 LEFT	THRUST REVERSER DOOR 9912110-1 *CF			202-0002-501 RC1768	MTH 22-Nov-1986		O/C			
783006 RIGHT	THRUST REVERSER DOOR 9912110-1 *CF			202-0002-502 RC17671	MTH 22-Nov-1986		O/C			
783007 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-1 RC1770	MTH 22-Nov-1986		O/C			
783007 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-1 RC1767	MTH 22-Nov-1986		O/C			
783008 LEFT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-3 RC1770	MTH 22-Nov-1986		O/C			
783008 RIGHT	THRUST REVERSER MECH ASSEMBLY 9912110-1 *CF			202-0004-5 RC1767	MTH 22-Nov-1986		O/C			
783009 LEFT	THRUST REVERSER FAN DUCT 9912110-1 *CF			202-0012-1 RC1770	MTH 22-Nov-1986		O/C			
783009 RIGHT	THRUST REVERSER FAN DUCT 9912110-1 *CF			202-0012-1 RC1767	MTH 22-Nov-1986		O/C			
783010 LEFT INBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1942	MTH 22-Nov-1986		O/C			
783010 LEFT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1944	MTH 22-Nov-1986		O/C			
783010 RIGHT INBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1876	MTH 22-Nov-1986		O/C			
783010 RIGHT OUTBOARD	THRUST REVERSER ACTUATOR 9912110-1 *CF			62270 1951	MTH 22-Nov-1986		O/C			
793001	OIL TEMPERATURE INDICATOR 9912147-11 *CF			VSDL-OC219F 400A	MTH 22-Nov-1986		O/C			
793003	OIL PRESSURE INDICATOR 9912147-10 MCO			VSDL-OC204H 300FA	MTH 02-Nov-2003 HRS 5039		O/C	0		
793004 LEFT	OIL PRESSURE TRANSMITTER 9912164-1 AZO			123479 38552	MTH 02-Mar-1990 HRS 1358		O/C	0		
793004 RIGHT	OIL PRESSURE TRANSMITTER 9912164-1 *CF			123479 38194	MTH 22-Nov-1986		O/C			
792003 E1	OIL FILTER GYH			3111843-01 SN-UNKNOWN	MTH 25-Jan-2007 HRS 5947		O/C	534		
792003 E2	OIL FILTER			PN SN-UNKNOWN	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		O/C	0 0 0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Components

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
832001 E1	MAIN GEAR BOX ASSY -- GYH	3018390 SN-UNKNOWN	MTH HRS	25-Jan-2007 5947		O/C		3479		
832001 E2	MAIN GEAR BOX ASSY -- PRI	3023370 SN-UNKNOWN	MTH HRS	16-Jan-1997 3596		O/C		0		



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-03-01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-03 R01	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			RECOMMENDED			-			
	MOC :									
SL CIL-99-03	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP) (SUPERSEDED BY CIL-99-03 R01)			RECOMMENDED MTH			-			
	MOC :									
SL S550-01-02 <i>01SL-02</i>	CORRECTION TO INSTALLED EQUIPMENT LIST	DPA		RECOMMENDED	MTH 24-Feb-1989 HRS 903		A/R			Complete
	MOC : COMPLIED WITH									
SL S550-03-02 R01	CERTIFICATION REQUIREMENTS - SUPPLEMENTAL TYPE CERTIFICATE (STC) (THIS SL IS REPLACED BY CIL-03-01, DATED JUNE 3, 2013)			INFORMATIONAL			-			
	MOC :									
SL S550-99-04 R07	CESCOM PRICES (THIS SL IS CANCELS SLS550-99-04 R6 AND PREVIOUS)			INFORMATIONAL			-			
	MOC :									
SL S550-99-07	MISCELLANEOUS - CESSNA PART NUMBER SUFFIXES FOR REMANUFACTURED PARTS			INFORMATIONAL			A/R			
	MOC :									
SL S550-99-08	MISCELLANEOUS - CESSNA SERVICE DOCUMENT CHANGE NOTIFICATION			INFORMATIONAL			A/R			
	MOC :									
SL CIL-99-04	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			INFORMATIONAL			-			
	MOC :									
SB S550-11-03 <i>11SB-03</i>	SEAT PLACARD INSTALLATIONS AND EMERGENCY EXIT HANDLE GUARD DECAL REPLACEMENT (SUPERSEDED BY S550-11-03 R01)	AZO		MANDATORY	MTH 13-Aug-1987 HRS 302		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-11-04 <i>11SB-04</i>	AIRSPED LIMITATIONS PLACARD REPLACEMENT	AZO		MANDATORY	MTH 28-Sep-1988 HRS 748		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-11-05 <i>11SB-05</i>	FLAP NO STEP PLACARD INSTALLATION	MCO		RECOMMENDED	MTH 14-Jul-1995 HRS 3149		A/R			Complete
	MOC : COMPLIED WITH									
SB S550-11-06 <i>11SB-06</i>	FIRE EXTINGUISHER PLACARD INSTALLATION	CRQ		OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-11-01 <i>11SL-01</i>	DATA PLATE RELOCATION	CRQ		OPTIONAL	MTH		A/R			
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL CIL-99-01 R01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R02)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-01 R02	USE OF CORROSION INHIBITING COMPOUNDS			INFORMATIONAL			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL CIL-99-01	USE OF CORROSION INHIBITING COMPOUNDS (SUPERSEDED BY CIL-99-01 R01)			INFORMATIONAL			-			
	MOC :									
SL CIL-99-02	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			MTH RECOMMENDED			-			
	MOC :									
SL CIL-20-01 R02	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL			INFORMATIONAL			-			
	MOC :									
SL CIL-20-01	STANDARD PRACTICES - CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY CIL-20-01 R01)			INFORMATIONAL			-			
	MOC :									
SL S550-20-01 R27	CESSNA CERTIFICATION OF NONDESTRUCTIVE TESTING FACILITIES/PERSONNEL (SUPERSEDED BY SLS550-20-01 R28)			INFORMATIONAL			A/R			
	MOC :									
SL S550-20-04	STANDARD PRACTICES - CESSNA STANDARD PRACTICES MANUAL			INFORMATIONAL			-			
	MOC :									
SL CIL-21-01	COMPRESSOR MOTOR BRUSH LIFE LIMIT			INFORMATIONAL			-			
	MOC :									
SL CIL-21-02 R01	ENVIRONMENTAL HOUR METER INSTALLATION			CRQ MANDATORY	MTH 05-Aug-2015 HRS 7996.3 LDG 5395		-			N/A
	MOC : NOT APPLICABLE - DOES NOT APPLY TO THIS AIRCRAFT, PLEASE REMOVE FROM TRACKING.									
SB S550-21-03 R01	FREON AIR CONDITIONING SYSTEM INSTALLATION - CANCELLED			CRQ CANCELLED	MTH			A/R		
<i>21SB-03 : S55R1</i>										
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-05	SUPPLEMENTAL COCKPIT AIR DISTRIBUTION SYSTEM			CRQ OPTIONAL	MTH			A/R		
<i>21SB-05</i>										
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-08	TAILCONE RAM AIR INLET PRESSURIZATION VALVE INSTALLATION			AZO OPTIONAL	MTH 28-Nov-1988 HRS 807			A/R		Complete
<i>21SB-08</i>										
	MOC : COMPLIED WITH									
SB S550-21-09 R02	TAILCONE FRESH AIR DUCT MODIFICATION (SUPERSEDED BY S550-21-09 R03)			CRQ OPTIONAL	MTH			A/R		
<i>21SB-09 : S55R2</i>										
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-10 R01	AIR DUCT RETENTION IMPROVEMENT (SUPERSEDED BY S550-21-10 R02)			MKE RECOMMENDED	MTH 23-Oct-1992 HRS 2145			A/R		Complete
<i>21SB-10 : S55R1</i>										
	MOC : COMPLIED WITH									
SB S550-21-10	AIR DUCT RETENTION IMPROVEMENT (SUPERSEDED BY S550-21-10 R01)			AZO RECOMMENDED	MTH 30-Nov-1990 HRS 1650			A/R		Complete
<i>21SB-10</i>										
	MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-21-11 21SB-11	ACM BLEED AIR DUCT SUPPORT CLAMP INSTALLATION			MTH			A/R			
	CRQ			OPTIONAL						
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-12 21SB-12	TAILCONE PRESSURE VALVE ACTUATOR WIRING MODIFICATION			MTH			A/R			
	CRQ			OPTIONAL						
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-14 21SB-14	ADDITIONAL OUTFLOW VALVE REPLACEMENTS			MTH	03-Mar-1995		A/R			Complete
	MCO			MANDATORY	HRS 3052					
	MOC : COMPLIED WITH									
SB S550-21-15 21SB-15	AIR CONDITIONING - COCKPIT SIDE WINDOW DEFOG SYSTEM MODIFICATION			MTH			A/R			
	CRQ			OPTIONAL						
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-16 21SB-16	CABIN FAN AND DEFOG BLOWER WIRING IMPROVEMENT			MTH			A/R			
	CRQ			DISCRETIONARY						
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-21-17	AIR CONDITIONING - TEMPERATURE CONTROLLER IMPROVEMENT									
				OPTIONAL			A/R			
	MOC :									
SL S550-21-02 21SL-02	TAILCONE FRESH AIR DUCT ROUTING INSPECTION			MTH	30-Oct-1992		A/R			Complete
	MKE			RECOMMENDED	HRS 2155					
	MOC : COMPLIED WITH									
SL S550-21-05 21SL-05	AIR CONDITIONING - TRANSMITTAL OF FORT WORTH AIRWORKS, INC. SERVICE BULLETIN 99-101, EVAPORATOR MODULE INSTALLATION 1250240 AND 1134240 SERIES.			MTH	15-Aug-2000		A/R			Complete
	GSO			RECOMMENDED	HRS 4418					
	MOC : COMPLIED WITH									
SB S550-23-04 23SB-04	COCKPIT VOICE RECORDER INSTALLATION (FAIRCHILD GA100)			MTH	19-Aug-1991		A/R			Complete
	ICT			OPTIONAL	HRS 1935					
	MOC : COMPLIED WITH									
SB S550-23-05 R03 23SB-05 : S55R3	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS			MTH			A/R			
				RECOMMENDED						
	OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
	MOC :									
SB S550-23-05 23SB-05	ELECTRICAL BONDING FLAP AND SPEED BRAKE PUSHRODS (SUPERSEDED BY S550-23-05 R01)			MTH	16-Apr-1993		A/R			Complete
	MKE			RECOMMENDED	HRS 2418					
	MOC : COMPLIED WITH									
SB S550-23-07 23SB-07	STATIC WICK REPLACEMENT			MTH	12-Apr-2005		A/R			Complete
	SDF			OPTIONAL	HRS 5512					
	MOC : COMPLIED WITH									
SB S550-23-08 R01 23SB-08 : S55R1	COLLINS 8.33 KHZ COMMUNICATION RADIO INSTALLATION			MTH			A/R			
	CRQ			OPTIONAL						
	MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-23-09 23SB-09	VLF NOISE FILTER CAPACITOR REMOVAL/REPLACEMENT (SUPERSEDED BY S550-23-09 R01)	GSO	MANDATORY	MTH 15-Aug-2000 HRS 4418		A/R			Complete
MOC : COMPLIED WITH									
SL S550-23-01 23SL-01	MICROPHONE REPLACEMENT PROGRAM	DPA	RECOMMENDED	MTH 29-Sep-1988 HRS 749		A/R			Complete
MOC : COMPLIED WITH									
SL S550-23-02 23SL-02	STATIC DISCHARGE WICK MODIFICATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-23-14 23SL-14	COMMUNICATIONS - AIRSHOW RELIABILITY IMPROVEMENTS AND SERVICE PACK SOFTWARE UPGRADE	SCF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-24-11 24SB-11	RIGHT PYLON WIRE BUNDLE PROTECTION	AZO	MANDATORY	MTH 02-Mar-1990 HRS 1358		A/R			Complete
MOC : COMPLIED WITH									
SB S550-24-12 24SB-12	CONTROL WHEEL ELECTRICAL CABLE REPLACEMENT (SUPERSEDED BY S550-24-12 R01)	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-24-14 R01 24SB-14 : S55R1	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION	MKE	RECOMMENDED	MTH 30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH									
SB S550-24-14 24SB-14	MAIN LANDING GEAR AXLE ANTISKID WIRE BUNDLE PROTECTION (SUPERSEDED BY S550-24-14 R01)	MKE	RECOMMENDED	MTH 30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH									
SB S550-24-15 24SB-15	WING WIRE BUNDLE ROUTING MODIFICATION	SCF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-24-17 24SB-17	AVIONICS POWER RELAYS REPLACEMENT	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-24-18 24SB-18	WING TIP WIRE BUNDLE PROTECTIVE COVER INSTALLATION	*CF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-24-19 R01 24SB-19 : S55R1	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-24-19 24SB-19	ELECTRICAL CABLE CHAFING PROTECTION INSTALLATION W.S. 44.0 AND W.S. 54.07 (SUPERSEDED BY S550-24-19 R01)			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-24-21 R01 24SB-21 : S55R1	OVERVOLTAGE MONITOR SYSTEM INSTALLATION			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-24-22 24SB-22	BATTERY DISCONNECT RELAY ACCESS IMPROVEMENT			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-24-23 R01 24SB-23 : S55R1	MAIN POWER WIRE ANCHOR IMPROVEMENT	CRQ		RECOMMENDED	MTH HRS 6006	18-May-2007	A/R			Complete
MOC : COMPLIED WITH										
SB S550-24-24	ELECTRICAL POWER - MAGNETIC CIRCUIT BREAKER REPLACEMENT			OPTIONAL			A/R			
MOC :										
SL S550-24-01 R01 24SL-01 : S55R1	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	AZO		RECOMMENDED	MTH HRS 748	28-Sep-1988	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-01 24SL-01	TAILCONE WIRE BUNDLE REROUTING AND CLAMPING	TOL		RECOMMENDED	MTH HRS 485	28-Jan-1988	A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-24-02A 24SLA02	PILOT ADVISORY, AC POWER INVERTER FAILURES (SUPERSEDED BY SLS550-24-02A R01)	DPA		MANDATORY	MTH HRS 251	15-Jun-1987	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-03 24SL-03	REPLACEMENT OF SPC38B INVERTERS	DPA		RECOMMENDED	MTH HRS 749	29-Sep-1988	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-04 24SL-04	KGS SPC38B INVERTER UPDATE	AZO		MANDATORY	MTH HRS 926	16-Mar-1989	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-06 24SL-06	500 HOUR MID-LIFE BEARING CHANGE FOR 9912125-1 (23085-004 AND 23085-004 MOD A) STARTER GENERATORS	AZO		RECOMMENDED	MTH HRS 1209	14-Nov-1989	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-07 24SL-07	COCKPIT CIRCUIT BREAKER INSPECTION/REPLACEMENT	AZO		RECOMMENDED	MTH HRS 1650	30-Nov-1990	A/R			Complete
MOC : COMPLIED WITH										
SL S550-24-08 24SL-08	DELETE THE 500 HOUR MID-LIFE BEARING CHANGE REQUIREMENT FOR THE 9912125-1 (23085-004 MOD A) STARTER/GENERATOR	AZO		RECOMMENDED	MTH HRS 1808	27-Mar-1991	A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-24-10 24SL-10	ANTI-ICE RELAY BASE ORIENTATION INSPECTION/MODIFICATION (SUPERSEDED BY SLS550-24-10 R01)	MKE		RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-09 25SB-09	CREW SEAT BACK MODIFICATION			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
ASB S550-25-16A 25SBA16	INTERIOR CABINTRY ELECTRICAL POWER SOURCE DISABLEMENT	DPH		MANDATORY	MTH 07-Feb-1987 HRS 59		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-18 25SB-18	PASSENGER SEAT ARMREST RELEASE LEVER REPLACEMENT	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-25-20 25SB-20	FORWARD REFRESHMENT CENTER OVERBOARD DRAIN RELOCATION (SUPERSEDED BY S550-25-20 R01)	AZO		RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SB S550-25-21 25SB-21	CREW SEAT PAN REPLACEMENT	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-25-29 R02 25SB-29 : S55R2	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT) (SUPERSEDED BY S550-25-29 R03)			OPTIONAL			A/R			
MOC : - SERVICE BULLETIN ON HOLD.										
SB S550-25-29 R03 25SB-29 : S55R2	ARTEX C406-2 THREE-FREQUENCY EMERGENCY LOCATOR TRANSMITTER (ELT)			OPTIONAL			A/R			
MOC :										
SB S550-25-30 R01 25SB-30 : S55R1	GLARESHIELD LEATHER STRIP INSTALLATION	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL S550-25-02 R04 25SL-02 : S55R4	INTERIOR CABINTRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION	AZO		MANDATORY	MTH 28-Nov-1988 HRS 807		A/R			Complete
MOC : COMPLIED WITH										
SL S550-25-02 25SL-02	INTERIOR CABINTRY WIRING AND ELECTRICAL COMPONENT INSPECTION AND MODIFICATION (SUPERSEDED BY SLS550-25-02 R01)	SDF		MANDATORY	MTH 10-Oct-1997 HRS 3770		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL S550-25-04 25SL-04	SWITLIK INFLATABLE LIFE PRESERVER INSPECTION	DPA		INFORMATIONAL	MTH 29-Sep-1988 HRS 749		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-25-07 25SL-07	TRANSMITTAL OF EASTERN AERO MARINE SERVICE BULLETIN SBV-25-2, EQUIPMENT/FURNISHINGS - LIFE PRESERVERS AND INDIVIDUAL FLOTATION DEVICES REPLACEMENT OF CO2 INFLATOR - MANDATORY	GSO	MANDATORY	MTH 31-Oct-1997 HRS 3811		A/R			Complete
MOC : COMPLIED WITH									
SL S550-25-08 25SL-08	EQUIPMENT/FURNISHINGS - GLARESHIELD ATTACHMENT SCREW(S) INSPECTION/REPLACEMENT	MCO	RECOMMENDED	MTH 10-Apr-2002 HRS 4735		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING	KCRQ	MANDATORY	MTH 29-May-2019 HRS 8392 LDG 5651		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH SL CIL-26-01 R01 FIRE EXTINGUISHER BOTTLE GROUND STUD TORQUE. NO FAULT FOUND.									
SL CIL-26-01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING (SUPERSEDED BY CIL-26-01 R01)		MANDATORY	MTH		-			
MOC :									
SB S550-26-02 26SB-02	FIRE BOTTLE WIRE IDENTIFICATION SLEEVE INSTALLATION	GYH	MANDATORY	MTH 20-Dec-2005 HRS 5678		A/R			Complete
MOC : COMPLIED WITH									
ASL SLS550-26-01A 26ASL01	TRANSMITTAL OF MEGGITT SAFETY SYSTEMS SERVICE BULLETIN 26-36 -THERMISTORS DETECTORS	CRQ	MANDATORY	MTH 28-Sep-2007 HRS 6157		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT SERIAL NUMBER.									
SB S550-27-04 27SB-04	TRIM TAB ACTUATOR INSPECTION AND LUBRICATION (SUPERSEDED BY S550-27-04 R01)	AZO	RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH									
SB S550-27-05 27SB-05	RUDDER TRIM WHEEL BEARING INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-05 R01)	AZO	RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH									
SB S550-27-06 27SB-06	EXTENDED PEDESTAL AILERON PULLEY BRACKET MODIFICATION (SUPERSEDED BY S550-27-06 R01)	FCT	RECOMMENDED	MTH 27-Oct-1991 HRS 1976		A/R			Complete
MOC : COMPLIED WITH									
SB S550-27-07 R01 27SB-07 : S55R1	AILERON CONTROL QUADRANT BOLT INSPECTION/REPLACEMENT (SUPERSEDED BY S550-27-07 R02)	ICT	MANDATORY	MTH 26-Aug-1992 HRS 2074		A/R			Complete
MOC : COMPLIED WITH									
SB S550-27-08 27SB-08	AILERON/RUDDER INTERCONNECT CLAMP MODIFICATION	GSO	RECOMMENDED	MTH 15-Aug-2000 HRS 4418		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-27-09 27SB-09	FLIGHT CONTROLS - TRIM TAB ACTUATOR GREASE FITTING INSTALLATION	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-27-05 27SL-05	FLAP/ELEVATOR TRIM MIXER ACTUATOR ASSEMBLY INSPECTION/REPLACEMENT	MKE	RECOMMENDED MTH	23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH									
SL S550-27-07 R01 27SL-07 : S55R1	RUDDER/AILERON INTERCONNECT BOLT INSPECTION	GSO	MANDATORY MTH	10-Jun-1999 HRS 4139		A/R			Complete
MOC : COMPLIED WITH									
SL S550-27-08 27SL-08	RUDDER PEDAL SUPPORT INSPECTION	KGJT	RECOMMENDED MTH	26-Mar-2014 HRS 7917.9 LDG 5340		A/R			Complete
MOC : COMPLIED WITH - COMPLIED WITH SERVICE LETTER SL S550-27-08 RUDDER PEDAL SUPPORT INSPECTION. ALL WORK PERFORMED IAW CESSNA S550 SERVICE LETTER SL S550-27-08.									
SB S550-28-03 28SB-03	WING LEADING EDGE RIB FLAPPER VALVES INSTALLATION	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-28-04 28SB-04	MOTIVE FLOW FUEL LINE INSPECTION AND SUPPORT INSTALLATION		RECOMMENDED MTH			A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-28-05 28SB-05	FUEL SYSTEM PLUMBING CLAMP ADDITIONS		RECOMMENDED MTH			150			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-28-06 28SB-06	IMPROVED FUEL CROSSFEED SELECT KNOB AVAILABILITY	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-28-07 28SB-07	FUEL LINE SUPPORT INSTALLATION		RECOMMENDED MTH			A/R			
MOC :									
SB S550-28-08 28SB-08	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	MCO	MANDATORY MTH	06-Dec-2004 HRS 5363		A/R			Complete
MOC : COMPLIED WITH									
SB S550-28-09 R01 28SB-09	FUEL - FUEL CHECK VALVE MODIFICATION		RECOMMENDED MTH			A/R			
MOC :									
SB S550-28-09 28SB-09	FUEL CHECK VALVE MODIFICATION (SUPERSEDED BY S550-28-09 R01)		RECOMMENDED MTH		12	A/R			
OPERATOR CHOOSES TO PERFORM AT NEXT PHASE 5.									
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-28-01 R01 28SL-01 : S55R1	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION (SUPERSEDED BY SLS550-28-01 R02)	MKE	RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH									
SL S550-28-01 R03 28SL-01 : S55R3	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION	MCO	RECOMMENDED	MTH 10-Apr-2002 HRS 4735		A/R			Complete
MOC : COMPLIED WITH									
SL S550-28-01 28SL-01	FUEL QUANTITY COMPENSATOR INSTALLATION ATTACHMENT INSPECTION (SUPERSEDED BY SLS550-28-01 R01)	MKE	RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH									
ASL SLS550-28-03A 28SLA03	TRANSMITTAL OF PARKER HANNIFIN CORPORATION -AIRBORNE AIR & FUEL PRODUCTS SERVICE LETTER NO. 41, RAPCO FLEET SUPPORT INC. OVERHAUL OF AIRBORNE FUEL PUMPS (SUPERSEDED BY SLS550-28-03A R01)	SDF	MANDATORY	MTH 10-Oct-1997 HRS 3770		A/R			Complete
MOC : COMPLIED WITH									
SB S550-29-01 29SB-01	ECOLOGY (OVERFLOW) BOTTLE INSTALLATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-29-02 29SL-02	HYDRAULIC LINE INSPECTION (SUPERSEDED BY SLS550-29-02 R01)	AZO	RECOMMENDED	MTH 10-Jul-1990 HRS 1498		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-30-01 R01	ICE AND RAIN PROTECTION - APPROVED DEICING PROGRAM UPDATES		INFORMATIONAL			-			
MOC :									
SB S550-30-11 30SB-11	ICE DETECTOR REPLACEMENT (SUPERSEDED BY S550-30-11 R01)	AZO	RECOMMENDED	MTH 28-Sep-1988 HRS 748		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-13 30SB-13	WING WIRE BUNDLE ROUTING MODIFICATION	AZO	RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-14 30SB-14	FLUID ANTI-ICE SYSTEM WING CUFF AND FAIRING PANELS INSPECTION AND PURGE CYCLE MODIFICATION (SUPERSEDED BY S550-30-14 R01)	AZO	MANDATORY	MTH 19-Jun-1991 HRS 1926		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-15 30SB-15	ANTI-ICE SYSTEM IMPROVEMENT	ICT	RECOMMENDED	MTH 19-Aug-1991 HRS 1935		A/R			Complete
MOC : COMPLIED WITH									
SB S550-30-16 30SB-16	ICE DETECTOR TEST CYCLE TIME DELAY MODIFICATION (SUPERSEDED BY S550-30-16 R01)		RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-30-17 30SB-17	WINDSHIELD BLEED AIR ORIFICE INSPECTION/REMOVAL (SUPERSEDED BY S550-30-17 R01)	ICT		MANDATORY	MTH 19-Aug-1991 HRS 1935		A/R			Complete
MOC : COMPLIED WITH										
SB S550-30-18 30SB-18	TKS AUXILIARY TANK SEALER REMOVAL	MKE		RECOMMENDED	MTH 16-Apr-1993 HRS 2418		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-31-01	INDICATING/RECORDING SYSTEMS - CVR, FDR, AND CVDR 90-DAY BATTERY UNDERWATER LOCATOR BEACON (ULB) INSTALLATION			INFORMATIONAL			-			
MOC :										
SL CIL-32-01	LANDING GEAR - IMPROVED NOSE WHEEL GREASE SEAL			INFORMATIONAL			-			
MOC :										
SL CIL-32-03	NLG UPLOCK ROLLER BRACKET INSPECTION	KGJT		RECOMMENDED	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		-			Complete
MOC : COMPLIED WITH - COMPLIED WITH CESSNA INFORMATION LETTER CIL-32-03 NOSE LANDING GEAR UPLOCK ROLLER BRACKET INSPECTION. INSPECTED UPLOCK ROLLER BRACKET AND VERIFIED CORRECT INSTALLATION. NO FURTHER ACTION TAKEN. ALL WORK PERFORMED IAW CESSNA INFORMATION LETTER CIL-32-03, DATED 11/12/2014.										
SL CIL-32-04	WIRELESS TIRE PRESSURE MONITORING SYSTEM INSTALLATION			INFORMATIONAL			-			
MOC :										
SB S550-32-02 R02 32SB-02 : S55R2	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R03)	AZO		RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-02 32SB-02	ANTI-SKID WIRE BUNDLE ROUTING IMPROVEMENT (SUPERSEDED BY S550-32-02 R01)	AZO		RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-03 32SB-03	HYDRAULIC AND PNEUMATIC BRAKE HOSE REPLACEMENT	TOL		RECOMMENDED	MTH 28-Jan-1988 HRS 485		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-04 32SB-04	MAIN LANDING GEAR DOORS REPLACEMENT (IMPROVED SLUSH AND SNOW OPERATION) (SUPERSEDED BY S550-32-04 R01)	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-32-05 R01 32SB-05 : S55R1	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R02)	AZO		MANDATORY	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-05 R02 32SB-05 : S55R2	MAIN LANDING GEAR TORQUE LINK MODIFICATION	AZO		MANDATORY	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-32-05 32SB-05	MAIN LANDING GEAR TORQUE LINK MODIFICATION (SUPERSEDED BY S550-32-05 R01)	AZO		MANDATORY	MTH 26-Oct-1988 HRS 781		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-07 32SB-07	BF GOODRICH BRAKES AND WHEELS INSTALLATION (SUPERSEDED BY S550-32-07 R01)	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-32-08 32SB-08	INCREASED MAXIMUM GEAR EXTEND SPEED	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-32-11 R01 32SB-11	BFGOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT	KCRQ		OPTIONAL	MTH 16-Feb-2017 HRS 8195.5 LDG 5532 ACH 4258.7		A/R			
MOC : DECLINED - OPERATOR DECLINED SB S550-32-11 & SUBSEQUENTLY DECLINED SB S550-32-21.										
SB S550-32-11 32SB-11	BF GOODRICH BRAKE BLEEDER BLOCK INSTALLATION AND HOSE REPLACEMENT (SUPERSEDED BY S550-32-11 R01)	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-32-12 32SB-12	MAIN LANDING GEAR WHEEL WELL AFT SPAR BOX HYDRAULIC/PNEUMATIC LINES GROMMET REPLACEMENT	MKE		RECOMMENDED	MTH 24-Mar-1993 HRS 2392		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-13 32SB-13	ANTISKID DRIVE CLIP REPLACEMENT			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-32-15 32SB-15	POWER BRAKE HYDRAULIC PUMP SCREW REPLACEMENT	GSO		RECOMMENDED	MTH 31-Oct-1997 HRS 3811		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-16 32SB-16	ANTISKID SYSTEM DIODE REMOVAL	GSO		RECOMMENDED	MTH 15-Aug-2000 HRS 4418		A/R			Complete
MOC : COMPLIED WITH										
SB S550-32-18 R02 32SB-18 : S55R2	LANDING GEAR ON GROUND OPERATION MODIFICATION			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-32-19 R01 32SB-19 : S55R1	LANDING GEAR - PARKING BRAKE CABLE REPLACEMENT	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-32-21 R01	REPLACEMENT OF BLEEDER SCREWS AND FITTINGS WITH BLEEDER PLUGS	KGJT	RECOMMENDED	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		-			N/A
MOC : NOT APPLICABLE - CESSNA SERVICE BULLETIN SB S550-32-21 R1, DATED 11/20/2013 IS NOT APPLICABLE DUE TO CURRENT EQUIPMENT INSTALLED. AIRCRAFT IS EQUIPPED WITH CLEVELAND BRAKES. NO FURTHER ACTION TAKEN.									
SL S550-32-02 32SL-02	MAIN LANDING GEAR WHEEL-HALF SEALS FOR COLD WEATHER OPERATION		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-32-05 32SL-05	NOSE GEAR STEERING LOWER JOINT BEARING INSPECTION	AZO	RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-06 32SL-06	CLEVELAND BRAKE INSPECTION	DPH		MTH 07-Mar-1988 HRS 515		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-07 32SL-07	MODIFICATION OF P/N 1523200-3 (CESSNA P/N 9912120) NOSE GEAR ACTUATOR	AZO	RECOMMENDED	MTH 31-Mar-1988 HRS 558		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-09 32SL-09	MAIN LANDING GEAR PISTON AXLE ADAPTER AND AXLE CORROSION INSPECTION, REMOVAL, AND PREVENTION	AZO	RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH									
ASL SLS550-32-10A 32SLA10	INSPECTION OF MAIN LANDING GEAR UPPER AND LOWER TORQUE LINK CONNECTING HARDWARE	DPA	MANDATORY	MTH 04-May-1988 HRS 589		DAILY DAILY DAILY			Complete
MOC : COMPLIED WITH									
SL S550-32-13 32SL-13	MAIN LANDING GEAR AXLE INTERNAL CORROSION INSPECTION	AZO	RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-17 32SL-17	LANDING GEAR EMERGENCY EXTENSION CONTROL ASSEMBLY PIN INSPECTION	AZO	RECOMMENDED	MTH 10-Jul-1990 HRS 1498		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-21 32SL-21	STRUT EXTENSION INSPECTION AND PISTON UPPER BEARING RETENTION IMPROVEMENT (SUPERSEDED BY SLS550-32-21 R01)	MKE	RECOMMENDED	MTH 30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH									
SL S550-32-22 32SL-22	EMERGENCY LANDING GEAR BLOWDOWN BOTTLE LEVER SAFETY WIRE INSPECTION/REPLACEMENT	AZO	RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-24 32SL-24	MAIN LANDING GEAR DRAG BRACE ATTACH NUT REPLACEMENT	AZO		RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-26 32SL-26	NOSE AND MAIN LANDING GEAR UPLOCK SPRING INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-32-26 R01)	AZO		RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-27 32SL-27	ANTI-SKID SYSTEM CONTROL UNIT CALIBRATION VERIFICATION	DPA		RECOMMENDED	MTH 04-Mar-1991 HRS 1772		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-29 32SL-29	NOSE LANDING GEAR UPLOCK LINE INSPECTION	MKE		RECOMMENDED	MTH 30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-30 32SL-30	LANDING GEAR HANDLE LOCKING SOLENOID RIGGING INSPECTION	MKE		RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-34 32SL-34	NOSE GEAR TRUNNION FINISH INSPECTION/REFINISH	MKE		RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-37 32SL-37	BRAKE AND SPOILER/SPEEDBRAKE EXTENDED HYDRAULIC LINE(S) ROUTING INSTPECTION/MODIFICATION	MKE		RECOMMENDED	MTH 30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-40 32SL-40	CLEVELAND SERVICE BULLETIN ESB7028 BRAKE ASSEMBLY BOLT REPLACEMENT	MKE		MANDATORY	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-41 R02 32SL-41 : S55R2	TEIJIN SEIKI MAIN AND NOSE LANDING GEAR ACTUATOR DOWN AND LOCKED SWITCH INSPECTION/ REPLACEMENT (SUPERSEDED BY SLS550-32-41 R03)	MCO		RECOMMENDED	MTH 16-Aug-1994 HRS 2885		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-45 32SL-45	NOSE LANDING GEAR WHEEL AND TIRE ASSEMBLY AND WIDE DOOR ATTACH HARDWARE INSPECTION / REPLACEMENT *KAT UPDATED	MCO		RECOMMENDED	MTH 14-Jul-1995 HRS 3149		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-46 32SL-46	MAIN LANDING GEAR EXTEND PNEUMATIC LINE CLEARANCE INSPECTION (SUPERSEDED BY SLS550-32-46 R01)	MCO		RECOMMENDED	MTH 14-Jul-1995 HRS 3149		A/R			Complete
MOC : COMPLIED WITH										
SL S550-32-48 32SL-48	TRANSMITTAL OF PARKER HANNIFIN CORP. CLEVELAND WHEEL & BRAKES SERVICE BULLETIN SB7054 - CITATION BRAKE ASSY - BRAKE ROTOR DISC - INSPECT/REPLACE	SDF		MANDATORY	MTH 09-May-1997 HRS 3673 LDG 2423		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-32-52 R01 <i>32SL-52 : S55R1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-32-54 <i>32SL-54</i>	EMERGENCY GEAR RELEASE INSPECTION		MANDATORY	MTH 22-Sep-2010 HRS 7219 LDG 4789		24 400			Complete
MOC : COMPLIED WITH - COMPLIED WITH THE CESSNA S550 MANDATORY SERVICE LETTER SL550-32-54. NO DEFECTS OR DISCREPENCIES WERE NOTED AT THIS TIME.									
SL CIL-33-01	LIGHTS - TRANSMITTAL OF RADIANT POWER CORP. SB-RPC-001, PROCEDURE TO REPLACE OBSOLETE CONNECTOR ASSEMBLY FOR CBS28 EMERGENCY BATTERY		INFORMATIONAL			-			
MOC :									
SB S550-33-01 <i>33SB-01</i>	LANDING LIGHT RELOCATION (SUPERSEDED BY S550-33-01 R01)	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-04 R01 <i>33SB-04 : S55R1</i>	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R02)	TOL	MANDATORY	MTH 28-Jan-1988 HRS 485		A/R			Complete
MOC : COMPLIED WITH									
SB S550-33-04 <i>33SB-04</i>	AFT CABIN PSU LIGHT WIRE REPLACEMENT (SUPERSEDED BY S550-33-04 R01)	AZO	MANDATORY	MTH 19-Nov-1987 HRS 421		A/R			Complete
MOC : COMPLIED WITH									
SB S550-33-07 <i>33SB-07</i>	LANDING LIGHT ELECTRICAL CIRCUIT MODIFICATION (SUPERSEDED BY S550-33-07 R01)	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-08 <i>33SB-08</i>	INDIRECT LIGHTING CONNECTOR CONTACT INSPECTION/REPLACEMENT	AZO	RECOMMENDED	MTH 10-Jul-1990 HRS 1498		A/R			Complete
MOC : COMPLIED WITH									
SB S550-33-11 R01 <i>33SB-11 : S55R1</i>	WING TIP NAV/COLLISION LIGHT MODIFICATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-12 R03 <i>33SB-12 : S55R3</i>	WING TIP MOUNTED LANDING LIGHT INSTALLATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-13 <i>33SB-13</i>	LANDING LIGHT CIRCUIT SWITCH MODULE INSTALLATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-14 <i>33SB-14</i>	INDIRECT LIGHTING LAMP AND CONNECTOR UPGRADE	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-33-15 R01 33SB-15 : S55R1	LIGHTS - EMERGENCY LIGHTING BATTERY PACK UPGRADE		OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-33-16 33SB-16	LED TAIL POSITION LIGHT INSTALLATION		OPTIONAL MTH			A/R			
MOC : - SERVICE BULLETIN ON HOLD.									
SL S550-33-03 R02 33SL-03 : S55R2	CABIN INDIRECT LIGHTING SYSTEM INSPECTION	MCO	RECOMMENDED MTH	25-Jul-1996 HRS 3482		A/R			Complete
MOC : COMPLIED WITH									
SL S550-33-03 33SL-03	CABIN INDIRECT LIGHTING SYSTEM INSPECTION (SUPERSEDED BY SLS550-33-03 R01)	AZO	RECOMMENDED MTH	27-Mar-1991 HRS 1808		A/R			Complete
MOC : COMPLIED WITH									
SL S550-33-06 33SL-06	LANDING LIGHT SWITCH INSPECTION/REPLACEMENT (SUPERSEDED BY SLS550-33-06 R01)	ICT	MANDATORY MTH	17-Oct-1993 HRS 2560		A/R			Complete
MOC : COMPLIED WITH									
SB S550-34-17 R01 34SB-17 : S55R1	STATIC PORT DOUBLER INSTALLATION	AZO	RECOMMENDED MTH	13-Aug-1987 HRS 302		A/R			Complete
MOC : COMPLIED WITH									
SB S550-34-25 R01 34SB-25 : S55R1	STARTER-GENERATOR AND GCU FILTER INSTALLATION	MKE	RECOMMENDED MTH	30-Oct-1992 HRS 2155		A/R			Complete
MOC : COMPLIED WITH									
ASB S550-34-26 R01 34SBA26 : S55R1	VG14A VERTICAL GYRO INSPECTION	AZO	MANDATORY MTH	14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH									
SB S550-34-27 34SB-27	VN-212 SIGNAL GROUND WIRING MODIFICATION	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-34-35 34SB-35	COPILOT ALTIMETER INSTALLATION - KOLLSMAN	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-34-36 R02 34SB-36 : S55R2	NAVIGATION - REDUCED VERTICAL SEPARATION MINIMUM (RVSM) OPERATION MODIFICATION	MCO	OPTIONAL MTH	06-Dec-2004 HRS 5363		A/R			Complete
MOC : COMPLIED WITH									
SB S550-34-37 34SB-37	TRAFFIC COLLISION AVOIDANCE SYSTEM (TCAS) II AND MST-67A TRANSPONDER UPGRADE FOR ELEMENTARY SURVEILLANCE	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-34-38 34SB-38	SANDEL ST3400 TAWS INSTALLATION	CRQ	OPTIONAL MTH			A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-34-39 <i>34SB-39</i>	SIGMA-TEK CONTROL PANEL INSTALLATION	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-34-40	NAVIGATION - HONEYWELL TRAFFIC ALERT AND COLLISION AVOIDANCE SYSTEM II (TCAS II) VERSION 7.1 SOFTWARE UPDATE			OPTIONAL						
MOC :										
SL S550-34-06 <i>34SL-06</i>	DORNE AND MARGOLIN DMN4-17-4 NAV ANTENNA COUPLER INSPECTION	CRQ		RECOMMENDED	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
ASL SLS550-34-15A <i>34SLA15</i>	KLN 89B, KLN 90B AND KLN 900 GPS INSTRUMENT LANDING SYSTEM APPROACH RESTRICTIONS	GSO		MANDATORY	MTH 31-Oct-1997 HRS 3811		A/R			Complete
MOC : COMPLIED WITH										
SL CIL-35-05	OXYGEN - TRANSMITTAL OF ZODIAC AEROSPACE SB MCF-SBU-35-001	CRQ		MANDATORY	MTH 11-Feb-2016 DAYS 8050.1 HRS 5439 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE										
SB S550-35-03 R01 <i>35SB-03 : S55R1</i>	EROS OXYGEN MASK INSTALLATION	CRQ		OPTIONAL	MTH 12-Oct-2009 HRS 6867		A/R			Complete
MOC : COMPLIED WITH - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-35-04 R01 <i>35SB-04 : S55R1</i>	CHAFING PROTECTION INSTALLATION OF TAILCONE LINES AND WIRE BUNDLES			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-35-03	OXYGEN BOTTLE INSPECTION			INFORMATIONAL	MTH		A/R			
MOC :										
SL S550-35-04 R01	OXYGEN - TRANSMITTAL OF INTERTECHNIQUE SERVICE BULLETIN MXH-35-240	KGJT		MANDATORY	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		-			N/A
MOC : NOT APPLICABLE - CESSNA SERVICE LETTER SL S550-35-04 R1 DATED 10/25/2012 IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED. PILOT OXYGEN MASK P/N MC10-15-109, S/N 57795, OVERHAULED - 10-2016, MANUF. DATE 06/1996. COPILOT OXYGEN MASK P/N MC10-15-109 S/N 14836 OVERHAULED - 03/2013, MANUF. DATE (UNK)										
SB S550-36-02 <i>36SB-02</i>	DOOR SEAL PLUMBING INSPECTION AND MODIFICATION	SDF		RECOMMENDED	MTH 25-Apr-2002 HRS 4745		A/R			Complete
MOC : COMPLIED WITH										
SB S550-36-04 R01 <i>36SB-04 : S55R1</i>	ENGINE BLEED AIR CONNECTOR IMPROVEMENT	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-36-05 36SB-05	DOOR SEAL VALVE REPLACEMENT CRQ			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
ASL S550-52-03	DOORS - EMERGENCY EXIT INSPECTION KCRQ			MANDATORY	DAYS 09-Mar-2011 HRS 7338.7 LDG 4870		A/R			Complete
MOC : COMPLIED WITH - COMMENTS: COMPLIED WITH MANDATORY ALERT SERVICE LETTER ASLS550-52-03 BY COMPLETING THE INSPECTION AND THE APPLICATION OF PETROLEUM JELLY TO THE EMERGENCY EXIT DOOR SEAL AS REQUIRED BY THE INSTRUCTIONS IN THE DESCRIPTION SECTION OF THIS LETTER. NO FURTHER ACTION(S) IS REQUIRED.										
SB S550-52-02 R02 52SB-02 : S55R2	ENTRY STEP ASSEMBLY IMPROVEMENT AZO			RECOMMENDED	MTH 19-Nov-1987 HRS 421		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-04 52SB-04	TAILCONE BAGGAGE DOOR RESTRAINT CABLE INSTALLATION AZO			OPTIONAL	MTH 21-Jun-1989 HRS 1054		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-05 52SB-05	BAGGAGE DOOR POSITIVE SAFETY LOCK INSTALLATION (SUPERSEDED BY S550-52-05 R01) AZO			RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH										
SB S550-52-06 52SB-06	WIDE DOOR INSTALLATION (SUPERSEDED BY S550-52-06 R01) CRQ			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-52-08 52SB-08	WIDE DOOR RETRACT CABLE MODIFICATION (SUPERSEDED BY S550-52-08 R01) CRQ			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-52-09 52SB-09	ENTRY DOOR STEP CATCH COVER INSTALLATION (WITH STANDARD DOOR AND STEP) RECOMMENDED			MTH			A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-52-01 52SL-01	NOSE AND TAILCONE BAGGAGE DOOR INSPECTION AZO			RECOMMENDED	MTH 16-Mar-1989 HRS 926		A/R			Complete
MOC : COMPLIED WITH										
SL S550-52-02 52SL-02	EMERGENCY EXIT INNER HANDLE ATTACH SCREW INSPECTION/REPLACEMENT ICT			MANDATORY	MTH 26-Aug-1992 HRS 2074		A/R			Complete
MOC : COMPLIED WITH										
SB S550-53-01 53SB-01	TAILCONE BALLAST INSTALLATION (SUPERSEDED BY S550-53-01 R01) CRQ			OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-53-05 R01 53SB-05 : S55R1	TAILCONE BAGGAGE COMPARTMENT GUSSET INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-05 R02) MKE			RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB S550-53-08 53SB-08	FRAME BRACE INSPECTION/INSTALLATION (SUPERSEDED BY S550-53-08 R01)	MKE	RECOMMENDED	MTH 16-Apr-1993 HRS 2418		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-09 53SB-09	CABIN INTERIOR ATTACH/CONTACT POINT CORROSION PROTECTION (SUPERSEDED BY S550-53-09 R01)	MKE	RECOMMENDED	MTH 16-Apr-1993 HRS 2418		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-10 53SB-10	FLIGHT CREW SEAT RAIL AND BEAM RIVETS INSPECTION/INSTALLATION	*CF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-53-11 53SB-11	DORSAL FIN INSTALLATION AND MATERIAL IMPROVEMENT	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-53-12 53SB-12	MAP COMPARTMENT ASSEMBLY INSPECTION/REPLACEMENT	SDF	RECOMMENDED	MTH 25-Apr-2002 HRS 4745		A/R			Complete
MOC : COMPLIED WITH									
SB S550-53-14 53SB-14	AN3-5A BOLT INSPECTION/REPLACEMENT	SCF	RECOMMENDED	MTH HRS		24 300			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-53-15 53SB-15	FUSELAGE MOISTURE DRAIN INSTALLATION	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SB S550-53-16 53SB-16	FUSELAGE - MAIN CARRY-THRU LUG INSPECTION	SDF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-53-17 53SB-17	WHEEL WELL BOX/SKIN GAP IMPROVEMENT	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-53-03 53SL-03	DORSAL FIN VANE INSPECTION		RECOMMENDED	MTH 29-May-2007 HRS 6008		A/R			Complete
MOC : COMPLIED WITH									
SL S550-53-04 R01 53SL-04 : S55R1	INTERCOSTAL DRAINAGE PATH INSPECTION	CRQ	RECOMMENDED	MTH 17-May-2007 HRS 6006		A/R			Complete
MOC : COMPLIED WITH									
SL S550-55-01 R01 55SL-01 : S55R1	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION	AZO	RECOMMENDED	MTH 27-Mar-1991 HRS 1808		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-55-01 <i>55SL-01</i>	RUDDER TORQUE TUBE INTERNAL CORROSION INSPECTION (SUPERSEDED BY SLS550-55-01 R1)	AZO		RECOMMENDED	MTH 02-Mar-1990 HRS 1358		A/R			Complete
MOC : COMPLIED WITH										
SB S550-57-03 <i>57SB-03</i>	FLAP ACTUATOR UPPER BELLCRANK BRACKET REPLACEMENT (SUPERSEDED BY S550-57-03 R01)	ICT		RECOMMENDED	MTH 19-Aug-1991 HRS 1935		A/R			Complete
MOC : COMPLIED WITH										
SB S550-57-06 R01 <i>57SB-06 : S55R1</i>	STUB WING DOUBLER INSTALLATION CRQ			OPTIONAL	MTH		A/R			Complete
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SB S550-57-06 <i>57SB-06</i>	STUB WING DOUBLER INSTALLATION (SUPERSEDED BY S550-57-06 R01)	ICT		OPTIONAL	MTH 19-Aug-1991 HRS 1935		A/R			Complete
MOC : COMPLIED WITH										
SB S550-57-07 <i>57SB-07</i>	FLAP PROTECTOR INSTALLATION (SUPERSEDED BY S550-57-07 R01)	CRQ		OPTIONAL	MTH		A/R			Complete
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SB S550-57-09 <i>57SB-09</i>	FLAP VENT HOLES INSTALLATION GSO			RECOMMENDED	MTH 15-Aug-2000 HRS 4418		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-57-01A <i>57SLA01</i>	FLAP DRAIN HOLE INSPECTION DPA			MANDATORY	MTH 25-May-1988 HRS 614		A/R			Complete
MOC : COMPLIED WITH										
SL S550-57-02 <i>57SL-02</i>	AILERON EXTERNAL BALANCE WEIGHT INSPECTION AZO			RECOMMENDED	MTH 08-Aug-1989 HRS 1111		A/R			Complete
MOC : COMPLIED WITH										
SL S550-71-01 <i>71SL-01</i>	JT15D-4B MINIMUM FUEL FLOW ADJUSTMENT AZO			RECOMMENDED	MTH 19-Nov-1987 HRS 421		A/R			Complete
MOC : COMPLIED WITH										
SL S550-71-02 <i>71SL-02</i>	ENGINE BREATHER TUBE EXTENSION AZO			OPTIONAL	MTH 13-Aug-1987 HRS 302		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-04 <i>72SL-04</i>	IMPROVED RETENTION OF P3 AIR-TO-FUEL CONTROL BOSS AZO			RECOMMENDED	MTH 13-Aug-1987 HRS 302		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-05 <i>72SL-05</i>	JT15D FAN BLADE INSPECTION AZO			RECOMMENDED	MTH 26-May-1987 HRS 233		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-06 R01 <i>72SL-06 : S55R1</i>	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R02)	AZO		RECOMMENDED	MTH 28-Sep-1988 HRS 748		A/R			Complete
MOC : COMPLIED WITH										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-72-06 R02 72SL-06 : S55R2	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R03)	AZO		RECOMMENDED	MTH 31-Mar-1988 HRS 558		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-06 72SL-06	LOW COMPRESSOR CASE INSPECTION (SUPERSEDED BY SLS550-72-06 R01)	AZO		RECOMMENDED	MTH 31-Mar-1988 HRS 558		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-07 72SL-07	LOW COMPRESSOR CASE DAMPENING RING INSTALLATION (SUPERSEDED BY SLS550-72-07 R01)	AZO		RECOMMENDED	MTH 31-Mar-1988 HRS 558		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-72-09A LEFT ENGINE 72SLA09 : S550L	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	AZO		CANCELLED	MTH 26-Oct-1988 HRS 781		A/R			Complete
MOC : COMPLIED WITH										
ASL SLS550-72-09A RIGHT ENGINE 72SLA09 : S550R	JT15D-4B HIGH TURBINE BLADE SHAFT (CANCELLED)	AZO		CANCELLED	MTH 26-Oct-1988 HRS 781		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-11 R01 72SL-11 : S55R1	JT15D-4B HIGH TURBINE BLADE SHIFT	MKE		RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-11 72SL-11	JT15D-4B HIGH TURBINE BLADE SHIFT (SUPERSEDED BY SLS550-72-11 R01)	AZO		RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SL S550-72-19 72SL-19	TRANSMITTAL OF P&WC SERVICE LETTER JT15D-023 REPLACEMENT OF OIL PUMP PLUG	SDF		RECOMMENDED	MTH 03-May-2001 HRS 4543		A/R			Complete
MOC : COMPLIED WITH										
SB JT15D-72-7001 R25 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R25 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R26)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R26 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R26 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS (SUPERSEDED BY SB 72-7001 R27)			RECOMMENDED			-			
MOC :										
SB JT15D-72-7001 R27 E1	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7001 R27 E2	APPROVED LISTING OF (SYNTHETIC) LUBRICATING OILS			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7002 R42 E1	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R42 E2	SERVICE LIVES - ROTOR COMPONENTS (SUPERSEDED BY SB 72-7002 R43)			CATEGORY 3			A/R			
	MOC :									
SB JT15D-72-7002 R43 E1	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7002 R43 E2	SERVICE LIVES - ROTOR COMPONENTS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7003 R35 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R35 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R36)						-			
	MOC :									
SB JT15D-72-7003 R36 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R36 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R37)						-			
	MOC :									
SB JT15D-72-7003 R37 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R37 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R38)						-			
	MOC :									
SB JT15D-72-7003 R38 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)						-			
	MOC :									
SB JT15D-72-7003 R38 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R39)						-			
	MOC :									
SB JT15D-72-7003 R39 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R40)			RECOMMENDED			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7003 R39 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY (SUPERSEDED BY SB 72-7003 R40)			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7003 R40 E1	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			A/R			
	MOC :									
SB JT15D-72-7003 R40 E2	ENGINE OPERATING TIME BETWEEN OVERHAULS AND HOT SECTION INSPECTION FREQUENCY			RECOMMENDED			A/R			
	MOC :									
SB JT15D-72-7144 R20 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	MOC :									
SB JT15D-72-7144 R20 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING						-			
	MOC :									
SB JT15D-72-7144 R21 E1	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7144 R21 E2	ENGINE FUELS AND ADDITIVES - REQUIREMENTS AND APPROVED LISTING			RECOMMENDED			-			
	MOC :									
SB JT15D-72-7244 R05 E1	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7244 R05 E2	LOW TURBINE DISK AND TURBINE SHAFT ASSEMBLY - IMPROVED DURABILITY			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7288 R04 E1	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7288 R04 E2	REPLACEMENT OF OVERSPEED CONTROL WIRE ROPE			CATEGORY 5			-			
	MOC :									
SB JT15D-72-7292 R01 E1	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7292 R01 E2	INTRODUCTION OF IMPROVED FUEL MANIFOLD TRANSFER TUBE LOCKING BRACKETS			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7364 R03 E1	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7364 R03 E2	CONVERSION OF JT15D-4 ENGINE TO JT15D-4B CONFIGURATION			CATEGORY 8			-			
MOC :										
SB JT15D-72-7459 R01 E1	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
MOC :										
SB JT15D-72-7459 R01 E2	REPLACEMENT OF IGNITER (SUPERSEDED BY SB 72-7459 R02)			CATEGORY 8			A/R			
MOC :										
SB JT15D-72-7459 R02 E1	REPLACEMENT OF IGNITER			CATEGORY 8			-			
MOC :										
SB JT15D-72-7459 R02 E2	REPLACEMENT OF IGNITER			CATEGORY 8			-			
MOC :										
SB JT15D-72-7522 R06 E1	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R06 E2	MODIFICATION OF GAS GENERATOR CASE (SUPERSEDED BY SB 72-7522 R07)			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R07 E1	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7522 R07 E2	MODIFICATION OF GAS GENERATOR CASE			CATEGORY 5			-			
MOC :										
SB JT15D-72-7588 R02 E1	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
MOC :										
SB JT15D-72-7588 R02 E2	REPLACEMENT/MODIFICATION OF ACCESSORY GEARBOX INPUT DRIVE GEAR			CATEGORY 8			-			
MOC :										
SB JT15D-72-7589 R01 E1	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
MOC :										
SB JT15D-72-7589 R01 E2	HIGH TURBINE DISC BALANCING ASSEMBLY - REPLACEMENT OF			CATEGORY 8			-			
MOC :										
SB JT15D-72-7618 R02 E1	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										
SB JT15D-72-7618 R02 E2	REPLACEMENT / MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7618 R03 E1	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7618 R03 E2	REPLACEMENT/MODIFICATION OF NO. 4 BEARING SLEEVE, HOUSING ASSEMBLY AND ROTOR AIR SEAL			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7621 R01 E1	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7621 R01 E2	REPLACEMENT OF OIL FILTER ELEMENT			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7625 R01 E1	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 R01 E2	REPLACEMENT OF GASKET			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E1	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7625 E2	REPLACEMENT OF GASKET (SUPERSEDED BY SB 72-7625 R01)			CATEGORY 6			A/R			
	MOC :									
SB JT15D-72-7627 E1	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7627 E2	LOW PRESSURE TURBINE INTERSTAGE ROTOR AIR SEAL AND ROTOR AIR SEAL -REPLACEMENT OF			CATEGORY 6			-			
	MOC :									
SB JT15D-72-7633 E1	ALTERNATE SOURCE RETAINING RING			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7633 E2	ALTERNATE SOURCE RETAINING RING			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7634 E1	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7634 E2	REPLACEMENT OF SHIPPING CAPS FOR SHIPPING CONTAINERS			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7636 E1	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7636 E2	REPLACEMENT OF CADMIUM PLATED BOLTS			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7639 R01 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7639 R01 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R02)			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7639 R02 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7639 R02 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 3			-			
	MOC :									
SB JT15D-72-7639 R03 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7639 R03 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7639 E1	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7639 E2	REPLACEMENT OF PACKING TRANSFER TUBE / OIL FILLER BALL VALVE ASSEMBLY (SUPERSEDED BY JT15D-72-7639 R01)			CATEGORY 4			-			
	MOC :									
SB JT15D-72-7640 E1	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7640 E2	REPLACEMENT OF SHIPPING PLUG			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7642 R01 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
	MOC :									
SB JT15D-72-7642 R01 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 10			-			
	MOC :									
SB JT15D-72-7642 E1	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 9			-			
	MOC :									
SB JT15D-72-7642 E2	TRANSFER OF MANUFACTURING RIGHTS FOR VARIOUS PARTS			CATEGORY 9			-			
	MOC :									
SB JT15D-72-7643 E1	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7643 E2	REPLACEMENT OF SHIPPING CONTAINER			CATEGORY 7			-			
	MOC :									
SB JT15D-72-7644 E1	REPLACEMENT OF T1 THERMOCOUPLE HARNESS			CATEGORY 7			-			
	MOC :									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SB JT15D-72-7644 E2	REPLACEMENT OF T1 THERMOCOUPLE HARNESS		CATEGORY 7			-			
MOC :									
ASB S550-73-01A R03 <i>73SBA01 : S55R3</i>	9912031-6 FUEL FLOW TRANSMITTER INSPECTION	AZO		MTH 03-Nov-1990 HRS 1650		N/A			Complete
MOC : COMPLIED WITH									
ASB S550-73-01A <i>73SBA01</i>	9912031-6 FUEL FLOW TRANSMITTER INSPECTION (SUPERSEDED BY S550-73-01A R01)	DPA	MANDATORY	MTH 07-Aug-1989 HRS 1110		A/R			Complete
MOC : COMPLIED WITH									
SB S550-73-02 R01 <i>73SB-02 : S55R1</i>	9912031-6 FUEL FLOW TRANSMITTER THREAD INSPECTION	AZO	MANDATORY	MTH 27-Mar-1991 HRS 1808		A/R			Complete
MOC : COMPLIED WITH									
SL CIL-74-01 R01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE	KCRQ	MANDATORY	DAYS 04-Jun-2013 HRS 7845.6 LDG 5284		-			Complete
MOC : COMPLIED WITH - COMPLETED CIL BY ADJUSTING THE IGNITOR CABLE ROUTING.									
SL CIL-74-01	INSPECTION OF IGNITION CABLE AND THROTTLE LINKAGE (SUPERSEDED BY CIL-74-01 R01)		MANDATORY	DAYS		-			
MOC :									
SL S550-74-02 <i>74SL-02</i>	IGNITION - TRANSMITTAL OF PRATT & WHITNEY CANADA SERVICE BULLETIN 7567R1 TURBOFAN ENGINE IGNITER BOX GROUNDING STRAP - INTRODUCTION OF	SCF	RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
MOC :									
SB S550-78-04 <i>78SB-04</i>	EXHAUST - THRUST REVERSER THROTTLE LOAD LIMITER MODIFICATION (SUPERSEDED BY S550-78-04 R01)	ICT	RECOMMENDED	MTH 31-May-1992 HRS 2039		A/R			Complete
MOC : COMPLIED WITH									
SB S550-78-05 <i>78SB-05</i>	EXHAUST - THRUST REVERSER THROTTLE STOP SOLENOID GROUND IMPROVEMENT	CRQ	OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME									
SL S550-78-02 <i>78SL-02</i>	THRUST REVERSER JUNCTION BOX MODIFICATION (SUPERSEDED BY SLS550-78-02 R01)	AZO	RECOMMENDED	MTH 13-Aug-1987 HRS 302		A/R			Complete
MOC : COMPLIED WITH									
SL S550-78-04 R02 <i>78SL-04 : S55R2</i>	THRUST REVERSER DOOR MODIFICATION	MKE	RECOMMENDED	MTH 23-Dec-1992 HRS 2228		A/R			Complete
MOC : COMPLIED WITH									
SL S550-78-04 <i>78SL-04</i>	THRUST REVERSER DOOR MODIFICATION (SUPERSEDED BY SLS550-78-04 R01)	AZO	RECOMMENDED	MTH 14-Nov-1989 HRS 1209		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
SL S550-78-05 78SL-05	THRUST REVERSER SYSTEM OPERATIONAL TEST (SUPERSEDED BY SLS550-78-05 R01)	AZO		RECOMMENDED	MTH 30-Nov-1990 HRS 1650		A/R			Complete
MOC : COMPLIED WITH										
SL S550-78-08 78SL-08	THRUST REVERSER STANG FAIRING SUPPORT FORMER REPLACEMENT			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-78-10 R01 78SL-10 : S55R1	TRANSMITTAL OF NORDAM SERVICE BULLETIN CITSII 78-12 R1, EXHAUST - THRUST REVERSER - REPLACEMENT OF THRUST REVERSER STANG FAIRING SUPPORT FORMER			RECOMMENDED	MTH		A/R			
OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
MOC :										
SL S550-79-01 79SL-01	NEW OIL FILLER NECK ASSEMBLY	AZO		RECOMMENDED	MTH 02-Mar-1990 HRS 1358		A/R			Complete
MOC : COMPLIED WITH										
SB S550-80-01 80SB-01	STARTING - REPLACEMENT OF SUPPRESSION DIODE WITH TRANSZORB	CRQ		OPTIONAL	MTH		A/R			
MOC : - OPERATOR DOES NOT WISH TO COMPLY AT THIS TIME										
SL CIL-99-01 R03	MISCELLANEOUS - USE OF CORROSION INHIBITING COMPOUNDS			CANCELLED			-			
MOC :										
SL CIL-99-02 R01	MISCELLANEOUS - AVOID OPERATIONS ON RUNWAYS TREATED WITH RUNWAY DE-ICE (RDI) FLUIDS. AIRCRAFT WASHING RECOMMENDED AFTER EXPOSURE TO RDI FLUIDS			CANCELLED			-			
MOC :										
SL CIL-99-03 R02	MISCELLANEOUS - CORROSION PREVENTION AND CONTROL PROGRAM (CPCP)			CANCELLED			-			
MOC :										
SL CIL-99-04 R01	MISCELLANEOUS - INCREMENTAL LIBRARY UPDATES FOR CESVIEW			CANCELLED			-			
MOC :										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1990-07-10 <i>21AD-01</i>	TO PREVENT FAILURE OF THE ELEVATOR OR RUDDER CONTROL CABLES	DPA	SUPERSEDED	MTH 23-Apr-1990 HRS 1358		-			Complete
MOC : COMPLIED WITH									
FAA 1993-05-15 <i>78AD-01</i>	MODIFY THE THRUST REVERSER THROTTLE LOAD LIMITER	CRQ	MANDATORY	MTH 05-Oct-2009 HRS 6867		A/R			Complete
MOC : COMPLIED WITH									
FAA 1995-25-10	REPLACEMENT OF OUTFLOW/SAFETY VALVES WITH SERVICEABLE VALVES.	UNK	MANDATORY	MTH 17-Feb-2014 HRS 7917.9 LDG 5340		A/R			N/A
MOC : NOT APPLICABLE - PER EQUIPMENT PN									
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)	KCRQ	MANDATORY	DAYS 24-Jun-2013 HRS 7870.1 LDG 5302		-			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS	KCRQ	MANDATORY	DAYS 24-Jun-2013 HRS 7870.1 LDG 5302		-			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION		MANDATORY	MTH 24-Jun-2013 HRS 7870.1 LDG 5302		-			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM		MANDATORY	MTH 24-Jun-2013 HRS 7870.1 LDG 5302		A/R			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM		MANDATORY	MTH 24-Jun-2013 HRS 7870.1 LDG 5302		A/R			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS		MANDATORY	MTH 24-Jun-2013 HRS 7870.1 LDG 5302		-			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM			MANDATORY	MTH 24-Jun-2013 HRS 7870.1 LDG 5302		-			N/A
MOC : NOT APPLICABLE - NA, BY MOTOR PART NUMBER										
FAA 2015-17-12 PARA (G)	INSPECT THE A/C COMPRESSOR MOTOR TO DETERMINE WHETHER P/N FWA1134104-1 OR P/N FWA1134104-5 IS INSTALLED	CRQ		MANDATORY	DAYS 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12 PARA (H)	DETERMINE THE HOUR READING ON THE A/C COMPRESSOR HOUR METER (IF, DURING THE INSPECTION REQUIRED BY PARA (G) OF THIS AD, ANY A/C COMPRESSOR MOTOR HAVING P/N FWA1134104-1 OR P/N FWA1134104-5 IS FOUND	CRQ		MANDATORY	DAYS 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12 PARA (I)	REPLACE THE A/C COMPRESSOR MOTOR BRUSHES WITH NEW BRUSHES (USING THE HOUR READING ON THE A/C COMPRESSOR HOUR METER DETERMINED IN PARA (H) OF THIS AD)	CRQ		MANDATORY	MTH 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12 PARA (K)	DEACTIVATE THE A/C SYSTEM (IN LIEU OF REPLACING THE A/C COMPRESSOR MOTOR BRUSHES AS REQUIRED BY THIS AD)	CRQ		MANDATORY	MTH 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12 PARA (L)	IF THE A/C SYSTEM IS DEACTIVATED, AS SPECIFIED IN PARA (K), PRIOR TO THE A/C SYSTEM BEING REACTIVATED: PERFORM THE INSPECTION SPECIFIED IN PARA (H), AND DO THE REPLACEMENTS SPECIFIED IN PARA (I), AT THE TIMES SPECIFIED IN PARA (I). RETURN THE A/C SYSTEM TO SERVICE	CRQ		MANDATORY	MTH 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12 PARA (M)	SEND THE REMOVED BRUSHES TO CESSNA AIRCRAFT COMPANY	CRQ		MANDATORY	DAYS 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 2015-17-12	AIR CONDITIONING - INSPECTIONS TO DETERMINE IF CERTAIN A/C COMPRESSOR MOTORS ARE INSTALLED AND TO DETERMINE THE ACCUMULATED HOURS ON CERTAIN A/C COMPRESSOR MOTOR ASSEMBLIES; AND REPETITIVE REPLACEMENT OF THE BRUSHES IN THE A/C COMPRESSOR MOTOR ASSEMBLY, OR, AS AN OPTION TO THE BRUSH REPLACEMENT, DEACTIVATION OF THE A/C SYSTEM AND PLACARD INSTALLATION; AND RETURN OF REPLACED BRUSHES TO CESSNA	CRQ		MANDATORY	MTH 06-Nov-2015 HRS 8021.9 LDG 5416		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE TO THIS AIRCRAFT. A/C COMPRESSOR MOTOR P/N FWA13410 S/N 074 INSTALLED										
FAA 1988-06-02	ELECTRICAL POWER	UNK		MANDATORY	MTH 17-Feb-2014 HRS 7917.9 LDG 5340		-			N/A
MOC : NOT APPLICABLE - BY AIRCRAFT SN										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1987-03-15 <i>25AD-01</i>	SUPERSEDED BY AD 1988-24-16 DPH			SUPERSEDED	MTH 07-Feb-1987 HRS 59		-			Complete
MOC : COMPLIED WITH										
FAA 1988-24-16 <i>25AD-03</i>	TO PRECLUDE WIRING FAILURE, WHICH CAN RESULT IN CABIN SMOKE AND/OR FIRE AZO			MANDATORY	MTH 28-Nov-1988 HRS 807		A/R			Complete
MOC : COMPLIED WITH										
FAA 1989-06-01 <i>25AD-04</i>	APPLIANCE AD - TO PREVENT THE IMPROPER FUNCTIONING OF THE CO2 INFLATORS AZO			MANDATORY	MTH 08-Aug-1989 HRS 1111		A/R			Complete
MOC : COMPLIED WITH										
FAA 1998-25-10 <i>25AD-07</i>	APPLIANCE AD - TO PREVENT FAILURE OF THE SEAT RESTRAINT SYSTEM SDF			MANDATORY	MTH 09-Jan-1999 HRS 4077		A/R			Complete
MOC : COMPLIED WITH										
FAA 2015-10-02 PARA (G)	GENERAL VISUAL INSPECTION FOR CRACKING OF SEAT BACKREST LINKS HAVING PART NUMBER (P/N) 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2			MANDATORY	MTH		-			
MOC :										
FAA 2015-10-02 PARA (H)	CORRECTIVE ACTIONS - CRACKING IS FOUND ON THE LINK			MANDATORY			-			
MOC :										
FAA 2015-10-02 PARA (I)	REPLACE ALL SEAT BACKREST LINKS, HAVING P/N 90-000200-104-1, P/N 90-000200-104-2, P/N 90-000202-104-1 AND P/N 90-000202-104-2, WITH NEW LINKS			MANDATORY			-			
MOC :										
FAA 2015-10-02	APPLIANCE AD - EQUIPMENT/FURNISHINGS - ZODIAC SEATS FRANCE - INSPECTION/REPLACEMENT			MANDATORY	MTH		-			
MOC :										
FAA 2017-16-01 PARA (G)	PERFORM GENERAL VISUAL INSPECTIONS OF THE ELT FOR DISCREPANCIES; CHECKS , TESTS AND VERIFICATIONS AS APPLICABLE, TO ENSURE THE ELT IS FUNCTIONING, AND ALL APPLICABLE CORRECTIVE ACTIONS	CRQ			MTH 23-Oct-2018 HRS 8363.4 LDG 5632		-			N/A
MOC : NOT APPLICABLE - FAA 2017-16-01 PARA(G), AIRCRAFT IS NOT EQUIPPED WITH AFFECTED ELT P/N & MANUFACTURER, THEREFORE FAA 2017-16-01 PARA (G) IS NOT APPLICABLE.										
FAA 2017-16-01 PARA (J)	OPTIONAL TERMINATING ACTION: REPLACE ELT WITH A SERVICEABLE FAA-APPROVED ELT	CRQ		MANDATORY	MTH 23-Oct-2018 HRS 8363.4 LDG 5632		-			N/A
MOC : NOT APPLICABLE - FAA 2017-16-01 PARA(G), AIRCRAFT IS NOT EQUIPPED WITH AFFECTED ELT P/N & MANUFACTURER, THEREFORE FAA 2017-16-01 PARA (G) IS NOT APPLICABLE.										
FAA 2017-16-01	APPLIANCE AD - EQUIPMENT / FURNISHINGS - AMERI-KING CORPORATION MODEL AK-450() AND AK-451() SERIES EMERGENCY LOCATOR TRANSMITTERS - REPETATIVE INSPECTIONS, CHECKS, TESTS AND VERIFICATIONS	CRQ		MANDATORY	MTH 23-Oct-2018 HRS 8363.4 LDG 5632		-			N/A
MOC : NOT APPLICABLE - FAA 2017-16-01 PARA(G), AIRCRAFT IS NOT EQUIPPED WITH AFFECTED ELT P/N & MANUFACTURER, THEREFORE FAA 2017-16-01 PARA (G) IS NOT APPLICABLE.										



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2001-22-14 26AD-01	APPLIANCE AD - TO PREVENT DAMAGE TO FIRE EXTINGUISHING SYSTEM COMPONENTS CAUSED BY A FIRE EXTINGUISHING SYSTEM BOTTLE CARTRIDGE ACTIVATING WITH EXCESSIVE ENERGETIC	SDF	MANDATORY	MTH 11-Jan-2002 HRS 4714		A/R			Complete
MOC : COMPLIED WITH									
FAA 2006-04-10 26AD-02	SUPERSEDED BY 2007-11-17	GYH	SUPERSEDED	MTH 21-Dec-2006 HRS 5918		-			Complete
MOC : COMPLIED WITH									
FAA 2007-11-17 26AD-06	ENSURE FIRE EXTINGUISHING BOTTLES ARE ACTIVATED IN THE EVENT OF AN ENGINE OR APU FIRE	CRQ	MANDATORY	MTH 07-Sep-2007 HRS 6102		A/R			Complete
MOC : COMPLIED WITH									
FAA 2010-04-16 PARA (G) 26AD-07	REPLACE TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI WITH SERVICABLE UNIT	KSDL	MANDATORY	DAYS 20-Jul-2010 HRS 7153 LDG 4738		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY REASERCH AND FOUND EQUIPMENT NOT INSTALLED, AD NOT APPLICABLE.									
FAA 2010-04-16	APPLIANCE AD - TYPE H1-10 AIR HALON 1211 (BCF) PORTABLE FIRE EXTINGUISHERS MANUFACTURED BY SICLI		MANDATORY	MTH 20-Jul-2010		A/R			N/A
MOC : NOT APPLICABLE - COMPLIED WITH BY REASERCH AND FOUND EQUIPMENT NOT INSTALLED, AD NOT APPLICABLE.									
FAA 2006-06-03 28AD-02	PREVENT FUEL VAPOR IGNITION	GYH	MANDATORY	MTH 21-Dec-2006 HRS 5918		A/R			Complete
MOC : COMPLIED WITH									
FAA 1988-13-03 R01 32AD-02 : S55R1	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS	AZO	MANDATORY	MTH 26-Oct-1988 HRS 781		A/R			Complete
MOC : COMPLIED WITH									
FAA 1988-13-03 32AD-02	TO PREVENT LOSS OF CONTROL OF THE AIRPLANE DURING LANDING OR TAKEOFF DUE TO FAILURE OF THE COTTER PINS SECURING THE MAIN LANDING GEAR TORQUE LINK CONNECTIONS (SUPERSEDED BY 1988-13-03 R01)	DPA	SUPERSEDED	MTH 18-Jul-1988 HRS 680		-			Complete
MOC : COMPLIED WITH									
FAA 1990-07-08 33AD-02	APPLIANCE AD - SUPERSEDED BY AD 1990-07-08 R1	DPA	SUPERSEDED	MTH 08-Oct-1990 HRS 1588		-			Complete
MOC : COMPLIED WITH									
FAA 1990-14-06 33AD-03	APPLIANCE AD - SUPERSEDED BY AD 1995-22-01	DPA	SUPERSEDED	MTH 08-Oct-1990 HRS 1588		-			Complete
MOC : COMPLIED WITH									
FAA 1995-22-01 33AD-04	APPLIANCE AD - TO PREVENT SMOKE, FIRE, ELECTRICAL SHOCK AND POSSIBLE ELECTROMAGNETIC INTERFERENCE CAUSED BY HIGH VOLTAGE ARCING	MCO	MANDATORY	MTH 01-Nov-1996 HRS 3535		A/R			Complete
MOC : COMPLIED WITH									
FAA 1990-03-02 34AD-01	APPLIANCE AD - SUPERSEDED BY AD 1990-06-13	AZO	SUPERSEDED	MTH 10-Jul-1990 HRS 1498		-			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1990-06-13 <i>34AD-02</i>	APPLIANCE AD - TO PREVENT ERRONEOUS ATTITUDE DISPLAY	DPA	MANDATORY	MTH 08-Oct-1990 HRS 1588		A/R			Complete
MOC : COMPLIED WITH									
FAA 1998-25-02 <i>34AD-06</i>	APPLIANCE AD - TO PREVENT THE DISPLAY OF TARGET INDICATORS ON THE WRONG SIDE OF THE AIRCRAFT CAUSED BY AN INTERNAL COMPONENT FAILURE IN THE SKY497 INSTALLATIONS	SDF	MANDATORY	MTH 09-Jan-1999 HRS 4077		A/R			Complete
MOC : COMPLIED WITH									
FAA 2001-23-17 <i>34AD-26</i>	APPLIANCE AD - TO PREVENT INACCURATE COURSE DEVIATION DISPLAYS IN THE GNS 430 UNIT	MCO	MANDATORY	MTH 10-Apr-2002 HRS 4735		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2003-13-08 <i>34AD-13</i>	APPLIANCE AD - TERRAIN AWARENESS WARNING SYSTEMS (TAWS)	SDF	MANDATORY	MTH 01-Aug-2003 HRS 5003		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2004-08-15 <i>34AD-14</i>	APPLIANCE AD - CORRECTION: GOODRICH AVIONICS SYSTEMS, INC TAWS8000 TERRAIN AWARENESS WARNING SYSTEM	MCO	MANDATORY	MTH 06-Dec-2004 HRS 5363		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE-EQUIPMENT NOT INSTALLED									
FAA 2006-16-18 <i>34AD-34</i>	APPLIANCE AD - SUPERSEDED BY AD 2006-16-18 R01	GYH	SUPERSEDED	MTH 21-Dec-2006 HRS 5918		-			Complete
MOC : COMPLIED WITH									
FAA 2014-18-01	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51-E	APPLIANCE/EMERGENCY AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS.		MANDATORY	MTH		-			
MOC :									
FAA 2015-10-51	APPLIANCE AD - AVIDYNE INTEGRATED FLIGHT DISPLAY (IFD)- INCORPORATE OPERATIONAL LIMITATIONS INTO LIMITATIONS SECTION OF THE AFM OR AFMS		MANDATORY			-			
MOC :									
FAA 1994-19-06 <i>35AD-01</i>	APPLIANCE AD - TO PREVENT THE FLIGHT CREW FROM EXPERIENCING DIFFICULTY IN EXHALING	MCO	MANDATORY	MTH 03-Mar-1995 HRS 3052		A/R			Complete
MOC : COMPLIED WITH - NOT APPLICABLE BY COMPONENT PART NUMBER.									
FAA 1999-08-21 <i>35AD-02</i>	APPLIANCE AD - TO PREVENT REDUCED OXYGEN CONSUMPTION WHEN PASSENGERS ARE REQUIRED TO USE DEFECTIVE OXYGEN MASKS	SDF	MANDATORY	MTH 22-Dec-1999 HRS 4305		A/R			Complete
MOC : COMPLIED WITH									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-08-07 PARA (G)	INSPECT THE INFLATABLE HARNESS FITTED TO EACH FLIGHTCREW OXYGEN MASK REGULATOR TO DETERMINE IF THE INFLATABLE HARNESS IS INSTALLED WITH A PART NUMBER AND A BATCH NUMBER IDENTIFIED IN APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240, REVISION 7, DATED SEPTEMBER 1, 2011	KGJT	MANDATORY	MTH 08-Jun-2017 HRS 8250.5 LDG 5563		-			N/A
MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE FAA 2015-08-07 PARA G, IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED. PILOT OXYGEN MASK P/N MC10-15-109, S/N 57795, OVERHAULED - 10-2016, MANUF. DATE06/1996. COPILOT OXYGEN MASK P/N MC10-15-109 S/N 14836 OVERHAULED - 03/2013, MANUF. DATE (UNK)									
FAA 2015-08-07 PARA (H)	REPLACE THE INFLATABLE HARNESS IDENTIFIED IN PAPERGRAPH G WITH A NEW OR RE-IDENTIFIED HARNESSES	KGJT	MANDATORY	MTH 08-Jun-2017 HRS 8250.5 LDG 5563		-			N/A
MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE FAA 2015-08-07 PARA G, IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED. PILOT OXYGEN MASK P/N MC10-15-109, S/N 57795, OVERHAULED - 10-2016, MANUF. DATE06/1996. COPILOT OXYGEN MASK P/N MC10-15-109 S/N 14836 OVERHAULED - 03/2013, MANUF. DATE (UNK)									
FAA 2015-08-07	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHTCREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF INFLATABLE HARNESSES	KGJT	MANDATORY	MTH 08-Jun-2017 HRS 8250.5 LDG 5563		-			N/A
MOC : NOT APPLICABLE - AIRWORTHINESS DIRECTIVE FAA 2015-08-07 PARA G, IS NOT APPLICABLE DUE TO EQUIPMENT INSTALLED. PILOT OXYGEN MASK P/N MC10-15-109, S/N 57795, OVERHAULED - 10-2016, MANUF. DATE06/1996. COPILOT OXYGEN MASK P/N MC10-15-109 S/N 14836 OVERHAULED - 03/2013, MANUF. DATE (UNK)									
FAA 2015-23-09 PARA (G)	INSPECT EACH FLIGHTCREW OXYGEN MASK REGULATOR TO IDENTIFY THE PART NUMBER AND SERIAL NUMBER	CRQ	MANDATORY	MTH 11-Feb-2016 DAYS 8050.1 HRS 5439 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2015-23-09 PARA (H.1)	REPLACE EACH AFFECTED FLIGHTCREW OXYGEN MASK WITH A PART IDENTIFIED IN PARAGRAPH (H)(1)(I) OR (H)(1)(II).	CRQ	MANDATORY	MTH 11-Feb-2016 DAYS 8050.1 HRS 5439 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2015-23-09 PARA (H.2.I)	REVISE THE EMERGENCY PROCEDURES SECTION OF THE AIRPLANE FLIGHT MANUAL (AFM) BY INSERTING THE STATEMENT PROVIDED IN FIGURE 1	CRQ	MANDATORY	MTH 11-Feb-2016 DAYS 8050.1 HRS 5439 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2015-23-09 PARA (H.2.II)	FABRICATE AND INSTALL A PLACARD ON THE FLIGHTCREW OXYGEN MASK CONTAINER THAT STATES: "USE SELECTOR ON 100% OR EMERGENCY ONLY."	CRQ	MANDATORY	MTH 11-Feb-2016 DAYS 8050.1 HRS 5439 LDG		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2015-23-09 PARA (I)	REGULATOR REPLACEMENT	CRQ	MANDATORY	MTH 11-Feb-2016 HRS 8050.1 LDG 5439		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 2015-23-09	APPLIANCE AD - OXYGEN - ZODIAC AEROTECHNICS (FORMERLY INTERTECHNIQUE AIRCRAFT SYSTEMS) FLIGHT CREW OXYGEN MASK REGULATORS - INSPECTION / REPLACEMENT OF OXYGEN MASK REGULATORS	CRQ	MANDATORY	MTH 11-Feb-2016 HRS 8050.1 LDG 5439		-			N/A
MOC : NOT APPLICABLE - NOT APPLICABLE									
FAA 2016-11-20 PARA (G)	PHYSICALLY INSPECT THE PBE POUCH TO DETERMINE IF IT HAS AN INTACT VACUUM SEAL IN ACCORDANCE WITH B/E AEROSPACE SERVICE BULLETIN NO. 119003-35-011, REV .000, DATED FEBRUARY 4, 2015, PARA III.A.1 SUPERSEDED BY FAA AD 2017-18-12	KCRQ	MANDATORY	MTH 12-Oct-2016 HRS 8151.1 LDG 5499 ACH 4258.7		-			N/A
MOC : NOT APPLICABLE - FAA 2016-11-20(G) OXYGEN INSPECTION & REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE) P/N 119003-11, IS NOT APPLICABLE, NOT INSTALLED ON AIRCRAFT.									
FAA 2016-11-20 PARA (H.1)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, THAT DOES NOT HAVE AN INTACT VACUUM SEAL. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2016-11-20 PARA (H.2)	REPLACEMENT OF A PBE POUCH, FOUND DURING THE INSPECTION IN PARAGRAPH (G) OF THIS AD, WHERE THE VACUUM SEAL IS INTACT. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY	MTH		-			
MOC :									
FAA 2016-11-20	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 THAT ARE INSTALLED ON AIRPLANES. SUPERSEDED BY FAA AD 2017-18-12		MANDATORY			-			
MOC :									
FAA 2017-18-12 PARA (G)	INSPECTION RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KCRQ	MANDATORY	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		-			N/A
MOC : NOT APPLICABLE - FAA 2017-18-12 PARA (I) & (J), AIRCRAFT NOT EQUIPPED WITH PBE, THEREFORE FAA 2017-18-12 IS NOT APPLICABLE.									
FAA 2017-18-12 PARA (H)	REPLACEMENT RETAINED FROM AD 2016-11-20 FOR AIRPLANES WITH PBE, P/N 119003-11, INSTALLED	KCRQ	MANDATORY	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		-			N/A
MOC : NOT APPLICABLE - FAA 2017-18-12 PARA (I) & (J), AIRCRAFT NOT EQUIPPED WITH PBE, THEREFORE FAA 2017-18-12 IS NOT APPLICABLE.									
FAA 2017-18-12 PARA (I) & (J)	INSPECT TO DETERMINE IF THE S/N OF THE INSTALLED PBE, P/N 119003-21, IS WITHIN THE RANGE OF 004-14768M THROUGH 004-21093M OR 004-02393M THROUGH 004-03033M AND IF FOUND WITHIN THE S/N RANGE REPLACE IT.	KCRQ	MANDATORY	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		-			N/A
MOC : NOT APPLICABLE - FAA 2017-18-12 PARA (I) & (J), AIRCRAFT NOT EQUIPPED WITH PBE, THEREFORE FAA 2017-18-12 IS NOT APPLICABLE.									
FAA 2017-18-12	APPLIANCE AD - OXYGEN - INSPECTION AND REPLACEMENT OF B/E AEROSPACE PROTECTIVE BREATHING EQUIPMENT (PBE), PART NUMBER 119003-11 AND 119003-21 THAT ARE INSTALLED ON AIRPLANES	KCRQ	MANDATORY	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		-			N/A
MOC : NOT APPLICABLE - FAA 2017-18-12 PARA (I) & (J), AIRCRAFT NOT EQUIPPED WITH PBE, THEREFORE FAA 2017-18-12 IS NOT APPLICABLE.									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
FAA 1988-11-07 <i>57AD-01</i>	TO PREVENT LOSS OF A FLAP PANEL	DPA		MANDATORY	MTH 25-May-1988 HRS 614		A/R			Complete
	MOC : COMPLIED WITH									
AD 72-01	JT15D FAN BLADE INSP	AZO			MTH 26-May-1987 HRS 233		-			Complete
	MOC : COMPLIED WITH									
AD 72-03	HP TURB. BLADE SHIFT	ICT			MTH 19-Aug-1991 HRS 1935		-			Complete
	MOC : COMPLIED WITH									
AD 72-04	GAS GEN CASE INSP	ICT			MTH 26-Aug-1992 HRS 2074		-			Complete
	MOC : COMPLIED WITH									
FAA 1987-10-01 E1	PREVENT FAILURE OF CERTAIN FAN BLADES	UNK		MANDATORY	MTH 26-May-1987 HRS 7278.13 LDG 4817		-			Complete
	MOC : COMPLIED WITH									
FAA 1987-10-01 E2	PREVENT FAILURE OF CERTAIN FAN BLADES			MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY SB 7257.									
FAA 1988-22-03 E1	HT BLADE SHIFT INSP	AZO		SUPERSEDED	MTH 26-Oct-1988 HRS 781		-			Complete
	MOC : COMPLIED WITH									
FAA 1988-22-03 E2	HT BLADE SHIFT INSP	AZO		SUPERSEDED	MTH 26-Oct-1988 HRS 781		-			Complete
	MOC : COMPLIED WITH									
FAA 1991-15-02 E1	TO PREVENT RUPTURE OF THE GAS GENERATOR CASE (GGC) WHICH COULD RESULT IN AN INFLIGHT SHUTDOWN	UNK		MANDATORY	MTH 26-Aug-1992 HRS 7278.13 LDG 4817		A/R			Complete
	MOC : COMPLIED WITH - CESCOM NOT TRACKING FOR ENGINE #1. LOG SHOWS CW ON 8-26-92									
FAA 1991-15-02 E2	TO PREVENT RUPTURE OF THE GAS GENERATOR CASE (GGC) WHICH COULD RESULT IN AN INFLIGHT SHUTDOWN			MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		A/R			N/A
	MOC : NOT APPLICABLE - N/A TO ENGINE S/N.									
FAA 1993-18-08 E1	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693	MCO		MANDATORY	MTH 16-Aug-1994 HRS 2885		-			Complete
	MOC : COMPLIED WITH									
FAA 1993-18-08 E2	PREVENT A HIGH PRESSURE TURBINE (HPT) ASSEMBLY FAILURE. AMENDMENT 39-8693			MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY SB'S 7297, AND (7296 OR 7307)									
TCCA CF-1988-03 R01 E2	INSPECT THE LOW PRESSURE COMPRESSOR CASE INNER DIAMETER FOR FAN BLADE RUB			MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		-			Complete
	MOC : COMPLIED WITH - PREVIOUSLY SB'S 7268, 7300.									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Part Number Mod Lvl Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
TCCA CF-1991-03 E2	PERFORM BORESCOPE INSPECTION OF GGC IN ACCORDANCE WITH P&WC MAINTENANCE MANUAL (PART NO. 3017542) TEMPORARY REVISION (TR) 72-95		MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		-			N/A
MOC : NOT APPLICABLE - N/A TO ENGINE S/N. SB'S 7240R1, 7262R2, 7286R1									
FAA 1974-26-05 E2	TO PREVENT FUEL LEAKS, INSPECT FUEL CONTROL UNITS FOR POSSIBLE INTERFERENCE BETWEEN THE FUEL OUTLET HOUSING AND THE FUEL CONTROL MAIN BODY		MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		25			N/A
MOC : NOT APPLICABLE - BY PART NUMBER N/A TO HMU P/N. UAC SI-74.									
TCCA CF-1991-37 R01 E2	MODIFICATION OF THE EMERGENCY FUEL SHUT -OFF LINKAGE TO IMPROVE INTERGRITY		MANDATORY	MTH 30-Sep-2010 HRS 7278.13 LDG 4817		-			Complete
MOC : COMPLIED WITH - PREVIOUSLY SB'S 7288, 7306, 7384									



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
21FO-01A <i>21FO-01 : 550/A</i>	INDICATOR CABIN TEMPERATURE FACTORY OPTION	*CF		06A FO	MTH 22-Nov-1986		-			
21FO-04A <i>21FO-04 : 550/A</i>	COCKPIT AIR SUPPLEMENTAL FACTORY OPTION	*CF		179A FO	MTH 22-Nov-1986		-			
21FO-05A <i>21FO-05 : 550/A</i>	RH FAN INSTALLATION FORWARD DIVIDER FACTORY OPTION	*CF		180A FO	MTH 22-Nov-1986		-			
24FO-01B <i>24FO-01 : 550/B</i>	BATTERY & MONITOR FOR 20 CELL FACTORY OPTION	*CF		12B FO	MTH 22-Nov-1986		-			
25FO-05J <i>25FO-05 : 550/J</i>	STRGE DRAWER #3 AFT FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104J FO	MTH 22-Nov-1986		-			
25FO-05L <i>25FO-05 : 550/L</i>	STRGE DRAWER #4 AFT FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104L FO	MTH 22-Nov-1986		-			
25FO-05M <i>25FO-05 : 550/M</i>	STRGE DRAWER #5 FWD FCG SEAT LATERL TRACK FACTORY OPTION	*CF		104M FO	MTH 22-Nov-1986		-			
25FO-05W <i>25FO-05 : 550/W</i>	STORAGE DRAWER #10 SEAT LATERAL TRACK FACTORY OPTION	*CF		104W FO	MTH 22-Nov-1986		-			
25FO-10B <i>25FO-10 : 550/B</i>	CENTER CLUB SEATING FACTORY OPTION	*CF		112B FO	MTH 22-Nov-1986		-			
25FO-20U <i>25FO-20 : 550/U</i>	EXECUTIVE TABLE LH USED W/CENTER CLUB FACTORY OPTION	*CF		124U FO	MTH 22-Nov-1986		-			
25FO-20V <i>25FO-20 : 550/V</i>	EXECUTIVE TABLE RH USED W/CENTER CLUB FACTORY OPTION	*CF		124V FO	MTH 22-Nov-1986		-			
25FO-22B <i>25FO-22 : 550/B</i>	FLUSH TOILET AFT RELIEF TUBE ONLY FACTORY OPTION	*CF		131B FO	MTH 22-Nov-1986		-			
25FO-37 <i>25FO-37 : 550/B</i>	CHIMES UNIT FACTORY OPTION	*CF		166 FO	MTH 22-Nov-1986		-			
27FO-01A <i>27FO-01 : 550/A</i>	ELECTRIC TRIM SWITCH COPILOT FACTORY OPTION	*CF		33A FO	MTH 22-Nov-1986		-			
31FO-02 <i>31FO-02 : 550/B</i>	CLOCK DIGITAL ELECTRIC 24 HOUR RH FACTORY OPTION	*CF		182 FO	MTH 22-Nov-1986		-			
33FO-02B <i>33FO-02 : 550/B</i>	LIGHT-RECOGNITION WING-TIP MOUNTED FACTORY OPTION	*CF		49B FO	MTH 22-Nov-1986		-			
33FO-04 <i>33FO-04 : 550/B</i>	FLOOD LIGHT VERTICAL TAIL FACTORY OPTION	*CF		54 FO	MTH 22-Nov-1986		-			
34FO-03 <i>34FO-03 : 550/B</i>	HORIZON GYRO ELECTRIC STANDBY FACTORY OPTION	*CF		142 FO	MTH 22-Nov-1986		-			
34FO-04 <i>34FO-04 : 550/B</i>	LOCATOR BEACON EMERGENCY FACTORY OPTION	*CF		175 FO	MTH 22-Nov-1986		-			
34FO-07D <i>34FO-07 : 550/D</i>	2ND TRANSPONDER- COLLINS TDR-90 FACTORY OPTION	*CF		623D FO	MTH 22-Nov-1986		-			



CESCOM 10 - Aircraft Status Report

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:46AM**

Tracking Rate	Hours	Events/ Landings	Last Actual Date	Average Daily Utilization
AIRCRAFT	8392.47	5660	05-Sep-2019	.03
ENG 1	8152.33	5632	05-Sep-2019	.17
ENG 2	8170.33	5507	05-Sep-2019	.9
AIR COND	4353.2		05-Sep-2019	.9

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
34FO-08	ALT REPORT DUAL W/DC ENCODING ALTIMETER FACTORY OPTION	*CF		625 FO	MTH 22-Nov-1986		-			
34FO-14Z <i>34FO-14 : 550/Z</i>	RADIO ALTIMETER-ALT55B FACTORY OPTION	*CF		672Z FO	MTH 22-Nov-1986		-			
34FO-15B <i>34FO-15 : 550/B</i>	FLIGHT DIRECTOR LH-5 " SINGLE CUE SPERRY FACTORY OPTION	*CF		679B FO	MTH 22-Nov-1986		-			
34FO-15J <i>34FO-15 : 550/J</i>	FLIGHT DIRECTOR REM CRS & HDG SGL SPERRY FACTORY OPTION	*CF		679J FO	MTH 22-Nov-1986		-			
34FO-16J <i>34FO-16 : 550/J</i>	2ND DME COLLINS DME4 0 FACTORY OPTION	*CF		681J FO	MTH 22-Nov-1986		-			
34FO-20P <i>34FO-20 : 550/P</i>	TRUE AIRSPEED FACTORY OPTION	*CF		693P FO	MTH 22-Nov-1986		-			
34FO-20R <i>34FO-20 : 550/R</i>	VLF NAV GLOBAL GNS500A SER 3 FWD FACTORY OPTION	*CF		693R FO	MTH 22-Nov-1986		-			
34FO-96A <i>34FO-96 : 550/A</i>	RADAR-PRIMUS 400 SL- COLOR FACTORY OPTION	*CF		632A FO	MTH 22-Nov-1986		-			
35FO-02B <i>35FO-02 : 550/B</i>	OXYGEN SYSTEM 64 CUBIC FEET FACTORY OPTION	*CF		66B FO	MTH 22-Nov-1986		-			
73FO-01C <i>73FO-01 : 550/C</i>	ENGINE SYNCHRONIZING INSTRUMENT W/TH REV FACTORY OPTION	*CF		76C FO	MTH 22-Nov-1986		-			
78FO-01	THRUST REVERSERS FACTORY OPTION	*CF		193 FO	MTH 22-Nov-1986		-			



CESCOM 20 - Projected Maintenance Due

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:48AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	8392.47	5660	05-Sep-2019	.03	0.66	497.07	370	756	24
ENG 1	8152.33	5632	05-Sep-2019	.17	0.66	497.07	370	756	24
ENG 2	8170.33	5507	05-Sep-2019	.9	0.66	497.07	370	756	24
AIR COND	4353.2		05-Sep-2019	.9	0.16	124.23		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
051233N	INSPECT CONCORDE BATTERY INSPECTION	KCRQ			MTH 29-May-2018 HRS 8334.1 LDG 5614		12 600		31-May-2019 8934.1	-3 m 5 d 541.63
										Over Due
053464	INSPECT NAV DATA UPDATE	KCRQ			DAYS 23-May-2019 HRS 8392.9 LDG 5654 MSC				20-Jun-2019	-2 m 16 d
										Over Due
256003	REPLACE LOCATOR BEACON TRANSMITTER BATTERY	KGJT			MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4220.4		24	0	30-Jun-2019	-2 m 5 d
										Over Due
5-12-26 051226	PHASE 26	KGJT			MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		24 3000		30-Jun-2019 11250.1	-2 m 5 d 2857.63
										Over Due
5-12-52 051252	PHASE 52	KCRQ			MTH 16-Aug-2018 HRS 8346.4 LDG 5621	-47	12		30-Jun-2019	-2 m 5 d
										Over Due
A237003 051221 : CVR	INSPECT COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	KGJT			DK100 MTH 08-Jun-2017 DV15665 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
										Over Due
A341006 051220	CHECK STATIC PORT HEIGHT AND SLOPE CHECK (AIRPLANES CERTIFIED FOR RVSM): PHASE 20	KGJT			MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
										Over Due
B237004 051221 : CVR	OPERATIONAL TEST COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON : PHASE 21	KGJT			DK100 MTH 08-Jun-2017 DV15665 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
										Over Due
B341003 LEFT 051220 : L-ALT	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT			4016341-905 MTH 08-Jun-2017 6110287 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
										Over Due
B341003 NO. 1 051220 : ADC	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20	KGJT			7024900-30302 MTH 08-Jun-2017 05011012 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d
										Over Due



CESCOM 20 - Projected Maintenance Due

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:48AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	8392.47	5660	05-Sep-2019	.03	0.66	497.07	370	756	24
ENG 1	8152.33	5632	05-Sep-2019	.17	0.66	497.07	370	756	24
ENG 2	8170.33	5507	05-Sep-2019	.9	0.66	497.07	370	756	24
AIR COND	4353.2		05-Sep-2019	.9	0.16	124.23		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
B341003	AUTOMATIC PRESSURE ALTITUDE REPORTING SYSTEM, AIR DATA COMPUTER AND ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20									
STANDBY		570-24929-013	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : STDBY		2288	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341003	CALIBRATION TEST ADC/ALTIMETER -- : PHASE 20									
STANDBY		70251N02D04	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : ADC#2		040413500	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341004	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20									
LEFT		4016341-905	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : L-ALT		6110287	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341004	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20									
STANDBY		570-24929-013	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : STDBY		2288	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341005	LEAK TEST STATIC SYSTEM: PHASE 20									
LEFT			MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : L			HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341005	LEAK TEST STATIC SYSTEM: PHASE 20									
RIGHT			MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : R			HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341107	CHECK ALTIMETER (AIRPLANES CERTIFIED FOR RVSM): PHASE 20									
LEFT		4016341-905	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : L-ALT		6110287	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341107	CHECK AIR DATA COMPUTER (AIRPLANES CERTIFIED FOR RVSM) : PHASE 20									
NO. 1		7024900-30302	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : ADC		05011012	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341107	BAROMETRIC ALTIMETER - PERFORM CALIBRATION TEST: PHASE 20									
STANDBY		570-24929-013	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : STDBY		2288	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due
B341107	CHECK ADC/ALTIMETER -- (AIRPLANES CERTIFIED FOR RVSM): PHASE 20									
STANDBY		70251N02D04	MTH	08-Jun-2017			24		30-Jun-2019	-2 m 5 d
051220 : ADC#2		040413500	HRS	8250.5						
			LDG	5563						
			ACH	4320.4						Over Due



CESCOM 20 - Projected Maintenance Due

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:48AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	8392.47	5660	05-Sep-2019	.03	0.66	497.07	370	756	24
ENG 1	8152.33	5632	05-Sep-2019	.17	0.66	497.07	370	756	24
ENG 2	8170.33	5507	05-Sep-2019	.9	0.66	497.07	370	756	24
AIR COND	4353.2		05-Sep-2019	.9	0.16	124.23		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Overdue Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
B345001 LEFT 051221	CALIBRATION TEST TRANSPONDER	KGJT		TRANSPONDER SYSTEM: PHASE 21 622-1270-001 28045	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
B345001 RIGHT 051221 : R	CALIBRATION TEST TRANSPONDER	KGJT		TRANSPONDER SYSTEM: PHASE 21 622-1270-001 28174	MTH 08-Jun-2017 HRS 8250.5 LDG 5563 ACH 4320.4		24		30-Jun-2019	-2 m 5 d Over Due
053460	INSPECT BFG ADI-330	CRQ			MTH 07-Jul-2016 HRS 8069.5 LDG 5456 ACH 4258.7		36 1200		31-Jul-2019 9269.5	-1 m 5 d 877.03 Over Due
B350004 051222 : OXY	HYDROSTATIC TEST OXYGEN CYLINDER ASSEMBLY	CRQ		DOT 3HT 1850 OR DOT 3FC1850 OR MANUFACTURED UNDER DOT-SP-8162. 176176-64 633812	MTH 07-Jul-2016		36		31-Jul-2019	-1 m 5 d Over Due
5-12-18 051218	PHASE 18	KCRQ			MTH 16-Aug-2018 HRS 8346.4 LDG 5621		12		31-Aug-2019	-5 d Over Due

Scheduled Maintenance Tasks

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	C/W Time 1 C/W Time 2	Adj. + or -	TBO 1 TBO 2	TSO 1 TSO 2	(ENG) DUE 1 (ENG) DUE 2	Remains Remains
5-12-0B 051200B	PHASE B	KGJT			MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		150		8400.1	7.63
A262003 AFT 051208 : A	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X561984	MTH 07-Mar-2019		6		30-Sep-2019	25 d
A262003 FORWARD 051208 : F	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X571070	MTH 07-Mar-2019		6		30-Sep-2019	25 d
B342004 051211	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY	KCRQ		LEAD ACID PS835 BATTERY PACK: PHASE 11 501-1228-04 12500	MTH 14-May-2019 HRS 8392 LDG 5651		6		30-Nov-2019	2 m 25 d
053424A	INSPECT EGPWS 12 MO				MTH 15-Feb-2017 HRS 8195.5 LDG 5532		36 1200		29-Feb-2020 9395.5	5 m 24 d 1003.03
053462	INSPECT GPS NAV				MTH 15-Feb-2017 HRS 8195.5 LDG 5532		36 1200		29-Feb-2020 9395.5	5 m 24 d 1003.03
053463	INSPECT RDR-2100				MTH 15-Feb-2017 HRS 8195.5 LDG 5532		36 1200		29-Feb-2020 9395.5	5 m 24 d 1003.03
059983I	INSPECT IHAS 1200H/36M				MTH 15-Feb-2017 HRS 8195.5 LDG 5532		36 1200		29-Feb-2020 9395.5	5 m 24 d 1003.03



CESCOM 20 - Projected Maintenance Due

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:48AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	8392.47	5660	05-Sep-2019	.03	0.66	497.07	370	756	24
ENG 1	8152.33	5632	05-Sep-2019	.17	0.66	497.07	370	756	24
ENG 2	8170.33	5507	05-Sep-2019	.9	0.66	497.07	370	756	24
AIR COND	4353.2		05-Sep-2019	.9	0.16	124.23		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
230017 237010	COCKPIT VOICE RECORDER UNDERWATER LOCATOR BEACON CRQ			DK100 DV15665	MTH 01-May-2014 HRS 7931.8 LDG 5349		72	2	31-Mar-2020	6 m 26 d
262101 FORWARD LEFT 262003 : FL	FIRE EXTINGUISHER CARTRIDGE			AE13083-5 LOT 0610358544	MTH 10-Jul-2010 HRS 7115 LDG 4716		120	0	31-Mar-2020	6 m 26 d
262101 FORWARD RIGHT 262003 : FR	FIRE EXTINGUISHER CARTRIDGE			AE13083-5 LOT 0610358544	MTH 10-Jul-2010 HRS 7115 LDG 4716		120		31-Mar-2020	6 m 26 d
A262003 AFT 051208 : A	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8			KCRQ A352TS X561984	MTH 07-Mar-2019		6		31-Mar-2020	6 m 26 d
A262003 FORWARD 051208 : F	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8			KCRQ A352TS X571070	MTH 07-Mar-2019		6		31-Mar-2020	6 m 26 d
057110 E1	MINOR INSPECTION	KCRQ			MTH 26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
057110 E2	MINOR INSPECTION	KCRQ			MTH 26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
741030 E1 LOWER	VISUAL INSPECT IGNITION EXCITER	KCRQ		9049770-3 NNA06465140	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
741030 E1 UPPER	VISUAL INSPECT IGNITION EXCITER	KCRQ		9049770-3 NNA06465140	MTH 26-Apr-2018 HRS 8318.3 LDG 5605		24 300		30-Apr-2020 (8365.9)8618.3	7 m 25 d 225.83
741030 E2 LOWER	VISUAL INSPECT IGNITION EXCITER	KCRQ		NB01201 R7153	MTH 26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
741030 E2 UPPER	VISUAL INSPECT IGNITION EXCITER	KCRQ		NB01201 K8974	MTH 26-Apr-2018 HRS 8314.22		24 300		30-Apr-2020 (8392.1)8614.22	7 m 25 d 221.75
5-12-0B 051200B	PHASE B	KGJT			HRS 8250.1		150		8550.1	157.63
B342004 051211	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY	KCRQ		LEAD ACID PS835 BATTERY PACK: PHASE 11 501-1228-04 12500	MTH 14-May-2019		6		31-May-2020	8 m 26 d
5-12-MA	PHASE MA	KCRQ			MTH 19-Oct-2017 HRS 8286.5 LDG 5582 ACH 4334.4		300		8586.5	194.03
5-12-05 051205	PHASE 5	KGJT			MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		36 1200		30-Jun-2020 9450.1	9 m 25 d 1057.63
5-12-49 051249	PHASE 49	KGJT			MTH 08-Jun-2017 HRS 8250.1 LDG 5563 ACH 4320.4		36 1200		30-Jun-2020 9450.1	9 m 25 d 1057.63
262003 FORWARD LEFT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 LOT 0610358544	MTH 10-Jul-2010		120		31-Jul-2020	10 m 26 d
262003 FORWARD RIGHT	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE)			AE13083-5 LOT 0610358544	MTH 10-Jul-2010		120		31-Jul-2020	10 m 26 d
5-12-01 051201	PHASE 1	KCRQ			MTH 16-Aug-2018 HRS 8346.4 LDG 5621		24 300		31-Aug-2020 8646.4	11 m 26 d 253.93



CESCOM 20 - Projected Maintenance Due

Owner: **MT PROPERTY GROUP, LLC**
 Aircraft Model: **S550 - CITATION SII**
 Aircraft Serial: **S550-0119**
 Unit: **0119** Reg No: **N616TG**
 Airworthiness: **22-Nov-1986**
 Print Date: **05-Sep-2019 11:48AM**

Tracking Rate	Last Actual			Daily Utilization		Projection			
	Hours	Events/Landings	Date	Average	Projected	Hours	Events/Landings	Days	Months
AIRCRAFT	8392.47	5660	05-Sep-2019	.03	0.66	497.07	370	756	24
ENG 1	8152.33	5632	05-Sep-2019	.17	0.66	497.07	370	756	24
ENG 2	8170.33	5507	05-Sep-2019	.9	0.66	497.07	370	756	24
AIR COND	4353.2		05-Sep-2019	.9	0.16	124.23		756	24

**** Please note the presentation of Service Bulletins without due times will no longer appear on this report. All applicable Service Bulletins can still be found on the CESCOM 10 report. Please contact your Aircraft Analyst for any questions regarding this change.**

Scheduled Maintenance Tasks

Item Code	Description	Part Number	C/W Time 1	Adj.	TBO 1	TSO 1	(ENG) DUE 1	Remains		
Position	Drawing # / Task #	City	Mod Lvl	Part Serial No	C/W Time 2	+ or -	TBO 2	TSO 2	(ENG) DUE 2	Remains
5-12-02 <i>051202</i>	PHASE 2	KCRQ		MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
				HRS	8346.4		300		8646.4	253.93
				LDG	5621					
5-12-03 <i>051203</i>	PHASE 3	KCRQ		MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
				HRS	8346.4		300		8646.4	253.93
				LDG	5621					
5-12-04 <i>051204</i>	PHASE 4	KCRQ		MTH	16-Aug-2018		24		31-Aug-2020	11 m 26 d
				HRS	8346.4		300		8646.4	253.93
				LDG	5621					
052513	INSPECT GALY/VANTY 300 HRS	CRQ		MTH	16-Aug-2018					
				HRS	8346.4		300		8646.4	253.93
				LDG	5621					
5-12-58	PHASE 58	KCRQ		MTH	16-Aug-2018					
				HRS	8346.4		300		8646.4	253.93
				LDG	5621					
A262003 AFT <i>051208 : A</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X561984	MTH	07-Mar-2019	6		30-Sep-2020	12 m 25 d
A262003 FORWARD <i>051208 : F</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X571070	MTH	07-Mar-2019	6		30-Sep-2020	12 m 25 d
B342004 <i>051211</i>	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY LEAD ACID PS835 BATTERY PACK: PHASE 11	KCRQ		501-1228-04 12500	MTH	14-May-2019	6		30-Nov-2020	14 m 25 d
5-12-0B <i>051200B</i>	PHASE B	KGJT		HRS	8250.1		150		8700.1	307.63
243001 RIGHT	STARTER/GENERATOR	KCRQ		23085-004-1 98060	MTH	20-Dec-2012		0		
				HRS	7748.2		1000	0	8748.2	355.73
				LDG	5206			0		
B326003 <i>051222 : GEAR</i>	HYDROSTATIC TEST EMERGENCY GEAR AIR BOTTLE : PHASE 22	CRQ		212940-2 2262	MTH	28-Feb-2018	36		28-Feb-2021	17 m 23 d
A262003 AFT <i>051208 : A</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X561984	MTH	07-Mar-2019	6		31-Mar-2021	18 m 26 d
A262003 FORWARD <i>051208 : F</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X571070	MTH	07-Mar-2019	6		31-Mar-2021	18 m 26 d
B342004 <i>051211</i>	INSPECT/OPERATIONAL TEST STANDBY GYRO POWER SUPPLY LEAD ACID PS835 BATTERY PACK: PHASE 11	KCRQ		501-1228-04 12500	MTH	14-May-2019	6		31-May-2021	20 m 26 d
5-12-0B <i>051200B</i>	PHASE B	KGJT		HRS	8250.1		150		8850.1	457.63
5-12-MA	PHASE MA	KCRQ		HRS	8286.5		300		8886.5	494.03
A262003 AFT <i>051208 : A</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X561984	MTH	07-Mar-2019	6		30-Sep-2021	24 m 25 d
A262003 FORWARD <i>051208 : F</i>	INSPECT/WEIGH PORTABLE FIRE EXTINGUISHER : PHASE 8	KCRQ		A352TS X571070	MTH	07-Mar-2019	6		30-Sep-2021	24 m 25 d